SUPPLEMENTAL ENVIRONMENTAL PROJECT – QUANTIFYING THREAT TO WATER QUALITY FROM SEWAGE SPILLS FROM PRIVATE PROPERTIES AND LATERALS AND PROPOSED CONTROL MEASURES IN THE SANTA ANA REGION OF ORANGE COUNTY

Prepared for:

Orange County Sanitation District

10844 Ellis Avenue Fountain Valley, California 92708-7018 Contact: Ann Crafton, SR/WA

Prepared by:

750 Second Street Encinitas, California 92024 *Contact: Steve Jepsen*

JUNE 2008

TABLE OF CONTENTS

Page No.

EXECUTIVE SUMMARYiii
PURPOSE1
BACKGROUND1
DATA ACQUISITION AND ANALYSIS
EXCLUSIONS
BEACH CLOSURES
FINDINGS
PATTERNS10
EXISTING LOCAL PROGRAMS11
BEST MANAGEMENT PRACTICES12Educational Outreach14Fats, Oils and Grease Reduction Program14Inspection After An Overflow16Public Agency Notification to Property Owners17Scheduled Reoccurring Lateral Inspections17Scheduled Lateral Inspections Based Upon Remodels18Lateral Inspection Upon the Sale or Transfer of Property18Certification Program for Licensed Plumbers19Financial Assistance Programs19
IMPLEMENTATION OF BMPS20
SYNOPSIS
APPENDICES
ACKNOWEDGEMENT

LIST OF APPENDICES

- A Modified Master Private Property Spills 2002–2006 Sorted by Agency
- B Modified Master Private Property Spills 2002–2006 Sorted by Date
- C Modified Master Private Property Spills 2002–2006 Sorted by Cause
- D Modified Master Private Property Spills 2002–2006 Sorted by Property Type
- E Modified Master Private Property Spills 2002–2006 Sorted by Impact
- F Modified Master Private Property Spills 2002–2006 Sorted by Beach Closure
- G Initial Summary Analysis
- H Region 8 and 9 Orange County Boundary Line
- I City of La Palma Sewer Ordinance
- J Private Property BMP Ranking
- K CR&R Waste & Recycling Services Letter
- L City of Santa Barbara Private Lateral Policy
- M City of Berkeley Private Lateral Policy
- N City of Burlingame Private Lateral Policy
- O City of Pacific Grove Certified Plumbers List

LIST OF TABLES

1	Summary of Private Property Spills in Region 8, Orange County
	May 2002 – December 2006

EXECUTIVE SUMMARY

Because of concerns for the potential of private property sewage spills to result in threats to the environment and to the public health as well as economic loss from beach closures, the Santa Ana Regional Water Quality Control Board, Region 8 provided a supplemental environmental projects grant to the Orange County Sanitation District to conduct a study on private property sewage spills. The intent of the study was to determine if the frequency and spill volume from private property spills is a significant threat to the environment. If the threat was considered to be significant, the study would determine best management practices to reduce private property spills and their impact.

The portion of Orange County within Region 8 was chosen for the study. This area was chosen as the dischargers had been under waste discharge requirements imposed by Region 8 since April 26, 2002. The waste discharge requirements required reporting of all sewage spills, public and private, of any volume, to the Santa Ana Regional Water Quality Control Board. These spill reports along with spill reports filed with the Orange County Health Care Agency were the basis for the private property spill study.

To assist in the private property spill study, the Orange County Sanitation District contracted with Dudek Engineering. A committee was formed comprised of individuals from Orange County Sanitation District, Dudek and Ken Theisen of the Santa Ana Regional Water Quality Control Board staff to review the analyzed data, rate the best management practices and ensure the study met the established goals of the supplemental environmental project.

The Santa Ana Regional Water Quality Control Board staff provided spill reports from all of the Region 8 dischargers who reported from May 2002 through December 2006. The Orange County Health Care Agency provided its private property spill reports and beach closure reports from the same geographical area and time period. These reports were analyzed to eliminate duplicates and any spills from public agencies. They were then categorized to determine spill cause, property type, location, impact on receiving waters and resulting beach closures.

Based upon the analyzed data, it was determined that the primary threat from private property spills came from multifamily residential dwellings with grease being the primary cause for these spills. It was also determined that these private property spills result in beach closures at approximately the same rate as public agency spills. The data also indicated that although public agency spills were tending to decline during the study period, private property spills tended to increase. Based upon the analyzed data, the committee determined that private property spills are significant and best management practices for their reduction should be employed.

Nine best management practices were developed to address private property spills. The best management practices were ranked by the committee for their effectiveness in addressing the issue, feasibility and cost. Of the nine, one was considered the most effective and recommended for implementation. This best management practice involves the closed circuit television inspection of the private sewer lateral within a specified number of days following an overflow. The committee recommended the remaining eight best management practices as alternatives for future use. The committee further recommended the best management practices only be applied to multifamily residential dwellings as the potential threat from these spills far exceeds those from single-family residential dwellings. Commercial spills are almost entirely from food service establishments who are currently under fats, oil and grease reduction programs through their local sewering agencies.

Implementation of the best management practices would initially be voluntary in cooperation with the local sewering agencies. Should the desired effect not be achieved, the Santa Ana Regional Water Quality Control Board may need to develop waste discharge requirements, similar to those in place for public sewering agencies, for multifamily residential dwellings to ensure proper maintenance and operation of these private sewer systems, thus reducing the potential for sewage spills.

PURPOSE

The purpose of this private property sewage spills study is to determine the impact that spills had on the environment from May 2002 through December 2006. The Santa Ana Regional Water Quality Control Board, Region 8 initiated the study through a grant issued to the Orange County Sanitation District (OCSD). A private property sewage spill is one that occurs on private property due to a blockage, failure or overflow of the private sewer lateral that serves that property. A sewage spill that occurs on private property due to a blockage or failure of the public sewer system is not a private property sewer spill. Only private property sewage spills were considered for this study.

The study was conducted in two phases. In Phase One, spill data was collected, organized, and analyzed from all reported sewer spills that occurred in Orange County within the jurisdiction of the Region 8 Board. In Phase Two, effective best management practices (BMPs) were developed to reduce private property sewer spills if in Phase One the spills were shown to cause a significant threat to the environment.

BACKGROUND

In May 2002, the Region 8 Board adopted General Waste Discharge Requirements (WDR) for all publicly owned sewage collection systems within Region 8. Based upon the Capacity, Management, Operations and Maintenance (CMOM) regulations adopted by the Environmental Protection Agency, Region 4, the WDR required affected agencies to develop a Sewer System Management Plan (SSMP) and required the reporting of all (public and private) sanitary sewer overflows (SSOs). Reporting timelines and requirements for public spills were based upon the severity of the spill, with private spills being reported on a monthly summary as the agency became aware of them. The WDR did not require the public agencies to take responsibility for private property spills other than to report them if they became aware of them.

The Region 8 WDR was implemented on April 26, 2002, with a new element required approximately every six months. These elements, which constitute the SSMP, included establishing system goals; legal authority; system maintenance program; emergency response plan; a fats, oils and grease reduction program; a system evaluation and capacity assurance program; a communications program; and a dedicated source of funding. The goal was to establish a minimum standard for the operation and maintenance of Region 8 collection systems in Orange County.



DATA ACQUISITION AND ANALYSIS

The Orange County Health Care Agency (OCHCA) and Region 8 provided the data used in this study. To review and analyze the data, a committee was formed with members from OCSD and Dudek and Ken Theisen from Region 8. Regularly scheduled meetings were held to review progress and make decisions based upon the data received and reviewed.

OCHCA Data

Larry Honeybourne from OCHCA was contacted and asked to provide data on all private property spills reported to the OCHCA from May 2002 through December 2006 within the Region 8 area. OCHCA provided a Microsoft Excel spreadsheet extending from September 27, 1999, to July 24, 2007. The spreadsheet was found to also contain some data from South Orange County, Region 9. A modified spreadsheet was created that only included data from May 2002 through December 2006. Entries that were obviously in Region 9 (San Clemente, Dana Point, Laguna Beach, etc.) were removed. Those entries that were in the service areas of Irvine Ranch Water District (IRWD) and the El Toro Water District (ETWD) were left in, as these agencies have jurisdiction in both Regions 8 and 9. This overlap may account for some of the spill reports from OCHCA that do not appear on either IRWD or ETWD Region 8 spill reports.

The OCHCA spill spreadsheet was also found to have numerous duplicated reports. One entry was repeated four times, and almost all of the entries from the cities of La Habra and La Palma were entered twice. The OCHCA spreadsheet was also incompatible with the reporting format used by most of the Region 8 dischargers. To rectify this, a new spreadsheet was created and patterned after the one used for the Region 8 data. Data records from the OCHCA spreadsheet were cut and pasted into the new spreadsheet. "N/A" was placed in the data fields where data was unavailable from the OCHCA spreadsheet. This spreadsheet was then added to the Master Monthly Report worksheet that is broken down by reporting agency. To eliminate duplicate reports, each data record on the OCHCA spreadsheet was compared to data records on the Master Monthly Report worksheet. Date of spill, spill volumes, spill address, and other pertinent data was compared. If an OCHCA data record in the Master Monthly Report worksheet contained a spill report that was duplicated by another reporting agency, that data record was removed from the OCHCA section of the Master Monthly Report worksheet. The remaining data records in the OCHCA section of the Master Monthly Report worksheet are spill reports reported to the OCHCA but apparently not to Region 8. Of the 310 spill reports on the original OCHCA spreadsheet extending from May 2002 through December 2006, 231 were removed for being duplicate reports or having been reported by another agency in Region 8. Lastly, 79 spill reports

remain as not having been reported to Region 8 (several of the spill reports reported to OCHCA may actually be in Region 9 but are close to the boundary between Regions 8 and 9).

In addition to the report submitted by OCHCA, the Beach Closure Reports for years 2002 through 2006 were used to determine how many private property spills resulted in Orange County beach closures. The reports are compiled by the OCHCA and are available online. Upon review of the Beach Closure Reports, several new spills were found that were not listed in either the reports from the individual agencies of Region 8 or the OCHCA submitted report or that were listed but not marked as private property spills. These spills were added to the data being analyzed and are shown in *Appendix F*.

Region 8 Data

The original data received from Region 8 was insufficient to conduct this study. Due to a major computer failure at the Region 8 office, only about 30% of the data originally sent to the regional office by the Orange County cities and districts was available, and some of that appeared to be corrupted. None of this data was used in this study. To remedy this problem, Region 8 requested that all of the cities and districts in the Orange County portion of Region 8 resubmit their May 2002 through December 2006 summary reports via email to the regional office. Once received, the data was forwarded to Dudek for use in this study.

In 2002, as Region 8 was getting its WDR prepared for adoption, OCSD formed a WDR Steering Committee, comprised of select agency representatives from its member agencies. This group was charged with assisting the WDR permittees in complying with the new order by developing policies, procedures, models, and templates necessary for the development and implementation of the SSMP. To assist in this effort, OCSD developed an Excel spreadsheet that was comprised of 47 different data fields for each spill report or spill record. This spreadsheet satisfied the reporting requirements of the new WDR and was provided as a template for use by OCSD's member agencies. Use of the template was voluntary.

Of the data that was supplied by Region 8 for this study, only about half of the agencies utilized the OCSD template (or some close derivative) for their summary report. Of these, some of the agencies provided a single spreadsheet that summarized all spills from May 2002 through December 2006; others provided individual monthly or yearly reports that had to be summarized. A couple of agencies had locked their spreadsheets or had omitted several months of data. These agencies were contacted, and they provided the missing or unlocked data. For those agencies that chose not to use the OCSD template, or who were not OCSD member agencies, data was provided in Excel, Microsoft Word tables, or single spill reports in Microsoft Word format.

Because of this, the data provided was inconsistent between agencies. Some agencies were very detailed in their reporting, while others were very limited in the information provided.

To provide an accurate analysis, data had to be placed into a consistent format. To assist with this, a progress meeting was held at OCSD on November 7, 2007 to discuss the preliminary data and determine the most appropriate data for the study. A modified version of the OCSD template was chosen as the format. The number of data fields was reduced from 47 to 18 to make the data more manageable while eliminating those fields that were not directly related to private property spills. At this meeting, it was also determined that the spills should be categorized based upon their cause and the type of property involved in the spill. Spill causes consisted of Unknown, Grease, Roots, Debris, Grease and Roots, and Structural. The property types selected were: Unknown, Single-Family Residential, Multifamily Residential, Commercial, and Institutional/Public. Spill causes and property types are further defined in the Appendices section of this report.

To prepare the data for analysis, each agency was given its own folder containing the data provided by Region 8 for that agency. A private property spill spreadsheet was created based upon the 18 chosen data fields, with a copy placed in each agency folder. Each spill record was reviewed to determine if a spill report was private or public. If the "Responsible Party" field indicated that the spill was private, it was categorized as such. If the "Responsible Party" field indicated that the agency was responsible, the remaining data, "Likely Cause of SSO," "Overflow Cause Detailed Description," "Remarks," and other fields were reviewed to determine if the spill was public or private. This was done in a copy of each agency's spill report so that the original data would remain intact. If the agency already had a summary spreadsheet for all of its spills during the study period, the private property spills were cut and pasted into the new private property spills spreadsheet. If the agency submitted its data by month or year, a single summary spreadsheet was created. Data from that spreadsheet was then cut and pasted into that agency's private property spreadsheet. If the agency utilized some different format for reporting the private property spills, spill data was extracted and pasted into the private property spreadsheet, trying to match the required data fields as closely as possible. The cut-and-paste method was used to transfer data and reduce the potential of data error due to data reentry.

Midway City Sanitation District (MCSD) submitted its data as individual spill reports in Microsoft Word. Each report was reviewed to determine if it was a private or public spill. Data was extracted from the private property spill reports and entered into the private property spill spreadsheet created for MCSD. Likewise, IRWD's submission utilized Microsoft Word tables that had to be converted into the Excel private property spreadsheet.

Once each agency, including OCHCA, had a populated private property spill spreadsheet that reflected all private property spill reports from that agency, a Master Monthly Report worksheet was created. The Master Monthly Report worksheet contains all of the private property spill records, broken down by agency. The Master Monthly Report worksheet is part of the "MODIFIED MASTER Monthly SSO (Private Property Overflow Only) Reports 2002 to 2006-REVIEWED-7.xls" file included as *Appendix A* of this report and is the basis for the spill analysis that was conducted.

EXCLUSIONS

Certain data was excluded even though it was reported as private property spills. Spills that were caused by construction accidents (e.g., a contractor drilled through or broke the sewer line or failed to remove the bulkhead prior to putting a line in service) were not included in the study. Likewise, spills involving recreational vehicles dumping their holding tanks on public streets or parking lots, or spills involving the vandalism of Port-A-Potties, were omitted. There were less than a dozen of these types of spills reported during the period from May 2002 through December 2006. Spills that were reported in the harbor involving boats and the pump-out facilities were also excluded. BMPs for these types of spills are already in place.

Not all cities and districts that responded to Region 8's request for data are found in the study. The city of Sunset Beach verbally reported that they did not have any spills during the study period. Villa Park verbally reported that they only had one spill during the study period but did not include information about the spill. The city of Yorba Linda is listed in the study but includes no data, as the data they provided only include date, address, and spill volume for six spills, with no indication of the spills being public or private. For this reason, they were all considered to be public spills.

The city of Buena Park and the Garden Grove Sanitary District (GGSD) provided only limited information about their spills. The only data fields provided were spill date, responsible party, whether the spill entered receiving waters, spill volume lost and spill volume recovered. Addresses and other data that appear for these two agencies are actually from the OCHCA's spill reports that were matched during the analysis process. To avoid large areas of blank space on the worksheets, "N/A" was added to denote that the data field was reviewed but no data was present.

The city of Cypress provided data similar to the city of Buena Park and GGSD but included the addresses of its private property spills. The city of Orange also provided an abbreviated report similar to those mentioned but noted probable cause of the spill when it was known.

The study only examines spills that originated on private property. It does not consider spills that occurred in a public system that were a result of the activities of the private property owner. Some examples are grease, debris, or root balls forced into the public system through the cleaning or unblocking of private laterals. There is insufficient data in the reports to comment on the number or volumes released from this type of spill.

BEACH CLOSURES

OCHCA will close beaches that exhibit high bacteria levels caused by sewer spills or stormwater runoff. OCHCA posts information for public viewing on its Orange County Beach Info website (http://www.ocbeachinfo.com/) as part of its Ocean Water Protection Program. Annual reports of beach closures are available on the website from 1999 to present. These reports give a brief description of the reason for the beach closure, the dates of the closures, the number of days the beach was closed, and the beach mile days. Beaches that are closed as a result of sewage spills are normally closed for a minimum of three days. It takes 24 hours to process a water sample. Samples taken the day of the spill are not processed until the next day. If the sample exceeds ocean water quality standards, a second sample is taken that will not complete processing until the next day. The beach will remain closed until the bacteria levels meet ocean water quality standards.

Beach mile days are used by the OCHCA and others as a performance indicator to determine what effect sewage spills and other forms of pollution have on the beneficial use of the Orange County coastline. Beach mile days are a calculation of the linear footage (percent of a mile) of beach that is affected multiplied by the number of days the beach remains closed. For example, if one mile of beach is closed for one day, the result is one beach mile day. The amount of beach that is closed due to a sewage spill depends on several factors. These include: the volume of the spill; where the spill entered the water the geography and location of the beach; ocean currents and tides; OCHCA guidelines, etc. Not all sewage spills result in a beach closure. When a sewage spill is reported to the OCHCA, officials will consider the drainage of the watershed and its course to the ocean, the volume of the spill, the location of spill, OCHCA guidelines, and other factors to determine the probability of the sewage spill impacting the ocean beaches. A sewage spill occurring in a beach city is more likely to result in a beach closure than the same size sewage spill occurring in an inland city.

FINDINGS

Table 1 summarizes the information obtained from the private property spill analysis. The details of each spill are available in the Appendices. The volumes listed in *Table 1* are in gallons and

have been rounded to the nearest whole number. Percentages have also been rounded to the nearest whole percent. For the purpose of calculation, when spill volumes were reported as a range, the average of the range was used as the spill volume. If a greater than (>) or less than (<) symbol preceded a spill volume in the spill report, the symbols were omitted and only the spill volume used, as all spill volumes are considered to be estimates.

(Special note: Since not all of the cities and districts utilized the OCSD template or did not account for wash water, it is assumed wash water amounts are included in the amount lost and recovered data.)

Table 1

Summary of Private Property Spills in Region 8, Orange County May 2002 – December 2006

Approximate number of spills occurring in OC/R-8 5/2002-12/2006	1,403								
Number of private property spills (PP) reported (R-8 & OCHCA - minus duplicate reports)									
Percentage of PP spills to total spills									
Total PP spills reported to OCHCA	310								
Sumber of spills reported to OCHCA but not to R-8									
Number of private property spills reported by year									
2002 (partial)	104								
2003									
2004									
2005	163								
2006	168								
Private property spill volumes in gallons	·								
Total PP spill volume (volume lost + volume recovered + ww lost)	407,078								
Spill volume lost	208,254								
Spill volume recovered	149,389								
Wash water recovered	129,007								
Wash water lost									
Private property spill volumes by year in gallons									
Total PP spill volume (volume lost + volume recovered + ww lost)									
2002 (partial)	68,126								
2003	104,329								
2004									
2005									
2006									
Total private property spill volume lost by year in gallons									
2002 (partial) (volume lost + ww lost)	46,504								

2003		78,856						
2004	40,713							
2005	36,849							
2006	54,767							
Private property spills that reached surface waters		,						
Total number of spills to reach surface waters	115							
Percent to total number of spills	8%							
Total spill volume to reach surface waters in gallons (volume + ww lost)	95,542							
Total PP spills to reach surface waters by year	Volume							
2002	23	17,331						
2003	20	24,686						
2004	18	15,613						
2005	22	14,067						
2006	32	23,845						
Private property spills causing a beach closure	·							
Total number of spills that resulted in a Beach Closure		25						
Total spill volume that resulted in a Beach Closure (volume + ww lost)		19,990						
Beach Closures by Days and Miles of Impact	Days	BMD						
Total number of days closed and beach mile days (BMD).	71	8.97						
2002	25	3.00						
2003	14	2.90						
2004	9	1.00						
2005	0.38							
2006	13	2.07						
Private property spills listed by cause								
Total private property spills by cause and volume (lost + recovered)	Number	Volume						
Unknown	253	78,808						
Grease	240	132,477						
Roots	68	73,641						
Debris	57	19,783						
Grease & Roots	16	14,824						
Structural	38,115							
PP spills involving a grease trap or interceptor	28	5,923						
Private property spills by property type								
Total PP spills by property type and volume (lost + recovered)								
Unknown	34,297							
Single-family	73	2,831						
Multifamily	215	208,892						
Commercial	268	104,533						

Table 1 (Cont.)



Institutional/Public	6	7,090							
Private property spills with known causes by property type									
Single-family residential	Percent								
Known cause	38	53%							
Grease	4	11%							
Roots	17	45%							
Debris	9	24%							
Structural	8	21%							
Multifamily residential									
Known cause	155	72%							
Grease	91	59%							
Roots	25	16%							
Debris	18	12%							
Structural	17	11%							
Commercial									
Known cause	205	76%							
Grease	147	72%							
Roots	14	7%							
Debris	20	10%							
Structural	24	12%							
Private property spill averages									
Private property spill averages in gallons		Volume							
Average size private property spill		591							
Average size private property spill lost to environment		374							
Average amount of sewage recovered per spill		217							
Average size PP spill due to unknown cause		311							
Average size PP spill due to grease		552							
Average size PP spill due to roots		1,083							
Average size PP spill due to debris		347							
Average size PP spill due to grease & roots									
Average size PP spill due to structural cause									
Average size PP spill from a single-family residence		693 39							
Average size PP spill from a multifamily residence		972							
Average size PP spill from a commercial establishment		390							
Average size PP spill from a institutional/public establishm	ent	1,182							
Average amount of spill to reach surface waters		831							

Table 1 (Cont.)



Approximately 1,403 spills occurred in Region 8 during the period that the Region 8 WDR was in force. Of these, 689 spills (49%) were reported as private property spills. This does not include approximately a dozen spills that were a result of construction accidents, spills occurring at the harbor involving vessel pump-out facilities, recreational vehicle dumping, or vandalism involving Port-A-Potties.

The highest number of spills reported was in 2006 (168 spills). The highest spill volume (104,329 gallons) and the highest spill amount to reach surface waters (24,686 gallons) occurred in 2003. Of the spills to reach surface waters, 25 (19,990 gallons) resulted in 8.97 beach mile days and 71 days of beach closures. The highest year for beach closures was 2002 (partial year), with 25 days of closure and 3.00 beach mile days.

The primary cause of private property spills was grease. There were 240 spills that caused a release of 132,477 gallons of wastewater for which grease was the primary cause or a contributing factor. There were 28 spills from grease traps or interceptors which released 5,923 gallons of wastewater. Because the requirement for having properly maintained and inspected grease control devices was not implemented until the latter years of the study period, it is anticipated that spills involving grease control devices should drop as the cities' and districts' grease control programs mature.

The largest overall source of private property spills is multifamily residential units. Although multifamily spills (215) were slightly less than commercial spills (268), the volume of the spills was almost twice as high. Multifamily spills released 208,892 gallons, whereas commercial spills released 104,533 gallons. Single-family units had 73 spills and released 2,831 gallons of wastewater.

As a group, the average size of a private property spill was 591 gallons, with an average of 374 gallons being lost to the environment. However, for those private property spills that were reported to have reached surface waters, the average release was 831 gallons. The average size spill was 39 gallons from a single-family residential unit, 972 gallons from a multifamily unit, and 390 gallons from a commercial establishment. Although the table shows a significant average spill size from institutional/public, the sample size (number of spills) is too small for the data to be considered relevant.

PATTERNS

There were several interesting patterns that emerged as data were analyzed. With most cities and districts, the ratio of private spills to public spills dramatically increased during the study period.

OCSD reported a total of 107 spills, of which 66 (62%) were on private property. The same was true for the city of Anaheim, which reported a total of 130 spills, of which 88 (68%) were private property spills. Smaller agencies posted similar numbers; Rossmoor/Los Alamitos Area Sewer District reported 12 total spills, seven of which (58%) were private property spills. For the entire study period, there were approximately 1,324 spills reported to the Regional Board, of which 608 (excluding OCHCA reported spills), or 46%, were private property spills.

For those cities and districts that were able to determine a cause for their private property spills, the overwhelming factor was grease, with 240 spills in this category. This number increased to 256 spills (59% of the total spills with a known cause) when spills involving grease and roots were included.

During the review of the private property spills, it was common to see the public agencies as the first responder. It was also common to see the public agencies assisting the property owner in the remediation of the spill. This included clearing the blockage, spill cleanup, or assisting the property owner's contractor with the spill remediation.

For cities, it was also common to see the spill turned over to the city's code enforcement officer if there was an apparent code violation. In some cases, citations were issued or other punitive actions taken.

EXISTING LOCAL PROGRAMS

The majority of cities and districts within Region 8 only accept responsibility and ownership for the sewer mains. The lateral that services the individual property, including its connection to the mainline, is the sole responsibility of the property owner in most cases. There are exceptions where the city or district, by policy or practice, has taken responsibility for at least a portion of the private property lateral.

The city of Santa Ana has taken over the responsibility for the lower lateral, which runs from the property line to the mainline within the public right-of-way. Santa Ana will repair or replace defective lower laterals within the public right-of-way.

The city of Huntington Beach, although they have not taken over the ownership, will repair or replace the lower lateral within the public right-of-way if the lateral has collapsed or become defective to the point of not being serviceable. The homeowner retains responsibility for maintenance of the entire lateral.

The city of Newport Beach, like the city of Santa Ana, accepts responsibility for the lower lateral, provided that the property owner installs a cleanout at the property line.

The city of Fullerton will also accept responsibility for maintenance of the lower lateral and will routinely clean it, provided that the lateral is adjacent to a city-owned tree and the property owner installs a cleanout at the property line.

The city of Placentia will, on a case-by-case basis, reimburse property owners for damage done to a private lateral from a city-owned tree, but the city will also remove the offending tree.

The El Toro Water District (ETWD) maintains responsibility for the lower lateral to three feet beyond the property line. ETWD will repair or replace the lower lateral, including the removal of blockages should they occur within the lower lateral.

The newest program to assist homeowners is from the Costa Mesa Sanitary District (CMSD). With its Residential Sewer Lateral and Clean Out Financial Assistance Program, CMSD will pay 50%, up to \$1,800, per residential parcel, to clean the lateral, conduct closed-circuit television (CCTV) investigation of the lateral, install a cleanout, or make necessary lateral repairs.

BEST MANAGEMENT PRACTICES

The intent of the private property spill study was to analyze the effects of private property sewage spills and determine their impact on the environment. If the impact was determined to be significant, then BMPs were to be developed as tools to reduce the occurrence of private property sewage spills. After all the provided spill data had been analyzed, the results were reviewed by the committee and it was determined that the impact of private property spills was significant enough to recommend BMPs. This conclusion was endorsed by Ken Theisen at the March 26, 2008 progress meeting in part because the ratio of private property spills that resulted in beach closures was almost the same as for all spills that resulted in beach closures. Beach closures, in addition to being a serious health risk, have a significant financial impact on Orange County businesses.

There is no intent through the recommendation or development of BMPs to require public agencies (cities, counties or special districts) to accept responsibility for the private property owner's sewer system or to hold public agencies responsible, in any way, for sewer spills that occur in private systems. Current law does not allow public agencies to be liable or accept responsibility for property they do not own. Many cities and districts have ordinances that specifically define the responsibilities of the public agency and the private property owner for the

sewer system. The city of La Palma's Ordinance 2007-02 is provided as an example in *Appendix I* and states that the city is responsible for the mainline with the private property owner being responsible for the entire sewer lateral serving the property, including the connection point with the city's mainline.

BMPs are intended to provide cities and districts with additional tools to help operate and maintain the sewage collection system. These BMPs can be of particular importance to cities in the enforcement of their stormwater NPDES (National Pollutant Discharge Elimination System) permits. Because private property spills tend to migrate into the city's stormwater collection system, these BMPs will offer cities additional tools to help prevent future private property overflows.

Nine BMPs were developed for the committee's consideration. These BMPs are not new; in concept they have all been utilized by different agencies to differing degrees throughout the state. What is new is to not limit the BMPs to one or two, which is the most common practice, but to have all of them developed for future use based upon site-specific conditions. The BMPs would be applied progressively and would target specific property types that present the highest potential for environmental harm. This ensures that the BMPs would have a positive cost/benefit with resources being directed to specific problem areas and not simply spread over the entire community. To this end, the committee determined that the BMPs would initially only target multifamily residential dwellings. The data suggests that multifamily residential dwellings represent the single highest risk of substantial sewer overflows, thus the greatest risk to the environment. A greater emphasis would also be placed upon coastal communities as opposed to inland communities. Private property spills in coastal communities have a greater potential for causing a beach closure than spills occurring in inland communities. At this time, single-family residential dwellings and commercial properties would not be subject to the BMPs unless a city or district felt they needed to impose them on a case-by-case basis. Spills from single-family residential dwellings were determined to be insignificant due to their relatively low (average 39 gallons) volume. The vast majority of commercial spills involved food service establishments. The consensus of the committee is that there are sufficient requirements in the GWDR that implementing additional BMPs for commercial establishments is not necessary at this time.

At the March 26, 2008 progress meeting, the nine proposed BMPs were ranked by the committee. The ranking looked at each BMP's effectiveness, their ability to address the problem, the cost, who would pay the cost, and feasibility. Rankings were ordered from 1 to 5 with 5 being the most desirable and 1 being the least desirable. Rankings were also based upon implementing the BMPs only for multi-family residential dwellings. The rankings established by

the committee are in *Appendix J*. The following nine BMPs were reviewed and ranked by the committee with the committee's comments included with each BMP.

Educational Outreach

The educational outreach program would stress the proper use of the sewer system with instruction of what types of material may or may not be disposed of within the sewer system. Although the committee acknowledged the need and benefit of an educational outreach program, it was concluded that for this study, an educational outreach program specifically aimed at private property spills would have a low level of effectiveness. This is primarily due to the time that it takes for educational outreach programs to change the behavior patterns of a targeted community. The California state recycling program is an example of a program that literally took decades to reach the level of success that it has today. Several of the cities and districts in the study are already conducting educational outreach efforts through their stormwater programs and the communications segment of GWDR. New emphases on pharmaceutical disposal and the current wave of "flushable" products will require the updating of existing educational outreach programs and, in the long term, change the community's habits of disposing these items through the sewer system.

The educational outreach programs ranked average on addressing the private property spill problem but had one of the lowest cost impacts. This is because once the outreach material is developed it only needs to be periodically updated and reprinted. Dispersion is generally through water bill stuffers or community newsletters, keeping the mailing costs to a minimum. Normally, the agency bears the cost of such outreach programs. Although educational outreach programs ranked high (four out of five) as being feasible, the committee determined that developing an educational outreach program to specifically address private property spills would not achieve the desired results at this time. Educational outreach programs would also be spread over the whole community and not just a specific property type. The committee determined that the initial effort to reduce private property spills should be focused toward the greatest offender, multifamily residential dwellings.

Fats, Oils and Grease Reduction Program

A source control FOG reduction program requires that FOG is kept out of the sewer system by the individual property owner or tenant. This type of a program is utilized by several public agencies throughout the state. These programs stress the use of disposable grease containers or plastic lids for use on small cans for the collection of cooking fats, oils and grease. Once full, the containers are deposited into the trash. Similar to the FOG reduction programs utilized by FSEs,

many of these programs also stress the use of strainers in sinks and the disposing of solids in the trash as opposed to using the garbage disposal and the scraping of plates and dry wiping of cooking pots, pans and utensils to remove FOG. OCSD has initiated a pilot FOG reduction program in some of the more densely populated areas of the city of Tustin. This pilot program set up control and study groups to determine the effectiveness of FOG source control by individual property owners. Residents were fully informed of the program objectives and what role they were to play. Each dwelling was given a metal container and ten double-walled, heat resistant Ziploc plastic bags. The property owners were instructed to insert a plastic bag in the metal container and deposit all FOG into the bag. As the bag filled, coffee grounds, kitty litter or some other form of absorbent material was to be added to soak up the liquid. Once filled, the plastic bag was removed from the metal container and deposited into the trash and a new bag inserted into the metal container. Prior to starting the study, OCSD cleaned and video inspected the laterals and sewer lines to establish a base for their evaluation of the pilot project. The study targeted the holiday period extending from November through December. Upon the reinspection of the laterals and sewer lines there was a marked reduction in FOG buildup in those laterals and lines where the residences were utilizing FOG source control. This kind of program requires voluntary participation by the individual property owner or tenant and does not guarantee success however.

Because FOG is the primary cause of private property spills at multifamily residential dwellings, this BMP rated a five for both effectiveness and addressing the problem. Unfortunately, it is also rated a five for cost even though the cost would be spread among the agencies, property owners and tenants. The FOG reduction program also rated the lowest (1) for feasibility. These negative attributes come from a problem that has recently been revealed by the solid waste haulers and handlers.

In a letter (*Appendix K*) and at both a recent WDR Steering Committee and WDR General Meeting, Mr. Dean Ruffridge, Senior Vice President of CR&R Waste and Recycling Services discussed alleged problems of having FOG deposited in the solid waste stream. Most multifamily residential dwellings utilize three-yard bins for trash. In such cases, all trash, including recyclables, is deposited in the same bin. These bins are emptied into trash trucks for transport to a Material Recovery Facility (MRF) where recyclable materials are separated from the general trash. During transport, the trash is compacted frequently, which could cause FOG containers to break open allowing FOG to leak out onto into the trash, and possibly onto the roadway. Mr. Ruffridge stated that that FOG can damage the trommels and shakers at the MRF requiring significant repairs and maintenance. FOG also contaminates much of the recyclable material it comes in contact with, which could minimize its recyclable value.



Depositing FOG into the general trash may also contrary to AB 939, the Integrated Waste Management Act of 1989. This act sets requirements for the amount of solid waste that must be diverted away from landfills. In a rather unscientific experiment, approximately one cup of used cooking oil was placed in a double-walled Ziploc bag. Kitty litter was added as an absorbent to the cooking oil as the bag was kneaded. It took almost 1½ pounds of kitty litter to absorb the oil to the point where no oil would leak from the bag if the bag were punctured. The impact of such practices on solid waste generation have not been measured scientifically.

For a multifamily FOG reduction program to be most effective, a whole new waste stream would have to be developed where FOG collection containers would be made available, picked up and transported to an appropriate recycler. An alternative to year-round collection of FOG would be a program that established FOG collection sites during the holiday season, Thanksgiving through New Years, with an emphasis on collection of larger amounts of FOG from home turkey fryers and similar devices. Some agencies currently employ this type of a program with centralized FOG collection during the holiday season to allow their residents a simple way to dispose of their used fryer cooking oil.

Inspection After An Overflow

This BMP would require an inspection of the sewer lateral within a specified number of days following a blockage or overflow of the sewer lateral. The inspection would consist of at least a CCTV inspection performed by a licensed plumber with the results of the inspection being made known to the local sewering agency. No inspection would be required if the sewer lateral backed up due to a malfunction in the public sewer main.

The committee determined this is the most promising of all of the BMPs scoring a five in effectiveness, addressing the problem and feasibility. It also scored a low one and one-half for cost with the cost being borne by the property owner or management company. The inspection would provide current information on the condition of the sewer lateral, whether the cause of the blockage was mitigated and what additional work might be required to ensure the lateral would not experience additional overflows in the future. This BMP would be the first BMP to be implemented, with additional BMPs available only if needed. The city of Santa Barbara has a similar policy (*Appendix L*) but, unlike Santa Barbara, whose policy extends to all properties, this BMP would initially only apply to multifamily dwellings.

This BMP would only be invoked after a private property spill had occurred and would be key to initiating any additional BMPs that might be needed. Only multifamily properties where lack of diligence for maintaining their sewer lateral resulted in a blockage or overflow would be required

to comply. If repeat overflows were to occur, the property could be placed under more stringent BMPs, such as scheduled reoccurring inspections.

Public Agency Notification to Property Owners

This BMP would encourage public sewering agencies to notify property owners or management companies of any maintenance issue (e.g., root balls or significant grease buildup) or structural deficiency (e.g., broken connection to the sewer main) discovered in the private lateral as the public agency is performing its routine CCTV inspections of the public sewer main. The public sewering agency would notify the property owner within a specified number of days of the discovery and, as appropriate, present the property owner with a digital photograph and written description of the maintenance issue or deficiency. Notification would be by mail, door hanger, or other appropriate means. The private property owner or management company would have a specified number of days to rectify the problem and notify the public sewering agency of its remediation.

Several agencies, including OCSD, currently provide this as a service to their customers. By working with the property owner, the public agency can avert the potential problem of having root or debris balls pushed into the public system without the public agency's knowledge. This is a recurring problem for sewering agencies throughout the state where roots and debris cleaned from a private lateral are pushed into the public main, often resulting in an SSO.

This BMP was ranked by the committee as a five for effectiveness and four and one-half forboth addressing the problem and feasibility. Although considered both effective and feasible, the frequency would depend on how often the public agency inspects their sewer mains. Cost was ranked as one-half and would be borne by the agency. The cost ranking was low as most of the expense is considered administrative with most of the expense incurred during the normal sewer line inspection process.

Scheduled Reoccurring Lateral Inspections

This BMP would require that multifamily sewer laterals be routinely inspected based upon a predetermined frequency. Inspections would consist of at least a CCTV inspection by a licensed plumber and provide the local public sewering agency with proof that the sewer lateral has passed the inspection. For new or replacement laterals, inspections might not be required until the lateral has been in service for a predetermined time period. Laterals less than 3 total pipe joints or 10 feet would be exempt.

The committee determined that this BMP should be an alternate BMP for future implementation if deemed necessary. This BMP is initially intended only for multifamily dwellings and only as needed. The committee ranked the BMP as a five for effectiveness, addressing the problem and feasibility. The cost was ranked at one and one-half with the property owner or management company incurring the expense. The city of Santa Barbara (*Appendix L*) requires that all nonresidential and common interest development properties have scheduled sewer lateral inspection every 10 years.

Scheduled Lateral Inspections Based Upon Remodels

This BMP would require the sewer lateral to be inspected before any remodel of a specified dollar value or the addition of a specified number of square feet of habitable space is finalized, or when a specified number (or more) of new plumbing fixtures are attached to the existing sewer lateral. The cities of Santa Barbara (*Appendix L*) and Berkeley (*Appendix M*) currently have policies requiring sewer lateral inspections during remodels or with the addition of plumbing fixtures for residential or commercial properties.

This BMP is also considered to be an alternate BMP for future implementation for multifamily dwellings. This BMP ranked a four for effectiveness, three for addressing the problem and four and one-half for feasibility. The cost was ranked at one and one-half with the property owner paying all costs. This BMP is considered to have limited impact as typically a remodel for a multifamily dwelling is a major undertaking and occurs much less frequently than remodels to single-family dwellings.

Lateral Inspection Upon the Sale or Transfer of Property

With this BMP, whenever a multifamily property is sold or title transferred, the property would be subject to a sewer lateral inspection. The inspection would be required if the lateral was over a predetermined age and had not been inspected within a predetermined time period. The sale or transfer of individual units within a complex would not require a sewer lateral inspection. The city of Burlingame (*Appendix N*) currently utilizes a similar policy for all properties within the city.

The committee determined that this BMP be an alternate BMP for possible implementation at a later date. The BMP was ranked a four for effectiveness, a three for addressing the problem and a two for feasibility. Cost was ranked at one and one-half with the property owner absorbing all costs. The low feasibility ranking was due in part to the relatively infrequent (as compared to single-family dwellings) sale or transfer of multifamily complexes.

Certification Program for Licensed Plumbers

For this BMP, public sewering agencies would develop a certification program and maintain an upto-date listing of certified licensed plumbers who are acceptable to the public sewering agency for performing inspections and repairs on private sewer laterals. The certification program would ensure that plumbers have a current license with the state and are aware of any local private lateral programs and their requirements that the local sewering agency might support. This would not be an endorsement of any plumber, plumbing contactor or plumbing company. It would only be a listing of qualified local area plumbers and intended only to provide property owners a resource for selecting a plumber.

This BMP is considered an alternate BMP for possible implementation at a later date. Overall, the committee ranked this BMP lowest of all nine BMPs. The BMP ranked one for effectiveness, one-half for addressing the problem and three for feasibility. The cost was ranked as two with the agency bearing the cost. The concept is not to have an agency endorse any particular private plumbing contractor(s) but to offer knowledgeable information as to what local contractors are licensed and have the capability and equipment to provide the required service. With multifamily dwellings this has less importance as typically multifamily dwellings are managed by a management company who either has its own staff of professional plumbers or has business arrangements with plumbing contractors they wish to utilize.

There are several cities and districts in the state that do maintain a list of licensed plumbers for their constituents. *Appendix O* is from the city of Pacific Grove and is posted on their website. The city of Laguna Beach indicates they have a similar listing that is available upon request.

Financial Assistance Programs

Financial assistance programs provided by public agencies to assist their constituents have been growing in popularity. Many of these programs have been established to assist the agency in controlling inflow and infiltration (I&I) as defective laterals are a known source of I&I. Some of these programs have been in the form of insurance pools where funds are collected as part of the sewer fee, pooled and then distributed to qualified property owners for the repair or replacement of their sewer laterals. These pooled programs have been very successful in the St. Louis Missouri area. Other programs offer grants or low or no interest loans to assist with lateral repairs or replacement. Most of the financial assistance programs have a maximum amount available and require matching funds from the property owner. Likewise, most are offered as a one-time event for the life of the property and only cover the repair or replacement of the lateral that has been deemed unserviceable. Normally, the public agency does not do the repair or

replacement but does oversee the process to ensure the lateral qualifies for replacement and that the work is properly completed. The program initiated by the CMSD is unique in that it not only offers financial assistance for the repair or replacement of the lateral; it also offers financial assistance for the inspection and cleaning of the lateral.

There is at least one private water company, American Water, which offers a nationwide insurance program for both the sewer lateral and the water service line. The city of Anaheim had considered partnering with American Water to offer this benefit to the residence of the city. The project was abandoned when the city determined that there were significant obstacles with this approach. Most of these obstacles related to the state's current insurance laws.

Although the committee ranked this BMP as a five for effectiveness, addressing the problem and cost with the agency funding the program, it was ranked as a one for feasibility. It is also considered an alternative BMP.

IMPLEMENTATION OF BMPS

It is common for public sewering agencies to take action against a private property owner who has had a sewage spill. There are several instances noted in the spill reports submitted to the Regional Board of public agencies involving code enforcement to correct violations or to recoup costs incurred because of a private property spill. It is believed that the practice of recouping costs associated with private property sewer spills, in addition to reimbursing the public agency, demonstrates to the property owner the importance of maintenance to control costs. Sometimes even more drastic measures are required. A case in point occurred in the city of Placentia in July 2004. A five-unit multifamily residential dwelling was involved in an intermittent sewage overflow over a period of days where the property owner's efforts to clear the blockage were inadequate. A nonlicensed plumber was being used. To ensure the property owner was aware of the seriousness of the situation, the city's Code Compliance Officer began the process of issuing non-habitation orders for inadequate sanitation. This got the property owner's attention who summoned a professional plumbing contractor with the necessary skills and equipment to clear the line. It turns out a ball was lodged in the lateral creating the blockage and resulting spill. The property owner was issued a Notice of Noncompliance.

BMPs are intended to be tools to be used by public sewering agencies to reduce or prevent private property sewage spills. Of the nine BMPs, the BMP for sewer lateral CCTV inspections after a sewer spill is the only BMP recommended to be implemented at this time. Other BMPs could be implemented at a later date or if additional measures are needed to prevent reoccurring spills from a property. Initially, only multifamily dwellings would be targeted for BMPs. The

intent is to not encumber the entire community as the data indicates that the potentially higher spill volumes from multifamily dwellings pose the greatest threat to the environment and to the public health. Implementation of the BMPs would be with the cooperation of the public sewering agencies. Public agency involvement would be voluntary since public sewering agencies are not responsible for private property sewage spills. Cities do have the responsibility to protect their stormwater systems and remain compliant with their NPDES Stormwater Permits. Private property sewage spill BMPs could prove very helpful for cities in enforcing their stormwater programs. To implement the BMPs, different actions could be taken as follows:

- Do nothing
- Voluntary implementation of the BMPs
- Regional Board impose waste discharge requirements on private properties

Do nothing. With this approach the public sewering agency would simply not enforce or require the private property owner to abide by the BMPs. This approach does not address the problem and may require additional actions to be taken by the Regional Board to protect the environment and public health.

Voluntary implementation of the BMPs. The public sewering agencies would voluntarily implement the BMPS within their jurisdictions. The specific BMPs to be implemented would depend upon the public agency as would be the course of action followed for repeat offenders or for expanding the BMPs to additional property types. Different cities or districts may implement different BMPs or combinations of BMPs depending upon their success in reducing or eliminating private property sewage spills. This would remain voluntary with the public agency not incurring any additional responsibility for private property sewage spills.

Regional Board involvement. The Regional Board would develop and implement waste discharge requirements for essentially residential dwellings within its jurisdiction. These waste discharge requirements would require essentially residential properties to maintain their private sewer laterals, lift stations and other waste conveying systems consistent with recognized standards. Regular cleaning, inspection, repair, replacement or rehabilitation would be required to ensure the private sewer system remains capable of transporting sewage without an overflow. Design capacity would also be reviewed to ensure that the private system's capacity is adequate for the number of occupants living at the facility. Should an overflow occur, the Regional Board would determine if the private property owner's program was sufficient and enact enforcement as necessary.



SYNOPSIS

Forty-six percent of all sewage spills reported to the Santa Ana Regional Water Quality Control Board, Region 8 from northern Orange County during May 2002 through December 2006 were private property spills. A private property spill is an SSO whose origin is within the private lateral serving a private property and is not caused by any failure in the public sewage collection system. Private property spills are normally of a smaller volume than spills that occur in the public system but still accounted for approximately 407,078 gallons of spilled wastewater during the study period. Although much of the wastewater was recovered, an estimated 95,542 gallons did reach surface waters with an estimated 19,990 gallons causing twenty-five beach closure incidents. In fact, approximately eight percent of all reported private property spills resulted in a beach closure. This is similar to the approximate ten percent of public spills that result in a beach closure. Aside from being a health concern, sewage spills that result in a beach closure have a distinct negative effect upon the Orange County economy. After reviewing the facts, the committee formed to review the information provided in this study determined that private property spills have a significant negative impact upon the environment and BMPs should be developed to assist in reducing or preventing private property spills.

Spill data was received from the Santa Ana Regional Water Quality Control Board, Region 8 and OCHCA. Data from the Regional Board included spill summaries from all but a couple of the districts and cities that operate sewage collection systems in the Orange County portion of Region 8. Spill data from OCHCA likewise provided spill information that was reported to them. Data on beach closures was retrieved from OCHCA's Ocean Water Protection Program website. Since data was being received from multiple agencies and in multiple formats, care had to be taken to compare individual spill locations, dates and volumes to prevent a spill from being entered multiple times. All of the data concentrated on the period from May 2002 through December 2006. This period was selected for study as it was the only period of time when all public agencies in the Region 8 portion of Orange County were required to report all private property spills in addition to all public spills to the Regional Board.

To better understand the cause and effect of the private property spills occurring in the study area, each spill report was categorized by location, cause, property type, impact on surface waters and whether the spill resulted in a beach closure. Table 1 is an overview of the categorization of the private property spills. By categorizing all private property spills, the property types and causes that presented the highest potential risk to the environment could be identified. Spill locations and volumes that would have the most severe environmental impact were also identified. After analyzing all of the spill data, it was concluded that multi-family residential dwellings presented

the greatest threat from private property spills. This is due to their potential to have spills in much greater volumes than the other property types. Although there were slightly more commercial property (predominately food service establishments) sewage spills during the study period, the volume for multi-family residential sewage spills was twice as high. Like commercial property spills, multi-family residential sewage spills are predominately caused by grease buildup in the private lateral. Of the approximate 215 multifamily residential sewage spills, 155 had a listed cause. Grease was the primary or contributing factor to 91 (59%) of all the multifamily spills with a stated cause. Roots were the next largest category with 25 (16%) of the multifamily spills with a listed in 18 (12%) spills with structural defects listed 17 (11%) of the spills with a known cause.

After analyzing the categorized data, the committee determined that single-family residential spills do not represent a significant environmental threat. The average single-family residential sewage spill is approximately 39 gallons as compared to the average multifamily residential spill of 972 gallons. Likewise, commercial property spills were not deemed to be a significant environmental threat at this time. This is because the vast majority of commercial spills involved food service establishments who are now under strict FOG reduction programs as part of the statewide General Waste Discharge Requirements. These commercial properties were under similar if not identical FOG reduction programs when the Region 8 WDR was in effect, but the FOG element of the Region 8 WDR did not become effective until the final months of the Region 8 WDR. Unfortunately, there was insufficient time during the study period, to see any significant effect of the Region 8 WDR FOG reduction programs. It is anticipated that FOG related spills from commercial properties will be drastically reduced as the FOG reduction programs mature.

Categorizing the spill data also provided information on what spill locations were most likely to result in a beach closure. Not surprisingly, even small spills that occur in areas adjacent to the beach will most likely result in a beach closure. Spills occurring at inland locations would need to be progressively larger and with more direct access to tributary waters to result in beach closures.

Because private property spills can result in beach closures that, in addition to creating health concerns, have a negative economic impact upon Orange County economics, nine BMPs were developed to assist public agencies in reducing the frequency and volume of private property sewage spills. The primary target of these BMPs is multifamily residential dwellings. Multifamily residential dwellings were chosen as the data clearly reflects that currently multifamily residential dwellings have the highest potential to affect the environment, especially those units located in the beach communities. Of the nine BMPs, the committee emphasized one BMP. That BMP requires the property owner or management company of a multifamily residential dwelling provide a

CCTV inspection of their sewer lateral within a specified number of days following a sewage spill that involved a blockage or defect in the lateral. If the blockage or defect was in the public collection system and only exited the private lateral, an inspection of the lateral is not required. The remaining eight BMPs are considered alternative BMPs that could be used in the future.

Implementation of the BMPs is initially intended to be voluntary in cooperation with the local sewering agencies. If the voluntary approach is ineffective or is insufficient to address the problem of private property sewage spills, the Regional Water Quality Control Board, Region 8 should be prepared to initiate waste discharge requirements for multifamily residential dwellings. These waste discharge requirements would require multifamily residential properties to clean, inspect, ensure adequate capacity, repair, replace or rehabilitate and maintain their private sewage systems to keep them free from sewage overflows.

The Region 8 portion of Orange County has approximately two to three times the mileage of private property sewage lines compared to publicly owned sewer lines. They are all part of the sewage transport system needed to eliminate wastes generated by the County's inhabitants while protecting the public health, beaches and the environment. Sewage spills are regularly occurring in these private sewer lines. In fact, data indicated a trend during the study period that the reported number of private property spills has been increasing while the reported number of public spills has been decreasing. Total control over the entire sewage collection system from source to treatment cannot be achieved without some means of control over the private lines to ensure their proper maintenance and operation.

APPENDICES

The appendices are the worksheets developed to provide the analysis of the private property spills that occurred in Region 8 from May 2002 through December 2006.

Appendix A is the Master Monthly Report and includes all the data provided relative to all of the private property spills reported. *Appendix A* has all 18 data fields displayed and is broken down alphabetically by reporting agency. For ease of access, the data from OCHCA was amended to the end of this appendix, with its totals included in the final totals.

Appendix B displays all of the private property spill data, including OCHCA, chronologically broken down by calendar year. This appendix shows how the reporting progressed over time.

Appendix C displays all of the private property spill report data chronologically grouped by spill cause. The cause categories are: Unknown (spills whose cause was unknown or not provided), Grease (spills whose cause was grease or grease traps and interceptors), Roots (spills whose cause was to be tree roots), Debris (spills whose cause was various types of debris other than grease or roots), Grease and Roots (spills whose cause was a combination of grease and tree roots), and Structural (spills whose cause was a line break or other structural failure).

Appendix D chronologically lists all private property spills based upon the property type involved. All spill addresses, unless the property type was listed in the report, were reviewed using the satellite feature of Google Maps. The satellite feature presents an aerial photograph of the property assisting in determining the property type. The property types are: Unknown (spill reports are in this category because no address was provided, the wrong or incomplete address was provided, or Google could not find the address), Single-Family (spills involving single-family residences), Multifamily (spills involving multifamily residences, apartments, condo complexes, hotels, motels, and hospitals; condo complexes were a particular problem, as it can not be determined if an individual condominium has its own lateral or shares a lateral with other units in the complex), Commercial (spills involving commercial establishments including restaurants, strip malls, and other retail or manufacturing establishments, other than hotels, motels, or hospitals), and Institutional or Public (spills involving schools or other publicly owned facilities).

Appendix E chronologically lists all private property spills that were reported to have entered receiving waters and is broken down by calendar year.



Appendix F is a listing of all private property spills in Region 8 that resulted in a beach closure. This appendix includes the number of days the beach was closed and the beach mile days for each private property spill that resulted in a beach closure. The beach closure report is compiled by OCHCA and is available online. Beach mile days are a calculation that includes the number of days a beach is closed and the linear footage (converted to miles) of beach that is affected. Several of the entries on the beach closure report were only found on that report and were added to the other appendices as appropriate. During the study period, only two inland cities (Anaheim and La Habra) had a spill that resulted in a beach closure, whereas even minor spills from beach cities resulted in a beach closure.

Appendix G compares all cities' and districts' total spills to private property spills.

Appendix H is a map showing the boundary between Region 8 and Region 9.

Appendix I is the city of La Palma's sewer ordinance that defines the responsibilities of the public agency and private property owners for the sewage collection system including the private laterals.

Appendix J is the worksheet showing the committee's rankings of the nine BMPs.

Appendix K is a letter from CR&R Waste & Recycling Services outlining the problems with including FOG containers in the comingled solid waste system.

Appendix L lists the current policies utilized by the city of Santa Barbara for inspections after an overflow of a private sewer lateral.

Appendix M is the policy of the city of Berkeley requiring a private lateral inspection due to remodeling or the addition of plumbing fixtures.

Appendix N is the policy of the city of Burlingame that requires private lateral inspections upon sale of the property.

Appendix O is the certified plumbers list from the city of Pacific Grove.



ACKNOWLEDGEMENT

Ken Theisen California Regional Water Quality Control Board, Santa Ana Region Staff Environmental Scientist

Nick Arhontes, PE Orange County Sanitation District Director of Operations & Maintenance

Patrick McNelly Orange County Sanitation District Principal Staff Analyst

Ann Crafton, SR/WA Orange County Sanitation District Regional Assets & Property Management

Dindo Carrillo Orange County Sanitation District Senior Environmental Specialist

James Colston Orange County Sanitation District Environmental Supervisor

Larry Honeybourne County of Orange Health Care Agency Water Quality Program Chief



APPENDIX A

Modified Master Private Property Spills 2002–2006 Sorted by Agency

Modified MASTER Private Property Spills 2002-2006

Date & Time SSO is First Reported to Responding Agency	Responsible Party	Did SSO reach surface waters other than a storm drain?	SSO Volume Lost (Gallons)	Recovered SSO Volume (Gallons)	Recovered wash Water & Sewage Contaminated Water Volume	Lost Wash Water & Sewage Contaminated Water Volume	Location of overflow: Street	Location of overflow: City	Location of potential blockage or problem point	Description of component from which spill occurred	Likely cause of SSO	Overflow Cause - Detailed Description	Name or Description of Initial Receiving Water	Name or Description of Secondary Receiving Water	If the SSO did not reach surface waters, describe the final destination of sewage	Was the Local Health Services Agency Notified?	n Remarks
Anaheim																	
9/16/2002 1400	CITY OF ANAHEIM	NO	200	200	300	0	1511 N. Euclid Ave.	Anaheim	Clean out at back alley of 'Super Torta'	private clean out	grease; possible lint	grease and possible lint	N/A	N/A	ponded in gutter	YES	
9/18/2002 1600	Private: Lusardi Development	NO	0	50	50	0	Harbor Blvd. N/O Ball Rd.	Anaheim	Sewer line break at Giannelli Electric, Harbor Blvd. N/O Ball Rd.	sewer line	Break in sewer line	e Sewer line break at Giannelli Electric	N/A	N/A	N/A	YES	
9/26/2002 1300	Private: Seris Regio Group	YES	200	20	70	200	2050 Winston Rd.	Anaheim	cleanout near center of drive area at 2050 Winstor Rd.	n clean out onsite	break in the private sewer lateral	^e broken lateral in private sewer	Santa Ana River		N/A	YES	Property owner was notified of spill at 2:00 on 9/26/02 and was told the line would have to be cleaned immediately. Private plumber did not show up until the 27th. Due to difficulties cleaning the line it was determined there was a treat in the private sever lateral. Work to repair this line was completed on the 28th.
10/17/2002 1500	Private: Twin Pines Apts.	NO	5028	4800	8800	5028	2880 W. Ball Road	Anaheim	Blockage in lateral	private clean outs	Grease buildup	Grease buildup	N/A	N/A	Contained within storm drain system	YES	Sewage was vacuumed up downstream in storm drain sump area in the City of Stanton. Vaccuming continued until little or no flow was observed entering sump area.
10/19/2002 1345	Private: Twin Pines Apts.	NO	1776	1500	3000	1776	2880 W. Ball Road	Anaheim	Blockage in sewer lateral a appartment complex	at private clean-out	Grease buildup	Grease buildup	N/A	N/A	Contained within storm drain system	YES	Sewage was vacuumed up downstream in storm drain sump area in the City of Stanton. Vaccuming continued until little or no flow was observed entering sump area.
12/28/2002 0000	Private: Property Management Group, 1398 N. Mako Ln.	No	425	75	275	425	1398 N. Mako Lane	Anaheim	Near 1398 N. Mako Lane	Manhole	Grease and Roots	Grease and roots blocking flow	Carbon Creek	Pacific Ocean		YES	Property Management Group, Jerry O'Donnell, (714) 408-3469 headquarters.
3/12/2003 0000	Private - PCM Mgt. Co. View Point North Comm. Assoc.	No	750	300	350	750	7807 East Viewrim Drive	Anaheim	Near 7807 East Viewrim Drive	Private Manhole	Grease	The sewer line was obstructed by grease.	Santa Ana River	N/A	N/A	YES	The property where the spill occurred is private property. The city had no responsibility for the spill and responded only to assist in the containment to prevent additional sewage from reaching our storm water catch basin system.
5/7/2003 0000	700 N. Valley Street	Yes	200	20	30	200	700 N. Brookhurst Street	Anaheim	On Gramercy Avenue, eas of Brookhurst Street	Private sewer clean tout at Mobile Gas Station	Paper towels obstructing the flow.	Paper towels were obstructing the sewer line which caused the overflow.	Carbon Creek	N/A	N/A	YES	The owner of the Mobile Gas station, Morteza Yassini stated there was a small flow spilling from the clean out on 55/03 at 11 p.m. At the time, he assumed it was just water since the clean out had all time stated "Water" on L Operations Crew Supervisor, Glenn Bowers arrived on site at approximately 1:45 p.m., assessed the situation and set up all necessary prevainings to a crew arriving. By 2:10 p.m. the line was clear and overflow was corrected.
6/18/2003 0000	Private Party	No	0	400	60	0	409 N. Jeanine Drive	Anaheim	Near 409 N. Jeanine Drive	Private cleanout	Trash / Debris	Debris blocking the flow of sewer line.	N/A	N/A	Spill ponded. Did not reach storm drain.	YES	The City of Anaheim responded to assist in the containment of the spill from a private clean-out. Sewage did not enter the storm drain.
7/1/2003 2000	Private Property Owner: 278 N. Wilshire Street	Yes	590	10	20	590	278 N. Wilshire Street	Anaheim	Near 278 N. Wilshire Street	Private Manhole	Swale in sewer lateral	Swale in pipe allowed debris to settle and accumulate resulting in blockage	Carbon Creek	N/A	NA	Yes	Property Management was very difficult to get a hold of, however, the delay in their response will result in a large bill being issued to them for cost recovery, in conjunction with he notice of violation. Copy of the report was provided to OC Health Care on 7/203 for follow-up. (Previously issued as 279 N. Pearl, however correct address is actually 276 N. Wilshite)
7/14/2003 1455	Private Property Owners (4) of shared lateral.	No	20	40	340	20	1320 S. State College Boulevard	Anaheim	Near 1320 S. State College Boulevard	Private Cleanout	Grease	Grease buildup obstructing sewer flow.	N/A	N/A	Ponded in SD	Yes	Unusual situation as there are four (4) properties served by a single lateral. Based on desensitions in was clear the cause of the blockage was accessive greate. The Bouward. However, because all our properties disclarates to his line, he responsibility for the spill as well as the routine maintenance must be shared.
7/17/2003 0915	Private Property: Paradise Pier Hotel 1717 Harbor Boulevard	Yes	100	200	1000	100	1717 Disneyland Drive	Anaheim	Near 1717 Disneyland Drive	Private Cleanout	Paper Towels	Overflow caused by buildup of paper towels in sewer line.	East GG Channel	Bolsa Chica	N/A	Yes	Disney was very forthcoming in providing the appropriate information, as well as notifying proper CIV and other agency staff for this incident. For many reasons, Disney has focused a genet deal of derifor on preventing avginalir agelia in sine. Ib dute and for this reason as well as the submitted of appropriate OAM schedules, atocks is not warranted at this time, however brochuses and informational popularies have been provided and Dianey staff has been reminded of the prohibition on disposing of paper burels in sever.
7/23/2003 0200	Private Property: Mandas Konstantinos - 910 S. Euclid Street	No	50	10	210	50	910 S. Euclid Street	Anaheim	Near 910 S. Euclid Street	Private Cleanout	Grease	Grease buildup obstructing sewer flow.	N/A	N/A	Ponded in SD	Yes	City was notified of al leak of some kind at 2:00 am on 7/23/03, however upon arriving on scene there was no spill. A follow up inspection later that morning revealed a slow leak from the cleanout.
7/25/2003 1229	Private Property: Crown Point Homeowners Association	No	13167	798	998	13167	400 Crown Point Drive	Anaheim	Near 400 Crown Point Drive	Private sewer manhole on Crown Point Drive	Roots	Roots obstructed the sewer flow.	N/A	N/A	It is suspected that a sump area in Cal Trans Right of Way received the spill.	Yes	Spill could not be found at Santa Ana channel where it would empty into. It is suspected that a sump area in Cal Trans Right of Way received the spill.
8/25/2003 0000	Private Party	No	200	50	1000	0	2508 West Chain Street	Anaheim	Near 2508 West Chain Street	Sinkhole in Street	Break	Pipe failure allowed sewage to seep into the ground	N/A	N/A	Seeped into the ground	YES	Report of possible sinkhole first came to the City at 4.45 PM on August 25, 2003. Subsequent investigation on August 27 Indicated a water feak, however further investigation on August 28 revealed the water was in fact servage. The servage in the sinkhole was vacuumed by the City, but the hole had to be widered by the Givange likely contraded from the server due to distribution the target was carried away to create the sinkhole. Some servage served into the ground.
10/2/2003 0000	Private- William Lyon Property Management	No	30	210	20	0	5601 E. Orangethorpe Ave	Anaheim	5601 E. Orangethorpe Ave	Private Manhole	Roots	Roots obstructed sewer flow, causing the overflow at the manhole	Santa Ana River	N/A	N/A	YES	Mark Williams of OCHCA responded to the scene and informed the property owner of the seriousness of the situation
11/17/2003 1957	5665 E La Palma	Yes	2700	100	200	500	5665 E. La Palma Avenue	Anaheim	5665 E. La Palma Avenue	Private cleanout	Paper Towels	Paper towels obstructed the flow of the sanitary sewer line causing it to overflow.	Santa Ana River	N/A		Yes	The majority of the sewage remaining on the surface of the parking lot was collected during a washdown with the CPy's vactor truck. However, due to a missilagionise of firmended to clear trucked sewage and fusih out remaining sewage in storm drain this portion of the washdown was not collected.
11/18/2003 1110	540 North Euclid	No	20	19	50	0	540 North Euclid Avenue	Anaheim	540 North Euclid	Private sewer manhole	Grease	Grease obstructed the flow of the sanitary sewer line causing it to overflow	N/A	N/A	Spill Ponded in Catch Basin	Yes	

Modified MASTER Private Property Spills 2002-2006

11/29/2003 0836	777 Convention Way	No	50	0	50	0	Hotel Way East of 777 Convention Way	Anaheim	777 Convention Way	Private sewer manhole	Grease	Grease released by Anaheim Hilton obstructed the flow of the sanitary sewer line causing the overflow	N/A	N/A	Spill Ponded in Catch Basin	Yes	
12/02/03 1412	Private property owner	No	100	1600	1600	0	1758 W. Sumac Lane	Anaheim	1758 W. Sumac Lane	Clean out in laundry room	Roots	Roots clogged the sewer latteral	East Garden Grove Channel	N/A	N/A	YES	Property owner was initially unresponsive to the City's and OCHCA's calls notifying him of the situation. Owner finally arrived onscene and obtained the services of a private plumber 8 hours after initial contact.
12/10/2003 0925	Private property owner	Yes	300	500	200	0	6103 Morningview Drive	Anaheim	6103 Morningview Drive	Private Cleanout PC192423	Roots	Roots clogged the sewer line and caused a overflow	Santa Ana River	N/A	N/A	YES	
12/12/2003 1620	Private property owner	No	0	125	200	0	1616 West Katella Avenue	Anaheim	1616 West Katella Avenue	Private Cleanout	Metal from broken grate	Metal from broken grate fell into latteral and obstructed the flow, causing the overflow	N/A	N/A	Vacuumed by private contractor and disposed of in sewer	YES	This incident started with a complaint of odor which was the result of flow coming from an outdoor trash compactor. The owner/operator of the compactor. Food 4 less, was required to stop this flow, and moved the compactor to do so. However, in moving 1, they broke the grate which covered the seven cleanout under the compactor, dropping metai into the lateral resulting in an obstruction and subsequently a sever spill.
1/4/2004 0800	Private Property Owner	Yes	600	0	0	0	1415 W. Ball Rd.	Anaheim	1415 W. Ball Rd.	Private Manhole	Grease	Grease obstructed the flow of the Sanitary Sewer Line causing it to overflow	Westminster	N/A	N/A	Yes	The Anaheim Fire Department responded initially. Then Streets and Sanitation was called out and responded. Split duration was estimated at 1 hour as the property manager found here were mathole diverging out heavy? Fire said trat the split was inches about the mathole when they amende When Streets and Stantation arrived, the split has tapped as the water supply had been shut of.
1/17/2004 1230	Private Property Owner	No	560	1600	500	0	1630 W. Katella Ave.	Anaheim	1630 W. Katella Ave.	Private Cleanout	Grease	Grease obstructed the flow of the Sanitary Sewer Line causing it to overflow	Westminster	N/A	N/A	Yes	Second spill in 15 months
2/24/2004 1115	Private Property Owner	No	50	100	500	0	2610 E Katella Ave.	Anaheim	2610 E. Katella Ave.	Private cleanout and private clarifier	Grease	Grease formation caused the sanitary sewer line to overflow	Santa Ana River			Yes	The staff at Orange County offices (located new door to J.T. Softmitt's) network the frite of varies it of J03 and notifies the restravant namages. Phintle plurhes animed by 11:00 AM to clear blockage and City of Anaheim was notified at 11:15 AM. Anaheim Inspectre responded to les at 11:30. Constituents thad already been established by Oranje County Staff, at that time, and Private Plumber had just cleared the obstruction.
3/7/2004 1820	Sycamore Canyon Townhomes	Yes	800	200	200	0	8282 E. Oak Ridge Circle	Anaheim	8282 E. Oak Ridge Circle	Private clean out	Roots	Roots obstructed private clear out	ⁿ Santa Ana River		N/A	Yes	Private plumber did not arrive until 9:35 pm and had difficulty with their equipment. Obstruction was finally cleared at 3am. Private plumber and City Staff worked to washdown and clean affected area.
3/19/2004 1130	Parkview One Homeowners	Yes	960	60	1000	0	6518 E. Camino Vista	Anaheim	6518 E. Camino Vista	Private Sewer Manhole	Roots	Roots obstructed private sewer line.	City Golf Course	Santa Ana River	N/A	Yes	The spill was not reported for an estimated 2 days, due to the fact that the residents of this complex did not identify this spill as being sewage.
4/12/2004 1030	Foodland Market	No	100	50	0	0	910 S. Euclid St.	Anaheim	910 S. Euclid St.	Private Cleanout	Grease	Grease caused obstruction.	Ponded in SD	N/A	N/A	Yes	Meetings have been held with representatives from Foodland.
4/15/2004 0930	City of Anaheim / Anaheim Fire Station #9	Yes	150	50	200	0	6300 Nohl Ranch Rd.	Anaheim	6300 Nohl Ranch Rd.	Sewer Lateral Cleanout	Construction damaged the lateral and allowed roots to invade sewer line	Roots	Flood Control Channel	Santa Ana River	N/A	Yes	NA
5/22/2004 1715	C & C Property Management Group	No	5	50	50	0	411 N. Park Vista St.	Anaheim	411 N. Park Vista St.	Private cleanout in alley	Grease	Grease caused private lateral to become blocked and to back up.	Ponded in CB	N/A	N/A	Yes	
6/10/2004 1550	2349 W. La Palma Ave., Anaheim	No	10	40	500	0	2349 W. La Palma Ave.	Anaheim	2349 W. La Palma Ave.	Private Manhole	Sewer lateral offset	Private stormdrain installed may have offset the Sewer lateral, allowing a cell phone to block the restricted line.	Ponded in SD	N/A	N/A	Yes	Apparent delay in notification to RWOCB was due to the fact that the spill had apparently not left the sile when Cby Staff arrived. However, after interviewing oran personnel, it was discovered that the sign had left the sile but the water was voluntarily shut off which stopped the spill and made it appear as if it had not left the sile. The plumber that the private property owner hirsh ont only shut off the water, but deaned and televised the sever lateral. An offset was discovered and was though to have been caused by a private stormdiant installation, completed over a year ago. This could not be shown conclusively so the City performed repair.
6/21/2004 1240	1331 E. Katella Ave., Anaheim 92805 (714) 978- 8088	No	182	250	200	0	1221 E. Katella Ave.	Anaheim	1221 E. Katella Ave.	Private clean out	Grease	Grease obstructed the flow of the Sanitary Sewer Lateral causing it to overflow	Ponded in SD	N/A	N/A	Yes	
6/21/2004 1815	AAA Management 661-252- 9035	No	50	0	1000	0	5600 E. Santa Ana Cyn Rd.	Anaheim	5600 E. Santa Ana Cyn Rd.	Private property clean out in parking lot	Grease	Grease obstructed the flow of the Sanitary Sewer Lateral causing it to overflow	Santa Ana River	Santa Ana River	N/A	Yes	
6/25/2004 1945	Terry Stola 8130 Orangewood Ave., Stanton, CA 90680	No	0	20	50	0	604 W. Provential Dr.	Anaheim	604 W. Provential Dr.	Private cleanout	Grease	Grease obstructed the flow of the Sanitary Sewer Lateral causing it to overflow	N/A	N/A	N/A	Yes	
7/29/2004 0000	1743 S. Clementine (Extended Stay America)	Yes	260	1100	300	200	1742 S. Clementine Street	Anaheim	1742 S. Clementine Street	Private Manhole	Cloth and other debris	Cloth and debris clogged pipeline, causing sewage to overflow.	Bolsa Chica	N/A	Bolsa Chica	Yes	
9/13/2004 1640	James Estrella - Facility Manager	No	5	10	10	0	1628 South Anaheim Way	Anaheim	1628 South Anaheim Way	Private cleanout	Foreign objects	Foreign objects clogged sewe line	^r Ponded in SD	N/A	N/A	Yes	The flow was intermittent resulting in an estimated rate of 10 gal/hr
9/21/2004 1720	Lincoln Inn, Kelly Erickson - Maint. Manager	Yes	100	0	100	0	2748 W. Lincoln Avenue	Anaheim	2748 W. Lincoln Avenue	Private cleanout	Feminine hygiene products	Feminine hygiene products got lodged in line.	Carbon Creek	N/A	N/A	Yes	Hotel cleared blockage with their own equipment and proceeded to wash the spill into the nonitie drop inlet before City Staff arrived consist. Hotel Management was informed that the spill had to be contained onsista and City had to be contacted in the event of a spill. This requirement will be reiterated in the Compliance Order.
10/8/2004 1900	Wendy's Restaurant	No	10	20	0	0	2011 East La Palma Avenue	Anaheim	2011 East La Palma Avenue	Private manhole	Grease	Grease clogged sewer line	Santa Ana River	N/A	Ponded in SD	Yes	Any washdown was performed by Restaurant staff under supervision of OCHCA.

Modified MASTER Private Property Spills 2002-2006

11/12/2004 0830	Anaheim Hilton	Yes	880	20	400	0	777 Convention Way	Anaheim	777 Convention Way	Private Manhole and Cleanout	Grease	Grease blocked sewer line, causing sewage to overflow.	Anaheim Barber Channel	NA	Anaheim Barber Channel	Yes	This spill was cheared on Wednesday flowing only for a couple hours in the morning which is shart the flow estimate is based on. There is clear evidence that despite the large flow carried by the 15 flow which was obstrated, the actual anount of sewage spilled was not large compared with the flow. This is because here is an overflow to-pass of the spinon where the obstration occurred, which allowed a limited flow to continue in the sewar. Also, it appears that the spill only courred at pask flow (morning primarily) and was not substantial based on location and minimal solids deposition.
12/11/2004 0300	Woo Chung. 9944 Garden Grove Blvd., Garden Grove	No	20	80	100	0	2801 W. Ball Road	Anaheim	2801 W. Ball Road	Private Cleanouts	Grease	Roots blocked pipeline, causing sewage to overflow.	Ponded in SD	N/A	N/A	Yes	Apparently very little sewage actually reached the storm drain as it tended to pond on-site. Tenants informed us that a plumber had worked at this location before and removed a large amound of roats. However, on this occasion hard evidence of discharging gresse to the sewer line was the primary factor for the problem.
12/21/2004 1500	Ron Marshall, Manager of Mr. Stox restaurant	Yes	188	100	400	0	1105 E. Katella Avenue	Anaheim	1105 E. Katella Avenue	Private cleanout	Paper Towels	Paper Towels blocked pipeline, causing sewage to overflow.	Bolsa Chica	N/A	N/A	Yes	OCHCA visited the location to determine if there were any issues inside the restaurant.
1/4/2005 0950	Lake Summit Association	Yes	60	40	500	0	920 S. Ridgecrest Circle	Anaheim	Near 920 S. Ridgecrest Circle	Private Manhole	Grease	Grease blocked pipeline, causing sewage to overflow.	Santa Ana River	Pacific Ocean	N/A	Yes	Spill appeared to be flowing at a far greater rate than 50 gph. However, the sewer line that was obstructed only serves 20 homes and a typical flow at 10 am would way be approximately 50 gph. Therefore, the additional two is suspected to be from inflow and influeton. Sewage flowing from the manhole was very dear in appearance, turker suppring this suspection.
1/25/2005 1330	Victoria Townhouse Apartments	Yes	1050	7500	500	0	2256 W. Lincoln Ave.	Anaheim	2256 W. Lincoln Ave.	Private Manhole	Grease & Roots	Roots and grease blocked pipeline, causing sewage to overflow.	Coyote Creek	San Gabriel River	N/A	Yes	Property owner called private plumber at 2:00 PM but did not show up until 6:00 PM. City crews cleared the obstruction at 5:46 PM. Plumber would not have been belto to clear blockage anyways, since the did not have the equipment to do so. Attached are two volume calculation forms, which use two different methods to anive at virtually the same estimate of thors, 1800 gallons per hour. Property owner is currently disputing his responsibility for this spill.
2/8/2005 0905	1310 W. Pearl St.	No	0	60	300	0	1310 W. Pearl St.	Anaheim	1310 W. Pearl St.	Private Cleanouts	Grease & Paper Towels	Grease and paper towels blocked pipeline, causing sewage to overflow.	N/A	N/A	N/A	Yes	
2/20/2005 1410	El Pollo Loco	No	20	20	20	0	969 S. Euclid St.	Anaheim	969 S. Euclid St.	Private cleanout and Private Manhole	Grease or possibly other.	Grease blocked pipeline, causing sewage to overflow.	N/A	N/A	N/A	Yes	Upon arrival, spoke with the Manager of Little Caesar's Pizza (Maria) that initially reported the spill at neighboring business. El Polo Loco. City statt then went to direck dry's main lies and found it to Browing weil. Conclused the assistant of a local contract on the property and running onto the sidewalk. He immediately contracted the jurnher and the purimer want on the side 34.30 PM and had the blockage opened at 3.55 PM. City staff contained and cleaned up spill.
4/12/2005 1910	Private	No	200	100	50	0	1770 Harbor Blvd. Anaheim	Anaheim	1770 Harbor Blvd. Anaheim	Private clean out	Grease / Break in sewer line	Grease caused blockage. Pipeline broken during cleanout process	N/A	N/A	Contained and collected by vactors Disposed into sew	Yes	Video showed evidence of a break. Repairs are required by July 2
5/4/05 0940	Private	Yes	50	0	0	0	1773 W. Lincoln Ave.	Anaheim	1773 W. Lincoln Ave. Anaheim	Private clean out	Grease	Grease caused obstruction.	Carbon Creek	N/A	Carbon Creek	Yes	The spill had occurred intermittently over the 24 hours prior to City Staff arrival. A clear link, which Bakery management acknowledged, was made between the excessive amounts grease in the manhole and the obstruction which caused the spill.
5/27/2005 2250	Private	no	0	20	200	200	1731 W. Katella Ave. Anaheim	Anaheim	1731 Katella Ave Anaheim	Private clean out	Paper towels and grease	Paper towels and grease caused obstruction.	N/A	N/A	N/A	Yes	
5/29/2005 2214	Private	Yes	3000	1200	200	200	801 N. Loara Street Anaheim	Anaheim	801 N. Loara Street Anaheim	Private clean out	Rags	Blockage caused by rags clogging lateral line.	Carbon Creek	Crecent Retarding Basin	Crecent Retarding Basin	Yes	
6/4/2005 1315	Private	No	0	20	50	50	1384 S. Gilbuck St.	Anaheim	1384 S. Gilbuck St.	Private clean out	Roots	Roots caused obstruction.	N/A	N/A		Yes	The volume of the spill was likely larger than the 20 gallons that were cleaned up. However, since the leak was very slow and ponded in street over a couple days, evaporation accounts for the remaining approximately 100 gallons.
6/6/2005 1245	Private	No	0	40	200	200	175 S. Harbor Blvd.	Anaheim	175 S. Harbor Blvd.	Private clean out	Grease	Grease caused obstruction.	N/A	N/A		Yes	NA
6/10/2005 1020	Private	Yes	100	800	200	200	537 N. Magnolia Ave.	Anaheim	537 N. Magnolia Ave.	Private clean out and private manhole	Pump shut down	Pump shut down caused obstruction	Coyote Creek	N/A		Yes	The property owner/manager contacted a pump company (Orange County Pumping) who corrected the problem with the pump station. The area in front of the building van swatched by the Chy stati, however, other areas along the side of the building-ot-accessable by the Chy stati, however, other areas along the side of the building-ot-accessable by the Chy equipment was not cleaned. Property Manager Diama Chavec (616-9970) was inburned of this fact and the need to clean these areas, she said it would get cleaned by the end of the day.
6/28/2005 1315	Private	No	360	350	200	200	1151 N. Euclid St	Anaheim	1151 N. Euclid St	Private clean out	Grease	Grease caused obstruction.	N/A	N/A		Yes	N/A
7/7/2005 1120	Private	No	2	200	500	2	627 North Euclid Street	Anaheim	627 North Euclid Street	Private clean out	Grease	Grease caused obstruction	N/A	N/A		Yes	NA
7/27/2005 1035	Private	No	0	900	600	0	2108 E. Lincoln Ave.	Anaheim	2108 E. Lincoln Ave.	Private clean out	Grease	Grease caused obstruction	Ponded in gutter	N/A		Yes	Mark Williams from County Environmental Health Barricos arrived on value at 1225 PM Ib investigate and satissis. Split data renach underground storm dans in system because sandhaga and filter tablic ware already blocking catch healt in street, since constructions is underway on the LincolA weSE. Chelge Bild, widening project. Additionally the obstruction occurred in the middle of the private onsile sever collection system, therefore, the focus of the remedial actions will be on those businesses upstream of the obstruction.
9/24/2005 0925	Private	Yes	2160	1200	200	0	1199 N. Euclid Street	Anaheim	1199 N. Euclid Street	N/A	Grease	Grease caused spill	Fullerton Creek	San Gabriel River		Yes	OCHCA assisted onscene and washdown was performed by a private party.
10/3/2005 0805	Private	No	970	100	300	0	2138 W. Brownwood Ave.	Anaheim	2138 W. Brownwood Avenue	N/A	Grease/Break	Grease and/or Break caused the obstruction	Carbon/Creek	N/A	Ponded in Storm Drain	Yes	This was an unusual spill due to the fact that we never were able to contact the owner by phone (or by any other method). HCA investigated contact information and Chy Code Enforcement as well as Utilities Billing were unable to debain a good plant of the owner. The residents of both units also did not have a phone united.

N N N N N N N N N N N N N N N N N 101 N N N N N N N N N N N N N N 111 N <td< th=""><th></th><th>1</th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th>r</th><th>1</th><th>1</th><th>T</th><th>r</th><th>r</th><th></th><th></th></td<>		1										r	1	1	T	r	r		
Norme Normandeddddddddddddddddddddddddddddddddddd	10/24/2005 2010	Privat	te N	D	5	45	40	0	732 N. East Street	Anaheim	732 N. East Street	N/A	Roots	Roots caused obstruction	Carbon Creek	N/A	Ponded in Storm Drain	Yes	N/A
Math Math <t< td=""><td>1/9/2006 1015</td><td>Privat</td><td>te Ye</td><td>is</td><td>30</td><td>90</td><td>40</td><td>0</td><td>1721 Claudina Avenue</td><td>Anaheim</td><td>1721 Claudina Avenue</td><td>Private Cleanout</td><td>Roots</td><td>Roots caused obstruction</td><td>Los Alamitos</td><td>Bolsa Chica</td><td></td><td>Yes</td><td>N/A</td></t<>	1/9/2006 1015	Privat	te Ye	is	30	90	40	0	1721 Claudina Avenue	Anaheim	1721 Claudina Avenue	Private Cleanout	Roots	Roots caused obstruction	Los Alamitos	Bolsa Chica		Yes	N/A
Main	1/9/2006 1330	Privat	te N	D	0	120	50	0	407 State College Blvd	Anaheim	407 State College Blvd.	Private Cleanout	Grease	Grease caused the obstruction	N/A	N/A		Yes	restaurant did not have or would not release his information. Code enforcement as
MAX VAC VA <td>1/10/2006 1600</td> <td>Privat</td> <td>te N</td> <td>Þ</td> <td>0</td> <td>40</td> <td>50</td> <td>0</td> <td>407 State College Blvd</td> <td>Anaheim</td> <td>407 State College Blvd.</td> <td>Private Cleanout</td> <td>Grease</td> <td></td> <td>N/A</td> <td>N/A</td> <td></td> <td>Yes</td> <td>N/A</td>	1/10/2006 1600	Privat	te N	Þ	0	40	50	0	407 State College Blvd	Anaheim	407 State College Blvd.	Private Cleanout	Grease		N/A	N/A		Yes	N/A
Math Math <t< td=""><td>1/16/2006 1315</td><td>Privat</td><td>te Ye</td><td>IS</td><td>2050</td><td>250</td><td>1000</td><td>0</td><td>453 W. Summerfield Circle</td><td>Anaheim</td><td>453 W. Summerfield Circle</td><td>Private Cleanout</td><td>Grease</td><td></td><td>East GG Wintersburg</td><td>N/A</td><td></td><td>Yes</td><td>This is the first clear instance of a repeat spill in many years. This will require high level enforcement to ensure this does not happen again.</td></t<>	1/16/2006 1315	Privat	te Ye	IS	2050	250	1000	0	453 W. Summerfield Circle	Anaheim	453 W. Summerfield Circle	Private Cleanout	Grease		East GG Wintersburg	N/A		Yes	This is the first clear instance of a repeat spill in many years. This will require high level enforcement to ensure this does not happen again.
and ind ind <td>1/30/2006 1520</td> <td>Privat</td> <td>te N</td> <td>D</td> <td>740</td> <td>2500</td> <td>1000</td> <td>0</td> <td>627 N. Euclid Street</td> <td>Anaheim</td> <td>627 N. Euclid Street</td> <td>Private Cleanout</td> <td>Grease and Break</td> <td></td> <td>ponded in Anaheim</td> <td>Carbon Creek</td> <td></td> <td>Yes</td> <td>HCA requested that the property manager perform disinfection of the affected area on private property. Although it is not common practice, the City allowed this work to proceed under HCA supervision and with the vactor truck fully containing the sp downstream.</td>	1/30/2006 1520	Privat	te N	D	740	2500	1000	0	627 N. Euclid Street	Anaheim	627 N. Euclid Street	Private Cleanout	Grease and Break		ponded in Anaheim	Carbon Creek		Yes	HCA requested that the property manager perform disinfection of the affected area on private property. Although it is not common practice, the City allowed this work to proceed under HCA supervision and with the vactor truck fully containing the sp downstream.
new 1 <th1< th=""> 1 1 1</th1<>	2/3/2006 1400	Privat	te N	Þ	2360	2500	1000	0	627 N. Euclid St.	Anaheim	627 N. Euclid St.	Private cleanout	Grease and Break		Ponded in	Carbon Creek		Yes	N/A
And And <td>2/7/2006 1050</td> <td>Privat</td> <td>te N</td> <td>D</td> <td>160</td> <td>2000</td> <td>1000</td> <td>0</td> <td>627 N. Eulid St.</td> <td>Anaheim</td> <td>627 N. Euclid St.</td> <td>Private cleanout</td> <td>grease and break, but discovered to</td> <td>metal disk caused spill</td> <td>Ponded in</td> <td>Carbon Creek</td> <td></td> <td>Yes</td> <td>entry where the majority of the sewage left the property, in order to capture and contain any spills in the near future and prevent them from leaving the property. Additionally, the disk which likely was the cause of the recent spills should be</td>	2/7/2006 1050	Privat	te N	D	160	2000	1000	0	627 N. Eulid St.	Anaheim	627 N. Euclid St.	Private cleanout	grease and break, but discovered to	metal disk caused spill	Ponded in	Carbon Creek		Yes	entry where the majority of the sewage left the property, in order to capture and contain any spills in the near future and prevent them from leaving the property. Additionally, the disk which likely was the cause of the recent spills should be
12100 No. No. </td <td>2/15/2006 0950</td> <td>Privat</td> <td>te N</td> <td>D</td> <td>120</td> <td>30</td> <td>200</td> <td>0</td> <td>2080 S. Harbor Blvd.</td> <td>Anaheim</td> <td>2080 S. Harbor Blvd.</td> <td>Private cleanout</td> <td>Grease</td> <td>Grease caused obstruction</td> <td>N/A</td> <td>N/A</td> <td></td> <td>Yes</td> <td>N/A</td>	2/15/2006 0950	Privat	te N	D	120	30	200	0	2080 S. Harbor Blvd.	Anaheim	2080 S. Harbor Blvd.	Private cleanout	Grease	Grease caused obstruction	N/A	N/A		Yes	N/A
2 Norme <	2/23/2006 1000	Privat	te N	D	0	50	200	50	917 W. Lodge Ave.	Anaheim	917 W. Lodge Ave.	Private cleanout		Soap/sewer buildup caused obstruction	ponded onsite	and in street		Yes	respond in a timely manner, resulting in the property manager and his assistant clearing the drain with own tools. City vactor onsite to washdown and dispose of
instruction	2/26/2006 1345	Privat	te N	D	40	40	500	0	1040 N. Magnolia Ave.	Anaheim	1040 N. Magnolia Ave.	Private cleanout	Break	Break caused obstruction	Ponded in street	Fullerton Creek		Yes	also the reporting party, did all that was possible at the time to address the spill an investigate the problem, including hiring 2 separate plumbers. Despite having one of the plumbers perform a repair on a cleanout which had damaged the lateral line the spill started agaon on 2/28, subsequent to this repair work. The owner was
14.100000000000000000000000000000000000	3/7/2006 1335	Privat	te Ye	15	500	40	20	0	105 E. Leatrice Ln.	Anaheim	105 E. Leatrice Ln.	Private cleanout	Vandalism	Vandalism caused spill	Los Alamitos	Garden Grove		Yes	This spill was reported to have been flowing for several days by the tenants. The odor in the area and the volume of solids near the spill bears this out. However, it property owner was very responsive in taking care of the obstruction as well as aiding in the cleanup.
And A	3/14/2006 0900	Privat	te N	D	30	20	500	0	777 Convention Way	Anaheim	777 Convention Way	Private cleanout	Grease	Grease caused obstruction	Ponded in	storm drain		Yes	grease discharged to the sewer, and implemented a fairly successful sewer line cleaning program, the problem with sewer spills persists. Therefore, despite the potentially high cost, structural controls (grease interceptors and/or traps) will be frequired to be installed at appropriate locations and will be sized adequately and
442000 H00 Preak Yes 140 0 400 0.0 Pole S. Evold St. Preak e lean O Preak e lean O Pole A lean O Desk e lean O	3/23/2006 1630	Privat	te Ye	15	255	1500	500	0	3170 W. Lincoln Ave.	Anaheim	3170 W. Lincoln Ave.	Private cleanout	Grease	Grease caused obstruction	Carbon Creek	N/A		Yes	Property owner was very cooperative and reported this spill to the City themselver There was a delay, however, in clearing the sewer line, since the "anake" that the first plumber used was not effective in clearing the obstruction. The second plumber managed to clear the obstruction with a jetting tool.
Since No. No. Since Sin	4/6/2006 1650	Privat	te Ye	is	140	0	40	0	969 S. Euclid St.	Anaheim	969 S. Euclid St.	Private cleanout	Grease and food	Grease and food caused obstruction	Los Alamitos	Bolsa Chica		Yes	On Ball Road it traveled west approximately 250 yards where it entered the catch
A columnA colu	5/10/06 0815	Privat	te N	D	0	80	0	0	1365 Knollwood Circle	Anaheim	1365 Knollwood Circle	sample box	and build up of fibers on sewer	Lack of capacity caused obstruction	N/A	N/A	N/A	Yes	Sewer spills have been experienced at this location in the past, under similar circumstances. However, there has not been a spill in over three years.
and to the rate rat	5/15/2006 1230	Privat	te N	Þ	95	5	0	0	1755 W. La Palma Ave.	Anaheim	1755 W. La Palma Ave.	Private cleanout	Grease	Grease caused obstruction	Coyote Creek	dry detention basis	N/A	Yes	N∕a
5/24/2006 (600) Pivate No 60 160 500 0 900 SE Vermont Ave. Pivate (second) Pivate (seco	5/23/2006 1430	Privat	te N	D	300	100	200	0	1731 W. Katella Ave.	Anaheim	1731 W. Katella Ave.	Private cleanout	Grease and paper	Grease and paper caused obstruction		Bolsa Chica	N/A	Yes	N/A
6/82/2006 1555 Physike No 10 10 10 10 258 W. Lincoln Ave., #3 Physike Cessor Brisk as deside obstruction NA NA NA Vas Middle of the house at the southwest competing on the bougetty, which finds the durby at the southwest competing. Middle of the house at the sout	5/24/2006 0600	Privat	te N	D	60	160	500	0	905 E. Vermont Ave.	Anaheim	905 E. Vermont Ave.	Private cleanout			Ponded in SD	N/A	N/A	Yes	Because the spill flowed a significant distance before reaching the catch basin, it is believed that a significant portion of the spill was contained and collected before it was discharged into the catch basin.
7/82006 1700 Pivate NA 300 800 S00 Point S00 Point Pivate	6/8/2006 1655	Privat	te N	D	10	10	15	10	2936 W. Lincoln Ave., #3	Anaheim	2936 W. Lincoln Ave., #3	Private cleanout	break	Break casued obstruction	N/A	N/A	N/A	Yes	kitchen of the house at the southwest corner of the property, and the other was fro regular parking lot and loading dock washout from the northern portion of the
Indexed from Private New 300 000 300 0 1590 W. Particulare Private defront instead	6/11/2006 1102	Privat	te Ye	15	600	1800	20	600	8000 Naples Ln.	Anaheim	8000 Naples Ln.	Private cleanout	roots	Roots caused obstruction	Santa Ana River	N/A	N/A	Yes	N/A
7/12/2006 1945 Private No 0 1620 4500 0 1620 4500 0 3534 W. Ball Road Anaheim 3534 W. Ball Road Private cleanout Unknown NA NA NA NA NA	7/8/2006 1700	Privat	te N/	A	300	800	500	0	1590 W. Palm Lane	Anaheim	1590 W. Palm Lane	Private cleanout	Grease	Grease caused obstruction	Westminster	Channel	N/A	Yes	Property management was very responsive in obtaining a private plumber to clear obstruction.
	7/12/2006 1945	Privat	te N	D	0	1620	4500	0	3534 W. Ball Road	Anaheim	3534 W. Ball Road	Private cleanout	Unknown	Unknown	N/A	N/A	N/A	Yes	N/A

									1			1					
7/30/2006 1000	Private	No	220	120	100	0	1919 W. Coronet Ave	Anaheim	1919 W. Coronet Ave	Private cleanout	Break	Break caused obstruction	ponded	storm drain	N/A	yes	N/A
8/5/2006 0930	Private	N/A	1000	5300	6000	1000	1250 S. Brookhurst St.	Anaheim	1250 S. Brookhurst St.	Private cleanout	Roots, break, unknown	Unknown cause of obstruction, possibly roots or a break in the line.	Anaheim Barber Channel	Bolsa Chica	N/A	Yes	Private plumber was unable to clear obstruction with snake. Another plumber with a jetter was called in, after several hours of delays, to eventually clear obstruction.
9/21/2006 0830	Private	No	30	20	500	0	537 N. Magnolia Ave.	Anaheim	537 N. Magnolia Ave.	Private cleanout	Grease	Grease caused obstruction	Catch basin	Carbon Creek	N/A	Yes	A previous spill occurred at this address on 6/10/06. The spill occurred when the sewage lift pump failed, partially as a result of the failure to implement the corrective actions required in the first Compliance Order, and partially due to new conditions.
11/6/2006 0600	Private	Yes	1000	1520	1000	0	967 S. Euclid St.	Anaheim	927 S. Euclid St. interceptor	Private cleanout	Grease and settlable food soli	Grease and solids build up in interceptor and caused obstruction	Catch basin	Anahiem Barber Channel/ Huntington Harbor	NA	Yes	A previous spill occurred at this address but not from this same line. Impliementing a program to prevent the discharge of solids to the interceptor as well as a more frequent inspection and/or cleaning program should resolve this situation.
11/30/2006 1100	Private	Yes	400	500	500	0	1830 W. Romneya Drive	Anaheim	Pump Station at N/W corner of Euclid and Romneya	Private manhole	pump station failure	A sensor which monitors the level of sewage in the wet wel failed	I Catch basin	Fullerton Creek/Coyote Cree	_k NA	Yes	This was an unusual spill as it was caused by a failure of a private pump station. This failure is unlikely to occur again, however we will require assurances from the owner/operator to ensure this.
12/22/2006 0940	Private	Yes	10	0	0	0	1151 N. Euclid St.	Anaheim	1151 N. Euclid lateral in alley behind building	Private cleanout	Grease	Grease caused obstruction	Catch basin	Fullerton Creek/Coyote Cree	k N/A	Yes	A previous spill occurred at this location. If routine cleaning and Kitchen BMPs can not prevent spills, an iterceptor will be required,.
12/28/2006 1730	Private	Yes	200	400	200	0	537 N. Magnolia Ave.	Anaheim	Pump Station Failure	Private manhole	pump station failure	pumps are believed to have burned out	Catch basin	Carbon Creek	NA	Yes	This was an unusual spill since it is the third at this location, however, since it was caused by something different each time it has occurred, the order will focus on terms that may on thave been satisfied in previous orders and items that would help prevent future recurrances of this spill.
12/30/2006 1200	Private	yes	100	2000	2000	2000	2704 W. Ball Road	Anaheim	lateral from last manhole complex to street	in Private cleanout	grease and perhaps roots or a break	Grease alone or in a conjunction with a break or roots caused the obstruction	Catch basin	anaheim barber channel	N/A	Yes	
Totals	88	31	49,563	50,987	50,528	27,718										88	
Brea	4							1	1		-			4			
																	The property management and Larry honeybourne from OC Health dept were on
8/4/2002 0830	Brea	N	200	200	250	0	650 Tamarack	Brea	Sewer	Manhole	paper products	NA	NA	NA	n/a	Y	the property than generations and any note potential room of house tops which only site at time of the sewer stoppage. Apartment management phone # 714.990.0150
11/21/02 1400	Private Property	N	120	120	60	0	361-371 Oak Place	Brea	Sewer	Manhole	Don't Know	NA	NA	NA	n/a	Y	This was a private property spill.
1/17/2004 1200	Brea	N	300	50	50	0	105 W. lambert Rd.	Brea	unknown	intercepter	unknown	NA	NA	NA	n/a	Y	The property management and Alexander Soles from OC Health dept were on site at time of the sewer stoppage.
1/17/2004 2300	Brea	N	0	300	350	0	730 Imp. Hwy.	Brea	unknown	intercepter	unknown	na	NA	NA	n/a	Y	The property management and Alexander Soles from OC Health dept were on site at time of the sewer stoppage. Apartment management phone # 714.990.0151
3/3/04 0820	Private Property	N	120	120	200	0	2540Country Hills Rd.	Brea	A-04	Manhole	unknown	NA	NA	NA	n/a	Y	Apartment Manager Kathy Hill (714)9905626
Totals	5	0	740	790	910	0										5	
Buena Park	1							1	1	1			1				
9/7/04 1700	Private Property	No	0	0	0	0	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
9/22/04 1500	Private Property	No	0	0	0	0	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
11/22/04 1400	Private Property	No	0	0	0	0	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
12/13/04 2000	Private Property	No	0	25	0	0	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
12/29/04 1345	Private Property	Yes	50	25	0	0	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
1/31/04 1200	Private Property	No	0	100	0	0	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
3/12/05 2030	Private Property	Yes	700	200	0	0	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
3/16/05 1600	Private Property	No	0	60	0	0	10488 Valley View	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	yes	n/a
4/5/05 2030	Private Property	No	0	100	0	0	8810 San Antonio	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	yes	n/a
5/19/05 0800	Private Property	No	0	60	0	0	7758 Knott Ave	Buena Park	n/a	n/a	Paper	n/a	n/a	n/a	n/a	yes	r/a
6/18/05 1030	Private Property	Yes	100	0	0	0	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	r/a
8/22/05 1745	Private Property	No	0	30	0	0	5317 Humbolt	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	yes	n/a
						-										,	

5/18/06 1840	Private Property	No	0	60	0	0	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
					U												
7/17/06 1800	Private Property	Yes	50	100	0	0	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
8/14/06 1400	Private Property	No	0	100	0	0	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
8/20/06 0000	Private Property	Yes	100	100	0	0	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Totals	16	5	1,000	960	0	0										4	
Costa Mesa SD																	
07/06/02 1715	Costa Mesa Sanitary District	N	300	300	500	0	1936 Wallace, Costa Mesa, CA	Costa Mesa, CA	Private Lateral	Private Lateral Cleanout	Blockage in Private lateral line	NA	NA	NA.	Sewage and rinse water vactored and returned to sewer system	NO	Sewage from private readential lateral spilled into street when private contractor laterator readential lateral and calonous. All sewage contractor in street. Approx. 2.5 gpm into street 1*120 minutes yields 300 gals spilled. Field crew dammed sewage Bijl, vaccided up sewage, flushed street with fresh water and vaccided up all flush water. Spill and filtach water returned to sewer system. No sewage reached storm drait, channele, to surface waters.
07/25/02 0750	Costa Mesa Sanitary District	N	25	25	1000	0	Marie Callender's;363 East 17th St, Costa Mesa, CA	Costa Mesa, CA	Private Lateral	Private Lateral Cleanout	Blockage: Grease in private lateral	NA	NA	NA	Sewage and rinse water vactored and returned to sewer system	NO	Marie Callender's private lateral blocked with grease; Rescue Rooter opened a 4 cleanout to clear the line. When opened, sewage spilled out from the sidewalk cleanout onto the street and curb for approx 10 minutes while contractor cleared the lateral line; Filed reve blocked domarisma storm drain to provide additional containment. See photos. District cree hydro-rodded the District Nami ne to treak up any grease didloged into it from the lateral; Storm drain was blocked to contain any sewage within it and all sewage was contained. District vaccured up steed and out spill, vaccured out the storm drain containment for interweater, mised the street with fresh water and vaccured up the misewater. See photos.
9/17/02 1630	El Pollo Loco Restaurant, 1941 Harbor Bivd, Costa Mesa, CA 92626	N	0	0	0	0	1941 Harbor Bivd	Costa Mesa, CA	Grease blocked El Pollo Loco grease trap and cleanout.	El Pollo Loco grease trap and cleanout in sidewalk between facility and drive-thru.	Pollo Loco grease	Grease blocked El Pollo Loco grease trap and cleanout, causing overflow across sidewalk, across drive thru, into alley down Bernard St gutter and into Harbor Blvd storm drain.	NA	NA	El Pollo Loco contractor and District Field Crew vactored Sevage and rinse water, returned to sewer system	Yes	Grease blocked EI Polio Loco grease trap and deanout, causing overflow across sidewalk, across drive thru, into aley down Benard St gutter and into Harbor BWo storm drain. EI Polio Loco contractor Careard grease trap and facility inside lines, but overflow flashed as described. Most important is the follow-up- Revisit to EI were replaced as a second and the second progen flashing- Provided copy of water Quality Gutdetines for Exterior Restaurant Cleaning Operations' (CO Somwater Program) and "Restaurant Owers Guide for Grease Control" (CMSD). Further Follow-up-Action. District is redistributing both guides with a "Warning Notice" attached and a District restaurant. Post-actively Dioorgaph Taken of ale inflecting casaned area, with only vehicular road grime in drive-thru, alley and strefts. El Polis Loco contractor & Bostici valored flash de somm drain.
10/17/02 1400	Koo Koo Roo Restaurant, 212 E 17th St. Costa Mesa, CA 92627	N	120	120	170	0	17th St between Orange Avenue and Westminster	Costa Mesa, CA	Koo Koo Roo Restaurant lateral , blocked with grease and paper towels	Koo Koo Roo Restaurant lateral cleanout		Grease and paper towels blocked Koo Koo Roo Restaurant lateral, causing SSO into E 17th St curb and gutter.	NA	NA	120 gallons of SSO spilled out of the lateral cleanout into the 17h St gutter - and completely contained & vactored. Crew flushed gal area with 50 gallons of trest water, also vactored and emptied into the sewer system.	No	Main line running clear: Koo Koo Roo contracted plumber cleaned out private lateral; preses blockage deared from lateral line into District Man Line; Crew contained SSO upon arrival; vacorden SSO, lathed area with 50 gals fresh water and vactored up rines water. Koo Koo Roo manager showed documentation of lateral clearing 3 months earlier; Feld Crew advised Koo Roo manager to lateral clearing 3 months earlier; Feld Crew advised Koo Roo manager to the state and the state of the state of the state of the state of the state of Field Crew ran Main Line to ensure uncleaged grasse did not block main line. Crew thirdre advised Koo Roo Romanger to instati a grasse rate; Satti is re-sending 2 brochures; CMSD "Restaurant Owner's Guide for Grasse Control" and "Warning" and O C" Watter Oually Guidelines for Sterior (Restaurant Clearing Operations." Also intorned Koo Koo Roo mapoyees of the need to properly dispose of paper towels in the trank of on this see erg plant.
12/31/02 0730	El Toro Bravo Restaurant, 739 W 19th St. Costa Mesa, CA 92627	N	0	480	300	0	El Toro Bravo restaurant @ 739 Wesi 19th St	Costa Mesa, CA	Grease/commeal plugged El Toro Bravo lateral line forcing SSO out of desnout cover and into th parking lot where it was contained, returned to sewer system. Field Crew informed El Toro Bravo manager of SSO status - asked manager to clean deanout.	located in the parking located in the parking lot, percolated raw sewage out of pickhole 2 inches in balable Ciald argument		El Toro Bravo restaurant cleanou, located in the parking lot, percolated raw sewage ou of pickhole 2 inches in height.	NA	NA	Contained SSO flush water were disposed of into the concord and into the server system.	Y	Grease/commail plugged EI Toro Bravo lateral line forcing SSO out of cleanout cover and into the parking lot. Field Crew informed EI Toro Bravo manager of SSO status – asked manager to clean cleanout. Approximately 480 gallons of SSO spilled out of clean out into EI Toro Bravo parking lot. Field Crew ensured manager fully contained SSO an parking lot. After Rescue Roster unblocked lateral line. manager fhuades daning lot. After Rescue Roster unblocked lateral line. Into the server system. Field Crew remained on site to ensure rate sweage was into the server system. Site of address water. SSO and their water vere edisposed or into the server system. Safet address the server rate sweage was of in the server system. Safet address clean data for an ensure rate sweage was formed of need to perform periodic lateral line maintenance. Staff provided copy or "Restaurant Owner's Guide For Grease Control," Sewage Spills Ref Cluide' to manager. Digal photos were taken. Saff a working with Cry of Cost at Meas (COM) Building representatives to clarity interpretation of CCM Ordinance 97-20 and Building servers.
5/06/03 0930	666 West 18th St Newport Mesa Townhome, Costa Mesa, CA 92626	N	0	165	100	0	SSO spilled out of lateral line cleanout at 666 W 18th St, Costa Mesa	Costa Mesa, CA	Location is in a residential neighborhood. SSO spille out of lateral line cleanout at 666 W 18th St. Costa Mesa. Lateral line blocker with roots and paper.	spilled out of lateral line cleanout at 666	Lateral line blocked with roots and paper.	Lateral line blocked with roo and paper.	IS NA	NA	Contained SSO and flush water were returned to/disposed of into the sewer system.	Y 5/06/2003 1045hrs	Approximately 165 gallons of SSO spilled out of private lateral line cleanout located at 660 West 19th St, Costa Mesa. Field Crew fully contained SSO In public right of way. Crew vacched SSO, flushed SSO with fresh water and disposed of SSO and flush water into the sewer system. Private plumber, Costa Plumbing, cleared line by cutting roots out of lateral; Digital photos were taken and are attached to this report.

1/13/04 1443	The Lodge, a Food Service Establishment (FSE) at The Camp, 2937 Bristol St, Costa Mesa, CA	N	100	100	200	100	The Lodge is one of 3 Food Service Establishments FSE) at The Camp address; Interceptor for The Lodge was blocked, forcing the SSO out of a vert hole at 2337 Bristol St.	Costa Mesa, CA	The Lodge is one of 3 Food Service Establishments FSEn) at The Camp address; Intercoptor for The Lodge was blocked, forning the SSO out of a vent hole at 2937 Bristol St.	The Lodge is one of 3 Food Service Establishments FSEs) at The Camp address; Interceptor for The Lodge was blocked, forcing the SSO out of a vent hole at 2937 Bristol St.	District Field Crew verified FSE grease blocked The Lodge interceptor.	District Field Crew verified FSE grease blocked The Lodge interceptor.	Santa Ana-Deihi Channel	None	100 gals of SSO entered storm drain leading to the Santa Ana-Deht Channel. 100 gals SSO wo ree contained. Vactored SSO and flush water were returned to District Main Line at the Corporate Yard.	Y 1/13/04 1712 hrs	OCSD informed CMSD of the SSD at the Food Service Establishment (FSE) known as The Lodge at 2337 Bristol SL. District Crew arrived, contained the SSD, discussed concretive action with The Lodge employees, called the City of Costa Meas National Pollutant Discharge Elimination System (NPDES) manager to the law and ensized the Lodge arranged for a plumber to class of the role and ensized the Lodge arranged for a plumber to class of the role and ensized for the Lodge arranged role manager to the directed the team (The Lodge) to implement a quarterplu timereption classing program. CMSD added the site to the District FSE contractor for follow-up visits and evolution to the appears to have experimented overlatives in the part at evolution by the drive manager and The Lodge manager that not addressed for privater SSOs to which the District must provide resources to control. Photos were taken and are attached.
4/04/2004 1500	CMSD	¥	2475	525	300	0	1599 Superior Ave / 700 Block of West 16th St;	Costa Mesa, CA	Root balls blocked private sewer lateral forcing SSO out of private cleanout; possible root entry point at Ductlie Iron Pipe fitting to lateral on private property;	Root balls blocked private sewer lateral forcing SSO out of private cleanout; possible root entry point at Ductile Iron Pipe fitting to lateral on private property;	Root balls blocked private sewer lateral forcing SSO out of private cleanout;	Root balls blocked private sewer lateral forcing SSO out of private cleanout;	t Newport Beach Harbor	None	Vactored SSO and rinse water were disposed of in the sanitary sever system at the Corporate Yard;	Y; 4/05/2004 @ 1545 hrs	Root balls blocked private severe lateral forcing SSO out of private cleanout: possible root entry point at Ducille iron Pipe fitting to lateral on private property: Clean Properties Propenty Manage 24 ES Schweitzer called for two plumhing companies to clean the SSO lateral blockage; First company unable to clean lateral with rotary cutiling black – but removed or cutilisters from tateral: Second company used a min lydrojet to clear remaining blockage; Dietrict Field Crew recommende the Property Manager wide he tateral: (or / of Cotas Maes NPDE S Manager also on-site and took photos, CMSD Crew dammed storm drain, vactored and disposed of the contained SSO and rines water into the blaint service system at the Corporate Yard; Photographs were taken and are attached.
9/27/04 @ 1200	Pacific City Property, 10 unit apartment complex, City of Costa Mesa	N	500	1500	500	500	584 W Hamilton Street	Costa Mesa, CA	Private lateral at Pacific City Property, 10 unit apartment complex, Costa Mesa	Private lateral at Pacific City Property, 10 unit apartment complex, Costa Mesa; SSO spilled from private backyard cleanout;	Private lateral at Pacific City Property, 10 unit apartment complex, was blocked with grease;	Private lateral at Pacific City Property, 10 unit apartment complex, was blocked with grease;	None	None	Vactored SSO and rinse water were disposed of in the District sanitary sewer system;	Y; 9/27/2004 @ ~1600 hrs	Private lateral at Pacific City Property, 10 unit apartment complex, was blocked with grease. SSO spilled from private backyard cleanout. CMSD Field Crew dammed SSO in street and cut and at the SD, vaccitered and disposed of the contained SSO and rines water into the District sanitary sever system; Of the estimated 2000 agains of total SSO. 500 gals were totis in the storm drain (SD) and to evenporation down 600 f path to SD; Costa Plumbing cleared the grease blocked lateral line at Pacific City Property 10 unit apartment complex. District intends to contact the US postal (carrier) service to determine the best protocol for carriers to report such events to the blatict upon discovery in the future; Photographs were unavailable as attachments to this report.
10/29/04 1030	Private party lateral blocked with roots;	N	1	6	31	1	690 West Hamilton St	Costa Mesa, CA	Roots blocked private lateral; SSO spilled from private lateral cleanout at 690 West Hamilton St; Fully contained;	Roots blocked private lateral; SSO spilled from private lateral cleanout at 690 West Hamilton St; Fully contained;	spilled from private lateral cleanout at	Roots blocked private lateral; SSO spilled from private lateral cleanout at 690 West Hamilton St; Fully contained;	None	None	Vactored SSO (6 gals) and 25 gals of rinse water were disposed of in the District sanitary sewer system;	Y; 11/01/2004 @ 1625 hrs;	Roots blocked private lateral: SSO spilled from private lateral cleanout at 690 West Hamilton St, Fully contained, Private owner obtained services of plumber and cleaned out the roots blocking the lateral line. (Zver eremend on-site until blockage cleaned; vactored SSO (6 gabla) and 25 gals of rinse water were disposed of in the Datrict sanitary server system; 3 gals SSO everyoated from earthen dam; Photographs were taken and are attached in Word format;
11/01/04 1415	Private party lateral blocked with grease;	N	0	50	100	0	200 East 17th St;	Costa Mesa, CA	SSO spilled from private lateral cleanout approximately 10 feet from the curb;	SSO spilled from private lateral cleanout approximately 10 feet from the curb; Grease interceptor appeared to not have been maintained as evidenced from rusted bolts and cover, leading to grease blockage;	interceptor and the	Grease blocked the private lateral cleanout at 200 E 17th St; Fully contained;	None	None	Vactored 50 gallons of SSO and 50 gallons of rines water were disposed of in the District sanitary sewer system;	Y; 11/01/2004 @ ~1625 hrs;	SSO spilled from private lateral clearout approximately 10 feet from the outry: Grasse interceptor appeared to not have been maintaned as indenced from mater holts and cover, leading to grasse blockage. District Creve blocked Stom Drain (SD) with rubber mate to July contain SSO, Blattic Creve estimated SSO via visual pool estimates of the SD and State SSO and State SSO via visual pool estimates of the SD and SSO and SSO. The state SSO via visual pool estimates of the SD and SSO and SSO and SSO and SSO and visual pool estimates. Private over a state of the state of the state of the state of that state state of planther and deaned out the lateral line - need to follow up to ensure interceptor is cleaned; placed site on maintenance program; Photographs were not taken;
11/5/2004 0815	Private party lateral cleanout blocked with roots;	N	0	50	100	0	2424 University Drive	Newport Beach	SSO spilled from private lateral cleanout in a recently built sidewalk in Newport Beach;	SSO spilled from private lateral cleanout in a recently built sidewalk in Newport Beach; Roots blocked lateral line	Roots blocked private lateral line;	Roots blocked private lateral line at 2424 University Drive;	None	None	Vactored 50 gallons of SSO and 50 gallons of rinse water were disposed of in the District sanitary sewer system;	Y 11/05/04 @ 1440 hrs	City of Newport Beach Onew and CMSD Disnical Craw blocked four in out-bleading to Back Say. Vactored Sip allotins of SSO and So pallons of rinary water were disposed of in the Datriet sample wave systems; Distinct Orwe estimated SSO via visual pool estimated to be So gallons = 5 gallinin x 100 minuter, ABRR Plumbing responded to Distinct for owner manager Max Yanada and deamed roots out of the lateral; Lateral line also videotaped. Photographs were taken and are attached;
3/16/2005 1623	Denny's Restaurant	N	0	60	160	0	105 East 17th St.	Costa Mesa, CA	Denny's Restaurant greas interceptor not maintained/cleaned; - Diatric Crew Fully Contained SS(o) in parking lot and vactored;	Denny's Restaurant grease interceptor not maintained/cleaned; - District Crew Fully Contained SSO in parking lot and vactored;	Denny's Restauran grease interceptor not maintained/cleaned ;- District Crew Fully Contained SSO in parking lot and vactored;	Denny's Restaurant grease interceptor not maintained/cleaned, - District Curve Fully Contention 4 Sto In parking lot and vactored,	None	None	Vactored 60 gallons of SSO and 100 gallons of rinze water were disposed of in the District sanitary sewer system;	Y; 3/16/2005 @ -1700 hrs;	OC Environmental representative Mile (714-433-6120) called SSO in to CMSD. OC Environmental indu down Derwy's Restaurant due to the SSO from the grease interceptor. Estimated 60 gallons SSO from single pickhole in a calenout. Crew contained SSO, SSO did not enter the storm drain (SD), battict crew vactored approximate/ 60 gallons SSO for sol to sol from switer, Crew disposed of vactored SSO and nineswater into District anihary sever; District Crew estimated SSO to be 60 galls – 530 china Y attor, Crew disposed of national stores and the sever; District Crew and/on a terminate Bernard Bernard and a vactored Store and the service sever; District Crew estimated a plumber to clean out the grease interceptor. District back-charged Denry's and avactored store of the requirement to maintain the grease interceptor. Denry's was placed on the District Hotspot Is the Chood Sarvice Establishiments (FSS) inspections, permitting and grease interceptor maintenance; Photos were taken and are attached;
5/16/2005 1500	Mesa Verde Town Homes;	N	40	60	160	40	666 West 19th St	Costa Mesa, CA	Roots in private lateral line of Newport Mesa Town Homes caused SSO to spill from cleanout;	Roots in private lateral line of Newport Mesa Town Homes caused SSO to spill from cleanout;	Roots in private lateral line of Newport Mesa Town Homes caused SSO to spill from cleanout;	Roots in private lateral line of Newport Mesa Town Homes caused SSO to spill from cleanout;	Miles of storm drain leading to Newport Bay;	None	Lost SSO due to it soaking into the ground and evaporation - estimate 40 gallons;	Y; 5/16/05 @ 1600 hrs;	One District Crew contained SSO (upon arrival) from further entering the Storm Drain (SS) will private plumber arrived to clear private lateral line of roots; District caled ou CAR purposition to clean the line. So load as addituat containment vessel; Crew vactored sewage from site and SD and disposed of it in the District landary sever; Estimated from rate of 2g adnos per hour to for borus yielding and SSO of 100 galous; Roots in private lateral line of hewport Mesa. Town Hornes and SD and 100 galous check and the strength of the strength of the lateral to formed Property Manager Chery Store to increase frequency of lateral line S-6-60; Photographs were taken and are attached.

7/29/2005 1700	Costa Mesa Sanitary District	N	0	5	55	0	584 Hamilton St	Costa Mesa, CA	Grease blocked private lateral line in a multifamily residential development forcing SSO out of private property cleanout;	Grease blocked private lateral line in a multifamily residential development forcing SSO out of private property cleanout;	residential development	Grease blocked private lateral line in a multifamily residential development forcing SSO out of private property cleanout;	None;	Vactored SSO was disposed of in the District Sanitary Sewer System;	Y; 8-04/05 @ 1420 hrs;	SSO trickles from private lateral cleanout onto private property and to the streat and nearby storm drain (SD) which acted as a containment vessel. Crew blocked SD and vacorder SSO while private planeth (Coast General Pumbring) was enrote to the site. Crew vaccherd servage and rines water from site (streat, curb and SD) and disposed of it in the District sinality sever. [District Crew and SDI and SDI and street, curb and SD. District formande sever. [District Crew and SDI and street, curb and SD. District formande ABCII Clar Properties (management company) of situation, recommended nucleased lateral cleaning frequency from quarterly to 3-investing and agender and agender cleaning the clargency the properties.] for District services. Photographs were not taken;
11/3/2005 0950	Costa Mesa Sanitary District	N	0	45	100	5	2520 Kincaid Drive	Costa Mesa, CA	Unknown blockage blocked private lateral line in a multifamily residential complex at Fairview State Hospital forcing SSO out of private property M/H;	residential complex at	Unknown blockage blocked private lateral line in a multifamily residential complex at Fairview State Hospital;	Unknown blockage blockad private lateral line in a multifamily realential complex at Fairview State Hospital;	None;	Vactored SSO was disposed of in the District Sanitary Sewer System;	Y; 11-17/05 @ 1650 hrs;	Unknown blockage blocked private lateral line in a multifamily residential complex a Faivlew State Hospital forcing SSO out of private property MH: blatict crew blocked SD, vacced SSO from the stere, curb and SD, hunde the area with freak rines water. District Staff contracted Fairview State Hospital Manager (Sharmon, TH Private glumber moved lateral line blockage; Vactored SD was disposed of in the District Sanitary Sever System; Pictures were taken and are attached;
	Property Manager for 1746 Placentia Ave, Costa Mesa, CA property:	N	20	154	254	20	779 Shalimar Dr;	Costa Mesa, CA	Roots blocked multifamily residential lateral causing overflow from an uncapped cleanout;	Uncapped cleanout;	Roots in private lateral line;	Roots blocked multifamily residential lateral causing overflow from an uncapped cleanout;	None;	City of Costa Mesa crew vactored SSO and rinse water and disposed of the wastewater in the District sanitary sewer system;	Y; 1/13/06 @ 1605 hrs;	Private resident of facility reported event to CMSD and CMSD Maintenance Supervisor, in turn: Estimate 17 4 galaxies SSO flowed from an uncapped private property cleanor. Estimate 20 galaxies SSO flowled from some drait (SS). Estimates Statistical SSO flowed from some drait statistical statistical statistical and rinse water and disposed of the wastewater in the District sanitary severe system: Roots bolked multitamily residential lateral causing overflow from an uncapped cleanout, CMSD Maintenance Supervisor remained on alte until commercial planet arrived and competed lateral cleaning/resonval of cods and capping the facility cleanout, CMSD Stati Informed Facility Manager, Ed Ginka, 71 625-6300; di need to increase lateral cleaning frequency and keep cleanouts capped, CMSD backcharged Facility Manager for services provided; Photos were taker.
	Maru Sushi Food Service Establishment manager;	N	0	260	360	0	1500 Adams Ave;	Costa Mesa, CA	Estimated 260 gallon SSO spilled from private property grease interceptor (GI);	grease-blocked	Grease blocked GI;	Estimated 260 gallon SSO spilled from grease-blocked Interceptor (GI);	None;	City of Costa Mesa crew vactored SSO and rinse water and disposed of the wastewater in the District sanitary sewer system;	Y; 1/23/06 @ 1650 hrs;	City of Costa Mesa Code Enforcement called event in to Comm Citr, District Maintenance Supervision, in turn, National Plant Services, inc contrator response Settimated 260 april 2014 (Settimate Plant Services), inc contrator response Interceptor (GI), City of Costa Mesa crew vactored SSO and rines water and disposed of the waterwater in the District sanitary severe system. District Salf and City of Costa Mesa NPDES Manager counseled Maru Sush Manager, Scott (346- 346-368), in City of Costa Mesa crew vactored SSO and rines water and Gity of Costa Mesa NPDES Manager counseled Maru Sush Manager, Scott (346- 346-368), in cincease frequency of Citeraing, to use Bet Management Practices (546/F) and aducate employees on proper disposal of Pais. Otis and Grease (FOG) Photos west salery.
2/17/06 1335	Lordon Management Company (825-967-7921, 3316), @ 1272 Coerter Court Drive, Covina, CA 91724, FAX: 626-966- 3918)	N	0;	82	132	O;	760 West 16th St;	Costa Mesa, CA	Grease, roots, rocks and debris blocked private lateral in a parking lot causing overlow from a cleanout;	Grease, roots, rocks and debris blocked private lateral in a parking lot causing overflow from an uncapped cleanout;	lateral in a parking	Grease, roots, rocks and debris blocked private lateral in a parking for causing overflow from an uncapped cleanout;	None;	District line cleaning contractor, NPSI, dammed SD, vactored SSO and rinse water and disposed o the wastewater in the District sanitary sewer system;	Y; 2/21/06 @ 1250 hrs;	Visually estimated #2 gallon SSO flowed from one private property deanout: Estimate Some SSO invided into Storm Drain (SD) used as a containment vessiti galance some SSO invided into Storm Drain (SD) used as a containment vessiti contractor, National Plans Services, Inc., demmed SD and vinctored SSO and rines atter and disposed of the wastrevent in the District santhy sever system. Phrive plumber purhed blockage into District line while deaning lateral line, Grease, rotts, rocks and dehter blocked private lateral in a parking for causing overflow from a cleanout, District Main. Line previously cleaned on 1-23-06; Lordon management Company (GE-97-721; X315) whitemed of the need to increase private lateral line maintenance to prevent future SSOs; Photos were taken and are attached; District back-charged London Management Company for services/resources used to manage the SSO;
2/23/06 1230	Lordon Management Company (828-967-7921, X3159), @ 1275 Center Court Drive, Covina, CA 91724; FAX: 626-986- 3918)	N	0	35	85	O	760 West 16th St;	Costa Mesa, CA	Roots/paper towels blocked private lateral in a parking for causing overflow from a cleanout;	Roots/paper towels blocked private lateral in a parking tot causing overflow from a cleanout;	Roots/paper towels blocked private lateral in a parking to causing overflow from a cleanout;	Rootsjopper towels blocked private bareal is a packing for causing overflow from a deanout;	None;	District line cleaning contractor, (NPS), and Cin, of Costa Meas crew dammed SD, vactored SS2 and rince water and disposed of the westweate in the Diatrict sanitary sewe system;	/ D Y; 3/1/06 @ 1120 hrs; r	London Management Company reported event to CMSD and CMSD Maintenance Supervisor, Respart similar event to 2/1706; Visually estimated 82 gallon SSD maintenance and the second second second second second second second train (SD) used as a containment vessel; Recovered/Visioned 82 gallons; Darite ine cleaning contractor, National Planet Services, Inc., MPNB, and Cly of Costa Mesa crew performed cleanup; District maintenance supervisor and MPSI dameed Som Drain (SD) and valocited SSD can direave tetra and disposed of the wastewater in the District sanitary severe system; Plivate plumber antived and proved rocktopaper towels while designing lateral line; Rocktopaper towels blocked private listeral in a parking to Casaing overflow from a Celenout, District Main Line (S2) 667-7021; X23D) informed of the need to homase private listeral Min maintenance to prevent Nutry SSDs: Photos were taken and are attached; Datirct backcharged London Management Company for services/resources used to manage the SSO;
3/30/06 1428	Property Manager for 1875- B Newport Bivd (Triangle Square), Costa Mesa, CA property;	N	20	85	205	20	1875-B Newport Blvd;	Costa Mesa, CA	Grease blocked commercial lateral causing overflow from two of three cleanouts;	Two of three parking lot cleanouts;	causing overflow	Grease blocked commercial lateral causing overflow from None; two of three cleanouts;	None;	City of Costa Mesa crew vactored SSO and rise water and disposed of the wastewater in the District sanitary sewer system;	Y; 4/6/06 @ 1800 hrs;	Estimated 105 galon S20 flowed from two of three private property cleanouts; Estimate 20 galons S20 trickled into stom dani (SD) used as a containment weak? Recovered Vactoried 55 galonics; Cityl of Cost Marca crew vactored SSO and rinee water and disposed of the wastewater in the District sanitary sever system; Grasse blocked commercial isterial causing overflow from two of three deanouts; CMSD District Maintenance Supervisor on site; Cityl of Costa Mesa crew blocked D and vactored wastewater in the street and cut while pumber was en route; Private pumber Proserve cleaned lateral line; CMSD contractor, National Plant Services, Inc., cleaned the remaining grasse pumbel not the District Main Line on 3-31-06 @ 0930 hours; Photos were taken and are attached;
4/10/06 1320	The Lodge Food Service Establishment (FSE);	N	0	10	60	0	2937 Bristol Street;	Costa Mesa, CA	Grease primarily and some debris blocked private lateral; SSO flowed from private MH on private property;	Private MH;	Grease primarily and some debris blocked private lateral;	Grease primarily and some debris blocked private lateral; None	None	City of Costa Mesa crew vactored SSO and rinsewater and disposed of the wastewater in the CMSD sanitary sewer system;	Y; via FAX: 4/10/06 @ 1730 hrs	AB&R Plumbing called CMSD Maintenance Supervisor, Estimated 10 gallon SSO flowed from private Manhole (MH) on private propenty into Curb - City of Cotat Mes and CMSD Maintenace Supervisor dammed Stom Traini (SD) - fully contained; City of Costa Mesa crew vactored SSO and mise water and disposed of the wastewater in the CMSD sanitary several virtues vater and disposed of the subsetweet in the CMSD sanitary several virtue system; Visual Estimate of 10 gallons pooled wastewater - very shallow - 10 gallons over 30 minutes – 33 gallons/minute Grease primarily and some debris blocked private lateral; Photographs were taken and are attached;

	1									1							
5/22/06 1851	PetSmart Store - Private party;	N	25	25	25	25	620 W 17th St - PetSmart Store lateral cleanout;	Costa Mesa, CA;	Private on-site PetSmart lift station failed - well contained large volume of wastewater;	Private on-site PetSmart lift station failed - well contained large volume of wastewater;	Private on-site PetSmart lift statio failed - well contained large volume of wastewater;	n Private on-site PetSmart lift station failed - well contained large volume of wastewater;	None;	None;	SSO vactored and disposed of into the CMSD sanitary sewer system;	Y; 523-06 @ 1930hrs;	Visual estimate of waterwater in SD and from path from the PetSnart clearout to the SD and the curl: S galaritos stor Is SD (1) galaros exerginated: 25 galaros vactored. Private on-site PetSnart tilt station taleet. veel contained large volume or waterwater, PetSnart Manage (Phil Mogenthaler (982-742-77) arronged for planches to repair station and clean out private tilt station veel. Manager cloaded the business for the next day to ensure repairs were completed whoth cadditional SSD occurrence. Manager information private tilt station ver a regular maintennane program; SSD vactored and disposed of into the CUSD sanitary aever system; Photographs were taken and are attached;
6/23/06 0845	PRIVATE SSO at Apartment complex at 2257 Maple St;	N	0	10	20	0	2257 Maple Street;	Costa Mesa, CA;	Small SSO flow from uncapped private cleanout in a 4-plex;	Small SSO flow from uncapped private cleanout in a 4-plex;	Small SSO flow from uncapped private cleanout in a 4-plex;	Small SSO flow from uncapped private cleanout in a 4-plex;	None;	None;	Commercial plumber vacuumed SSO and rinse water and disposed of the wastewater in a MH in the CMSD sanitary sewer system;	Y; 6/26/06 @ 1825 hrs;	PRIVATE SSO at Apartment complex at 2257 Maple St. City of Costa Mesa and CNSD Maintenance Supervisor blocked Storm Drain (SD) around the correct from the driveway site. Commercial plumber accurated SSO and times water and disposed of the wastewater in a MH in the CMSD sanking sever system. Visual estimate of shallow pooled wastewater in private driveway and from path from the Cost of the start of the cost of the start of the cost of the start of the start of the start of the start of the start of the start of the start of the start of the start of the start of the start of the start of the start of th
7/03/06 1140	PRIVATE SSO at Apartment complex at 1741 Tustin Ave, managed by South Coast Property Management Co (714-444- 2602-Voice, 714-444-3602- FAX);	N	25	75	150	25	1741 Tustin Ave;	Costa Mesa, CA;	Blockage in PRIVATE lateral line on PRIVATE property;	PRIVATE MANHOLE (MH) on private property at 1740 Tustin Ave;	Unknown blockage in PRIVATE latera line on PRIVATE property;	e Unknown blockage in I PRIVATE lateral line on PRIVATE property:	None;	None;	City of Costa Mesa vactored SSO in public ROW curb and gutter and disposed of SSO and rinsewater in CMSD sanitary sewer system at the Corporate Yard;	Y; 7/03/06 @ 1325 hrs;	PRIVATE SSO at Apartment complex at 1741 Tustin Ave, managed by South Coast Propenty Management Co (714-444-2022 Valice, 714-444-3002 FAX); Estimated 100 galom PRIVATE Splankov constained in private dive and cutty. Datatic crew dammed SD, PRIVATE plumber cleared PRIVATE listenal (Co) of Coast Meas aucencide SSO in public RVV can be object; Co y cod Coast Meas aucencide SSO in public RVV can be object; Co y cod Coast Meas aucencide SSO in public RVV can be object; Co y cod Coast Meas aucencide SSO in public RVV can be object; Co y cod Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO in public RVV can be object; Coast Meas aucencide SSO aucencide SSO au
7/12/06 0822	PRIVATE SSO from PRIVATE 4* force main from PRIVATE if station at 960 West 16th St;	N	2	15	65	2	960 West 16th St;	Costa Mesa, CA;	PRIVATE lift station 4* force main on PRIVATE property found to have a 316* hole in the plastic underground pipe;	PRIVATE lift station 4" force main on PRIVATE property found to have a 3/16" hole in the plastic underground pipe;	PRIVATE lift station 4" force main on PRIVATE property found to have a 3/16" hole in the plastic underground pipe;	PRIVATE lift station 4* force main on PRIVATE property found to have a 3/16* hole in the underground pipe: Undetermined cause for the 3/16* hole;	None;	None;		Y; 7/12/06 @ 1125 hrs;	PRIVATE SSO occurred from PRIVATE 4" force main from PRIVATE lift station a B60 West 16th 5t; Mesa Concolidate Water District dammed Storm Dirain (SD) which excavating potential water line lack and plagod 4" force main hole with a bo- Chy of Mergeric Breach, which are been and plagod 4" force main hole with a bo- chy of Mergeric Breach, "Berlin without registering and the semantic of brancy and pooled waterwaters for DRIVATE Instant of Storm 2016" hole in the plastic underground piece. Estimated flow of 15 galance over 1440 minutes = 0.1 ggm; Chy of Mergeric Breach, CMB) crew vacuumed SSO and rines water and disposed the waterwater in the CAB statisty vareer system, Recard cascut (1:550-560); Photographs were taken and are attached in and on PRIVATE property.
7/28/06 1635	Pacific Coast Properties (PCP) Management for 12- unit apartment complex located at 584 West Hamilton (Beth - Office 714- 378-1366, Cell - 714-331- 7847);	N	20	80	180	20	584 West Hamilton Street;	Costa Mesa, CA:	Blockage in PRIVATE lateral line on PRIVATE property;	Cleanout (CO) on PRIVATE property;	Grease and debris blockage in PRIVATE lateral line on PRIVATE property;	Grease and debris blockage in PRIVATE lateral line on PRIVATE property;	None;	None;	City of Costa Mesa vactored SSO in public ROW curb and gutter and disposed of SSO and nisewater in CMSD sanitary sewer system at the Corporate Yard;	Y; 7/28/06 @ 1700 hrs;	PRIVATE SSO called in to City of Costa Mesa Comm Center - Fire Dept and PD responded for potential hazardous materials spill and raffic control; CMSD Staff accountered SSO while traveling home from work; Pacific Case Properties (PC) Management for 12-unit apartment complex located at S4N West Hamihon Eden - PRIVATE program; Estimated & galaxies SSO contained hose to Locat: Cys of Costa Mesa (COM) vaccined SSO from SD, City of Costa Mesa vaccined SSO to public ROV curb and gather and disposed of SSO and rinewater in CMSD sanitary aever system at the Corporate Yard; CCM dammed SD, Phrate plumber cleaned cleaning and install another CO to assist in cleaning the lateral. "Photographs were takin and are attached."
8/31/06 1100	El Taco Mexican Restaurant owner (213-249-0756);	N	0	30	80	0	2101 Harbor Bivd;	Costa Mesa, CA;	Grease blocked PRIVATE lateral line from El Toro Mexican Restaurant;	Grease blocked PRIVATE lateral line from El Toro Mexican Restaurant;	Grease blocked PRIVATE lateral line from El Toro Mexican Restaurant;	Grease blocked PRIVATE lateral line from El Toro Mexican Restaurant;	None;	None;	City of Costa crew vactored SSO from curb and gutter and returned/disposed of SSO in District sanitary sewer system;	Y; 8/31/06 @ 1445 hrs;	El Taxo Mexican Restaurant overe (213-249-0756) called District Maintenance Supervisor: District Maintenance Supervisor called (€ 1100 hrs, bickcds SD @ 112 hrs, called C) of Costa Meas Public Bervisor ta sera Marcia and Lean Public ROV, flush alle with fresh water and vactor stite. Chy of Costa crew vactor SSO form curb and gatter and returned/geosed of SSO in District nanitary aver- system; Genes blocked FRVATE lanced ine from ET from Mexican Restaurant; in Director and the state of the state of the state of the state and the state of the state and the state of the state of the state of the state and the state into RPVIATE lanced ine and food the Cognision of BMPs, training, and records keeping. Photographs were taken and are submitted with this monthy report;
9/9/06 1530	PRIVATE FACILITY - South Coast Alcohol & Drug Program Facility;	N	25	25	100	25	2212 Placentia Ave;	Costa Mesa, CA;	PRIVATE lateral blocked with debris;	PRIVATE lateral blocked with debris;	PRIVATE lateral blocked with debris;	SSO flow from PRIVATE lateral blocked with debris from 8-unit apt complex to rear facility sump pump operated intermittently;	None;	None;	Up to 25 gallons of SSO was contained in the SD and evaporated; Costa Mesa Public Services vactored public ROW and disposed of SSO and rinsewater in the CMSD Sanitary Sewer system;	Y; 9/10/06 @ 0935 hrs;	City of Ocets Meas Comm Context called SSO In the District Maintenance Supervisor, District Maint Supervisor blocked form Orain (SD) (II 1534 ha and turned of fatality aroung pump; Cotat Mare Juhic Services warolen goble (right way (ROV) and returned/stopped of SSO into District saintary sewer system; District called CaR Dinaria to clear PRNT talestrati, the totag gallons of SSO was contained in the SD and exportance; Photographs were taken and are attached;
10/4/06 1345	PRIVATE SSO - Apartment Owner/Manager Ed Glinka - 714-926-3805;	Ν	288	0	0	288	779 Shalimar Drive;	Costa Mesa, CA;	PRIVATE PROPERTY deamout in rear of property in alley:	PRIVATE PROPERTY cleanout in rear of property in alley;	Root in lateral line in front of facility blocked lateral line which runs under the 4 unit apartment complex;	Root in lateral line in front of a facility blocked lateral line which runs under the 4 unit apartment complex. Later verified with private CCTV;	None'	None;	Estimated 288 gailons SSO not recoverable due to evaporation and entry into the SD;	Y; 10/0406 @ 1645 hrs;	City of Costa Mess Code Entorsoment Officer Tim Sun notified District Maintenano Supervisor, PRIVATE SSO - Apartment Owner/Minanger Ed Glinka - 71-4325- 3056 is the responsible party. A continuing facility istant problem caused an estimated 288 gallons of SSO to flow onto private property/alley over a 24 hour prioric Private plumber claneal tatestri, Noor d SSO evaporated while lowing to Stom Drain (SD): Estimated 288 gallons SSO ont recoverable due to waporation and entry into the SD. Root in liaberal the infort of facility blockal tateral line whi runs under the 4 unit apartment complex, later varified with private CCTV; CMSD Maintenance Supervisor and City of Costa Mesa Code Entrement Officer Tim Sun recommended Owen/Manager CCTV line to verity roots and work with the CI of Costa Mesa to possibly remove the based on the video and repart the lateral line to prevent future SSOs; Photographs were taken and are included;
11/28/06 0815	Der Wagenmeister owner, Richard (949-633-8033);	Ν	98	0	0	200	722 West 16th St;	Costa Mesa, CA;	Owner cleaned roots from lateral and pushed in roots into Main Line, 400ft (Drop MH) and 140ft from situs address;	backwater prevention	Pushed in tree roots from private property lateral;	Pushed in tree roots from private property lateral;	SD leads to Upper Newport Bay - too far away for SSO to reach it;	None;	Wastewater flowed East with owner Rinsewater 250ft to SD; Unrecoverable;	Y; 11/28-06 @ 1620hrs;	Der Wagenmeilder osener. Richard (M46-533-6013) reported PRIVATE SSO to CNSD: CMSD Crew unäble to enter private property to Vattor SSO and TransWater, Waterwater flowde with over Rinsresketz 2016 to SD. Unrecoverabl PRIVATE PROPERTY SSO due to lack of backwater prevention device - property in 2 back CMSD Houser on V 1655. SC CMSD recommended property owner reafal ta backwater prevention device in lateral line to prevent future backupa on private property. CCV Isaleta, and remove fle low trees directly our the private tateral line. Procographs were taken and are attached;

Totals	31	1	4,084	4,377	5,492	1,271										28	
Cypress										4			1				
11/12/03 1240	Private Party	n/a	40	305	0	0	10201 Valley View	Cypress	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
8/5/04 2000	Private Party	yes	20	180	0	0	4901 Lincoln Ave.	Cypress	n/a	n/a	n/a	n/a	Coyote Creek	n/a	n/a	n/a	
11/4/05 1620	Private Party	no	0	15	0	0	4001 Orange Ave	Cypress	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
1/8/06 1447	Private Party	no	0	40	0	0	8641 Moody Street	Cypress	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
3/1/06 1631	Private Party	no	0	200	0	0	5940 Cerritos Ave.	Cypress	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
5/9/06 1103	Private Party	no	0	20	0	0	6336 Orange Ave.	Cypress	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
Totals	6	1	60	760	0	0											
El Toro WD	1						1			1					1	T	
2/2/06 0000	Private	no	0	0	0	0	5175 Calzado	Laguna Woods	Private lateral	n/a	Calcium buildup	Calcium buildup in private residence lateral	n/a	n/a	Contained on site	yes	Intermittent overflow occurring at desnout only when homeowner used the water and was completely contained to diff area. District's staff used Hydrocleaner unit to break the blockage and cleaned small amount of debris around cleanout. Video impection of lateral line revealed vater deposit build up. Line was cleaned with chain cutter to remove all water deposits on 2/2/06.
Totals	1	0	0	0	0	0										1	
Foutain Valley																	
11/24/04 0000	FV	no	120	120	0	0	16175 Harbor Blvd	Fountain Valley			FOG accumulation	grease - no grease interceptor	N/A	N/A	All material removed & depositied in sewer line	yes	NA
2/26/05 0000	FV	no	50	500	600	50	Euclid & Edinger	Fountain Valley	Between building & street cleanouts		grease build up	grease	NA	NA	Vaccumed spill	yes	Inspectd OCSD trunk line, they were flowing free and clear. Assisted City of Fountain Valley w/vactor. Health Dept responded at 7:00pm and shut down the restaurant that was contributing to the spill.
04/07/05 0900	FV	no	45	45	0	0	17099 Brookhurst Street	Fountain Valley	private property sewer lateral		grease blockage	grease blockage private sewerlateral	NA	NA	Private company removal OCSD	yes	NA
4/9/05 12:00	FV	no	150	100	0	0	18030 Brookhurst	Fountain Valley	unknown		grease blockage	sewage line back up at lowest point	East Valley Channel	NA	Roto-rooter,sandbags vactor jet removal	yes	Grease interceptor maintenance needed.
5/15/05 1030	FV	no	30	30	0	0	9037 Garfield	Fountain Valley	private property sewer lateral		grease build up	grease blockage private sewe lateral	r NA	NA	vaccumed & returned to sewer	yes	NA
5/20/05 1000	FV	no	25	25	0	0	16275 Harbor Blvd	Fountain Valley	private property sewer lateral		blockage	clogged sewer lateral not grease interceptor	NA	NA	OCSD	yes	NA
6/6/05 900 pm	FV	no	15	15	0	0	11707 Edinger Ave	Fountain Valley	just past interceptor at lateral		grease build up	lack of interceptor maintenance	NA	NA	Cleaned by private company	yes	NA
06/30/05 1030	FV	no	70	70	0	0	17075 Bushard	Fountain Valley	private property sewer lateral		grease build up	private lateral	NA	NA	Vaccumed & returned to sewer	yes	NA
9/23/05 2025	FV	no	48	28	0	0	11045 Warner Ave	Fountain Valley	private property sewer lateral	ļ	grease build up	private lateral, multilpe restaurants	NA	NA	OCSD	yes	NA
02/16/06 1530	FV	no	75	2	0	0	17815 Newhope Street	Fountain Valley	private property sewer lateral		unknown	possible paper towel in toilet	East Valley Channel 05	NA		yes	NĂ
05/30/06 1400	FV	no	75	70	0	0	16155A-16175 Harbor Blvd	Fountain Valley	private property sewer lateral		grease build up	private	NA	NA	Catch basin & gutter vaccumed & returned to OCSD	yes	NA
8/20/06 0000	FV	no	10	10	0	0	9102 Edinger Avenue	Fountain Valley	private property sewer lateral		grease	private sewer lateral	NA	NA	OCSD	no	NA
09/15/06 9/16/06	FV	no	20	20	0	0	18774 Brookhurst Street	Fountain Valley	roots in private lateral		grease	roots in private lateral	NA	NA	OCSD	no	NA
Totals	13	0	733	1,035	600	50										11	
Fullerton																	
5/2/02 1146	Sunbridge Care Center For Fullerton, private property	No	20	60	0	0	2800 N Harbor Blvd	Fullerton	Private lateral	Private lateral cleanout	Unknown blockage on private property	NA	N/A		80 gal returned to sewer system by City of Fullerton crew, 20 gal lost to storm drain. Contact private property owner for additional cleanup information	Ŷ	Private four inch sever lateral backed up and vented out of cleanout on private property. Severage flowed onto CIp essement and a small amount of severage entered the storm drain. City creves reponded and contained spill. City creves notified maintenance man from Surbridge to have plumber rodsnake private sever lateral. Advised to call Emergency Service Restoration for cleanup.

5/13/02 1105	RS Properties Mgt. Private property	No	30	90	40	0	4050 W Franklin Ave	Fullerton	Private lateral	Private lateral cleanout	Unknown blockage on private property	N/A	N/A		90 gal returned to sewer system, 30 gal released to the environment	Y	Private four inch server lateral backed up and vented out of cleanout on private property. The city contained servage. The Management Co called private plumber (Rick the Happy Purther) to cleat blockage. The Cly washed down and vacuumed servage and returned it to the server system. Contact the Health Dept for their recommendations to the Management Co
9/17/02 1000	Private Management Company	No	0	0	0	0	1815 W Malvern Ave	Fullerton	Private Lateral	Private four inch cleanout	Roots and Toilet debris	Unknown	N/A	N/A	Unknown	N	On 91'6/02 Unit 340 (emerg night crew) responded to a report of a private sever problem, private plumber was on scene, no overflow observed. On 91'702. Jonge forcrakes (acting anistation specialitis) followed up by injecting problem tails and observed sevage around lateral cleanout and a mail amount at cuth. No sevage and overflowing at that time. Jonge Outsales constanced spill with dri at cuto and Management Co. advised they had private Co. to cleanup. Jonge Gorcales informed Code Enforcement and Supervisor to follow up. Service Request #028778
9/18/02 0634	Private Sewer Lateral	No	20	0	0	0	Behind 1730 Raintree Rd	Fullerton	Private Lateral	Private four inch lateral	Roots	Roots	N/A	N/A	Sewage soaked into dirt. Area was cordoned off and scarified.	N	City Employees Gonzalez, Bair and Miller responded with pickup truck and flatbed truck to private lateral overflow. City crew contained spill, cleared blockage, cordoned off area and scarfied approximately twenty feet of bridle trail. Service Request #0238767
11/19/02 1014	Private Property Owner	No	0	42	122	0	2046 E Wilshire Ave	Fullerton	Private Lateral	Private 4" lateral cleanout	Toilet Debri	Tollet Debri	N/A	N/A	All sewage was returned to sanitary sewer system	N	Jorge Gonzalez, acting sanitation specialist observed sewage around lateral cleanout. Cleanout was not overflowing at the time. Advised resident to call private plumber. City crew washed down and vacuumed area and returned all sewage to sewer system. Service Request #0242153
2/4/03 1000	Private (KFC)	No	0	5	105	0	150 W Orangethorpe Ave	Fullerton	Private Lateral	Lateral Cleanouts and Grease Interceptor	Grease	Lateral was plugged upon arrival. Likely cause-grease, possibly toile debris. KFC personnel rodded and cleared unknown blockage in lateral.	N/A	N/A		Yes	Upon arrived, City crew observed subliding grasses in curb and guiter area and on physics property at Kentucky Filed Olicken (KFC). KFC personnel on site informed curb and the second
3/10/03 0821	Private Business	No	0	10	60	0	150 S. Harbor Blvd.	Fullerton	Private grease trap manhole	Private grease trap manhole	Grease	Full grease trap	N/A	N/A		Yes	City crews Gonzalez, Hernendez and Rangel were called out to ocnisin a private present strag gait it Knowlwod restancians. Torese and sensing equiliel out of strates provide romanical sensitivity and parking bit to the near of building. Crews contained spill with the Ruiding ounce. Gode Enforcement, Police Dept. and Health Dept were notified. JC grease buyers was called to clean interceptor. City crews washed down, vacuumed and returned all sewage to sewer system.
4/3/03 0800	Private (resident)	No	o	15	75	0	745 N Euclid	Fullerton	Private lateral between driveway and connection to main	Private 4" lateral cleanout in driveway approach	Unknown	Unknown	N/A	N/A	All sewage was returned to sewer system	Yes	City crews Hernandez, Rangel, Davidson and Anzaldo responded to a report of a plugged lateral. When they arrived, sewage was observed seeping out of resident's private cleanout into gutter arras. City creas contained the sewage, washed down, vacuumed and returned to sewer system. Resident to three private plumber to clear line. City's nam was dowing fine. Resident had reported bioloxiage on 4/203, no overflow occured at that time, resident was to hire plumber.
7/30/03 1115	Private - Albertsons Inc	No	0	200	600	0	455 N State College Blvd	Fullerton	Private lateral	Private lateral cleanout in parking lot	Rags	Rags in lateral connection	N/A	N/A		Yes	Reynoso, Hemandez, Miller, Rangel, and supervisor Roseberry responded to report of sever overflow in the paring lot of Sav-on. Original notification was made to Di Fine Dest, who contained the spail in the guiter and notified the Polce Dept. Doog instruction of the spatial or overse were called the Debt. Doog helpyd message to Bill Roseberry and coreas were called to Libuiness was and blockage. City creases was also device the spatial sector of the sector of the blockage. City creases was harded down spail ense and vacuumed all sensage and weah water and returned to savilary sever system. Property owner later video inspected the lateral line and is in process of repairing defect.
10/30/03 0930	Private	Yes	17	21	300	0	1708 Peppertree Ln in alley behind apartments	Fullerton	Private lateral	Private lateral cleanout	Roots and debris	Root intrusion into 6 inch sewer lateral through defectiv joint	eBrea Creek Channel	Pacific Ocean		Yes	Crews responded to private lateral overflow. Overflow was intermittent between 0 and 3 gmr. City crews contained spiil, cleared blockage, washed down and vacumed area. Use to normal ringing normal right and than force, crews were unable to contain approximately 17 gallons of sewage that entered the storm drain system prior to that arrival. Property rown vide inspected lateral and tourd a defactive joint. City instructed owner to repair defactive pipe to prevent any further overflows.
2/3/04 1725	Private Property Owner	No	0	0	0	0	3133 Pearl Dr	Fullerton	Private lateral for kitchen area	Private lateral cleanout	Unknown	Unknown	N/A	N/A		Yes	Encoursor right crew Janning responded to report of latent blockage all againtmen on 2020. Advised resident to call a pluncher, no follow ga needed. Sanitation crears responded on 280% to check main line and found latenal problem and not been responded. City Code Encoursent and OC Hanh. Degt were called. City crews remained on scene to contain if necessary until water was shut off and City crews remained on scene to contain if necessary until water was shut off and City crews remained on scene to contain if necessary until water was shut off and City crews remained on scene to contain if necessary until water was shut off and City crews remained on scene to contain if necessary until water was shut off and City crews termained water water and the scene of the problem. Code enforcement and Health Dept supervised dry cleanup, Health Dept recommended adding scene line wells scartifying.
4/12/04 0948	Private Business	No	0	8	200	0	814 Williamson Ave	Fullerton	Private Lateral	Private Lateral Cleanout	Unknown		N/A	N/A	NA	Yes	City crews responded to report of sewage seeping out of cleanout. City crews assisted private business to contained intermittent overflow at a sump box approximately (of rom denout. City crews rodded private lateral to clear blockage. All sewage was confined to driveway, swale area and sump box at industrial area of Williamson. City crews washed down and vacuumed area and sump.
6/28/04 1125	Private property owner	No	0	35	2000	0	305 N Harbor on Wilshire side	Fullerton	Private lateral from 305 N Harbor Blvd	Private lateral cleanout on Wilshire Ave	Roots and debris	Possible roots from parkway tree. To be determined	N/A	N/A	NA	Yes	City crews responded to report of overflow on sidewalk. Flow was contained at 239 W Walkine Ave. City crews cleared root and debris blockage in private lateral from approximately 32 against of arwage combined with heavy irrigation on neft approximately 32 against of arwage combined with heavy irrigation on neft approximately 500 feet down Withirte Ave. gutter area. Lateral line with be video irrepacted to determine if roots from the parkway free area intruding into the lateral. Area sever mains were maintenance jetted, no problems found.

8/12/04 1530 Private prop	property owner	No	0	20	200	0	741 W Commonwealth Ave	Fullerton	Private lateral	Lateral cleanout near sidewalk	Unknown		N/A	N/A	NA	Yes	City Vocas row observed latent detrand from small balances complex overflowing from Cogy renex. Comer stopped nate at us Watch vocasume #70% Commonwealth Ave to contain spill. The City latent crew responded and detaued lockage in latent os top overflow. Only crews washed down and vacuumed sevage on street, sidewalk, and cutb. On 8-16-04, property owner was notified of problem and latent responsibilities. Owner had recently had latent cleaned and video inspected. We advised owner to have terans keep a close eye on the problem read latent deals, cut a juncter of another problem coccins, but to call the city) immailment deals call a juncter of another problem coccins, but to call the problem read latence that the second strengt contain spill unit plumber arrives. Owner was cooperative.
1/13/05 1100 Wonson Kir Fullerton In	ı Kim, owner, nını Hotel	Yes	700	200	3000	0	2601 W Orangethorpe - Fullerton Inn Hotel	Fullerton	Private lateral @ 2601 W Orangethorpe	Private lateral cleanout	Debris, paper	City lateral rod crew cleared unknown blockage from upstream	Ash Channel to Fullerton Creek Channel	Pacific Ocean		Yes	City sever crews noticed sewage flow from driveway at small hotel. City crews set up vactor vacuum at downatream catch basin while waiting for additional crews. City notiding crew and additional contox is responded, cleared private lateral, waited down and severe intelling particular to the severe and
3/8/05 0840 MBJ Proper	operty Management	Yes	290	400	2000	0	2500 E Chapman Ave @ St College	Fullerton	Private lateral to the rear o 2506 E Chapman Ave	f Private lateral cleanout	Unknown		Fullerton Creek Channel	Pacific Ocean		Yes	City crews responded to private lateral overflow from deanout to the rear of 2506 E Chapman Ave. Sewage was flowing down alley swale to atom drain inlet in approach to alley of St College BMC. City crews contained flow at storm drain and several areas in the alley. Vactor vacuum was set up to vacuum sewage while crews deared blockage. City crews contained for all sewage and tentrate to saintage standard down alley swale and vacuumed all sewage and tentrate to saintage trees washed down alley swale and vacuumed all sewage and tentrate to saintage and the second several several several several several several several several blockage. City crews were on some. Property manager was notified of tensponsibilities and has recently hired private plumber to video and assess lateral for possible replacement.
8/2/05 1705 Private later	lateral Tony Romas	Yes	20	100	200	0	1300 S Harbor Blvd	Fullerton	Private lateral	lateral cleanout	Paper		Discharge basin at Riverside Frwy	Unknown		Yes	The City's emergency crew responded to report of soo from private cleanout. City crew contained sewage at atom drain, dispatched sewer on call crews. Restaurant alled private putnets. There wan overflow riside faults. City crew senabled date at the company of the company of the company of paper in tateral line. The City's FOG control inspector will follow up at FSE.
11/28/05 1725 Private - To Restaurant	- Tony Roma's ant	Yes	160	30	50	0	1300 S Harbor Bivd	Fullerton	Private lateral	Private lateral cleanout	Grease, debris		Discharge basin at 91 Frwy/ S Harbor Blvd	Unknown		Yes	Emergency night crew responded to private lateral overflow at Tony Romas. Crews placed sand bags around storm drain. Sewer on call crew responded, cleared grease blockage lateral to stop overflow, cleaned area. Follow up activities will be performed by FOG inspection personnel. Private plumber responded for follow up, drain intel. General manager was informed or responsibilities and assured City staft the facility would increase their maintenance.
	- Calvin Sekhon, r owner (714) 878-	Yes	700	100	1000	0	2309 W Valencia	Fullerton	Private lateral	3 lateral cleanouts on property	Debris, grease		Fullerton Creek Channel	Pacific Ocean		Yes	Crews responded to private overflow from three cleanout locations within apartment complex. City crews contained SSO at private drain in parking area. City crews are up vactor vacuum in gutter, cleared blockage to stop overflow, washed down and vacuum area. Apartment maintenance person was instructed to thoroughly clean line to prevent re-occurrence. De residents at complex (who choose to remain anonymous) overflows occur often.
	- Calvin Sakhon, rowner (714) 878-	Yes	587	200	1000	0	2309 W Valencia	Fullerton	Private lateral	3 lateral cleanouts on property	Debris, grease	Private lateral line was not completely cleared from previous blockage	Fullerton Creek Channel	Pacific Ocean		Yes	Crews responded to private overflow from three cleanout locations within apartment complex. City crews contained SSO at private drain in parking area. City crews be unator vacaum in guiter, private plumber responded and devated blockage to stop overflow. City crews washed down and vacaumed area. Property owner responded and was instructed to honouply clean line to prevent re-occurrence. Private plumber had not cleaned entitle line due to short rodding equipment, explained streament of honour of private streament of regionary and was and the plumber had not cleaned entitle line due to short rodding equipment, explained streaments of SSO to some of private streament of regionary amonomic appacted line, found sags in lateral line but no other major defects.
3/4/06 1746 Private		Yes	113	150	100	0	501 N State College Blvd (Chipotle Grill)	Fullerton	Private lateral	Private lateral cleanout	Debris, grease		Fullerton Creek Channel	Pacific Ocean		Yes	City crews responded to private lateral overflow at Chipotle Grill/Pick up Stix restaurants. Health Care agency was on scene. Crews cleared blockage to stop verdflow, some grase retrieved on coding equipment. City crews washed down and vacuumed area. The City's FOG program inspector followed up on 3-6-06. Blockage location was prior to grases interceptor on property, but interceptor needed pumping. Pick up Stix calited to have shared interceptor pumped. Facilities will be resinepacted in 2 months.
1955 W No 3/29/06 1555 Park, Illinois	Albertsons Corp, North, Malrose nois 60160 Barbara Mott 708- 10	Yes	20	180	800	0	455 N State College Blvd (Sav-On)	Fullerton	Private lateral	3 lateral cleanouts in parking lot	Debris	Plumber cleared approx 10' of thick substance from line	Fullerton Creek Channel	Pacific Ocean		Yes	City crews responded to report of sewage in parking lot of Sav On at State College 8. Chapman Ave. Lateral deamouts in parking to twers seeping with small amount flow into gater and save to catch basin. Flow was contained in parking lot with plumber was called by manager of Sav On. City crews remained on sciene until plumber arrived and cleared vary thick bochage in line with nodding equipment. City crews assisted plumber with jetting of problem area in line. City crews and cleared vary thick bochage in line was. City contacted Sav On con office and recommended tollow up activities to prevent future problems flow and vaccuum deamole multiplication of the science until cere astachment).
	Health Care Center	Yes	630	0	0	0	RXR easement behind 2800 N Harbor	Fullerton	Private lateral	Lateral cleanout	Grease, debris		Brea Creek dirt channel		Sewage soaked into dirt	Yes	Crews responded, contained, and cleared blockage in private lateral to stop flow. Private plumber responded to follow up with clean up activities. All sewage soaked into the dirt channel near railroad easement. Skilled Healthcare Center will be

5/9/06 1300	Private - Sav On/Albertsons Store # 9598	No	0	20	400	0	455 N State College	Fullerton	Private lateral	Lateral cleanout in parking lot	6" lateral connection to 4" lateral cleanout wye	new 6* lateral from building was connected to existing 4* lateral line. problem appears to be at offset in connection	N/A	N/A	All sewage was vacuumed and returned to the sanitary sewer system	N/A	City sever crews working in the area observed lateral cleanout in parking lot appeared wet. Crews set up Camel at site and notified store manager who called private pulmber. Consenspondence with Sav On has been conjung due to a previous poerflow. Property owner had he line video respected. Video revealed severe offse save On is schedung the 4 ⁻¹ line to the replaced in July due to the severe offse save On is schedung the 4 ⁻¹ line to replaced in July due zone of with the City's main line replacement project at same location.
7/7/06 2142	Private Property Owner	No	0	20	400	0	Ziings / Revolucion Restaurants, 209 N Harbor Bivd (Rear driveway)	Fullerton	Private Grease Interceptor	Interceptor lid	Grease blockage in private lateral		N/A	N/A	N/A		City crews responded to report of grease interceptor overflowing behind restaurant complex. Crews contained and vacuumed overflow until blockage was cleared. Citigs and Revolution restaurants hared interceptor haben pumped within the past 3 months as required by the City's FOG program. Blockage in lateral line assumed to be grease. The City's FOG program. Risective will follow up and monitor maintenance activities to re-evaluate pumping schedule.
12/14/06 0825	Private Property owner 2630 W Porter	No	0	200	500	0	2630 W Porter - behind apartments in Alley	Fullerton	Private lateral	Lateral cleanout	Unknown		N/A	N/A	Contained in alley	Yes	City sewer crews working in the area noticed overflow in alley. Crews set up combo truck vacuum and contained/vacuumed sewage until water service was shut off to stop flow. Private plumber responded to clear blockage. Crews washed down/vacuumed area.
12/19/06 1530	Private Property owner, CVS Pharmacy	Yes	100	200	All	0	455 N State College Blvd	Fullerton	Private lateral	Lateral cleanout	Lateral defect, debris	6" lateral from building connects to old 4" lateral at sidewalk area creating offset	Fullerton Creek Channel	Pacific Ocean		Yes	City crews responded to private overflow in CVIS (formerly Sav-On) parking lot. Water crew responded to altrut off water service to stop overflow. Store manager was not aware of problem prior to our arrival. Private plumber was dispatched and responded to clear blockage. City crews washed down and vacuumed all sevage from guitter and strete, and contained overflow in parking plut. Drivate cleanup service was called by CVIS to clean parking tot. Sever staff requested response by OCHCA to record incident due to several plut relations at this facility. City staff will notify CVIS and require immediate repair of lateral line
Totals	27	11	3,407	2,306	13,152	0										22	
Garden Grove																	
7/30/02 10:56	Private	Unknown	10	10	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/30/02 10:56	Private	No	150	150	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/30/02 10:56	Private	No	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/30/02 10:56	Private	Y	450	120	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/30/02 10:56	Private	Ν	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/30/02 10:56	Private	Ν	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/10/02 19:49	Private	Ν	1215	1215	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/23/02 9:40	Private	Ν	98	98	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/31/02 0:10	Private	Ν	165	165	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
8/1/02 13:09	Private	Ν	50	50	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
9/16/02 15:13	Private	Ν	100	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
9/30/02 4:02	Private	Ν	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
9/30/02 8:33	Private	Ν	54	54	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
10/5/02 12:41	Private	Ν	30	30	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
10/17/02 14:05	Private	Ν	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/11/02 11:30	Private	Ν	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
1/5/03 11:03	Private	Ν	50	50	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
1/23/03 9:06	Private	Ν	179	179	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
1/29/03 8:24	Private	Ν	192	192	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
2/24/03 17:18	Private	Ν	75	75	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
3/7/03 16:25	Private	Ν	200	200	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	

land land <thland< th=""> land land <thl< th=""><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th>1</th><th>1</th><th></th><th></th><th>1</th><th></th><th>1</th><th></th></thl<></thland<>											1	1			1		1	
New New <td>3/12/03 19:00</td> <td>Private</td> <td>N</td> <td>15</td> <td>15</td> <td>0</td> <td>0</td> <td>n/a</td> <td>Garden Grove</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td></td>	3/12/03 19:00	Private	N	15	15	0	0	n/a	Garden Grove	n/a								
Image Image <th< td=""><td>5/6/03 10:20</td><td>Private</td><td>N</td><td>10</td><td>10</td><td>0</td><td>0</td><td>n/a</td><td>Garden Grove</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td></td></th<>	5/6/03 10:20	Private	N	10	10	0	0	n/a	Garden Grove	n/a								
Norm Norm <th< td=""><td>6/6/03 22:12</td><td>Private</td><td>N</td><td>25</td><td>25</td><td>0</td><td>0</td><td>n/a</td><td>Garden Grove</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td></td></th<>	6/6/03 22:12	Private	N	25	25	0	0	n/a	Garden Grove	n/a								
Norme Norma Norme Norme <th< td=""><td>7/30/03 14:28</td><td>Private</td><td>N</td><td>110</td><td>110</td><td>0</td><td>0</td><td>n/a</td><td>Garden Grove</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td></td></th<>	7/30/03 14:28	Private	N	110	110	0	0	n/a	Garden Grove	n/a								
Num Num <td>9/30/03 15:30</td> <td>Private</td> <td>No</td> <td>5</td> <td>5</td> <td>0</td> <td>0</td> <td>n/a</td> <td>Garden Grove</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td></td>	9/30/03 15:30	Private	No	5	5	0	0	n/a	Garden Grove	n/a								
Num Num <td>9/28/2003 3:35 P.M.</td> <td>Private</td> <td>No</td> <td>20</td> <td>20</td> <td>0</td> <td>0</td> <td>n/a</td> <td>Garden Grove</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td></td>	9/28/2003 3:35 P.M.	Private	No	20	20	0	0	n/a	Garden Grove	n/a								
Image Image <th< td=""><td>10/13/03 13:39</td><td>Private</td><td>No</td><td>115</td><td>115</td><td>0</td><td>0</td><td>n/a</td><td>Garden Grove</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td></td></th<>	10/13/03 13:39	Private	No	115	115	0	0	n/a	Garden Grove	n/a								
Onder Not Not </td <td>11/15/03 10:15</td> <td>Private</td> <td>No</td> <td>55</td> <td>55</td> <td>0</td> <td>0</td> <td>n/a</td> <td>Garden Grove</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td></td>	11/15/03 10:15	Private	No	55	55	0	0	n/a	Garden Grove	n/a								
Image Fraction Fraction <t< td=""><td>10/22/03 14:49</td><td>Private</td><td>No</td><td>0</td><td>180</td><td>0</td><td>0</td><td>n/a</td><td>Garden Grove</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td></td></t<>	10/22/03 14:49	Private	No	0	180	0	0	n/a	Garden Grove	n/a								
Image Image <th< td=""><td>10/30/03 9:35</td><td>Private</td><td>Yes</td><td>24</td><td>20</td><td>0</td><td>0</td><td>n/a</td><td>Garden Grove</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td></td></th<>	10/30/03 9:35	Private	Yes	24	20	0	0	n/a	Garden Grove	n/a								
Joshi Joshi <th< td=""><td>12/22/03 6:54</td><td>Private</td><td>No</td><td>5</td><td>5</td><td>0</td><td>0</td><td>n/a</td><td>Garden Grove</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td></td></th<>	12/22/03 6:54	Private	No	5	5	0	0	n/a	Garden Grove	n/a								
Image Image <th< td=""><td>12/22/03 6:54</td><td>Private</td><td>No</td><td>12</td><td>12</td><td>0</td><td>0</td><td>n/a</td><td>Garden Grove</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td></td></th<>	12/22/03 6:54	Private	No	12	12	0	0	n/a	Garden Grove	n/a								
Index No	2/19/04 14:15	Private	No	5	5	0	0	n/a	Garden Grove	n/a								
n n n n n n n n n n 12000 1700 170 </td <td>2/19/04 14:15</td> <td>Private</td> <td>No</td> <td>50</td> <td>50</td> <td>0</td> <td>0</td> <td>n/a</td> <td>Garden Grove</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td></td>	2/19/04 14:15	Private	No	50	50	0	0	n/a	Garden Grove	n/a								
Norme Norma Norme Norme <th< td=""><td></td><td>Private</td><td>No</td><td>52</td><td>55</td><td>0</td><td>0</td><td>n/a</td><td>Garden Grove</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td></td></th<>		Private	No	52	55	0	0	n/a	Garden Grove	n/a								
Index Index <th< td=""><td>2/19/04 14:15</td><td>Private</td><td>No</td><td>30</td><td>30</td><td>0</td><td>0</td><td>n/a</td><td>Garden Grove</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td></td></th<>	2/19/04 14:15	Private	No	30	30	0	0	n/a	Garden Grove	n/a								
12000000000000000000000000000000000000	5/19/04 15:20	Private	No	10	10	0	0	n/a	Garden Grove	n/a								
A PANE	8/4/04 8:34	Private	No	30	30	0	0	n/a	Garden Grove	n/a								
Active Active<	7/12/04 16:12	Private	No	45	45	0	0	n/a	Garden Grove	n/a								
Image Image <th< td=""><td>9/24/04 14:12</td><td>Private*</td><td>No</td><td>20</td><td>20</td><td>0</td><td>0</td><td>n/a</td><td>Garden Grove</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>Private spill in Midway Sanitary District juristiction. GGSD crews were first responders and acted in a support role only.</td></th<>	9/24/04 14:12	Private*	No	20	20	0	0	n/a	Garden Grove	n/a	Private spill in Midway Sanitary District juristiction. GGSD crews were first responders and acted in a support role only.							
No. No. <td>10/8/04 20:20</td> <td>Private</td> <td>No</td> <td>150</td> <td>150</td> <td>0</td> <td>0</td> <td>n/a</td> <td>Garden Grove</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td></td>	10/8/04 20:20	Private	No	150	150	0	0	n/a	Garden Grove	n/a								
1 <td>11/19/04 10:57</td> <td>Private</td> <td>No</td> <td>10</td> <td>10</td> <td>0</td> <td>0</td> <td>n/a</td> <td>Garden Grove</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td></td>	11/19/04 10:57	Private	No	10	10	0	0	n/a	Garden Grove	n/a								
Image: Note of the state of the st	11/15/04 11:51	Private	No	150	150	0	0	n/a	Garden Grove	n/a								
11110415.5 11105415.5 111	11/13/04 10:24	Private	No	360	360	0	0	n/a	Garden Grove	n/a								
1110047:1 100	11/12/04 17:14	Private	No	100	100	0	0	n/a	Garden Grove	n/a								
1 1	11/11/04 15:35	Private	No	100	100	0	0	n/a	Garden Grove	n/a								
$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$	11/10/04 7:11	Private	No	20	20	0	0	n/a	Garden Grove	n/a								
$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$	11/5/04 17:05	Private	No	110	100	0	0	n/a	Garden Grove	n/a								
$\begin{array}{ c c c c c c c c c c c c c c c c c c c$	11/1/04 16:10	Private	No	22	22	0	0	n/a	Garden Grove	n/a								
12/14/04 15.55 Private NO 100 100 0 0 100 100 0 0 100 100 0 100 100 100 0 100 100 100 0 100 100 100 0 100	1/3/05 12:13	Private	No	0	0	0	0	n/a	Garden Grove	n/a								
	12/14/04 15:55	Private	No	100	100	0	0	n/a	Garden Grove	n/a	Yes, but did not enter the storm drain channel. Contained at storm drain outlet to channel.							
12/10/04 17:19 Private No 0 0 0 0 0 n/a Garden Grove n/a	12/11/04 13:45	Private	No	150	150	0	0	n/a	Garden Grove	n/a								
	12/10/04 17:19	Private	No	0	0	0	0	n/a	Garden Grove	n/a								
1/15/05/18:01 Private No 3500 3500 0 0 10200 Chapman Grove Na S	1/15/05 18:01	Private	No	3500	3500	0	0	10200 Chapman	Garden Grove	n/a	у							

							1						1			1	
2/10/05 17:35	Private	No	5	5	0	0	11418 Knott	Garden Grove	n/a	у							
3/7/05 16:57	Private	No	842	842	0	0	10022 Garden Grove Blvd.	Garden Grove	n/a	у							
3/10/05 12:53	Private	No	64	64	0	0	12572 Harbor	Garden Grove	n/a	У							
3/14/05 15:50	Private	No	30	30	0	0	9691 Garden Grove Blvd.	Garden Grove	n/a	У							
3/20/05 9:17	Private	No	631	631	0	0	n/a	Garden Grove	n/a								
3/29/05 14:53	Private	No	175	175	0	0	n/a	Garden Grove	n/a								
4/18/05 0:32	Private	No	75	75	0	0	11072 Magnolia	Garden Grove	n/a	У							
4/5/05 21:50	Private	No	2020	2020	0	0	n/a	Garden Grove	n/a								
4/1/05 20:49	Private	No	14	14	0	0	8042 Garden Grove Blvd.	Garden Grove	n/a	У							
5/13/05 19:35	Private	No	79	79	0	0	n/a	Garden Grove	n/a								
5/23/05 9:01	Private	No	119	119	0	0	12991 Rosewood	Garden Grove	n/a	У							
5/30/05 12:10	Private	No	451	451	0	0	n/a	Garden Grove	n/a								
6/3/05 16:25	Private	No	28	28	0	0	12158 Brookhurst	Garden Grove	n/a	у							
6/13/05 14:39	Private	No	75	75	0	0	10212 Westminster	Garden Grove	n/a	У							
9/19/05 15:43	Private	No	61	61	0	0	10012 Westminster	Garden Grove	n/a	у							
10/10/05 0:00	Private	No	215	215	0	0	9855 Hewitt	Garden Grove	n/a	У							
10/19/05 15:34	Private	No	64	64	0	0	10072 Westminster	Garden Grove	n/a	У							
11/10/05 14:20	Private	No	20	20	0	0	9802 Katella	Garden Grove	n/a	У							
11/18/05 13:45	Private	No	121	121	0	0	8042 Garden Grove Blvd.	Garden Grove	n/a	у							
11/28/05 10:47	Private	No	355	355	0	0	12851 Haster	Garden Grove	n/a	У							
12/14/05 12:00	Private	No	0	0	0	0	n/a	Garden Grove	n/a								
12/16/05 10:38	Private	No	45	45	0	0	13946 Erin	Garden Grove	n/a	У							
12/29/05 12:20	Private	No	2	2	0	0	10240 Westminster	Garden Grove	n/a	у							
1/11/06 8:28PM	Private	No	229	229	0	0	12342 Brookhurst	Garden Grove	n/a	У							
2/2/06 1:05AM	Private	No	202	202	0	0	8519 Edgebrook	Garden Grove	n/a	у							
3/19/06 7:38PM	Private	No	3	3	0	0	13556 Robin Court	Garden Grove	n/a	у							
4/7/06 2:57PM	Private	No	98	98	0	0	12188 Brookhurst	Garden Grove	n/a	у							
5/11/06 4:04PM	Private	No	59	59	0	0	12912 Magnolia	Garden Grove	n/a	у							
5/17/06 11:53AM	Private	No	22	22	0	0	8903 Hewitt Place	Garden Grove	n/a	у							
6/5/06 2:20PM	Private	No	128	128	0	0	10761 Palma Vista	Garden Grove	n/a	у							
7/13/06 10:25AM	Private	No	44	44	0	0	11812 Poes	Garden Grove	n/a	у							
7/26/06 10:40AM	Private	No	144	144	0	0	12905 Palm	Garden Grove	n/a	у							
8/27/06 2:47PM	Private	No	215	215	0	0	12905 Palm	Garden Grove	n/a	у							
9/17/06 11:17PM	Private	No	395	395	0	0	10191 Lampson	Garden Grove	n/a	у							

	1							1				1				-	
11/8/06 11:38AM	Private	No	162	162	0	0	11072 Magnolia	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	У	
11/12/06 2:14PM	Private	No	531	531	0	0	12186 Solarno	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	у	
11/13/06 9:05AM	Private	No	162	162	0	0	11072 Magnolia	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	у	
Totals	92	2	16,393	16,232	0	0										32	
Huntington Beach							1					1		1			
															This storm drain pooled up		
4/27/02 12:00 PM	Private Property -Beachwall Condominiums	o No	675	350	0	0	19801 Shorecliff Lane	Huntington Beach	In the street at 19801 Shoredliff Lane.	4" Clean Out Lid	Grease	A buildup of grease in the line, probably caused by insufficient maintenance.	None	None	on the sand at the beach, was vacuumed up, liquids drained into the sewer and solids disposed of at OCSD.	Yes	
6/17/02 9:00 AM	Private Property -Beachwall Condominiums	o No	45	45	50	0	19771 Coastline Lane	Huntington Beach	In the street at 19771 Coastline Lane.	Manhole lid	Grease	A buildup of grease in the line, probably caused by insufficient maintenance.	None	None	Spill was contained on the street using a dam, vacuumed up by a private company and placed back into the sewer.	Yes	
7/6/02 8:30 PM	Rich Darling - Private Property	No	90	60	450	0	16490 Bolsa Chica Street	Huntington Beach	In the parking lot at 16490 Bolsa Chica Street.	Clean Out	Debris	Debris built up in the line, causing the blockage.	None	None	Spill was contained using a contaiment berm and diverted back into sewer.	Yes	Statements were obtained from employee's of Jon's Coffee Shop. Line was cleared before City crews arrived.
7/22/02 3:00 PM	Trans Pacific Management Services - Private Property	No	50	50	150	0	17152 Pacific Coast Highway	Huntington Beach	17152 Pacific Coast Highway	Laundry Room Drain	Grease, Debris	Appears to be lack of maintenance - grease and debris was found blocking the line.	None	None	Spill was contained using a contaiment berm and diverted back into sewer.	Yes	Cleanup was delayed because of lack of a representative from management company. Cleanup was halted until a board member approved the work.
8/14/02 11:30 AM	Gas Station	No	12	12	20	0	20002 Beach Blvd.	Huntington Beach	In the sidewalk alongside 20002 Beach Blvd	Clean Out	Debris	A gas station sewer line had become plugged by paper towels.	None	None	Spill was contained within the catch basin, vacuumed up by a private cleaning company and placed back into the sewer.	Yes	
8/18/02 5:45 PM	Private	Yes	2250	10	25	0	4752 Pearce Street	Huntington Beach	In front of 4752 Pearce Street.	Clean Out	Debris, Blockage	Blockage caused by paper in line. Problem started after a recent slip lining project, according to residents.	Heil Channel, Christiana Bay, Huntington Harbor	Pacific Ocean		Yes	Orange County Health, Michael Fennessy stated he recovered samples of affected waters.
8/29/02 8:21 AM	Jimni Service	Yes	528	100	50	0	20896 Seacoast	Huntington Beach	At the intersection of Beachcomber and Coastwatch	Manhole	Vandalism	Someone turned off power to pump station, causing the overflow.	None	None	Water went into Atlanta Storm Station which is currently being diverted to the sewer system.	Yes	Jimni Service cleaned up the spill and checked the pump station.
10/12/02 8:29AM	Harbor Breeze Apartments	Yes	5,400	100	600	0	4841 Heil	Huntington Beach	4841 Heil	Cleanout-Manhole	Grease	Grease had built up in the line, probably due to lack of maintenance	Orange County Flood Control	Huntington Harbour	N/A	Yes	
10/25/02 10:10AM	Betty Chamberlin	No	375	10	160	0	317 21st	Huntington Beach	317 21st	Cleanout	Cleanout Cap was blocking flow	Grease had built up in the line, probably due to lack of maintenance	None	None	Curb and Gutter	Yes	
11/1/2002 8:20AM	Mark Montgomery	No, The storm water pump station was diverted.	308	308	458	0	21372 Brookhurst	Huntington Beach	Southwest Corner of Property	Sewer Cleanout	Debris, Roots, Grease	Possible Lack of Maintenance, Debris and Grease	None	None	Storm water pump station- This station is diverted to the Sewer	Yes	None
11/3/02 14:00	Archstone Huntington Beach	Yes, Bolsa Chica	830	50	100	780	8925 Rockcreek	Huntington Beach	8925 Rockcreek	Manhole	Grease	Possible Lack of Maintenance Grease	East Wintersburg Channel	Bolsa Chica-Pacific Ocean	N/A	Yes	None
11/5/2002 10:00	Mark Montgomery	No, The storm water pump station was diverted.	800	350	450	450	21372 Brookhurst	Huntington Beach	Southwest Corner of Property	Sewer Cleanout	Debris, Roots, Grease	Possible Lack of Maintenance, Debris and Grease	None	None	Storm water pump station- This station is diverted to the Sewer	Yes	None
11/5/2002 11:15	Yousef Ibrahim	Wintersburg Channel	551	100	600	451	7232 Edinger	Huntington Beach	7232 Edinger	Manhole	Grease	Chunks of Asphalt	City Edinger Channel	Wintersburg Channel	N/A	Yes	None
11/13/2002 14:10	Seebreeze Management Company	Pacific Ocean	N?A	N/A	N/A	N/A	410 Lake Street	Huntington Beach	410 Lake Street	Cleanout	Maintenance Crew	Maintenance Crew was cleaning sewer lines and allowing the sewage to flow down the drain.	Pacific Ocean	None	N/A	Yes	None
11/15/2002 15:45	Pacific West Corp.	Outfall on Sand	150	5 Gal.	24	146	101 Main Street	Huntington Beach	101 Main Street	Grease Interceptor	Grease	Possible Lack of Maintenance Grease	Pond at Outfall to Ocean	None	N/A	Yes	None
12/3/2002 13:00	Richard Darling	Yes, OCFC-Sunset Channel	180	90	190	90	16490 Bolsa Chica	Huntington Beach	16490 Bolsa Chica	Cleanout in Parking Lot	Unknown at the time, turned out to be a separation in the pipe.	Unknown at the time, turned out to be a separation in the pipe.	OCFC Sunset Channel	Christiana Bay, Huntington Harbor	N/A	Yes	None
12/4/2002 14:00	HB Elks Lodge	HB Central Park which was dry.	218	100	250	118	7711 Talbert Ave.	Huntington Beach	7711 Talbert Ave.	Manhole cover in Parking Lot	Grease	Possible Lack of Maintenance Grease	HB Central Park which was dry.	None	Storm Drain Pipe	Yes	None
12/4/2002 15:00	Richard Darling	Yes, OCFC-Sunset Channel	480	400	490	90	16490 Bolsa Chica	Huntington Beach	16490 Bolsa Chica	Cleanout in Parking Lot	Unknown at the time, turned out to be a separation in the pipe.	Unknown at the time, turned out to be a separation in the pipe.	OCFC Sunset Channel	Christiana Bay, Huntington Harbor	N/A	Yes	None

1/7/2003 11:45	Rubios Restaurant	No	50	50	750	0	16672 Beach Blvd. Suite# 101	Huntington Beach	16672 Beach Blvd. Suite# 101	Grease Trap	Lack of Maintenance	Lack of Maintenance/Grease trap had not been cleaned out for over a year.	None	None	Parking Lot	Yes	None
1/16/2003 17:15	Freeway Industrial Park	Yes	2080	450	1070	1630	7402 Edinger	Huntington Beach	7402 Edinger	Cleanout	Lack of Maintenance	Lack of Maintenance/Grease/Crew Reported that grease logs were coming out into main sewer line	Murdy Channel	East Wintersburg Channel and Bolsa Chica	N/A	Yes	None
1/28/2003 21:00	Florida Gardens Apartments	No	50	30	45	20	18832 Florida	Huntington Beach	18832 Florida	Cleanout	Lack of Maintenance	Lack of Maintenance - Blockage cause by debris and Toilet Paper	None	None	Adams Pump Station which is on diversion to the sewer.	Yes	None
2/9/2003 17:30	Coral Cay HOA	Yes	55	5	25	55	16832 Coral Cay	Huntington Beach	16832 Coral Cay	Manhole	Grease	Grease/Lack of Maintenance	Harbor Channel	Pacific Ocean	N/A	Yes	None
5/1/2003 13:30	Elis Nourafchan	No	900	900	1100	0	6905 Warner Ave.	Huntington Beach	6905 Warner Ave.	Cleanout	Grease and debris blockage	Grease buildup from a number of restaurants in the complex.	None	None	Put back into the sewer system.	Yes	
5/26/2003 18:00	Huntington by the Sea MHP	Yes	960	40	40	920	21851 Newland Ave.	Huntington Beach	21851 Newland # 2-8	At hookup for the Coaches	Grease and debris blockage	Grease and debris from a lack of maintenance.	Talbert Marsh	Pacific Ocean		Yes	
6/7/2003 9:00	West Bay Café	No	40	40	40	0	6600 Admiralty Drive	Huntington Beach	6600 Admiralty Drive	Cleanout	Grease	Grease from Café caused blockage.	None	None	Catch Basin	Yes	None
6/11/2003 8:00	Kikuya Japanese Rest.	Yes	90	50	150	40	8052 Adams	Huntington Beach	Front of Restaurant on sidewalk	Manhole	Grease	Grease causes blockage in line, Lack of Maintenance	OC Flood Control D01	None	None	Yes	None
8/7/2003 12:40	The Saywitz Co. 4740 Von Karman, Suite 100, Newport Beach, Ca 92660	NO	150	150	250	0	7712 Cypress Ave., Huntington Beach Ca.	Huntington Beach	Property owners lateral at 7712 Cypress Ave., Huntington Beach Ca.	Clean out cover	Grease and debris.	A buildup of grease and debris in the lateral, probaly caused by insufficent maintenance.	None	None	Spill was contained at the gutter in front of location, vacuumed up and placed back into the sewer.	Yes	
8/13/2003 14:15	Richard Lee PO Box 2142, Huntington Beach, Ca 92647	NO	120	120	220	0	7872 Stark Ave., Huntington Beach Ca.	Huntington Beach	Property owners lateral at 7872 Stark Ave., Huntington Beach Ca.	Cleanout cover	Grease	A buildup of grease in the lateral, probably caused by insufficent maintenance.	None	None	Spill was contained at the storm drain, and the five gallons that got into the storm drain was vacuumed up using city equipment and placed back into the sewer system.	yes	
10/25/2003 14:40	Seacliff Health Care Center	Sewage needed to travel a mile and a half with many other storm drain inlets entering pipe before it entered a County Channel.	400	375	795	25	18811 Florida Street	Huntington Beach	Parking lot of Seacliff Health Care Center, 18811 Florida St.	Four inch clean out.	Debris clogged private lateral	Buildup of debris in line probably caused by insufficient maintenance.	County channel at Adams Ave and Beach Blvd.	Talbert Marsh	The sewage needed to travel about a mile and a half before it entered the County channel at Adams Ave. west of Beach Bivd	Yes	
10/27/2003 14:30	Solteros Apartment maint. personnel at 17301 Keelsor Ln. Huntington Beach.	No	25	25	45	0	17301 Keelson Lane	Huntington Beach	Front yard of Solteros Apartment complex at 17301 Keelson Ln	Four inch clean out.	Tree roots clogged private lateral.	Roots from tree clogged apartment complexes sewer lateral.	None	None	Spill was contained at the gutter, vacuumed up and placed into the sewer system.	Yes	
11/20/2003 13:00	Dr. Charles Kenyon, at his private residence.	None	55	55	105	0	17075 Roundhill Dr.	Huntington Beach	Private homeowners latera at 17075 Roundhill Dr.	Broken lateral line.		Private party tree roots clogged and broke their sewer lateral. City's Water Dept. dug hole checking out complaint of broken water line found broken sewer pipe.	None	None	Sewage was vacuumed up and put into the sewer system.	Yes	Problem spot was in street homeowners sewer lateral. Residence is upstream on a hill explaining some pressure.
12/9/2003 13:00	Bill Jarjour, owner of Hilltop Liquor	YES	1500	25	45	1475	815 Indianapolis Ave.	Huntington Beach	Private homeowners lateral at 815 Indianapolis Ave.	Private clean out	Grease	Grease clogged homeowners lateral line	Orange County Flood Control Channel DO-1	Talbert Marsh	Sewage was vacuumed up and put into the sewer system.	Yes	Difference of opinion by homeowner and person notifying city of spill as to length spill flowed. Location was next to bus stop see picture.
12/15/2003 8:30	Tritz Professional Management Services Inc.	YES	943	470	570	473	4171 Andros	Huntington Beach	Private eight-inch sewer line at 4171 Andros Ave.	Private sewer manhole	Grease and roots	Grease and roots caused the private homeowners sewer system to clog.	Huntington Harbor	Huntington Harbor		YES	
12/26/2003 13:47	Hugh Roberts	NO	200	200	300	0	705 Jay Circle	Huntington Beach	Private homeowners lateral at 705 Jay Cir.	Private clean out	Grease	Grease clogged homeowners lateral line	None	None	Sewage was vacuumed up and put into the sewer system.	YES	
12/29/2003 7:30	Richard LI, owner of the apartments	Yes	2312	200	300	2112	7872 Stark Street.	Huntington Beach	Private homeowners lateral at 7872 Stark Street	Private clean out	Grease	Grease clogged apartment complex lateral line	East Garden Grove Winter Burge Channel (C-05)	Bolsa Chica Ecological Reserve.		Yes	Agnes Do from the Orange County Health Care Agency was on scene and wrote a report.
12/31/2003 7:00	Richard Beachler	No	75	75	100	0	6571 Sabbicas Cir.	Huntington Beach	Private homeowners lateral at 6571 Sabbicas Cir.	Private clean out		Tree roots in private sewer lateral	None	None	Sewage was vacuumed up and put into the sewer system.	Yes	
1/26/2004 13:00	Coastline West Management Service	No	50	50	55	0	1035 12th Street	Huntington Beach	1035 12th Street	Sewer clean out pipe on private property	Roots	Apartment complex sewage line clogged with roots.	None	None	City sewer system.	Yes	
2/2/2004 1300:00 PM		no	300	200	250	100	782 Little Harbor	Huntington Beach	Private homeowners lateral at 782 Little Harbor	Roots caused a private sewer lateral to plug.	Tree roots clogged lateral line	Private party tree roots clogged sewer line and caused sewage to spill out of homeowners association manhole.	None	None	Sewage was vacuumed up and put into the sewer system.	Yes	Private cleanup company (Aladdin Emergency Services) contacted the City about the spill otherwise we might not have known.

2/2/2004 1640:00 PM	Dr. Wayne Brown rental property owner.	No	100	100	150	0	214 9th St. in alley	Huntington Beach	Private homeowners latera at 214 9th St.	I Private sewer lateral.	Broken sewer lateral.	Private broken sewer lateral caved in soil around it causing a blockage to overflow onto public property.	None	None	Sewage was vacuumed up and put into the sewer system.	Yes	
2/09/04 1030	Seaside Village Condo. Homeowners Association	No, all sewage that went into the storm drain system went to a storm water pump station that was being diverted into the sewer system.	1512	1512	1612	0	2100 Admiral Lane	Huntington Beach	1213 Admiral Lane, a private sewer lift station.	Private sewer manhole.	Problems with private lift station.	Private lift station was not working properly causing sewage to spill out of three manholes.	None	None	Sewage on site was vacuumed up and put into the sewer system. Sewage in storm drain system was diverted into the sewer system at the storm water pump station.	Yes	This condo complex has had problems before with their sewer lift station. Each time they say problem is fixed. Mr. Billard said the sewage had been spilling out of the manholes for three days.
2/12/04 2200	Norms Restaurant	No	400	400	900	0	16572 Beach Blvd.	Huntington Beach	Norms Restaurant 16572 Beach Blvd.	Cleanout drain.	Grease and food debris.	Grease and food debris from Norms clogged the sewer lateral causing sewage to come out of their cleanout pipe.	None	None	Sewage was vacuumed up and put into the sewer system.	Yes	Due to a construction project adjacent to the catch basin, sandbags existed at the catch basin prior to this SSO.
3/22/2004 10:00	Pacific Mobile Home Park	No	30	30	80	0	Pacific Mobile Home Park, 80 Huntington St.	Huntington Beach	Sewer clean out pipe	Mobile Home	Sewer pipe was clogged.	In ground sewage hook-up pipe for Mobile Home was clogged causing sewage to back-up and overflow.	None	None	Vacuumed up and put into the sewage system.	Yes Control #04-1562	Private property owner hired Emergency Services Restoration Company to do all the clean up
4/29/04 10:00	Orange County Head Start, INC.	No	5	5	0	0	14422Hammon Ln.	Huntington Beach	Drain pipe connecting to Grease Interceptor.	Grease Interceptor	Broken drain pipe.	Broken drain pipe connecting to Grease Interceptor.	None	None	Spill was contained at the grease interceptor vacuumed up and placed back into the sewer system.	Yes	Drain pipe for grease interceptor in the parking for broke and caused the asphalt to cave in. West Duke Plumbing took care of the pipe repair and clean up.
7/11/2004 13:00	Golden West Property Management Inc. (714) 491- 9005	Yes	3024	0	50	3024	Behind 6101 Morningside Drive	Huntington Beach	Grease blockage inside of eight inch private sewer line.	Manhole	Grease blockage	Grease buildup from a lack of maintenance.	Bolsa Chica Wetlands	None, all sewage stayed in wetland area.		Yes	Sewage flowes from 200 residents through this line. All upstreem sewer lines were cleaned 7/19/04. These lines will be put on a scheduled deaning.
9/5/2004 17:00	Broadmoor Huntington Harbour HOA	Yes	50	0	100	100	6905 Warner Ave.	Huntington Beach	Private sewer lateral at 3251 Moritz Drive.	Cleanout	Grease and debris blockage	Grease and debris buildup from two condo units sharing plumbing pipes.	Huntington Harbour	Pacific Ocean		Yes	Spill was reported to Huntington Beach Police Dept. they referred spill to wrong Dept Wastewater arrived at spill two hours after reported time and sewage flow was stopped.
9/11/2004 17:00	Prudential Real Estate	Yes	276	200	450	76	21851 Newland Ave.	Huntington Beach	Private sewer lateral at 7931 Stark Ave.	Cleanout	Tree roots	Tree roots clogged sewer lateral for an eight unit residential complex	Wintersburg Channel, CO5	Bolsa Chica Wetlands		Yes	
1/2/2005 11:38	7232 Edinger shopping center	Yes	70	980	1,480	70	7232 Edinger	Huntington Beach	City's 8 inch sewer line	Manhole cover pick holes	Grease	Grease from a private shopping center lateral flowed into City's main line.	Murdy Channel	East Garden Grove Winterburg Channel		Yes	
1/2/2005 14:53	George Galanoues owner of apartment complex	Yes	2,100	900	1,400	2,100	2208 Delaware St.	Huntington Beach	Private sewer lateral	Private 4 inch sewer clean out pipe.	Grease	Grease buildup in private sewer lateral.	Huntington Beach Channel	Talbert Channel at Brookhurst St.		Yes	There were several different estimates from residents in the complex stating when the sewage started flowing above ground.
1/13/2005 8:30	Gene Opfic homeowner of 8472 Arnett Dr.	NO	0	15	15	0	8472 Arnett Dr.	Huntington Beach	Sewer lateral	Sewer clean out pipe	Grease	Grease buildup in private sewer lateral. Renter at property removed clean out cap because owner would not repair.	None	None		Yes	Renter at property called City, because owner would not fix the problem. City contacted the property owner that called a plumber to repair.
2/28/2005 13:42	Richard Li property owner	YES	200	175	375	25	7872 Stark St.	Huntington Beach	Private sewer lateral	Private sewer lateral clean out at 7873 Stark St.	Grease	Buildup of grease in private sewer lateral.	East Garden Grove Winterburg Channel	Bolsa Chica wetlands		YES	Only one tenant home doing laundry at the time of the spill.
4/19/2005 17:00	Business Properties Management Company	No	300	300	0	0	10132 Adams Ave.	Humtiogton Beach	Private business complex sewer line.	Private property manhole	Grease	Sewer line had grease and debris blocking the line.	None	None	All storm water in the area goes to the Meredith storm water pump station, that is being diverted to the City's sewer system.	Yes	This shopping center has at least five FSE's. They are on a sewer cleaning maintenance program, but will be making this program more frequent.
5/27/2005 10:45	Watt Properties Management Company	No	25	25	25	0	8965 Atlanta Ave.	Huntington Beach	Private sewer pipe.	Sewer cleanout located on private property.	Broken sewer pipe	Broken sewer pipe at an isolation valve located in a shopping center.	None	None	City sewer system.	Yes	All storm water in this area is being diverted into the sewer system.
6/1/2005 13:12	Pacific West Management Corp.	No	300	300	500	0	5971 Warner Ave.	Huntington Beach	Private sewer line	Private system clean out.	Grease blockage	Grease blockage from restaurants in business complex.	East Garden Grove Wintersburg Channel	The Bolsa Chica Wetlands.		Yes	A clizen reported sewage spilling from this same clean out earlier in the day, but we could not see any exidence of this. If the spill did occur earlier in the day than an unknown amount of sewage could have made it into the E Garden Grove Wintensburg C
6/5/2006 7:15	Sterling Shopping Center, manager, Ross Cannon.	Yes	360	200	700	160	17436 Beach Blvd., Sterling shopping center	Huntington Beach	Blockage was in the private lateral line of the shopping center.	Pick hole of the clean out cover.	Grease blockage.	Grease and debris blocked the private lateral line.	Jefferson City Channel	County Ocean View Channel to the Wintersburg Channel then the Bolsa Chica Wetlands.		Yes	
6/24/2006 14:45	City of Huntington Beach	None	250	200	400	50 Gallons	17732 Goldenwest Street	Huntington Beach	Park Bench Café, 17732 Goldenwest Street	Private sewer lateral cleanout cap.	Grease and debris blockage.	Grease and debris buildup in the private sewer lateral.	None	None	Was put into the sewer system and some soaked into the grass.	Yes	The Park Bench Café is in a City park, the problem cleanout pipe is next to a large low grass area. All sewage was confined to this aera.

												r					
6/27/2006 11:00	Rainbow Disposal, trash hauler.	None	150	150	250	0	17121 Nichols Street	Huntington Beach	Blockage was in the private lateral line on Rainbow property.	Clean out pick hole.	Grease and debris blockage.	Grease and debris buildup in the private sewer lateral.	None	None	Was put into the sewer system.	Yes	
7/11/2006 13:45	Silk Thai Cuisine Restaurant	No	10	10	210	0	19690 Beach Blvd., Newland Shopping Center	Huntington Beach	Slik Thai Restaaurant in the Newland Shopping Center.	Cover of grease interseptor	Grease blockage	Phill's Plumbing while repairing the grease interceptor at The Silk Thai Restaurant 10 gallons of sewage spilled.	None	None	All sewage was put into the sewer system.	Yes	
7/27/2006 12:45	Pacific West Management Corporation, property manager Sharon Ference 714-433-7300	No	100	100	200	0	6941 Warner Avenue	Huntington Beach	Don Ramon's Mexican Restaurant in this shopping center.	Sewer lateral clean out cover.	Grease blockage	Grease blockage in the privat sewer lateral down stream of the Don Ramon's Restaurant	e None	None	All sewage was put into the sewer system.	Yes	
8/3/2006 13:30	Earl Benton 714-964-7697, home address 20271 Meander Lane, HB 92646.	No	20	20	170	0	4932 Kona Dr.	Huntington Beach	4932 Kona Dr., sewer line inside of apartment building.	The discharge pipe for the washing machine.	Grease blockage	Grease blockage in private sewer lateral line.	None	None	All the wash water and sewage was vacuumed up and put into the City's sewer system.	Yes	The owner of this four unit appartment complex does not do much maintenance or upkeep on this property.
8/11/2006 21:45	A.K.A. Japanese Restaurant 714-374-9600 and Cavallino Italian Restaurant 714-536-6665	No	55	55	155	0	8082 Adams Ave.	Huntington Beach	Between private manhole and City manhole at 8082 Adams Ave.	Pick holes of manhole cover.	Grease blockage	Grease buildup from two food service establishments.	None	None	All the wash water and sewage was vacuumed up and put into the City's sewer system.	Yes	
9/8/2006 17:00	Earl Benton, 20271 Meander Ln., HB 92646	No	5	5	105	0	4932 Kona Dr.	Huntington Beach	Lateral sewer line of 4932 Kona Dr.	Sewer discharge pipe in the laundry room.	Grease and root blockage	Grease and root blockage of private sewer line.	None	None	All sewage was put into the City sewer system.	Yes	From the looks of this four unit complex the owner, Eral Benton, does not maintain the property very well.
9/28/2006 9:30	Nora Ballikciagli, owner of the Moble Gas Station	No	25	25	45	0	2002 Beach Blvd.	Huntington Beach	Lateral sewer line of 2002 Beach Blvd.	Private sewer clean out cover.	Debris blockage	2002 Beach Blvd. Is a gas station. It is suspected that vandals put to much debris into the toilets.	None	None	All sewage was put into the City sewer system.	Yes	
11/6/2006 15:55	Market Broiler Restaurant	No	500	500	800	0	20111 Brookhurst Street	Huntington Beach	Broken sewer pipe three feet under the concrete slab of the Market Broiler building.	Concrete slab and sewer clean out cover.	Broken sewer pipe under the concrete slab.	Old sewer line had a break in it.	None	None	All liquid was put into the City sewer system.	Yes	
11/15/2006 17:00	Dominic J. Manna owner of this office building	No	25	25	75	0	17122 Beach Blvd.	Huntington Beach	Sewer lateral pipe at 17122 Beach Blvd.	Sewer clean out cover.	Plugged sewer lateral.	Roots and debris in the private sewer lateral.	None	None	All liquid was put into the City sewer system.	Yes	Owner of this office building was very cooperative and helpful.
11/16/2006 10:00	Service First Management Corporation, property manager Fica Werner 714- 963-5555 ext. 378.	No	3,500	3,500	4,100	0	17742 Beach Bivd.	Huntington Beach	Beach Medical Associates Center, 17742 Beach Bivd. lateral sewer pipe.	Sewer clean out cover.	Plugged sewer lateral.	Roots and debris in the private sewer lateral. The landscaping parallel to this private sewer lateral has abo ten Ficus trees planted in it. The plumbing company pulle out many roots from this sewer lateral. These roots restricted the sewage flow an	None	None	All liquid was put into the City sewer system.	Yes	Property Manager Erica Werner cell phone 949-683-7184.
11/20/2006 15:30	Service First Management Corporation, property manager Erica Werner 714- 963-5555 ext. 378.	No	1,200	1,200	1,500	0	17742 Beach Blvd.	Huntington Beach	Beach Medical Associates Center, 17742 Beach Blvd. lateral sewer pipe.	Sewer clean out cover.	Plugged sewer lateral.	Roots and debris in the private sewer lateral. Plumbe on 11/16/06 did not get all roots cut and removed from the sewer system.	r None	None	All liquid was put into the City sewer system.	Yes	Property Manager Erica Werner cell phone 949-683-7184.
12/7/2006 10:25	Charles Dunn Management Company, Laura Tarbutton Property manager	No	450	450	650	0	6918 Warner Avenue	Huntington Beach	6918 Warner Avenue	Clean out cover behind the Subway Sandwich shop.	Grease blockage	Grease blockage in the privat lateral sewer line.	e None	None	City sewer system.	Yes	
Totals	67	23	38,339	17,027	26,819	14,530										67	
IRWD																	
7/10/02 0:00	Private	n/a	480	20	0	0	25521 Commercenter	Lake Forest	n/a	n/a	Construction debris	Construction debris	n/a	n/a	n/a	n/a	
7/21/02 0:00	Private	n/a	1500	0	0	0	East Shore & East Yale Loop	Irvine	n/a	n/a	n/a	Unknown	n/a	n/a	n/a	n/a	
8/9/02 0:00	Private	n/a	0	0	0	0	5465 Alton Pkwy.	Irvine	n/a	n/a	Illegal connection to storm drain	Illegal connection to storm drain	n/a	n/a	n/a	n/a	
10/22/02 0:00	Private	n/a	20	0	0	0	7 Holland	Irvine	n/a	n/a	n/a	Unknown	n/a	n/a	n/a	n/a	
10/25/02 0:00	Private	n/a	5	0	0	0	21212 Bake Pkwy.	Lake Forest	n/a	n/a	n/a	Unknown	n/a	n/a	n/a	n/a	
11/2/02 0:00	Private	n/a	50	0	0	0	22606 Costa Bella Dr.	Lake Forest	n/a	n/a	Roots	Roots	n/a	n/a	n/a	n/a	
12/20/02 0:00	Private	n/a	640	1625	0	0	San Canyon & Burt Rd.	Irvine	n/a	n/a	Unknown	Unknown	n/a	n/a	n/a	n/a	
1/20/03 0:00	Private	n/a	0	0	0	0	3955 Alton Pkwy.	Irvine	n/a	n/a	Grease	Grease	n/a	n/a	n/a	n/a	
1/20/03 0:00	Private	n/a	3	0	0	0	6692 Ridge Park Rd.	Newport Beach	n/a	n/a	Paper	Paper	n/a	n/a	n/a	n/a	
						-			-	-							

									1	1			1	1		
1/23/03 0:00	Private	n/a	300	0	0	0	19752 Macarther Blvd.	Irvine	n/a	n/a	Unknown	Unknown	n/a	n/a	n/a n/a	
1/26/03 0:00	Private	n/a	360	0	0	0	50 Eastshore	Irvine	n/a	n/a	Grease	Grease	n/a	n/a	n/a n/a	
2/22/03 0:00	Private	n/a	0	0	0	0	24681 Shadowfax	Lake Forest	n/a	n/a	Roots	Roots	n/a	n/a	n/a n/a	
3/27/03 0:00	Private	n/a	0	0	0	0	20 Goodyear	Irvine	n/a	n/a	Rocks	Rocks	n/a	n/a	n/a n/a	
4/18/03 0:00	Private	n/a	2	0	0	0	4 Gillman	Irvine	n/a	n/a	Roots	Roots	n/a	n/a	n/a n/a	
5/1/03 0:00	Private	n/a	60	0	0	0	3 Burroughs	Irvine	n/a	n/a	Unknown	Unknown	n/a	n/a	n/a n/a	
9/9/04 0:00	Private	n/a	10	0	0	0	25361 Commerce Center Dr.	Lake Forest	n/a	n/a	Wood and concrete	Wood and concrete	n/a	n/a	n/a n/a	
11/15/04 0:00	Private	n/a	250	0	0	0	#1 Federation Way	Irvine	Private manhole	Private manhole	n/a	Private manhole, unknown blockage	n/a	n/a	n/a n/a	
11/26/04 0:00	Private	n/a	1080	0	0	0	22 Pergola	Irvine	Private manhole	Private manhole	Roots	Private manhole, roots in line	n/a	n/a	n/a n/a	
1/17/05 0:00	Private	n/a	123	0	0	0	14400 Culver Dr.	Irvine	Grease Trap	Grease Trap	Grease	Grease Trap overflow	n/a	n/a	n/a n/a	
2/17/05 0:00	Private	n/a	30	0	0	0	20041 Osterman St.	Lake Forest	Cleanout	Cleanout	n/a	4" private cleanout-blockage	n/a	n/a	n/a n/a	
5/24/05 0:00	Private	n/a	20	0	0	0	Jeffrey/Walnut	Irvine	Grease interceptor	Grease interceptor	Grease	Grease interceptor overflow- Chinese Restaurant	n/a	n/a	n/a n/a	
5/31/05 0:00	Private	n/a	100	0	0	0	17605 Harvard	Irvine	Grease interceptor	Grease interceptor	Grease	Grease interceptor overflow- Ralphs	n/a	n/a	n/a n/a	
6/21/05 0:00	Private	n/a	20	0	0	0	17 E. Yale Loop	Irvine	Cleanout	Cleanout	Grease	Private clean-out grease	n/a	n/a	n/a n/a	
7/24/05 0:00	Private	n/a	50	0	0	0	19211 Jasper Hill Rd.	Portola Hills	Cleanout	Cleanout	Asphalt debris	Asphalt blocked line-cleanou overflowed	t n/a	n/a	n/a n/a	
8/16/05 0:00	Private	n/a	20	0	0	0	6503 Quail Hill	Irvine	Effluent line	Effluent line	Plug	Plug left in effluent line from grease trap	n/a	n/a	n/a n/a	
11/25/05 0:00	Private	n/a	225	0	0	0	26652 Portola Pkwy	Foothill Ranch	Private lateral	Private lateral	n/a	Blockage in lateral between interceptor and main line	n/a	n/a	n/a n/a	
12/4/05 0:00	Private	n/a	1000	0	0	0	Lake Forest & Rockfield	Lake Forest	n/a	n/a	Grease	Grease blockage	n/a	n/a	n/a n/a	
1/28/06 0:00	Private	n/a	11900	0	0	0	17650 Rosa Drew Lane	Irvine	n/a	n/a	Roots	Roots	n/a	n/a	n/a n/a	
2/7/06 0:00	Private	n/a	10	0	0	0	23344 El Toro Rd.	Lake Forest	n/a	n/a	Grease	Grease blockage	n/a	n/a	n/a n/a	
2/25/06 0:00	Private	n/a	100	0	0	0	113 Rockwood St.	Irvine	n/a	n/a	n/a	Unknown blockage	n/a	n/a	n/a n/a	
5/7/06 0:00	Private	n/a	30	0	0	0	17575 Harvard Ave. (Corner Bakery)	Irvine	n/a	n/a	Grease	Grease blockage	n/a	n/a	n/a n/a	
10/12/06 0:00	Private	n/a	300	0	0	0	3955 Alton Pkwy Olive Garden	Irvine	Private lateral	Private lateral	n/a	Blockage in customer's latera	al n/a	n/a	n/a n/a	
11/15/2006 0:00	Private	n/a	0	10	0	0	52 Leesburg	Irvine	Private lateral	Private lateral	roots	Blockage in customer's latera (roots)	al n/a	n/a	n/a n/a	
Totals	33	0	18,688	1,655	0	0										
La Habra																
4/18/2003	Private Property	n/a	o	0	0	0	2220 S. Monte Vista	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a n/a	
6/21/2002	Private Property	n/a	0	0	0	0	2220 S. Monte Vista	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a n/a	
6/28/02 0:00	Private Property	n/a	0	0	0	0	631 S. Palm	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a n/a	
8/3/2002 0:00	Private Property	n/a	0	0	0	0	2220 S. Monte Vista	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a n/a	
10/22/2002 0:00	Private Property	n/a	0	0	0	0	301 Mountain View	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a n/a	
11/1/2002 0:00	Private Property	n/a	0	0	0	0	2300 E. Lambert	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a n/a	
12/10/2002 0:00	Private Property	n/a	0	0	0	0	1770 W. La Habra	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a n/a	
2/25/2003 0:00	Private Property	yes	3000	2000	0	0	1440 W. Lambert Rd.	La Habra	Line Blockage	Line Blockage	Grease	Grease line blockage	San Gabriel River	Pacific Ocean	n/a Yes	(Not listed in originally submitted OCHCA report. Listed in the OCHCA Beach Closure Report. Not indicated as private spill in Region 8 report)
L	·													*	· ·	4

5/15/2003 0:00	Private Property	n/a	0	0	0	0	1232 N. Palm	La Habra	n/a	Septic Tank	n/a	n/a	n/a	n/a	n/a	n/a	
6/9/2003 0:00	Private Property	n/a	0	0	0	0	331 Eunice Cr.	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/8/2003 0:00	Private Property	n/a	0	0	0	0		La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
9/12/2003 0:00	Private Property	n/a	0	0	0	0	1061 N. Euclid St.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
9/18/2003 0:00	Private Property	n/a	0	0	0	0	630 N. Beach Blvd.	La Habra	n/a	Washrack	n/a	n/a	n/a	n/a	n/a	n/a	
12/8/2003 0:00	Private Property	n/a	0	0	0	0	321 S. Idaho St.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
1/24/2005 0:00	Private Property	n/a	0	0	0	0	311 W. LAMBERT RD.	La Habra	n/a	Private lateral	n/a	n/a	n/a	n/a	n/a	n/a	
2/20/2005 0:00	Private Property	n/a	0	0	0	0	1360 W. LAMBERT RD	La Habra	n/a	n/a	Grease	n/a	n/a	n/a	n/a	n/a	
4/25/2005 0:00	Private Property	n/a	0	0	0	0	515-523 HEATHER AVE	La Habra	n/a	n/a	Grease & Roots	n/a	n/a	n/a	n/a	n/a	
4/26/2005 0:00	Private Property	n/a	0	0	0	0	1232 N. PALM	La Habra	n/a	Septic Tank	n/a	n/a	n/a	n/a	n/a	n/a	
4/29/2005 0:00	Private Property	n/a	0	0	0	0	119 1/2 LEORA ST	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
5/9/2005 0:00	Private Property	n/a	0	0	0	0	2212 S. MONTE VISTA ST.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
6/29/2005 0:00	Private Property	n/a	0	0	0	0	1300 W.LAMBERT RD	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
7/17/2005 0:00	Private Property	n/a	0	0	0	0	1800 W. WHITTIER BL.	La Habra	n/a	Grease Interceptor	Grease	n/a	n/a	n/a	n/a	n/a	
8/4/2005 0:00	Private Property	n/a	0	0	0	0	821 CORTO WAY	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
9/27/2005 0:00	Private Property	n/a	0	0	0	0	500 Teakwood Ave.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
11/3/2005 0:00	Private Property	n/a	0	0	0	0	1750 W.Lambert Rd.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
11/9/2005 0:00	Private Property	n/a	0	0	0	0	550 W. La Habra BL	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
12/2/2005 0:00	Private Property	n/a	0	0	0	0	1233 W. La Habra Bl.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
1/26/2006 0:00	Private Property	n/a	0	5	0	0	154 S.WALLACE ST.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
1/27/2006 0:00	Private Property	n/a	0	1	0	0	1671 DORWOOD AVE.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
5/8/2006 0:00	Private Property	n/a	0	0	0	0	730 W.5TH STREET	La Habra	n/a	Private lateral	n/a	n/a	n/a	n/a	n/a	n/a	
Totals	30	1	3,000	2,006	0	0										1	
La Palma																	
8/16/02 12:37pm	La Palma Hospital, private property	No	0	0	0	0	7901 Walker Street	La Palma	Private lateral	Manhole	Unknown blockage on private property	N/A	N/A		Returned to sewer system	Ŷ	Private sever lateral backed up and vented out of a manhole on private property. Sewage flowed onto City gutter and a small amount of sewage entered the storm diam. City of Laman Public Works Dup man responde and contained spill. City staff notified maintenance dept from La Planar Hospital to have plumber jet private server biteral. Advised to cat PL Wolker for Catenzy.
10/9/2002	Hannam Market, private property	No	0	0	0	0	4875 La Palma Ave.	La Palma	Private lateral	Manhole	Grease blockage on private property	Grease blockage on private property	N/A	N/A	Returned to sewer system	Y	Private contractor sanitized and cleaned up
11/15/02 9:30am	Carl's Jr,private property	No	0	20	0	0	5012 La Palma Ave.	La Palma	Private lateral	Private lateral cleanout	Grease blockage on private property	Grease blockage on private property	N/A		Returned to sewer system	Y	Private contractor sanitized and cleaned up
4/4/2003 3:00pm	Valley View Center, private property	Yes	540	210	275	0	7811 Valley View St.	La Palma	Private lateral	Private lateral cleanout	Grease	Grease blockage on private property as well as debris	Moody Creek	San Gabriel River		Y	Private contractor sanitized and cleaned up
8/24/03 12:30pm	Hannam Market, private property	No	0	50	55	0	4875 La Palma Ave.	La Palma	Private lateral	Manhole	Grease	Grease blockage on private property	N/A	N/A	Returned to sewer system	Y	Private contractor sanitized and cleaned up
12/28/03 10:00am	Complex,private property	No	0	15	20	0	7002 Moody St.	La Palma	Private lateral	Private lateral cleanout	Blockage	Blockage	N/A	N/A	Returned to sewer system	N	Private contractor sanitized and cleaned up
1/12/04 10:30am	La Palma Hospital, private property	No	0	300	500	0	7901 Walker Street	La Palma	Private lateral	Private lateral cleanouts	Grease blockage on private property as well as debris	Grease blockage on private property as well as debris	N/A	N/A	Returned to sewer system	Y	Private contractor sanifized and cleaned up

-																	
6/16/2004 2:15pm	Sushi Ya	No	100	75	100	175	50 Centerpointe Dr.	La Palma	Private lateral	Private lateral cleanout	Grease	Grease interceptor failure.	N/A	N/A	Recovered sewage was returned to sewer system. Remainder was soaked into soil on private property.	Y	Private contractor sanitized and cleaned up
2/23/2005 9:00	Carl's Jr	No	40	40	60	0	5012 La Palma Ave.	La Palma	Private Lateral	Manhole	Grease	Grease blockage from private property and sedement	⁹ N/A	N/A	Returned to sewer system	Y	Private contractor sanitized and cleaned up
5/7/2005 11:00	Hannam Matket	No	10	100	370	0	4800 La Palma Ave.	La Palma	Private Lateral	Manhole	Grease	Grease blockage from private property	⁹ N/A	N/A	Returned to sewer system	Y	Private contractor sanitized and cleaned up
5/31/2005 :00:00 PM	City of La Palma	No	0	15	40	0	7822 Walker Street	La Palma	Lateral line	Cleanout	Blockage	Roots	N/A	N/A	Emergency Services removes contamonated soil and water off site	Y	Private contractor sanitized and cleaned up
2/16/2006 8:00	Brookside Apts	No	0	180	80	0	5600 Orangethorpe Avenue	La Palma	Private Lateral	Cleanout	Grease & Blockage	Grease blockage from private property and sedement	⁹ N/A	N/A	Returned to the system	Y	Private contractor sanitized and cleaned up
2/17/2006 8:00	Brookside Apts	No	0	202	80	0	5600 Orangethorpe Avenue	La Palma	Private Lateral	Cleanout	Grease & Blockage	Grease blockage from private property and sedement	⁹ N/A	N/A	Returned to the system	Y	Private contractor sanitized and cleaned up
6/8/2006 14:00	La Palma Hospital, private property	No	0	90	110	0	7901 Walker Street	La Palma	Private Lateral	Manhole	Unknown Blockage	Blockage from private proper	ty N/A	N/A	Hauled away by OC Pumping	Y	Private contractor sanitized and cleaned up
Totals	14	1	690	1,297	1,690	175										13	
Midway City SD																	
7/2/02 2:51 AM	Hamilton Pacific	yes	50	750	0	0	15622 Brookhurst Westminster	Westminster			grease	grease on private property	n/a	n/a			
9/18/02 5:00 PM	Private Property	yes	0	0	0	0	6234 Industrial Way Westminster	Westminster			grease & roots	grease & roots on private property	n/a	n/a	storm drain in Huntington Beach		
11/6/02 4:00 PM	Private Property	no	0	100	50	0	9191 Bolsa Ave Westminster	Westminster	grease interceptor	grease interceptor	grease	grease interceptor not properly serviced	n/a	n/a		yes	
4/21/03 11:30 AM	Private Property	no	0	0	0	0	1400 Magnolia St. Westminster	Westminster	cleanout	cleanout	grease	grease	n/a	n/a			This spill occurred on private property. The private security guard who called the spill into the Westminister PO reported the spill had been occurring for an least 24 to 48 hours, but the property owners had instructed him nor to report it to anyone. He eventually reported to spill, but because it had been occurring for an undetermined mound of time, it was impossible for our even to accurately assess how much amound of the site was impossible for our even to accurately assess how much mediately called the OCHCA, and Jeff Warren responded.
5/12/03 5:00PM	8265 Maureen Condominium Complex	no	0	30	0	0	8265 Maureen Midway City	Midway City	cleanout	cleanout	debris	debris on private property	n/a	n/a	Returned to sewer system		Spill reported to District by property management company. Spill on private property.
6/13/03 7:30PM	Condominium Complex	no	50	325	0	0	Kramer & Stonehedge Lane Westminster	Westminster		manhole	grease	grease in sewer line	Wintersburg Channe	l n/a	Returned to sewer system	yes	Spill reported by Westminster PD. Spill on private property
6/30/03 2:35PM	Trailer Park run by Del Almo	no	0	80	0	0	9702 Bolsa Ave. Westminster	Westminster		manhole	grease	grease in sewer line on privat property	^{te} n/a	n/a	Returned to sewer system	yes	Spill on private property
7/25/03 3:30AM	Little Saigon Village	no	0	0	0	0	10161 Bolsa Ave. Westminster	Westminster		cleanout	grease	grease in sewer line on privat property	testorm drain on Bolsa Ave.	n/a	Returned to sewer system	yes	Spill on private property
11/5/05 1:15PM	Private Property	no	0	10	0	0	14636 Goldenwwest Ave Westminster	Westminster		cleanout	n/a	na	Westminster Channel	n/a	Returned to sewer system	no	Spill reported by Westminster City water standby.
totals	9	2	100	1,295	50	0										4	
Newport Beach																	
4/2/02 1:40 p.m.	Private	Unknown	0	0	0	0	2325 E. PCH	Newport Beach	Grease Interceptor	Grease Interceptor	Unknown	See Remarks	n/a	n/a	n/a	yes	Grease interceptor was overflowing (Brio Rest)
11/6/02 3:50 p.m.	Private-City owned facility	No	0	100	0	0	1 Newport Pier	Newport Beach	Cleanout	Cleanout under Lifeguard Headquarters was overflowing	Sand and grease	See Remarks	n/a	n/a	n/a	yes	Cleanout under Lifeguard Headquarters was overflowing
11/25/02 11:45 a.m.	Private	No	0	1500	0	0	1068 Rutland	Newport Beach	Cleanout	Cleanout	Unknown (possible roots)	See Remarks	n/a	n/a	n/a	yes	Cleanout overflow - OCH care Agncy closed Upper Newpor Bay Water
12/3/02 1:55 p.m.	Private	Unknown	150	100	0	0	Big Canyon Golf Course	Newport Beach	n/a	n/a	Roots and grease	See Remarks	n/a	n/a	n/a	yes	Overflow on Big Canyon Golf Course
12/5/02 8:30 a.m.	Private	No	500	100	0	0	1433 Superior Ave.	Newport Beach	Private system	Private system	Unknown	See Remarks	n/a	n/a	n/a	yes	Plumber onsite removed blockage in private system as CNB news arrive on site (Beach House Appartments. Reported in OCHCA Beach Closure Report, not in originally submitted OCHCA report)
1/30/03 4:40 p.m.	Private Spill	Unknown	1000	0	0	0	3435 Newport Blvd.	Newport Beach	n/a	n/a	Grease, Paper products	See Remarks	n/a	n/a	n/a	yes	(Pavillons Supermarket) Blockage of paper products, feminine hygiene products, grease. (Originally marked as unknown for surface water. Reported on OCHCA Beach Closure Report)
5/1/03 8:00 a.m.	Private	Yes	0	25	0	0	2751 Coast Hwy.	Newport Beach	Grease Trap	Grease Trap	Unknown	See Remarks	Pacific Ocean	n/a	n/a	yes	Grease trap was overflowing. 5 gallons per minute.
10/28/03 2:00 p.m.	Private Property	Unknown	0	0	0	0	Jamboree at Big Canyon Golf Course	Newport Beach	Private manhole	Private manhole	Roots and debris	See Remarks	n/a	n/a	n/a	yes	Opened manhole and cleared roots and debris over 10 ft deep manhole. Private manhole. Private property: Sea Island Community Association.
		1					*										

11/1/03 11:00 a.m.	Private	No	0	1,000	0	0	McArthur Blvd.	Newport Beach	Private force main	Private force main	Private forcemain was broken	See Remarks	n/a	n/a	n/a	yes	Private force main was broken Located Big Canyon Villas HOA.
3/22/04 12:45 a.m.	Private Spill	No	300	200	0	0	4525 W. Coast Hwy	Newport Beach	n/a	n/a	Grease spill at ChronicTaco	See Remarks	n/a	n/a	n/a	yes	Containment setup at storm drain. Vacuum truck clean up spill, grease and stop overflow.
6/24/04 8:00 a.m.	Private Spill	Unknown	400	100	0	0	500 Superior	Newport Beach	n/a	n/a	Unknown	See Remarks	n/a	n/a	n/a	yes	Vactor setup dirt berm@catch basin. Vacuum setup @ manhole to stop SSO.
7/12/04 1:15 p.m.	Private Spill	No	600	0	0	0	1000 Dove St.	Newport Beach	Private cleanout	Private cleanout	Grease & Paper Products	See Remarks	n/a	n/a	n/a	yes	Setup vactor on Dove to catch & contain overflow from private cleanout at driveway.
12/19/04 2:22 p.m.	Albertson's	n/a	0	200	0	0	3049 E. PCH, CDM	Newport Beach	Cleanout. Blockage on private lateral.	Cleanout	Blockage in private lateral	See Remarks	n/a	n/a	n/a	yes	Kitly litter used to build control dykes to contained flow from cleanout. Overflow from supermarket. Parking to twas shuddown from one and to another to stop cars from driving thru publicaties of severa jin to .COH (Control I) and RW026 (IOS) called. Convin Brown and Monica Mazur catable tack from OCHD. OES Control I is WH6555. Plumber called by Henry Henry (From Albertons') to caller blockage from private lateral. Vacuum unit 5503 and hydro Unit 5517 used to clean up parking lot.
1/14/05 2:30 p.m.	Pavilions Von's	No	0	700	0	0	Von's Pavilon	Newport Beach	n/a	n/a	Grease logs & grease in pipe	See Remarks	n/a	n/a	n/a	yes	Vactor used to vacuum up sewage flow. Flow did not enter drain.
6/20/05 8:30 a.m.	Vons Market	Yes	50	25	0	0	1000 Bayside Dr.	Newport Beach	n/a	n/a	Grease	See Remarks	Pacific Ocean	n/a	n/a		Water Crew built a berm to contain the overflow to and called for a vactor to clean up the spill. Vactor remained onsite until the blockage was clearned.
7/19/05 2:30 p.m.	Pacific Comm.	No	450	2800	0	0	1000 Dove St.	Newport Beach	Private Cleanout	Private Cleanout	Grease & Paper Products	See Remarks	n/a	n/a	n/a		Burmed the gutter before the storm drain then set up the vactor before the burm. Notified the owne to call a plumber because it is a private clean out.
7/26/05 2:30 p.m.	America	Unknown	0	50	0	0	3601 Jamboree Rd	Newport Beach	Grease interceptor	Grease interceptor	Grease, near the grease interceptor.	See Remarks	n/a	n/a	n/a	yes	Fire Dept, built a berm at the nearest catchbasin, Gen. Serv. StormDrain crew responded with a vactor to vacuum contained material, code enforcement took pictures & cited the Property Mgmt. Co. America West Properties, Cit#12005-0734.
8/13/05 3:00 p.m.	Sabatino's	No	0	10	0	0	251 Shipyard Way	Newport Beach	Holding tank	Holding tank	Grease	See Remarks	n/a	n/a	n/a	yes	Used vactor to sack out a 4'x4'x4' deep holding tank that was full and keeping the sewage from the bag.
10/25/05 1:50 P.M.	Private	Yes	20	10	0	0	behind 2235 Pacific Dr	Newport Beach	Broken pipe	Broken pipe	Broken pipe on the hillside that was discharging sewage.	See Remarks	n/a	n/a	n/a	yes	Setup beam and vactor on Bayside Dr. used two flagmen for traffic control. Contacted Michael Bayer at 2235 Pacific Dr. to advise him he had a problem.
6/26/2006 7:50 P.M.	Restaurant at the end of the Newport Pier	No	0	0	0	0	Restaurant at the end of the Newport Pier	Newport Beach	Pipe joint	Pipe hangers holding ABS piping under the pier failed due to rust & corrosion, the piping dropped & a joint pulled apart.		See Remarks	n/a	n/a	n/a	Yes	City of Newport Beach lift station orew tunned water off to Restaurant immediately and advised restaurant manager of the problem. Utilities office called Environmental Health Services and RWQCB.
11/3/06 8:35 a.m.	Joe's Crab	Unknown	0	20	0	0	2607 W. Coast Hwy	Newport Beach	Blocked Grease intercepto	r Grease interceptor	Blocked Grease Interceptor	See Remarks	Pacific Ocean	n/a	n/a	yes	Met vactor, called for sand to build a berm around the grease that overflowed from the Restaurant interceptor. Contacted workers inside restaurant to call for a plumber/pump rutual and informed there they would not be allowed to open until the problem was taken care of. Called the Orange County Health Dept. and Regional Water Qualty Count Doard.
12/1/06 3:45 P.M.	Private	No	10	40	0	0	415 Old Newport Bivd.	Newport Beach	Lateral	Lateral	Roots from the lateral before the CMSD mainline.	See Remarks	n/a	n/a	Returned to system	Yes	Call for hydroflusher and vactor built erm at private storm drain box and set up vactor. Beamed storm rain box and used hydro to flush curb and gutter to storm drain at hospital read to Newport Bbx. Centerend to particip of and vacumed at private storm drain box unit plumber arrived and cleaned he blockage. Used high pressure water to chem particip dar watershold watershold.
12/23/06 4:45 p.m.	Private	Yes	100	200	0	0	3435 Newport Blvd.	Newport Beach	Grease trap	Grease trap	Grease from their grease trap.	See Remarks	n/a	n/a	n/a	yes	Grease trap from Pavillions Market overflowing. Fire crew and Monica from Health Dept. already on scene. Set up vacuum truck in parking lot. Spocke with the Manager at the market and told him here needs to get a pulmere out. Health Dept. shut down the Market. Assisted pulmeter in clearing blockage. Used second vactor truck to sparky down entire parking lot. Lat a volce mail with Market Anni (RVCOE) and explaned shut we did. Monica from Health Dept. got the lifeguards to post bach downs where needed.
Totals	23	4	3,580	7,180	0	0										23	
OCSD																	
04/04/02	Private Property	Ν	25	0	0	25	1634 La Loma Dr.	Santa Ana	4" Sewer Line	Cleanout	Blockage	Misc. debris	NA	NA	Soaked into ground	U	NA
4/15/02 3:15 PM	Private Property	Ν	0	0	0	0	12622 Kingsview Rd.	Unincorporated County of Orange	4° Sewer Line	υ	Blockage	υ	NA	NA	Soaked into ground	NA	NA
4/19/02 9:00 AM	Private Property	Ν	10	8	8	2	18802 Bardeen Ave.	Irvine	4" Sewer Line	V-drain	Blockage	Root obstruction in lateral line & Possible Broken Lateral	NA	NA	U	Y; 4/19/2002 9:00:00 AM	NA
-																	

Image: Solution in the standing of the										1	1	r		1		I	1	
1 1 0	6/30/02 9:30AM	Private Property	Y	300	0	0	0	3rd St & French St.	Santa Ana	Private property lateral	Cleanout	Blockage Grease clog	Not applicable - Not OCSD SSO	Not applicable - Not OCSD SSO	Not applicable - Not OCSD SSO	Not applicable - Not OCSD SSO	Not applicable - Not OCSD SSO	Blocking in the apartment complex. At about 91:58m o relieve the Blocking, the pulmer opened the desinoux which allowed the severed of thow offsite and into the starm drain. The Fire Department was able to contain the spill which induct 15 m. the starm drain and the start of the starm drain to be down 300 gallows (15 min x 10 gans x 2 for conservancy) Health Care sponded. Toly vol Santa Ana Public Karen Anbhy, soon after. Has Mat Bato responded. City of Santa Ana Public
Image: Image:<	7/15/02 17:00	Private Property	Ν	0	0	0	0	1841 VON KARMAN		Private lateral	Indoors	N/A	N/A	None	N/A	N/A	N/A	Walt reports blockage cleared before his arrival, plumber at location. OCSD lines are running free and clear. No assistance needed.
Image: Properties of the state of	8/3/02 22:15	Private Property	N/A	0	0	0	0	2220 MONTE VISTA AVE VISTA APARTMENTS	La Habra	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Y	PRIVATE PROPERTY. LA HABRA EST. 20 GAL. FLOWED TO DRAIN ON PROPERTY, BUT NO ONE KNEW WHERE PRIVATE DRAIN GOES. SEE CITY
INCIMIN OWNER <	10/26/02 10:50 AM	Private Property	N/A	2	0	0	0	12421 Mystic Lane		Sewer	Clean-out	N/A	N/A	N/A	N/A	N/A	Y	
Intersection Number of the section Numb	12/2/02 1:00 PM	Private Property	Unknown	100	10	110	90		Irvine	Private Lateral Sewer	Clean out		N/A	N/A	N/A	Native surrounding soil	12/02/2002 at	N/A
Note Name	1/6/03 3:30 PM	Private Property	N/A	5	0	0	0	1621 FOOTHILL BLVD.	Unincorporated County of Orange	Private lateral line	Clean out	Unknown	N/A	N/A	N/A	Native soil	Y, 1/6/2003	contact OCSD's Engineering Dept. to try and figure out who the owner is and
No. No. No. NA Q Q Q Max Market Mach Marke	1/8/03 11:57 PM	Private Property	Unkown	40	20	100	0	1101 Packers Circle	Tustin	Private lateral line	Manhole	Grease clog	N/A		Newport Back Bay	Unknown		ECM, Collections, and Communications staff will be sending a letter to the Home Owners Association to notify owner of problem and the need to implement preventative maintenance schedule to ensure no future SSOs.
Label Part Part Part Part Part Part Part Part	1/16/03 8:00 PM	Private Property	N/A	0	0	0	0	14436 SAND BROOK DR.	Tustin	Private lateral line	Bathtub	Unknown	N/A	N/A	N/A	Bathtub	N	OCSD staff inspected OCSD lines and found them running normal. At the request of the resident staff showed him the structure at both ends of the line segment in front of his property. The resident was informed that this was his responsibility to clear the lateral.
Point Provint NA Q Q Q Q Point Provint Provintete Provint Provint Provinte Provint Provint Provin	1/29/03 7:00 PM	Private Property	N/A	0	0	0	0	1102 Hyde Park Dr.	Unincorporated County of Orange	Private lateral line	Bathtub and toilet		N/A	N/A	N/A	Bathtub and toilet	onsite when	OCSD will CCTV entrie Hyde Park Dr. line segments to investigate house lateral conditions for not intrusion. Resident was sent a letter explaining the cause of the swaye backup into his home (rotos in his lateral) so be caudid fie an insurance claim. OCSD will be sending a letter to all the residents in the area to notly them of the lateral or porchem and a request conflication of any future work they have done on the lateral lines so OCSD can inspect their main line for pushed in roots.
22805 20 M Peter Property N.M 0 0 0 777 MTCPEEL Table M Needs Property N.A N.A N.A N.A State M N.A	2/6/03 11:00 AM	Private Property	N/A	2	0	0	0	Foothill Blvd. and 1651	Unincorporated County of Orange	Private Lateral	Private Cleanout	Unknown	Unknown	N/A	N/A		Y; 2/6/2003 3:50:00 PM	N/A
17102 50 Mble Private Propenty N O O O O <td>3/28/03 5:20 PM</td> <td>Private Property</td> <td>N/A</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>Commin Dirid.</td> <td></td> <td>Private Sewer line</td> <td>Manhole</td> <td>Blockage Misc. debris</td> <td>N/A</td> <td>N/A</td> <td>N/A</td> <td>Street, sand berm</td> <td>Y; 3/28/03 5:37PM</td> <td>NA</td>	3/28/03 5:20 PM	Private Property	N/A	0	0	0	0	Commin Dirid.		Private Sewer line	Manhole	Blockage Misc. debris	N/A	N/A	N/A	Street, sand berm	Y; 3/28/03 5:37PM	NA
Lack CA SUMNSGSGSGSInitial Cult Nitities Luci.Initial Protect MarkProtect MarkGood of a NNGSSN5703 815 AMPrivate PropertyNGGG <td< td=""><td>4/17/03 8:30 AM</td><td>Private Property</td><td>N</td><td>0</td><td>0</td><td>0</td><td>0</td><td>13071 ST MARK ST</td><td>Santa Ana</td><td>Private lateral</td><td>Private Clean out</td><td>Blockage Misc. debris</td><td>N/A</td><td>Soaked into ground</td><td>N/A</td><td>Soaked into ground</td><td>4/17/2003 8:47 AM</td><td>N/A</td></td<>	4/17/03 8:30 AM	Private Property	N	0	0	0	0	13071 ST MARK ST	Santa Ana	Private lateral	Private Clean out	Blockage Misc. debris	N/A	Soaked into ground	N/A	Soaked into ground	4/17/2003 8:47 AM	N/A
5773 815 M Pivale Property N 0 0 0 RESTAURANT, TALEPERT N FOURTAN Lateral Cleanott Bodage Creat Column 14/leg NA Unknown 5773000 S774000 <	4/20/03 3:00 PM	Private Property	Ν	3	0	0	3	1091 OLD IRVINE BLVD.	Tustin	Private lateral	Private Clean out	Blockage Grease clog	N/A	Soaked into ground	N/A	U	4/20/2003 3:15 PM	N/A
SB03 340 PM Private Property N 0 0 0 CANTON LEPARCE NUM Originated Curry Leteral Ceanod Index NA NA Unknown N NA NA 5503 32 40 PM Private Property N 0 0 0 CANTON LEVARD Originated Curry Leteral Cleanodt Index NA Unknown N NA NA 51503 7.30 AM Private Property N 0 0 0 Difference	5/7/03 8:15 AM	Private Property	N	0	0	0		RESTAURANT, BROOKHURST ST. & TALBERT IN FOUNTAIN	Fountain Valley	Lateral	Cleanout	Blockage Grease clog	N/A	Channel to the	N/A	Unknown		NA
S1503 3:30 M Private Property N 0 0 0 Private MonOral Action County of Private Property NA Data Data Data Data Data Data Data Data	5/9/03 3:40 PM	Private Property	N	0	0	0	0		Unincorporated County of Orange	Lateral	Cleanout	obstruction in	N/A	None	N/A	Unknown	N	NA
5/15/03 5:30 PM Private Property N 20 30 30 0 7100 NNOT AVE: Buena Park Lateral Clean out Interal Inc. NA Unknown 220 PM NA Unknown 220 PM NA 6/11/03 10:40 PM Private Property Unknown 355 0 755 95 11407 ARROYO AVE Unknown bint private property NA Unknown Version <	5/15/03 7:30 AM	Private Property	N	0	0	0	0		Unincorporated County of Orange	Lateral	Cleanout	Blockage Misc. debris	N/A	Drain/Channel. Red	N/A			N/A
E/11/03 10:40 PM Private Property Unknown 35 0 75 95 11407 ARROYO AVE Unincorporated County Pinch private property after all NA NA V.612000 http://diadultaciance/status/s	5/15/03 5:30 PM	Private Property	N	20	30	30	0	7100 KNOTT AVE.	Buena Park	Lateral	Cleanout	obstruction in	N/A		N/A	Unknown	5/15/2003 7:20 PM	N/A
7/3/03 2.00 AM Private Property N 0 0 0 11772 HIGH VIEW DRIVE Unicorporated County of Orange Private sever line Bathtub and toilet U NA NA NA NA NA OCSD line was running freely. No sever spill in the area.	6/11/03 10:40 PM	Private Property	Unknown	35	0	75	95	11407 ARROYO AVE			manhole		N/A	Hicks Canyon	Unknown	N/A		The field report states that it did enter a storm drain. However, after taiking to Victor Hermein, he stated that it actually did not enter a storm drain. The spill had been contained in the guitter, which did equ , so it was not recovered via vacotor tuck. Should remove OCSD logo's on covers from private property manholes.
	7/9/03 2:00 AM	Private Property	Ν	0	0	0	0	11772 HIGH VIEW DRIVE	Unicorporated County of Orange	Private sewer line	Bathtub and toilet	U	U	N/A	N/A	N/A	N	OCSD line was running freely. No sewer spill in the area.

8/13/03 8:50 AM	Private Property	N	0	0	0	0	12523 HINTON WAY	Unicorporated County of Orange	Per Roy Parrino the problem was on Private Property and the problem stemmed from their clean- out. There was no spill, and the residents were tolk to contact a plumber and not to run any water.	N/A	N/A	NA	None	None	None	N	None
8/28/03 9:00 PM	Private Property	U	0	0	0	0	18802 BARDEEN AV	Irvine	SBCO 420 Charlie Ambriz to evaluate the problem. Spill was in the residential property.	N/A	N/A	N/A	None	None	None	N	Nane
8/28/03 11:30 PM	Private Property	Ν	0	0	0	0	12691 BROWNING AVE	Unicorporated County of Orange	Call out Div. 420 Standby Charlie Ambriz. 08/29/03 00:22 Charlie reported tha OCSD line was flowing clearly. Problem was at home owner's building sewer.	Bath tub and toilet	U	N/A	None	None	None	N	None
9/4/2003 8:15 PM	Private Property	N	0	0	0	0	17792 McFadden	Tustin	Blockage was determined to be in private property	Toilets backed up in Shopping Center Area	u	N/A	N/A	N/A	N/A	N	NA
10/10/03 1:30 PM	Private Property	N	0	0	0	0	2501, 2511 & 2521 W. SUNFLOWER AVE	SANTA ANA	U	U	U	U	N/A	N/A	N/A	N	N/A
10/28/03 2:25 PM	Private Property	Yes, possibly spill went into nearby creek.	0	0	0	0	JAMBOREE RD.	Newport Beach	8-inch clean out on private property	Clean out	Grease, other and debris	N/A	Nearby Creek	N/A	N/A	Y	NA
10/31/03 7:15 PM	Private Property	N	0	50	50	0	2000 JAMBOREE RD	Newport Beach	8-inch force main on private property	Force main	Failed pipe	8-inch force main failure	N/A	N/A	Sanitary Sewer System	Y	This spill began on 10/31/2003 and after initial containment on the evening of 10/31/2003, the spill resurfaced on 11/01/2003. OCSD responded to spill on 10/01/2003 to find that the cause of the spill was a troken shork force main line. Containment was set by the City of Newport Beach and then OCSD advised the private properly owner (Mer Property Minagement) that a vacuum outif should be notified to vacuum up the wet well to stop the spill until the repairs are complete.
11/4/03 7:58 PM	Private Property	N	0	0	0	0	17792 McFadden Ave	Tustin	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Resident Called in to report toilet back up. Spill was private property responsibility
12/16/03 2:55 PM	Private Property	N	0	7	257	0	11481 Skyline Drive	Santa Ana	4" Sewer Lateral	Clean out	Blockage, Misc. debris	N/A	N/A	N/A	N/A.	Y (via spill notification e- mail)	N/A
12/27/03 6:50 PM	Private Property	N	50	100	250	50	17231 E. 17th Street	Tustin	8" Sewer Lateral	Manhole	Blockage, Grease clog	N/A	Santa Ana River	N/A	N/A	Y; Called 12/27/2003 9:05:00 PM	N/A
5/29/04 11:00 PM	Private Property	U	0	0	0	0	17502 17TH STREET	Tustin	Sewer Line	Manhole	Blockage	Grease clog	U	U	U	Y; 5/30/2004	N/A
7/15/04 2:15 PM	Private Property	U	0	0	0	0	On Canyon Terrace Rd which is just below residents house @10372 Crawford Canyon Rd.	Unincorporated County of Orange	U	Cleanout	U	U	U	υ	U	Y; 7/15/2004 5:40:00 PM	NA
9/21/04 8:25 AM	Private Property	Y	0	400	0	0	15701 TUSTIN VILLAGE WAY	Unincorporated County of Orange	4" clean out	Clean out	Blockage	Misc. debris	Peters Canyon Wash	Peters Canyon Wash	Peters Canyon Wash	Y; 9/21/2004 9:05:00 AM	CITY OF TUSTIN TOOK PHOTOS & WILL FORWARD THEM TO OCSD. TOTAL SPILL LESS THAN 1,000 GALLONS PER FIELD OBSERVATION.
10/7/04 10:35 AM	Private Property	N	10	0	0	0	7621 TRASK AV	Westminster	8" sewer line	Manhole	Blockage	Grease Clog	N/A	N/A	Soaked into ground	Y	1030am, Possible spill at 7621 Trask Ave. In Westminster, Notfield OCSD / Dr.420 to check. No atom drain info. is inoon at this time, P787 J-7. Small spill at 7621 Trask Ave. is contained on private properly. Appost. Of gallons, Containment is set. NO storm drain impact. OCSD is looking for Apt. manager at this time.
11/8/04 9:46 AM	Private Property	N	0	0	0	0	1541 FOOTHILL BL	Santa Ana	υ	U	Other	U	N/A	N/A	Soaked into ground	Y; 11/8/2004 10:46:00 AM	N/A
11/23/04 2:10 PM	Private Property	Ν	0	0	0	0	171 FIRST ST.	Tustin	U	U	Blockage	Misc. debris	N/A	N/A	N/A	Y; 11/23/2004 4:09:00 PM	N/A
12/10/04 1:55 PM	Private Property	Ν	0	0	0	0	4516 CHAPMAN AVE	Orange	NA	Manhole	U	U	NA	NA	NA	U	NA
12/20/04 3:15 PM	Private Property	Ν	0	0	0	0	2355 MAIN ST	Irvine	U	Manhole	Blockage	Other Debris	NA	NA	NA	Y; 12/20/2004 4:00:00 PM	NA
12/28/04 11:00 AM	Private Property	N	0	0	0	0	13071 ST MARKS DR	Santa Ana	4"	Clean-out	Blockage	Root obstruction in lateral line	NA	NA	Soaked into ground	Y; 12/28/2004 12:45:00 PM	Spoke with Mike Fennessy, OCHCA, and requested his staff to inspect the site since OCSD manhole/line is in the Private Property yard.
12/30/04 2:15 PM	Private Property	Ν	0	0	0	0	10120 SUNRISE LN	Unincorporated County of Orange	4"	Clean-out	Blockage	Other Debris	NA	NA	NA	Y	NA
1/3/05 10:30 AM	Private Property	N	0	0	0	0	1462 FOOTHILL BLVD	Santa Ana	4" Clean out	Clean out	Blockage	Misc. debris	NA	NA	NA	U	NA
1/27/05 9:00 AM	Private Property	N	20	0	0	0	1722 MITCHELL	Tustin	4" Clean out	Clean out	Blockage	Grease clog	NA	NA	NA	U	NA
2/4/05 4:30 PM	Private Property	Ν	0	0	0	0	1581 N. FOOTHILL BLVD	Unincorporated County of Orange	NA	GROUND	U	U	NA	NA	NA	Y; 2/4/2005 4:30:00 PM	NA

norme	-							r -					r				
Number Num	2/14/05 10:15 AM Private Property	N	0	0	0	0	10511 EASTER HILL DR.		U	U	U	U	NA	NA	NA	NA	We set up flush truck and ran customer line 319 feet, bringing back nothing. Gated
Marce Marce A <	4/13/05 2:30 PM Private Property	N	50	0	0	50	1505 CLEARVIEW LN		4"	Cleanout	Blockage		Soaked into ground	Soaked into ground	Soaked into ground		Private Property
Normal Normal <td>4/23/05 4:10 PM Private Property</td> <td>N</td> <td>0</td> <td>1300</td> <td>1460</td> <td>0</td> <td>1171 PACKERS CIR</td> <td>Tustin</td> <td>8"</td> <td>Manhole</td> <td>Blockage</td> <td>Grease clog</td> <td>Contained in Storm Drain/Channel</td> <td></td> <td></td> <td>Y; 4/23/2005 4:55:00 PM</td> <td>Private Property</td>	4/23/05 4:10 PM Private Property	N	0	1300	1460	0	1171 PACKERS CIR	Tustin	8"	Manhole	Blockage	Grease clog	Contained in Storm Drain/Channel			Y; 4/23/2005 4:55:00 PM	Private Property
matrix	5/23/05 2:30 PM Private Property	N	0	15	15	0	1451 NISSON RD	Unincorporated County of Orange	Septic Tank	Manhole	Blockage	Misc. debris	NA	NA	NA		NA
math n <td>6/20/05 4:00 PM Private Property</td> <td>N</td> <td>300</td> <td>100</td> <td>300</td> <td>200</td> <td>13102 NEWPORT BLVD</td> <td>Tustin</td> <td>8" Private Sewer</td> <td>Private Manhole</td> <td>Grease</td> <td>Blockage</td> <td>Peters Canyon Wash</td> <td>NA</td> <td>Peters Canyon Wash</td> <td></td> <td>and Duane Smith to respond. Dindo Carrillo notified right away and called the</td>	6/20/05 4:00 PM Private Property	N	300	100	300	200	13102 NEWPORT BLVD	Tustin	8" Private Sewer	Private Manhole	Grease	Blockage	Peters Canyon Wash	NA	Peters Canyon Wash		and Duane Smith to respond. Dindo Carrillo notified right away and called the
MindingMarka<	6/22/05 8:15 AM Private Property	N	676	636	886	40	13102 NEWPORT BLVD	Tustin	8" Private Sewer	Private Manhole	Grease	Blockage	Peters Canyon Wash	NA	Peters Canyon Wash		Truck vactored up a total of 500 gallons, including 250 gallons of wash water. Spill was approx. 250 gallons. All was cleaned up at 1pm. Private plumber was called & Health Dept. on site as well. Approx. 40 gallons was not recovered from storm
Normal	7/11/05 12:00 PM Private Property	N	0	0	0	0	10072 FOX SPRING RD		U	Septic tank	Other	Other	NA	NA	Soaked into ground	Y; 7/11/2005 12:20:00 PM	NA
Marcian Marcian <t< td=""><td>8/16/05 8:10 AM Private Property</td><td>N</td><td>0</td><td>0</td><td>0</td><td>0</td><td>1771 LA LOMA DR.</td><td>Unincorporated County of Orange</td><td>Private Lateral</td><td>Cleanout</td><td>Blockage</td><td>Root obstruction in lateral line</td><td>Soaked into ground</td><td>NA</td><td>Soaked into ground</td><td>Y; 8/16/2005 11:30:00 AM</td><td>ran the line/manhole downstream of property and cleaned out some roots. H owever, lateral is blocked with roots on homeowers property at 4in. cleanout. Homeowner is not home but msgs. have been left for him to contact a private plumber before using anymore water. Spill is not flowing at present time & was</td></t<>	8/16/05 8:10 AM Private Property	N	0	0	0	0	1771 LA LOMA DR.	Unincorporated County of Orange	Private Lateral	Cleanout	Blockage	Root obstruction in lateral line	Soaked into ground	NA	Soaked into ground	Y; 8/16/2005 11:30:00 AM	ran the line/manhole downstream of property and cleaned out some roots. H owever, lateral is blocked with roots on homeowers property at 4in. cleanout. Homeowner is not home but msgs. have been left for him to contact a private plumber before using anymore water. Spill is not flowing at present time & was
Minterior <td>9/13/05 10:30 AM Private Property</td> <td>N</td> <td>15</td> <td>0</td> <td>0</td> <td>0</td> <td>19511 HOLIDAY LN</td> <td>Unincorporated County of Orange</td> <td>4-in lateral line</td> <td>Clean-out</td> <td>Blockage</td> <td>Root obstruction in lateral line</td> <td>NA</td> <td>NA</td> <td>Soaked into ground</td> <td></td> <td>NOT OCSD PROBLEM</td>	9/13/05 10:30 AM Private Property	N	15	0	0	0	19511 HOLIDAY LN	Unincorporated County of Orange	4-in lateral line	Clean-out	Blockage	Root obstruction in lateral line	NA	NA	Soaked into ground		NOT OCSD PROBLEM
Minder Air	10/16/05 9:15 AM Private Property	N	0	300	400	0		Stanton	NĂ	Manhole	Blockage	Grease Clog	NA	NA	NA		None
Markan	11/14/05 2:40 PM Private Property	N	0	0	0	0	13502 SUSSEX PLACE	Unincorporated County of Orange	8-inch lateral	u	Blockage	Misc. debris	NA	NA	NA	Y; 11/14/2005 4:00:00 PM	None
MarkedMarkedMM <th< td=""><td>12/19/05 2:30 PM Private Property</td><td>N</td><td>0</td><td>0</td><td>0</td><td>0</td><td>1451 NISSON RD</td><td>Tustin</td><td>Septic tank</td><td>Septic tank</td><td>U</td><td>υ</td><td>NA</td><td>NA</td><td>U</td><td>U</td><td>OCSD responded to this Private Property spill in an assistance capacity to the city of Tustin.</td></th<>	12/19/05 2:30 PM Private Property	N	0	0	0	0	1451 NISSON RD	Tustin	Septic tank	Septic tank	U	υ	NA	NA	U	U	OCSD responded to this Private Property spill in an assistance capacity to the city of Tustin.
And regionAnd regionAnd <th< td=""><td>12/25/05 10:45 AM Private Property</td><td>N</td><td>100</td><td>0</td><td>150</td><td>0</td><td>11021 GOLD STAR LN</td><td>Unincorporated County of Orange</td><td>8"</td><td>Manhole</td><td>Blockage</td><td>Roots in Main Line</td><td>NA</td><td>NA</td><td>Soaked into ground</td><td>Y; 12/25/2005 10:45:00 AM</td><td>Control 1 was notified by homeowner and Control 1 contacted Larry Honeybourne. Larry Honeybourne contacted OCSD of the spill.</td></th<>	12/25/05 10:45 AM Private Property	N	100	0	150	0	11021 GOLD STAR LN	Unincorporated County of Orange	8"	Manhole	Blockage	Roots in Main Line	NA	NA	Soaked into ground	Y; 12/25/2005 10:45:00 AM	Control 1 was notified by homeowner and Control 1 contacted Larry Honeybourne. Larry Honeybourne contacted OCSD of the spill.
Name	12/30/05 2:50 PM Private Property	N	1780	1180	1780	600	1777 MITCHELL AV	Tustin	8"	Manhole	Blockage	Grease clog	Peters Canyon Wash	NA	NA	Y; 12/30/2005 3:30:00 PM	Previous Private Property spill occurred at same location on 3/28/03. Initial visual estimate at spill location was 900 gallons.
2406 fb See Property N See Property N See Property See Propery See Property <th< td=""><td>1/10/06 10:00 AM Private Property</td><td>N</td><td>0</td><td>0</td><td>0</td><td>0</td><td>12322 EL ROY DR</td><td>Unincorporated County of Orange</td><td>Private property lateral</td><td>Clean-out</td><td>Blockage</td><td>Roots in lateral</td><td>NA</td><td>NA</td><td>Soaked into ground</td><td></td><td>FOUND DRIED PAPER ON PRIVATE PROPERTY. CREW USED VACTOR TRUCK, LINE IN STEET IS RUNNING OK. CREW IS CONTACTING CALLER AS</td></th<>	1/10/06 10:00 AM Private Property	N	0	0	0	0	12322 EL ROY DR	Unincorporated County of Orange	Private property lateral	Clean-out	Blockage	Roots in lateral	NA	NA	Soaked into ground		FOUND DRIED PAPER ON PRIVATE PROPERTY. CREW USED VACTOR TRUCK, LINE IN STEET IS RUNNING OK. CREW IS CONTACTING CALLER AS
2 Hold Fright N Main Fright N O O O O Main O Main N Main <	2/4/06 6:15 PM Private Property	N	50	0	0	0	1621 EDINGER AVE.	Tustin	U	Cleanout	Blockage	Other	υ	NA	U	7:23:00 PM Jenny McBride Heath Specialist 714	requested to standby until Orange County Health department arrived on scene.
Sale Property N O <	2/16/06 11:45 AM Private Property	N	0	0	0	0			U	U	Blockage	Root obstruction in lateral line	NA	NA	Soaked into ground	Y; 2/16/2006 2:52:00 PM	
Initial property N O	5/9/06 10:00 AM Private Property	N	0	0	0	0	1942 OMEGA DR		Lateral line	u	Blockage	Root obstruction in lateral line	NA	NA	u	NA	NA
9 Private Property N 0 0 0 0 100 <	7/10/06 8:10 PM Private Property	N	0	0	0	0	17672 ORANGE TREE LANE	Tustin	4-inch	Bathroom	Blockage	Unknown	NA	NA	NA		RWQCB was contacted with their after hours number and was left a voice message. Control 1 was contacted and spoke to John (Environmental Health).
111206 1130 ÅA Private PropertyU000010102 MICHELTusin24 inchManholeBickageMac. defrisNANANAV:11/220001130 hor. 11500 kr1130	9/26/06 6:26 PM Private Property	N	0	0	0	0	13626 ESTERO CIR	Tustin	Clean out	Clean out	Blockage	Misc. debris	NA	NA	NA		Care was asked to assist in speaking with Apartment Complex Manager so they
And the proof of the proof	11/12/06 11:30 AM Private Property	U	0	0	0	0	1192 MITCHELL	Tustin	24 inch	Manhole	Blockage	Misc. debris	NA	NA	NA	Y; 11/12/2006 11:50:00 AM	1130 hour. John Ralls (OCHCA) was asked to assist by speaking with apartment manager to call a plumber.
4/23/02.8.0.0am Physile Property n/a 1281 150 0 0 0 n/a Orange n/a	Totals 66	3	3,593	4,156	5,871	1,155										47	
	Orange																
11//23/02.3:15pm Private Property n/a 15 0 0 0 n/a Orange n/a n/a Grease n/a n/a n/a n/a n/a n/a n/a n/a	4/23/02 8:00am Private Property	n/a	1281	150	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a	n/a	n/a	Yes	n/a
	11/23/02 3:15pm Private Property	n/a	15	0	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a

1/6/03 9:00am	Private Property	n/a	300	300	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a	n/a	n/a	Yes	n/a
1/14/03 4:15pm	Private Property	n/a	0	0	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a	n/a	n/a	Yes	n/a
1/27/03 8:00am	Private Property	n/a	50	50	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a	n/a	n/a	Yes	n/a
4/29/03 10:20am	Private Property	n/a	200	200	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
5/19/03 4:00pm	Private Property	n/a	50	0	0	0	n/a	Orange	n/a	Pump Malfunct.	Pump Malfunct.	n/a	n/a	n/a	n/a	Yes	n/a
5/20/03 3:45pm	Private Property	n/a	0	30	0	0	n/a	Orange	n/a	n/a	Roots	n/a	n/a	n/a	n/a	Yes	n/a
6/30/03 10:00am	Private Property	n/a	150	150	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
8/20/03 8:00am	Private Property	n/a	0	150	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
9/15/03 pm	Private Property	n/a	150	100	0	0	n/a	Orange	n/a	n/a	Roots	n/a	n/a	n/a	n/a	Yes	n/a
10/30/2003 monthly rpt	Private Property	n/a	0	100	0	0	n/a	Orange	n/a	n/a	Grease/Roots/Pape r	n/a	n/a	n/a	n/a	Yes	n/a
11/25/03 2:00pm	Private Property	n/a	450	50	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a	n/a	n/a	Yes	n/a
3/25/04 8:55pm	Private Property	n/a	25	225	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
5/17/04 8:15am	Private Property	n/a	25	25	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a	n/a	n/a	Yes	n/a
6/23/04 9:00am	Private Property	n/a	500	0	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
7/12/04 11:00am	Private Property	n/a	100	50	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
7/13/04 9:30am	Private Property	n/a	50	150	0	0	n/a	Orange	n/a	n/a	Paper	n/a	n/a	n/a	n/a	Yes	n/a
7/17/2004 monthly rpt	Private Property	n/a	25	75	0	0	n/a	Orange	n/a	n/a	Grease/unknown	n/a	n/a	n/a	n/a	Yes	n/a
7/21/04 3:29pm	Private Property	n/a	150	50	0	0	n/a	Orange	n/a	Broken Line	Broken Line	n/a	n/a	n/a	n/a	Yes	n/a
10/14/04 1:45pm	Private Property	n/a	50	25	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
10/26/04 6:15am	Private Property	n/a	40	25	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
11/13/04 5:00pm	Private Property	n/a	25	225	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
12/21/04 7:45pm	Private Property	n/a	100	150	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
1/14/05 1:30pm	Private Property	n/a	50	50	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
3/22/05 9:00am	Private Property	n/a	0	4	0	0	n/a	Orange	n/a	Cleanout Cap Rmvd	Cleanout Cap Rmvd	n/a	n/a	n/a	n/a	Yes	n/a
4/01/05 1:45pm	Private Property	n/a	200	250	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
5/31/05 12:15pm	Private Property	n/a	100	250	0	0	1040 Katella	Orange	n/a	Grse/Brkn Equip	Grse/Brkn Equip	n/a	n/a	n/a	n/a	Yes	n/a
6/17/05 5:45pm	Private Property	n/a	75	40	0	0	2127 Quincy	Orange	n/a	n/a	Pumped to St.	n/a	n/a	n/a	n/a	Yes	n/a
8/16/05 11:00am	Private Property	n/a	0	63	0	0	274 N Glassell	Orange	n/a	BckFlw Mlfnct/Grs	BckFlw Mlfnct/Grs	n/a	n/a	n/a	n/a	Yes	n/a
8/17/05 8:30am	Private Property	n/a	0	0	0	0	n/a	Orange	n/a	n/a	Grease/ Vandalism	n/a	n/a	n/a	n/a	Yes	n/a
9/06/05 8:15am	Private Property	n/a	500	1000	0	0	n/a	Orange	n/a	Cleanout Cap Rmvd	Cleanout Cap Rmvd	n/a	n/a	n/a	n/a	Yes	n/a
10/24/05 7:30am	Private Property	n/a	25	15	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
11/14/05 8:15am	Private Property	n/a	0	100	0	0	426 W. Almond Ave.	Orange	n/a	Building basement and Railroad right of way	Grease/Roots	Building basement and Railroad right of way	n/a	n/a	n/a	Yes	n/a
1/06/06 9:00am	Private Property	n/a	0	3500	0	0	n/a	Orange	n/a	n/a	Roots	n/a	n/a	n/a	n/a	Yes	n/a
l	۱				L I		+	+	+	l	l	L	+	l	l		Į

Single																		
Mark	1/25/2006 monthly rpt	Private Property	n/a	0	3	0	0	n/a	Orange	n/a	Cleanout Cap Rmvd	Cleanout Cap Rmvd	n/a	n/a	n/a	n/a	Yes	n/a
Normal Normal <td>2/08/06 9:45am</td> <td>Private Property</td> <td>n/a</td> <td>0</td> <td>20</td> <td>0</td> <td>0</td> <td>828 N. Glassell</td> <td>Orange</td> <td>n/a</td> <td>n/a</td> <td>Grease</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>Yes</td> <td>n/a</td>	2/08/06 9:45am	Private Property	n/a	0	20	0	0	828 N. Glassell	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
Normal Normal <td>3/23/06 12:00pm</td> <td>Private Property</td> <td>n/a</td> <td>0</td> <td>450</td> <td>0</td> <td>0</td> <td>1538 E. Chapman</td> <td>Orange</td> <td>n/a</td> <td>n/a</td> <td>unknown</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>Yes</td> <td>n/a</td>	3/23/06 12:00pm	Private Property	n/a	0	450	0	0	1538 E. Chapman	Orange	n/a	n/a	unknown	n/a	n/a	n/a	n/a	Yes	n/a
Image	4/17/06 11:45am	Private Property	n/a	0	25	0	0	3340 E. Collins	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
Normal Normal<	7/04/06 10:00pm	Private Property	n/a	0	200	0	0	315 Bedford	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
Norm	Totals	40	0	4,686	8,250	0	0										40	
Image	Placentia									Р.								
Image	2/27/03 13:00	Private Property	na	25	180	180	25	2097 E Orangethorpe Placentia	Placentia	private lateral line	clean out	Grease	Grease build up	na	na	storm drain	yes	Yorba Linda Water district Responded and cleaned up the spill also picked up the wash water. This spill was located on priviate property.
MANUM No. MANUM No. MANUM No. MANUM No. No. MANUM No. No. MANUM No. No. MANUM No. No. <	3/13/03 8:00	Private Property	na	350	400	400	750	112 N Bradford Ave Placenti	a Placentia	private lateral line	Broken latteral line	roots	roots from tree	na	na	storm drain	yes	Bradford Senior homes hired contractor to repair latteral line City to charge back time and matterals for spill
Interface Inter	4/7/04 13:10	Private Property	No	100	40	0	100	164 Yorba Linda	Placentia	Priavate property lateral	lateral line	grease	grease	na	na	Storm drain	yes	
ALME Substrate Substrat Substrate Subs	6/29/04 9:30	Private Property	No	90	60	0	30	1300 Kraemer	Placentia	Private property lateral	lateral line	grease	grease	na	na	Storm drain	no	Spill was caused by grease from business located 1300 Kraemer in a priavate parking lot and ran through the parking lot ending ending up on Kraemer blvd.
Name No.	Totals	4	0	565	680	580	905										3	
Market Market <td>RLAASD</td> <td></td> <td></td> <td></td> <td></td> <td>1 1</td> <td></td> <td></td> <td></td> <td>1</td> <td>1</td> <td>1</td> <td></td> <td></td> <td></td> <td></td> <td>1</td> <td></td>	RLAASD					1 1				1	1	1					1	
Index of the second	11/11/02 12:25 p.m.		No	800	700	1500	0	3642 Katella	Los Alamitos	private lateral	private lateral clean out	grease	grease blockage	n/a	n/a	storm drain	yes	n/a
Prince Prine Prine Prine <td>11/13/02 7:21 a.m.</td> <td></td> <td>no</td> <td>500</td> <td>500</td> <td>1500</td> <td>0</td> <td>3642 Katella</td> <td>Los Alamitos</td> <td>private lateral</td> <td></td> <td>grease</td> <td>incomplete hydroflush</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>yes</td> <td>n/a</td>	11/13/02 7:21 a.m.		no	500	500	1500	0	3642 Katella	Los Alamitos	private lateral		grease	incomplete hydroflush	n/a	n/a	n/a	yes	n/a
VICUADE Marca Marca <	12/11/02 5:20 p.m.	Private Lateral Yucatan Grill Rest.	no	900	900	1500	0	12147 Seal Beach Blvd	Seal Beach	private lateral	private lateral clean out	grease	grease blockage	n/a	n/a	n/a	yes	n/a
Number of the state of the	4/7/03 7:45 a.m.		no	500	500	1500	0		Los Alamitos	private lateral		grease	grease blockage	n/a	n/a	n/a	yes	Grease interceptor was at a low point in the system and was not the cause.
22x80 2x9 Ange Ange Ange Ange Ange Ange Ange Ange	1/21/04 2:45 p.m.	Private Lateral St. Hedwig School	no	50	50	300	0	11482 Los Alamitos Blvd.	Los Alamitos	private lateral	private lateral clean out	roots	tree root blockage	n/a	n/a	n/a	no	n/a
Name Participant ParticipantName ParticipantName Participant ParticipantName Participant ParticipantName 	2/25/04 2:00 p.m.		no	500	490	1500	0	3642 Katella	Los Alamitos	private lateral	private lateral clean out	grease	grease blockage	n/a	na/	storm drain	yes	n/a
Same Area Yes 340 240 4.0 Area Area Private Property Yes 340 240 4.1 W. McFadden Avenue Same Area Private Property Clean of the barries Area Clean of the barries Area Clean of the barries Area Private Property Yes 340 240 550 0 411 W. McFadden Avenue Same Area Private Property Clean of the barries Area Private Property Ves Justice Area Yes Area	3/20/2006 3:30pm	Private Property Denny's Rest.	No	30	30	100	0	4232 Katella	Los Alamitos	private lateral	private grease interceptor	grease	grease blockage	n/a	n/a	n/a	n/a	n/a
View View Substrate View Substrate Substra Substra	Totals	7	0	3,280	3,170	7,900	0										5	
68/2020 120 Private Property Yes 340 240 580 0 4117 W. McFadeth Avenue Starts Area Private Property Clean out Decision of the starts and the system of the syst	Santa Ana																	
E242002 1400 Private Property Yes 100 250 450 0 \$10 E. Chestmit Avenue Sants Ana Private Property Clean out Blockage on seemt Blockage on seema Blockage on seemt Blockage on seema Blockage on se	6/6/2002 1320	Private Property	Yes	340	240	580	0	4117 W. McFadden Avenue	Santa Ana	Private Property	Clean out	Property. City of Santa Ana installed a siphon to make way for a storm drain system on the lateral. Spill occurred due to	installed a siphon to make way for a storm drain system on the lateral, the siphon	Wintersberg C-05	Wetlands	n/a	Yes - Monica Mazar	
6/25/2002 1420 Private Property - Owner (uttorw) Contained in gutter. 375 375 575 0 421 E 18h Street Santa Ana Private Property Clean out Grease and paper None None Outer Mahamad Babaland 8/22/2002 1630 PVA-Chy of Santa Ana N/A 90 450 450 90 2502 W. Seventeenth SL Santa Ana Private property Clean out Grease combined with surgical globes Grease combined with surgical globes Santa Ana River Ocean NA Ves Ves Mahamad Babaland Fease Santa Ana Private property Fease combined with with surgical globes Grease combined with with surgical globes Santa Ana River Ocean NA Ves Ves NA Ves Santa Ana Private property Private property Private property Private property Santa Ana River Ocean NA Ves NA Ves Mahamad 9/19/2002 1350 PMA-Chy of Santa Ana Yes Sonta Ana Private property Private property Private property spin.caude of Private property spin.caude of Debit None otherwait Santa Ana Ves Na Ves Na <td>6/24/2002 1400</td> <td>Private Property</td> <td>Yes</td> <td>100</td> <td>250</td> <td>450</td> <td>0</td> <td>510 E. Chestnut Avenue</td> <td>Santa Ana</td> <td>Private Property</td> <td>Clean out</td> <td>Blockage on sewer lateral was caused by grease and tree</td> <td>Blockage on sewer lateral war caused by grease and tree</td> <td>^sSanta Ana Delhi Channel</td> <td>Upper Newport Bay</td> <td>Upper Newport Bay</td> <td>Yes - Corwin Brown</td> <td></td>	6/24/2002 1400	Private Property	Yes	100	250	450	0	510 E. Chestnut Avenue	Santa Ana	Private Property	Clean out	Blockage on sewer lateral was caused by grease and tree	Blockage on sewer lateral war caused by grease and tree	^s Santa Ana Delhi Channel	Upper Newport Bay	Upper Newport Bay	Yes - Corwin Brown	
B222/2002 1530 PWA-City of Santa Ana NA 90 450 90 2502 W. Seventeenth St. Santa Ana Private property Clean out Grease combined with surgical gloves (dential office) Santa Ana River Ocean NA Yes MA 919/2002 1350 PWA-City of Santa Ana Yes 600 300 900 600 2101 S. Paolic Ave. Santa Ana Private property Plivate property Pliv	6/25/2002 1420	Private Property - Owner not known	Contained in gutter.	375	375	575	0	421 E. 16th Street	Santa Ana	Private Property	Clean out	Grease and paper	Grease and paper	None	None	Gutter	Mohamed	
9/19/2002 1350 PWA-City of Santa Ana Ara Yes 600 300 900 600 2101 S. Pacific Ave. Santa Ana Private lateral 4" clean out spill, cause of private property spill, cause of property spill, cause of private property spill, cause of pro	8/22/2002 1630	PWA-City of Santa Ana	N/A	90	450	450	90	2502 W. Seventeenth St.	Santa Ana	Private property	Clean out	with surgical gloves	Grease combined with surgical gloves (dental office)	Santa Ana River	Ocean	N/A	Yes - Mike	
	9/19/2002 1350	PWA-City of Santa Ana	Yes	600	300	900	600	2101 S. Pacific Ave.	Santa Ana	Private lateral	4" clean out	spill, cause of	Private property spill, cause o overflow unknown.	f Santa Ana, Ana - Delhi open channel	Upper Newport Bay	N/A	Yes - Dispatcher	

10/18/2002 1840	Private Property - Mr. Wilson	Yes	800	200	200	800	210 S. Newhope Street	Santa Ana	Private Lateral	Private lateral clean out	Grease: Build up of grease in private lateral.	Build up grease in private lateral.	Entered C-5-F city channel, flowed to C 5 O.C.F.C. channel to wetlands.	East Garden Grove Winterbergs wetlands	East Garden Grove - Winterbergs wetlands	Yes - J. Antonio Islas, Jr.	
11/6/2002 1100	Private Property - Sullivan Mgmt Group Inc.	Yes	150	650	800	150	751 S. Harbor Blvd	Santa Ana	20' S. of manhole where lateral connects to sewer system.	6" sewer clean out.	Grease build up caused by lack of routine maintenance program.	Grease build up caused by lack of routine maintenance program.	Entered storm drain at 901 S. Harbor Blvd.	Santa Clara River	Ocean	Yes - Karman Cheng	
1/12/2003 1230	Private Property - Royal Holiday Mobil Park	No	0	0	0	0	215 S. Sullivan Street	Santa Ana	Private - unknown	Clean out	Grease blockage	Grease blockage	None	None	Contained on private property - sewage was recovered Minute Man Pumping Company	Yes	
3/18/2003 0825	Daniel Moran, Investors Property Services	No	0	240	300	0	1212 S. Bristol Street, Santa Ana, CA	Santa Ana	Private Spill	Clean out	Grease/Private Spill: There are several restaurants located in the shopping center that maybe dumping grease in the lateral.	There are several restaurants located in the shopping center that maybe dumping grease in the lateral.	None	None	Sewage was picked up using a vaccum truck and returned to the sewer system.	Yes	This was a private spill handled by Orange County Health.
9/30/2003 0931	American Properties, P.O. Box 3895, Newport Beach (949) 363-7255	No	0	30	50	0	718 N. Lacy Street	Santa Ana	Private lateral	Sewer lateral clean out	Roots: Private spill, plumber pulled out roots/paper.	Private spill, plumber pulled out roots and paper.	None	None	Returned to sewer system	Yes	
10/1/2003 0730	George Ganzalez (714) 957- 2529 - Private	No	0	540	1800	0	1128 S. Bristol St.	Santa Ana	Private lateral	6° clean out	lateral is a 6" line that connects to a 4" lateral at the p/l. This lateral serves a market and a	Cause of spill was a combination of large amounts of grease and the lateral is a for line that connects to a 4" lateral at the p.t. This lateral averves a market and laundroma, this lateral should be a 0" all he way to the sever main.	None	None	Returned to sewer system	Yes	
10/3/2003 1220	George Gonzalez (714) 957- 2529 - Private	No	0	180	680	0	1128 S. Bristol St.	Santa Ana	Private lateral	Clean out	Grease - Cause of overflow was the same as the spill on 10/01/03, large amounts of grease.	Cause of overflow was the same as the spill on 10/01/03, large amounts of grease.	None	None	Returned to sewer system	Yes	
10/7/2003 1100	George Gonzalez (714) 957- 2529 - Private	No	0	120	420	0	1128 S. Bristol St.	Santa Ana	Private lateral	Clean out	Grease - Large amounts of grease from market.	Large amounts of grease in market.	None	None	Returned to sewer system	Yes	
6/28/2004 1045	Noble Mgmt. Company, 747 W. Katella Avenue, Orange, CA 92867	No	150	200	0	350	325 S. Flower Street - Private Spill	Santa Ana	clean out on lateral	Clean out	Blockage/Private Property: Large amount of paper and grease flowing from clean out.	Large amount of paper and grease flowing from clean out.	None	None	Sewage was returned to sewer system.	Yes	
9/23/2004 1100	Casa Management, 13526 E. Calora, Covina, CA 91724 (818) 468-2507, Patricia Hodura	No	720	670	1220	50	1317 S. Standard	Santa Ana	Praivate lateral	4" clean out	Paper/Grease/Priva te Property	Large amounts of paper and grease geing dumped in sewer by residents and lack of a routine maintenance program.	None	None	Returned to sewer system	Yes	Cecilia Flores, Code Enforcement - 667-2710 contacted PWA-Agency regarding spill on 9/23/04 @ 11.00 am.
10/21/2004 1700	New Mark Merill Companies - Ralph Woebkey 2180 E. Lincoln Ave., Santa Ana 92806 (714) 956-3411	Yes	690	690	2660	690	2307 S. Bristol St.	Santa Ana	Private lateral	Clean out	Grease	There are several restaurants located in the shopping center that maybe discharging grease into the sewer system.	Upper Newport Bay	Upper Newport Bay	N/A	Yes	State ID #04-5508
11/4/2004 0945	South Coast Village	No	0	600	600	0	1001 W. MacArthur	Santa Ana	Unclear	Drain in laundry room	Roots	Build up of roots in sewer lateral	N/A	N/A	Returned to sewer system	Yes	
12/16/2004 1120	Royale Health Care Center	Yes	300	1600	1600	300	1027 W. Central Ave.	Santa Ana	Private sewer line	Pick hole of manhole	Grease	Large amounts of grease deposits from poor maintenance program	Upper Newport Bay	None	Returned to sewer system	Yes	State ID #04-6597
1/19/2005 0900	Property Owner	Yes	60	100	200	60	3041 S. Bristol	Santa Ana	Private lateral	4" clean out	Paper/Grease/Priva te Property	Build up of paper and grease	Santa Ana/Alton Channel	None	N/A	Yes	None
1/19/2005 1100	Property Owner	No	0	0	0	0	201 E. 4th Street	Santa Ana	Private lateral	4" clean out	Grease	Plumber said there was grease in the lateral	None	None	N/A	No	None
1/6/2006 0830	Merit Management Group (Armstrong Ranch) 800- 428-5588	Yes	540	200	500	340	3301 S. Sheffield	Santa Ana	Private property sewer system	Starter pot	Grease/ Construction/ Private Property	Combination of construction debri and grease was the cause of the spill.	Santa Ana/ Delhi Channel	Upper Newport Bay	Upper Newport Bay	Yes	
2/5/2006 1135	Private Spill - Michael Brinkman (949) 650-9100	No	0	20	30	0	825 E. Chestnut - Private Property	Santa Ana	Private Property	Clean out	Cause unknown - private property	Ran out of parking structure, down driveway to street - cause unknown	None	None	None	Yes	Fire Dept. reported spill to both OC Health/Regional Board

11/9/2006 1658	Private Property	No	0	100	225	0	614-616 E. Pine Street	Santa Ana	Unknown	Clean out on property	Unknown	Plumber who cleared the line was not sure of what caused the backup.	None	None	Sewage was picked p with Vac truck and returned to sewer system	Yes	None
11/25/2006 1100	Private Property	No	405	0	0	0	1001 W. Stevens	Santa Ana	Private lateral	Private clean out	Grease	Grease in private lateral	Santa Ana Delhi Channel	None	Upper Newport Bay	Yes	None
12/11/2006 1400	Casa Linda Condos & Montero Planning	No	350	0	0	0	300 E. Chestnut Street, 92701	Santa Ana	At pump lift station.	Pump lift station	Private lift station	The City responded to check City sewer main and found no problems. The spill was coming from the parking garage at 300 E. Chestnut. Montero Plumbing was working on the lift station pumps.	Santa Ana Delhi Channel	Upper Newport Bay	NA	Yes	None
12/27/2005 1800	City of Santa Ana	No	450	200	250	200	300 W. Second St.	Santa Ana	H09-028	Manhole cover	Grease	No maintenance program caused grease build-up and resulted in flow back-up	None	None	Sewage was contained and removed with Vactor	Yes	Affected areas were cleaned up by Aladdin Emergency Clean-up Service. Increase maintenance from the Plaza del Sol Apartment complex.
Totals	26	9	6,120	7,955	14,490	3,630										25	
Seal Beach																	
9/21/2002	Private Property	No	87	0	0	0	16th Street	Seal Beach	residential sewer lateral	lateral sewer line	n/a	blockage	none	none	Contained at OC Flood Control Pump Station, then pumped back into the Seal Beach sewer system.	yes	n/a
1/16/03; 1:19 PM	Private Spill: Rodi Properties	No	0	175	275	1	12th Street	Seal Beach	Private property; parking lot behind restaurant	Cleanout	Grease	Restaurant grease interceptor had stoppage	n/a	n/a	City Sewer System	Yes	n/a
1/3/2006 5:45	Private Spill Kobe Restaurant	Yes, OC Flood Control Basin	120	50	200	0	3001 Old Ranch Parkway	Seal Beach	private sewer main line at 3001 Old Ranch Parkway	Restaurant clean-out	Grease	Restaurant had grease interceptor cleaned 3 days prior to overflow. Cleaning may have forced grease into their main line.	Bixby Storm Chann	el n/a	Los Alamitos Basin	Yes	nía
2/10/2006	Private Property in Leisure World	na	20	<50	250	0	Nassau & Brookline Drive	Seal Beach	Main line, Oakmont	Manhole, Brookline Dr.@Nassau Dr.	Grease	n/a	n/a	n/a	n/a	n/a	Private Property Spill
Totals	4	1	227	225	725	1										3	
Stanton		· · · · · · · · · · · · · · · · · · ·															
4/18/2002 1520	PRIVATE PROPERTY OWNER	n/a	150	150	0	0	9010 STACIE LANE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE - GREASE	n/a	n/a	n/a	n/a	n/a	n/a
10/22/2002 1940	PRIVATE PROPERTY OWNER-JIM YOUNG 761- 5872	n/a	1,000	0	0	0	9021 STACIE LANE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE	n/a	n/a	n/a	n/a	n/a	n/a
12/20/02 1115	PRIVATE PROPERTY OWNER - APT COMPLEX	n/a	100	0	0	0	7330 CERRITOS AVE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE	n/a	n/a	n/a	n/a	n/a	n/a
01/02/03 1700	PRIVATE PROPERTY OWNER	n/a	150	150	0	0	7326 CERRITOS AVENUE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE - PLASTIC BAGS, PATCHING COMPOUND, HEAVY GREASE	n/a	n/a	n/a	n/a	n/a	nía
01/09/03 1800	PACIFIC WEST MGMT CO.	n/a	450	0	0	0	12057 BEACH BLVD.	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE - GREASE	n/a	n/a	n/a	n/a	n/a	n/a
02/02/03 1045	FAIRCREST APARTMENTS	n/a	10,400	8,000	0	0	FERN AND CERRITOS	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE	n/a	n/a	n/a	n/a	n/a	n/a
3/1/03 0:00	PRIVATE PROPERTY OWNER - BURGER KING	n/a	300	100	0	0	12550 BEACH BLVD.	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE	n/a	n/a	n/a	n/a	n/a	n/a
Totals	7	0	12,550	8,400	0	0											
YLWD																	
11/14/02 1300	Private Party, Maguroya Japanese Restaurant located in the Yorba Station shopping center.	N	100	100	200	0	Yorba Station Shopping Center 18242 Imperial Hwy	Yorba Linda	Grease interceptor outside and behind restaurant	plugged interceptor device	grease	cooking grease in unmaintained grease interceptor.	n/a	n/a	n/a	Yes	This was a private property overflow. The local health services agency addressed the restaurant management.
Totals	1	0	100	100	200	0										1	
Yorba Linda																	
Yorba Linda																	

OCHCA																	
5/27/02 0:00	Private Property	ves	0	0	0	0	na	na	na	na	na	na	na	Newport Bay		yes	California Pizza Kitchen. Not listed in supplied OCHCA report or on Region 8
9/28/02 0:00	Private	- '	0	0	0	0	6 LOS OLIVOS	IRVINE	N/A	LINE BREAK	LINE BREAK	STREET CURB AND	N/A	N/A	N/A	Yes	reports May be R-9
11/30/02 0:00	Denny's Resturant	yes	165	35	0	0	n/a	n/a	Line blockage	Line Blockage	Line blockage	n/a	Santa Ana River	Pacific Ocean	n/a	yes	(Not in originally submitted OCHCA report or Region 8 reports. Listed in OCHCA Beach Closure report)
1/18/03 0:00	Private		4680	0	0	0	WINDROW COMMUNITY PARK	IRVINE	N/A	LINE BREAK	LINE BREAK	STREET, CURB, GUTTER AND INTO STORM DRAIN	N/A	N/A	N/A	Yes	Beach Closure report) May be R-9
8/1/03 0:00	Private		2500	0	0	0	MAIN & MAC ARTHUR	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN TO LANE	N/A	N/A	N/A	Yes	
8/3/03 0:00	Private	Yes	180	0	0	0	#7 ASPEN TREE LANE	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN TO SAN	SAN JOAQUIN CHANNEL	N/A	N/A	Yes	May be R-9
9/15/03 0:00	Private		19	20	0	0	2451 ELDEN AVE	COSTA MESA	N/A	LINE BREAK	LINE BREAK	STREET, CURB AND GUTTER AND INTO STORM	-	N/A	N/A	Yes	N/A
												DRAIN. ALL SEWAGE WAS					
10/14/03 0:00	Private	No	0	60	0	0	701 OCEAN	SEAL BEACH	N/A	LINE BREAK	LINE BREAK	CONTAINED ON SITE AND RETURNED TO SEWER.	N/A	N/A	RETURNED TO SEWER	Yes	N/A
12/5/03 0:00	Private	No	0	75	0	0	CAMPUS & CARLSON	IRVINE	N/A	LINE BREAK	LINE BREAK	ALL SEWAGE WAS CONTAINED.	N/A	N/A	N/A	Yes	N/A
4/13/04 0:00	Private		3000	0	0	0	NEWPORT COAST DR	NEWPORT BEACH	N/A	LINE BREAK	LINE BREAK	STORM DRAIN	N/A	N/A	N/A	Yes	NA
8/29/04 0:00	Private		9450	0	0	0	DEWBERRY / SANDBURG	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN.	N/A	N/A	N/A	Yes	NA
11/5/04 0:00	Private		150	0	0	0	STANFORD AT NELSON	GARDEN GROVE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN.	N/A	N/A	N/A	Yes	NA
11/17/04 0:00	Private	No	0	50	0	0	108 30TH STREET	NEWPORT BEACH	N/A	LINE BREAK	LINE BREAK	ALL SEWAGE WAS RECOVERED.	N/A	N/A	N/A	Yes	N/A
1/17/05 0:00	Private		20	0	0	0	250 CHANNEL ROAD	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	GUTTER	N/A	N/A	N/A	Yes	N/A
1/31/05 0:00	Private		0	0	0	0	4362 LINCOLN	CYPRESS	N/A	N/A	BLOCKAGE - UNKNOWN		N/A	N/A	N/A	Yes	NA
2/7/05 0:00	Private		0	0	0	0	233 CARNATION	NEWPORT BEACH	N/A	N/A	UNKNOWN	ON-SITE	N/A	N/A	N/A	Yes	NA
2/20/05 0:00	Private		50	0	0	0	905 IDAHO ST.	LA HABRA	N/A	N/A	GREASE	MANHOLE TO CURB AND GUTTER TO STORM DRAIN.	N/A	N/A	N/A	Yes	NA
2/26/05 0:00	Private		500	0	0	0	13011 NEWPORT	TUSTIN	N/A	N/A	BLOCKAGE - UNKNOWN	STORM DRAIN	N/A	N/A	N/A	Yes	N/A
3/1/05 0:00	Private	Yes	0	0	0	0	453 SUMMERFIELD CIRCLE	ANAHEIM	N/A	N/A	GREASE	STORM DRAIN -> EAST GARDEN GROVE WINTERSBERG CHANNEL - > LOWER BOLSA	WINTERSBERG CHANNEL	N/A	N/A	Yes	N/A
3/5/05 0:00	Private		40	0	0	0	540 FREEDOM	ORANGE	N/A	N/A	BLOCKAGE - UNKNOWN	STORM DRAIN/STREET	N/A	N/A	N/A	Yes	NA
3/20/05 0:00	Private	Yes	350	150	0	0	745 DOVER	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	PRIVATE CLEAN OUT TO PARKING LOT TO STORM DRAIN TO NEWPORT BAY	Newport Bay	N/A	N/A	Yes	N/A
3/26/05 0:00	Private	No	5	0	0	0	2212 S. MONTE VISTA	LA HABRA	N/A	N/A	BLOCKAGE - UNKNOWN	ALL DISCHARGE CONTAINED ON SITE.	N/A	N/A	N/A	Yes	NA
4/29/05 0:00	Private		100	0	0	0	6300 REGIO	BUENA PARK	N/A	LINE BREAK	LINE BREAK	STORM DRAIN.	N/A	N/A	N/A	Yes	NA
5/7/05 0:00	Private		0	0	0	0	4941 LA PALMA AVENUE	LA PALMA	N/A	N/A	GREASE	GUTTER TO STORM DRAIN	N/A	N/A	N/A	Yes	N/A
7/1/05 0:00	Private		0	0	0	0	2735 W. COAST HWY.	NEWPORT BEACH	N/A	N/A	GREASE	N/A	N/A	N/A	N/A	Yes	N/A
7/23/05 0:00	Private		0	4	0	0	1016 IRVINE AVENUE	NEWPORT BEACH	N/A	N/A	PAPER	PARKING LOT/DRIVEWAY	N/A	N/A	N/A	Yes	N/A
8/5/05 0:00	Private		65	0	0	0	8699 HILLCREST	BUENA PARK	N/A	N/A	CLEAN-OUT CAP MISSING	CLEAR WATER TO STORM DRAIN.	N/A	N/A	N/A	Yes	N/A
8/9/05 0:00	Private		0	50	0	0	1101 N. BAYFRONT	NEWPORT BEACH	N/A	N/A	PAPER	ALLEYWAYS	N/A	N/A	N/A	Yes	N/A
8/14/05 0:00	Private		0	5	0	0	1311 W. BAY	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	ALLEY	N/A	N/A	N/A	Yes	N/A
8/14/05 0:00	Private		0	2	0	0	1817 BEDFORD ROAD	NEWPORT BEACH	N/A	N/A	ROOTS	GUTTER	N/A	N/A	N/A	Yes	N/A
8/16/05 0:00	Private		0	0	0	0	6885 WARNER AVENUE	HUNTINGTON BEACH	H N/A	N/A	GREASE	STORM DRAIN WITH DIVERSION.	N/A	N/A	N/A	Yes	N/A

8/23/05 0:00 Private	No	0	15	0	0	28232 BEACH BLVD.	HUNTINGTON BEACH	N/A	N/A	ROOTS	CONTAINED IN CURB AND GUTTER	N/A	N/A	N/A	Yes	N/A
9/7/05 0:00 Private		2340	0	0	0	30 SCENIC BLUFF	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN TO CREEK	N/A	N/A	N/A	Yes	May be R-9
9/18/05 0:00 Private	No	0	100	0	0	310 S. JEFFERSON	PLACENTIA	N/A	N/A	BLOCKAGE - UNKNOWN	STAYED ON SITE	N/A	N/A	N/A	Yes	N/A
10/18/05 0:00 Private		400	425	0	0	18555 YORBA LINDA BLVD.	YORBA LINDA	N/A	N/A	BLOCKAGE - UNKNOWN	CURB & GUTTER -> STORM DRAIN	N/A	N/A	N/A	Yes	N/A
10/20/05 0:00 Private	Yes	29	50	0	0	17199 BLUEWATER LANE	HUNTINGTON BEACH	N/A	N/A	ROOTS & GREASE	MANHOLE TO SIDEWALK TO BULKHEAD TO BAY WATER	N/A	N/A	N/A	Yes	N/A
11/6/05 0:00 Private	No	0	80	0	0	1530 PLACENTIA	NEWPORT BEACH	N/A	N/A	GREASE	CONTAINED ON SITE	N/A	N/A	N/A	Yes	N/A
11/8/05 0:00 Private	No	0	0	0	0	20142 MCKINLEY LANE	HUNTINGTON BEACH	N/A	LINE BREAK	LINE BREAK	SOAKED INTO SOIL	N/A	N/A	N/A	Yes	N/A
11/20/05 0:00 Private		0	20	0	0	1101 PINE STREET	HUNTINGTON BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	N/A	N/A	N/A	Yes	N/A
12/9/05 0:00 Private		0	0	0	0	2085 N. HIGHLAND	ORANGE	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	N/A	N/A	N/A	Yes	N/A
12/14/05 0:00 Private	Yes	143	2	0	0	8052 ADAMS	HUNTINGTON BEACH	N/A	N/A	GREASE	STORM DRAIN -> TALBERT CHANNEL (DIVERTED TO SEWER SYSTEM)	TALBERT CHANNEL	N/A	N/A	Yes	NA
12/20/05 0:00 Private		0	0	0	0	2208 DELAWARE	HUNTINGTON BEACH	N/A	LINE BREAK	LINE BREAK	N/A	N/A	N/A	N/A	Yes	WA
12/27/05 0:00 Private	No	0	5	0	0	18302 GOTHARD	HUNTINGTON BEACH	N/A	N/A	ROOTS	VACUMMED UP FROM GUTTER	N/A	N/A	N/A	Yes	N/A
1/7/06 0:00 Private	No	0	120	0	0	1200 PACIFIC COAST HIGHWAY	HUNTINGTON BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	CLEAN OUT TO PARKING GARAGE FLOOR TO CONTAINED.	N/A	N/A	N/A	Yes	N/A
1/10/06 0:00 Private		0	0	0	0	104 EDINGER	HUNTINGTON BEACH	N/A	N/A	GREASE	N/A	N/A	N/A	N/A	Yes	NA
1/10/06 0:00 Private		0	0	0	0	1200 PACIFIC COAST HIGHWAY	HUNTINGTON BEACH	N/A	LINE BREAK	LINE BREAK	N/A	N/A	N/A	N/A	Yes	N/A
1/10/06 0:00 Private	No	0	0	0	0	2321 S. BRISTOL	SANTA ANA	N/A	N/A	BLOCKAGE - UNKNOWN	CONTAINED IN PARKING LOT	N/A	N/A	N/A	Yes	N/A
1/10/06 0:00 Private		0	500	0	0	5812 EDINGER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE & DEBRIS	PARKING LOT	N/A	N/A	N/A	Yes	N/A
1/20/06 0:00 Private		250	100	0	0	9882 ADAMS BLVD	HUNTINGTON BEACH	N/A	N/A	GREASE	CLEAN OUT TO PARKING LOT TO CURB AND GUTTEF TO STORM DRAIN.	N/A	N/A	N/A	Yes	N/A
1/24/06 0:00 Private	No	0	1000	0	0	12705 NEWBROOK	STANTON	N/A	N/A	BLOCKAGE - UNKNOWN	ALL DISCHARGE WAS RECOVERED AND RETURNED TO SEWER SYSTEM.	N/A	N/A	Sewer system	Yes	N/A
1/25/06 0:00 Private		0	0	0	0	1205 NEWBROOK	STANTON	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	N/A	N/A	N/A	Yes	N/A
1/25/06 0:00 Private	No	0	0	0	0	770 S. PLACENTIA AVENUE	PLACENTIA	N/A	N/A	BLOCKAGE - UNKNOWN	CURB/GUTTER -> COLLECTION	N/A	N/A	N/A	Yes	N/A
1/27/06 0:00 Private	No	0	2000	0	0	4600 BISON AVENUE (UCI)	IRVINE	N/A	N/A	BLOCKAGE - UNKNOWN	PONDED IN A PIT ON CAMPUS SITE.	N/A	N/A	N/A	Yes	N/A
1/28/06 0:00 Private	Yes	10800	0	0	0	5238 MICHELSON	IRVINE	N/A	N/A	ROOTS	MASON CREEK AND SAN DIEGO CREEK TO UPPER NEWPORT BAY	MASON CREEK AND SAN DIEGO CREEK	UPPER NEWPORT BAY	N/A	Yes	May be R-9
2/25/06 0:00 Private		100	0	0	0	107 ROCKWELL	IRVINE	N/A	N/A	BLOCKAGE - UNKNOWN	CONTAINED IN PLANTER.	N/A	N/A	N/A	Yes	May be R-9
4/5/06 0:00 Private	Yes	400	200	0	0	7850 SLATER AVENUE	HUNTINGTON BEACH	NA	N/A	GREASE	HUNTINGTON CENTRAL PARK LAKE - WILL POST SOME CLOSURE SIGNS AT DRAIN ENTRY TO LAKE FOR A FEW DAYS - INCIDENTAL CONTACT LAKE.	HUNTINGTON CENTRAL PARK LAKE	N/A	NA	Yes	NA
4/11/06 0:00 Private	Yes	15	160	0	0	7402 EDINGER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE	CONTROL CHANNEL (EAST GARDEN GROVE	EAST GARDEN GROVE WINTERSBERG CHANNEL	N/A	N/A	Yes	NA
4/24/06 0:00 Private	No	0	400	0	0	23691 ROCKFIELD	LAKE FOREST	N/A	LINE BREAK	LINE BREAK	SEWAGE CONTAINED ON SITE.	N/A	N/A	N/A	Yes	May be R-9
4/25/06 0:00 Private		50	100	0	0	21372 BROOKHURST	HUNTINGTON BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	STORM DRAIN	N/A	N/A	N/A	Yes	N/A
5/8/06 0:00 Private	No	0	300	0	0	23691 ROCKFIELD	LAKE FOREST	N/A	LINE BREAK	LINE BREAK	SEWAGE CONTAINED ON SITE.	N/A	N/A	N/A	Yes	May be R-9
· · · · ·	· · · · ·					*										*

5/27/06 0:00	Private	No	0	0	0	0	10001 N. FLOWER STREET	SANTA ANA	N/A	LINE BREAK	LINE BREAK	CONTAINED ON SPILL LOCATION	N/A	N/A	N/A	Yes	N/A
6/6/06 0:00	Private	No	0	100	0	0	441 GOLDENROD AVENUE	NEWPORT BEACH	N/A	N/A	ROOTS	CURB & GUTTER (CONTAINED AND CLEANED UP)	N/A	N/A	N/A	Yes	NA
6/12/06 0:00	Private		200	1800	0	0	3101 W. PACIFIC COAST HIGHWAY	NEWPORT BEACH	N/A	N/A	PUMP STATION FAILURE	STORM DRAIN -> NEWPORT BAY AT "MARINER MILE" MARINA DOCKS (3101 W. COAST HIGHWAY)	N/A	N/A	N/A	Yes	NA
6/14/06 0:00	Private	No	0	0	0	0	10631 LOS ALAMITOS	LOS ALAMITOS	N/A	LINE BREAK	LINE BREAK	SEWAGE DISCHARGED SUBSURFACE AND INTO DECORATIVE KOI POND.	N/A	N/A	N/A	Yes	N/A
7/4/06 0:00	Private	No	0	20	0	0	1723 E. OCEANFRONT	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	CURB & GUTTER - CONTAINED BY CITY CREW	N/A	N/A	N/A	Yes	N/A
7/6/06 0:00	Private		30	370	0	0	745 DOVER	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	PPO CLEAN OUT TO PARKING LOT TO STORM DRAIN.	N/A	N/A	N/A	Yes	N/A
8/5/06 0:00	Private	Yes	300	0	0	0	24401 MUIRLANDS	LAKE FOREST	N/A	N/A	GREASE	GREASE INTERCEPTOR TO PARKING LOT TO STORM DRAIN TO SAN DIEGO CREEK (DRY).	SAN DIEGO CREEK (DRY)	N/A	N/A	Yes	May be R-9
9/23/06 0:00	Private		0	0	0	0	4672 PLUMOSA DRIVE	YORBA LINDA	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	N/A	N/A	N/A	Yes	N/A
9/28/06 0:00	Private	Yes	25	0	0	0	Grant Street	Newport Beach	n/a	n/a	n/a	n/a	Nwport Slough	Santa Ana River	n/a	yes	(Listed only on the OCHCA Beach Closure Report)
10/5/06 0:00	Private	No	0	20	0	0	703 POPPY	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	YARD -> CURB & GUTTER - > ALL FLOW CONTAINED	N/A	N/A	N/A	Yes	N/A
10/16/06 0:00	Private	Yes	200	0	0	0	610 NEWPORT CENTER DRIVE	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	SEWAGE DISCHARGED TO STORM DRAIN AND INTO NEWPORT BAY	NEWPORT BAY	N/A	N/A	Yes	N/A
10/19/06 0:00	Private	No	0	8	0	0	23472 LOS ADORNOS	UNINCORPORATED COUNTY	N/A	N/A	ROOTS	ALL DISCHARGE WAS CAPTURED AND RETURNED TO SEWER.	N/A	N/A	RETURNED TO SEWER	Yes	N/A
10/21/06 0:00	Private		0	0	0	0	1139 / 1125 CERRITOS DR	FULLERTON	N/A	N/A	BLOCKAGE - UNKNOWN	PRIVATE CLEANOUT TO PRIVATE PROPERTY TO DIRT TRACK TO STORM DRAIN.	N/A	N/A	N/A	Yes	NA
10/30/06 0:00	Private		0	0	0	0	710 WASHINGTON AVENUE	SANTA ANA	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	N/A	N/A	N/A	Yes	N/A
11/11/06 0:00	Private		100	0	0	0	602 CHAPMAN	PLACENTIA	N/A	N/A	BLOCKAGE - UNKNOWN	PARKING LOT -> CURB AND GUTTER (NO BACK UP INTO RESTAURANTS ACCORDING TO CITY CREW)	N/A	N/A	N/A	Yes	Resturant
11/22/06 0:00	Private		0	0	0	0	235 W. LINCOLN	ORANGE	N/A	N/A	BLOCKAGE - UNKNOWN	SANTIAGO APARTMENTS - BY TRASH AREA NEXT TO LAUNDRY ROOM	N/A	N/A	N/A	Yes	N/A
11/25/06 0:00	Private		0	0	0	0	24371 EL TORO ROAD	LAKE FOREST	N/A	N/A	GREASE	CURB & GUTTER -> STORM DRAIN	N/A	N/A	N/A	Yes	May be R-9
12/20/06 0:00	Private	Yes	100	200	0	0	CHAPMAN/STATE COLLEGE	FULLERTON	N/A	N/A	CONSTRUCTION DEBRIS	PARKING LOT CLEAN OUT TO STREET, CURB AND GUTTER TO STORM DRAIN TO FULLERTON CHANNEL.	FULLERTON CHANNEL	N/A	N/A	Yes	NA
12/30/06 0:00	Private		0	0	0	0	4232 KATELLA	LOS ALAMITOS	N/A	N/A	GREASE INTERCEPTOR	STREET -> CURB & GUTTER	N/A	N/A	N/A	Yes	Denny's resturant
Totals	79	13	36,756	8,546	0	0										79	
TOTALS	689	108	208,254	149,389	129,007	49,435										502	

APPENDIX B

Modified Master Private Property Spills 2002–2006 Sorted by Date

Date SSO is First Reported to Responding Agency	Responsible Party	Did SSO reach surface waters other than a storm drain?	SSO Volume Lost (Gallons)	Recovered SSO Volume (Gallons)	Recovered wash Water & Sewage Contaminated Water Volume	Lost Wash Water & Sewage Contaminated Water Volume	Location of overflow: Street	Location of overflow: City	Location of potential blockage or problem point	Description of component from which spill occurred	Likely cause of SSO	Overflow Cause - Detailed Description	Name or Description of Initial Receiving Water	Name or Description of Secondary Receiving Water	If the SSO did not reach surface waters, describe the final destination of sewage	Was the Local Health Services Agency Notified?	Remarks
2002																	
4/2/02	Private	Unknown	0	0	0	0	2325 E. PCH	Newport Beach	Grease Interceptor	Grease Interceptor	Unknown	See Remarks	n/a	n/a	n/a	yes	Grease interceptor was overflowing (Brio Rest)
4/4/02	Private Property	Ν	25	0	0	25	1634 La Loma Dr.	Santa Ana	4" Sewer Line	Cleanout	Blockage	Misc. debris	NA	NA	Soaked into ground	U	NA
4/15/02	Private Property	Ν	0	0	0	0	12622 Kingsview Rd.	Unincorporated County of Orange	4* Sewer Line	U	Blockage	U	NA	NA	Soaked into ground	NA	NA
4/18/02	PRIVATE PROPERTY OWNER	n/a	150	150	0	0	9010 STACIE LANE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE GREASE	n/a	n/a	n/a	n/a	n/a	n/a
4/19/02	Private Property	Ν	10	8	8	2	18802 Bardeen Ave.	Irvine	4" Sewer Line	V-drain	Blockage	Root obstruction in lateral line & Possible Broken Lateral	NA	NA	υ	Y; 4/19/2002 9:00:00 AM	NA
4/23/02	Private Property	n/a	1281	150	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a	n/a	n/a	Yes	n/a
4/27/02	Private Property -Beachwalk Condominiums	No	675	350	0	0	19801 Shorecliff Lane	Huntington Beach	In the street at 19801 Shorecliff Lane.	4" Clean Out Lid	Grease	A buildup of grease in the line, probably caused by insufficient maintenance.	None	None	This storm drain pooled up on the sand at the beach, was vacuumed up, liquids drained into the sewer and solids disposed of at OCSD.	Yes	
5/2/02	Sunbridge Care Center For Fullerton, private property	No	20	60	0	0	2800 N Harbor Blvd	Fullerton	Private lateral	Private lateral cleanout	Unknown blockage on private property	N/A	N/A		80 gal returned to sewer system by City of Fullerton crew, 20 gal lost to storm drain. Contact private property owner for additional cleanup information	Y	Private four tech sever lateral backed up and vented out of channot on private property. Severage flowed onto City essement and a small amount of severage entered the storm drain. City crews responded and contained split. City crews notified maintenance m
5/13/02	RS Properties Mgt. Private property	No	30	90	40	0	4050 W Franklin Ave	Fullerton	Private lateral	Private lateral cleanout	Unknown blockage on private property	N/A	N/A		90 gal returned to sewer system, 30 gal released to the environment	Y	Private four inch sewer lateral backed up and vented out of cleanout on private property. The city contained sewage. The Management Co called private plumber (Rick the Happy Pumber) to clear blockage. The City washed down and vacuumed sewage and retur
05/27/02	Private Property	yes	0	0	0	0	na	na	na	na	na	na	na	Newport Bay		yes	California Pizza Kitchen. Not listed in supplied OCHCA report or on Region 8 reports
6/6/02	Private Property	Yes	340	240	580	0	4117 W. McFadden Avenue	Santa Ana	Private Property	Clean out	Grease - Private Property. City of Santa Ana installed a siphon to make way for a storm drain system on the lateral. Spill occurred due to grease build up.	The City of Santa Ana installed a siphon to make way for a storm drain system on the lateral, the siphon backed up due to grease.	East Garden Grove Wintersberg C-05 Channel	Wetlands	n/a	Yes - Monica Mazar	
6/17/02	Private Property -Beachwalk Condominiums	No	45	45	50	0	19771 Coastline Lane	Huntington Beach	In the street at 19771 Coastline Lane.	Manhole lid	Grease	A buildup of grease in the line, probably caused by insufficient maintenance.	None	None	Spill was contained on the street using a dam, vacuumed up by a private company and placed back into the sewer.	Yes	
6/21/02	Private Property	n/a	0	0	0	0	2220 S. Monte Vista	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
6/24/02	Private Property	Yes	100	250	450	0	510 E. Chestnut Avenue	Santa Ana	Private Property	Clean out	Grease and Roots: Blockage on sewer lateral was caused by grease and tree roots.	Blockage on sewer lateral was caused by grease and tree roots.	Santa Ana Delhi Channel	Upper Newport Bay	Upper Newport Bay	Yes - Corwin Brown	
6/25/02	Private Property - Owner not known	Contained in gutter.	375	375	575	0	421 E. 16th Street	Santa Ana	Private Property	Clean out	Grease and paper	Grease and paper	None	None		Yes - Mohamed Babielivari	
6/28/02	Private Property	n/a	0	0	0	0	631 S. Palm	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
6/30/02	Private Property	Y	300	0	0	0	3rd St & French St.	Santa Ana	Private property lateral	Cleanout	Blockage Grease clog	Not applicable - Not OCSD SSO	Not applicable - Not OCSD SSO	Not applicable - Not OCSD SSO	Not applicable - Not OCSD SSO	Not applicable - Not OCSD SSO	Called Don Cleveland to respond and evaluate, due to no response from Santa Ana Public Works. Don Cleveland arrived at this location at 1015 hour. City of Santa Ana Firo Department rrived onsite before 9am. A private plumber also responded to the site
7/2/02	Hamilton Pacific	yes	50	750	0	0	15622 Brookhurst Westminster	Westminster			grease	grease on private property	n/a	n/a			

7/6/02	Costa Mesa Sanitary District	N	300	300	500	0	1936 Wallace, Costa Mesa, CA	Costa Mesa, CA	Private Lateral	Private Lateral Cleanout	Blockage in Private lateral line	NA	NA	NA	Sewage and rinse water vactored and returned to sewer system	NO	Sewage from private residential lateral spilled into street when private contractor deared residential lateral and cleanout. All sewage contained in street. Approx 2.5 gpm into street * 120 minutes yields 300 gals spilled. Field crew dammed sewage spill.
7/6/02	Rich Darling - Private Property	No	90	60	450	0	16490 Bolsa Chica Street	Huntington Beach	In the parking lot at 16490 Bolsa Chica Street.	Clean Out	Debris	Debris built up in the line, causing the blockage.	None	None	Spill was contained using a contaiment berm and diverted back into sewer.	Yes	Statements were obtained from employee's of Jon's Coffee Shop. Line was cleared before City crews arrived.
7/10/02	Private	n/a	480	20	0	0	25521 Commercenter	Lake Forest	n/a	n/a	Construction debris	Construction debris	n/a	n/a	n/a	n/a	
7/10/02	Private	N	1215	1215	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/15/02	Private Property	N	0	0	0	0	1841 VON KARMAN	Irvine Buisness Complex	Private lateral	Indoors	N/A	N/A	None	N/A	N/A	N/A	Walt reports blockage cleared before his arrival, plumber at location. OCSD lines are running free and clear. No assistance needed.
7/21/02	Private	n/a	1500	0	0	0	East Shore & East Yale Loop	Irvine	n/a	n/a	n/a	Unknown	n/a	n/a	n/a	n/a	
7/22/02	Trans Pacific Management Services - Private Property	No	50	50	150	0	17152 Pacific Coast Highway	Huntington Beach	17152 Pacific Coast Highway	Laundry Room Drain	Grease, Debris	Appears to be lack of maintenance - grease and debris was found blocking the line.	None	None	Spill was contained using a contaiment berm and diverted back into sewer.	Yes	Cleanup was delayed because of lack of a representative from management company. Cleanup was haited until a board member approved the work.
7/23/02	Private	Ν	98	98	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/25/02	Costa Mesa Sanitary District	N	25	25	1000	0	Marie Callender's;363 East 17th St, Costa Mesa, CA	Costa Mesa, CA	Private Lateral	Private Lateral Cleanout	Blockage: Grease in private lateral	NA	NA	NA	Sewage and rinse water vactored and returned to sewer system	NO	Marie Callender's private lateral blocked with grease: Rescue Rooter opened a 4° cleanout to clear the line; When opened, sewage spilled out from the sidewalk cleanout onto the street and curb for approx 10 minutes while contractor cleared the lateral lin
7/30/02	Private	Unknown	10	10	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/30/02	Private	No	150	150	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/30/02	Private	No	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/30/02	Private	Y	450	120	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/30/02	Private	N	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/30/02	Private	N	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/31/02	Private	N	165	165	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
8/1/02	Private	N	50	50	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
8/3/02	Private Property	n/a	0	0	0	0	2220 S. Monte Vista	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
8/3/02	Private Property	N/A	0	0	0	0	2220 MONTE VISTA AVE VISTA APARTMENTS	La Habra	N/A	N/A	N/A	N/A	N/A	N/A	NA	Y	CALLED LA HABRA POLICE TO CONTACT WATER DEPT. ALSO CALLED OUT DIV. 400 STANDBY. UPON ARRIVAL. STANDBY VERIFIED THAT CITY OF LA HABRA HAD CONTANED THE SOX SOX NO LONGER FLOWING, AND NO FLOW WAS GOING TO PUBLIC STREET. PROBLEM CONTAINED ON PRIVATE PROVERT
8/4/02	Brea	N	200	200	250	0	650 Tamarack	Brea	Sewer	Manhole	paper products	NA	NA	NA	n/a	Y	The property management and Larry honeybourne from OC Health dept were on site at time of the sewer stoppage. Apartment management phone # 714.990.0150
8/9/02	Private	n/a	0	0	0	0	5465 Alton Pkwy.	Irvine	n/a	n/a	Illegal connection to storm drain	Illegal connection to storm drain	n/a	n/a	n/a	n/a	
8/14/02	Gas Station	No	12	12	20	0	20002 Beach Blvd.	Huntington Beach	In the sidewalk alongside 20002 Beach Blvd	Clean Out	Debris	A gas station sewer line had become plugged by paper towels.	None	None	Spill was contained within the catch basin, vacuumed up by a private cleaning company and placed back into the sewer.	Yes	
8/16/02	La Palma Hospital, private property	No	0	0	0	0	7901 Walker Street	La Palma	Private lateral	Manhole	Unknown blockage on private property	N/A	N/A		Returned to sewer system	Y	Private sewer lateral backed up and vented out of a manhole on private property. Sewage flowed onto City gutter and a small amount of sewage entered the storm drain. City of La Palma Public Works Duty man responded and contained spill. City staff not
8/18/02	Private	Yes	2250	10	25	0	4752 Pearce Street	Huntington Beach	In front of 4752 Pearce Street.	Clean Out	Debris, Blockage		Heil Channel, Christiana Bay, Huntington Harbor	Pacific Ocean		Yes	Orange County Health, Michael Fennessy stated he recovered samples of affected waters.

8/22/02	PWA-City of Santa Ana	N/A	90	450	450	90	2502 W. Seventeenth St.	Santa Ana	Private property	Clean out	Grease combined with surgical gloves (dental office)	Grease combined with surgical gloves (dental office) Santa A	Ana River	Ocean	N/A	Yes - Mike Haller	
8/29/02	Jimni Service	Yes	528	100	50	0	20896 Seacoast	Huntington Beach	At the intersection of Beachcomber and Coastwatch	Manhole	Vandalism	Someone turned off power to pump station, causing the overflow.		None	Water went into Atlanta Storm Station which is currently being diverted to the sewer system.	Yes	Jimni Service cleaned up the spill and checked the pump station.
9/16/02	CITY OF ANAHEIM	NO	200	200	300	0	1511 N. Euclid Ave.	Anaheim	Clean out at back alley of 'Super Torta'	private clean out	grease; possible lint	grease and possible lint N/A	1	N/A	ponded in gutter	YES	
9/16/02	Private	Ν	100	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
9/17/02	El Pollo Loco Restaurant, 1941 Harbor Blvd, Costa Mesa, CA 92526	N	0	0	0	0	1941 Harbor Blvd	Costa Mesa, CA	Grease blocked El Pollo Loco grease trap and cleanout.	El Pollo Loco grease trap and cleanout in sidewalk between facility and drive-thru.	Grease blocked El Pollo Loco grease trap and cleanout	Grease blocked El Pollo Loco grease trap and cleanout, causing overflow across sidewalk, across drive thru, into alley down Bernard St gutter and into Harbor Blvd storm drain.			El Pollo Loco contractor and District Field Crew vactored Sewage and rinse water, returned to sewer system	Yes	Grease blocked EI Polio Loco grease trap and cleanout, causing overflow across sidewalk, across drive thru, into aley down Bernard St gutter and into Harbor BM storm drain. EI Polio Loco contractor cleared grease trap and facility inside lines, but ove
9/17/02	Private Management Company	No	0	0	0	0	1815 W Malvern Ave	Fullerton	Private Lateral	Private four inch cleanout	Roots and Toilet debris	Unknown N/A		N/A	Unknown	N	On 9/16/02 Unit 340 (emerg night crew) responded to a report of a private sewer problem, private plumber was on scene, no overflow observed. On 9/17/02 Jorge Gonzales (acting sanitation specialist) followed up by inspecting problem site and observed sewa
9/18/02	Private: Lusardi Development	NO	0	50	50	0	Harbor Blvd. N/O Ball Rd.	Anaheim	Sewer line break at Giannelli Electric, Harbor Blvd. N/O Ball Rd.	sewer line	Break in sewer line	Sewer line break at Giannelli Electric		N/A	N/A	YES	
9/18/02	Private Sewer Lateral	No	20	0	0	0	Behind 1730 Raintree Rd	Fullerton	Private Lateral	Private four inch lateral	Roots	Roots N/A		N/A	Sewage soaked into dirt. Area was cordoned off and scarified.	N	City Employees Gonzalez, Bair and Miller responded with pickup truck and flatbed truck to private lateral overflow. City crew contained spill, cleared blockage, cordoned off area and scarified approximately twenty feet of bridle trail. Service Request #02
9/18/02	Private Property	yes	0	0	0	0	6234 Industrial Way Westminster	Westminster			grease & roots	grease & roots on private n/a property	1	n/a	storm drain in Huntington Beach		
9/19/02	PWA-City of Santa Ana	Yes	600	300	900	600	2101 S. Pacific Ave.	Santa Ana	Private lateral	4" clean out	Private property spill, cause of overflow unknown.	Private property spill, cause of Santa A overflow unknown. Delhi op	Ana, Ana - open channel	Upper Newport Bay	NA	Yes - Dispatcher	
9/21/02	Private Property	No	87	0	0	0	16th Street	Seal Beach	residential sewer lateral	lateral sewer line	n/a	blockage none			Contained at OC Flood Control Pump Station, ther pumped back into the Seal Beach sewer system.		nia
9/26/02	Private: Seris Regio Group	YES	200	20	70	200	2050 Winston Rd.	Anaheim	cleanout near center of drive area at 2050 Winston Rd.	clean out onsite	break in the private sewer lateral	broken lateral in private sewer Santa A	Ana River		N/A	YES	Property owner was notified of spill at 2:00 on 9/26/02 and was told the line would have to be cleaned immediately. Private plumber did not show up until the 27th. Due to difficulties cleaning the line it was determined there was a break in the private
9/28/02	Private		0	0	0	0	6 LOS OLIVOS	IRVINE	N/A	LINE BREAK	LINE BREAK	STREET CURB AND GUTTER, STORM DRAIN		N/A	N/A	Yes	May be R-9
9/30/02	Private	N	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
9/30/02	Private	N	54	54	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
10/5/02	Private	N	30	30	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
10/9/02	Hannam Market, private property	No	0	0	0	0	4875 La Palma Ave.	La Palma	Private lateral	Manhole	Grease blockage on private property	Grease blockage on private N/A property		N/A	Returned to sewer system	Y	Private contractor sanitized and cleaned up
10/12/02	Harbor Breeze Apartments	Yes	5,400	100	600	0	4841 Heil	Huntington Beach	4841 Heil	Cleanout-Manhole	Grease	Grease had built up in the line, probably due to lack of maintenance	e County Control	Huntington Harbour	N/A	Yes	
10/17/02	Private: Twin Pines Apts.	NO	5028	4800	8800	5028	2880 W. Ball Road	Anaheim	Blockage in lateral	private clean outs	Grease buildup	Grease buildup N/A		N/A	Contained within storm drain system	YES	Sewage was vacuumed up downstream in storm drain sump area in the City of Stanton. Vaccuming continued until little or no flow was observed entering sump area.
10/17/02	Koo Koo Roo Restaurant, 212 E 17h Si, Costa Mesa, CA 92627	N	120	120	170	0	17th St between Orange Avenue and Westminster	Costa Mesa, CA	Koo Koo Roo Restaurant lateral , blocked with grease and paper towels	Koo Koo Roo Restaurant lateral cleanout	Grease and paper towels blocked Koo Koo Roo Restaurant lateral.	Grease and paper towels blocked Koo Koo Roo Restaurant latenal, causing SSO into E 17th St curb and gutter.		NA	120 gallons of SSO spilled out of the lateral cleanout into the 17th St gutter - an completely contained & vactored. Crew flushed sp area with 50 gallons of fres water, also vactored and emptied into the sewer system.	ii No	Main line running clear; Koo Koo Roo contracted plumber cleaned out private lateral; grease blockage cleared from lateral line into District Main Line; Crew contained SSO upon arrival; vactored SSO, flushed area with 50 gals fresh water and vactored up ri
10/17/02	Private	N	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	

10/18/02	Private Property - Mr. Wilson	Yes	800	200	200	800	210 S. Newhope Street	Santa Ana	Private Lateral	Private lateral clean out	Grease: Build up of grease in private lateral.	Build up grease in private lateral.	Entered C-5-F city channel, flowed to C- 5 O.C.F.C. channel to wetlands.	East Garden Grove Winterbergs wetlands	East Garden Grove - Winterbergs wetlands	Yes - J. Antonio Islas, Jr.	
10/19/02	Private: Twin Pines Apts.	NO	1776	1500	3000	1776	2880 W. Ball Road	Anaheim	Blockage in sewer lateral a appartment complex	t private clean-out	Grease buildup	Grease buildup	N/A	N/A	Contained within storm drain system	YES	Sewage was vacuumed up downstream in storm drain sump area in the City of Stanton. Vaccuming continued until little or no flow was observed entering sump area.
10/22/02	Private	n/a	20	0	0	0	7 Holland	Irvine	n/a	n/a	n/a	Unknown	n/a	n/a	n/a	n/a	
10/22/02	Private Property	n/a	0	0	0	0	301 Mountain View	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
10/22/02	PRIVATE PROPERTY OWNER-JIM YOUNG 761- 5872	n/a	1,000	0	0	0	9021 STACIE LANE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE	n/a	n/a	n/a	n/a	n/a	n/a
10/25/02	Betty Chamberlin	No	375	10	160	0	317 21st	Huntington Beach	317 21st	Cleanout	Cleanout Cap was blocking flow	Grease had built up in the line, probably due to lack of maintenance	None	None	Curb and Gutter	Yes	
10/25/02	Private	n/a	5	0	0	0	21212 Bake Pkwy.	Lake Forest	n/a	n/a	n/a	Unknown	n/a	n/a	n/a	n/a	
10/26/02	Private Property	N/A	2	0	0	0	12421 Mystic Lane	Unincorporated County of Orange	Sewer	Clean-out	N/A	N/A	N/A	N/A	N/A	Y	STANDBY CHARLIE AMBRIZ RESPONDED. HE CHECKED OCSD LINES AND ALL WERE FLOWING NORMAL. HE DETERMINED THAT SPILL BELONGED TO PRIVATE PROPERTY OWNER. THEY WERE NOTIFIED TO CALL A PLUMBER.
11/1/02	Mark Montgomery	No, The storm water pump station was diverted.	308	308	458	0	21372 Brookhurst	Huntington Beach	Southwest Corner of Property	Sewer Cleanout	Debris, Roots, Grease	Possible Lack of Maintenance, Debris and Grease	None	None	Storm water pump station- This station is diverted to the Sewer	Yes	None
11/1/02	Private Property	n/a	0	0	0	0	2300 E. Lambert	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/2/02	Private	n/a	50	0	0	0	22606 Costa Bella Dr.	Lake Forest	n/a	n/a	Roots	Roots	n/a	n/a	n/a	n/a	
11/3/02	Archstone Huntington Beach	Yes, Bolsa Chica	830	50	100	780	8925 Rockcreek	Huntington Beach	8925 Rockcreek	Manhole	Grease	Possible Lack of Maintenance Grease	East Wintersburg Channel	Bolsa Chica-Pacific Ocean	N/A	Yes	None
11/5/02	Mark Montgomery	No, The storm water pump station was diverted.	800	350	450	450	21372 Brookhurst	Huntington Beach	Southwest Corner of Property	Sewer Cleanout	Debris, Roots, Grease	Possible Lack of Maintenance, Debris and Grease	None	None	Storm water pump station- This station is diverted to the Sewer	Yes	None
11/5/02	Yousef Ibrahim	Wintersburg Channel	551	100	600	451	7232 Edinger	Huntington Beach	7232 Edinger	Manhole	Grease	Chunks of Asphalt	City Edinger Channe	Wintersburg Channel	N/A	Yes	None
11/6/02	Private-City owned facility	No	0	100	0	0	1 Newport Pier	Newport Beach	Cleanout	Cleanout under Lifeguard Headquarters was overflowing	Sand and grease	See Remarks	n/a	n/a	n/a	yes	Cleanout under Lifeguard Headquarters was overflowing
11/6/02	Private Property - Sullivan Mgmt Group Inc.	Yes	150	650	800	150	751 S. Harbor Blvd	Santa Ana	20' S. of manhole where lateral connects to sewer system.	6" sewer clean out.	Grease build up caused by lack of routine maintenance program.	Grease build up caused by lack of routine maintenance program.	Entered storm drain at 901 S. Harbor Blvd.	Santa Clara River	Ocean	Yes - Karman Cheng	
11/6/02	Private Property	no	0	100	50	0	9191 Bolsa Ave Westminster	Westminster	grease interceptor	grease interceptor	grease	grease interceptor not properly serviced	n/a	n/a		yes	
11/11/02	Private Lateral Tony Romas Rest.	No	800	700	1500	0	3642 Katella	Los Alamitos	private lateral	private lateral clean out	grease	grease blockage	n/a	n/a	storm drain	yes	n/a
11/11/02	Private	Ν	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/13/02	Private Lateral Tony Romas Rest.	no	500	500	1500	0	3642 Katella	Los Alamitos	private lateral	private lateral clean out	grease	incomplete hydroflush	n/a	n/a	n/a	yes	n/a
11/13/02	Seebreeze Management Company	Pacific Ocean	N?A	N/A	N/A	N/A	410 Lake Street	Huntington Beach	410 Lake Street	Cleanout	Maintenance Crew	Maintenance Crew was cleaning sewer lines and allowing the sewage to flow down the drain.	Pacific Ocean	None	N/A	Yes	None
11/14/02	Private Party, Maguroya Japanese Restaurant located in the Yorba Station shopping center.	N	100	100	200	0	Yorba Station Shopping Center 18242 Imperial Hwy	Yorba Linda	Grease interceptor outside and behind restaurant	plugged interceptor device	grease	cooking grease in unmaintained grease interceptor.	n/a	n/a	n/a	Yes	This was a private property overflow. The local health services agency addressed the restaurant management.
11/15/02	Carl's Jr,private property	No	0	20	0	0	5012 La Palma Ave.	La Palma	Private lateral	Private lateral cleanout	Grease blockage on private property	Grease blockage on private property	N/A		Returned to sewer system	Y	Private contractor sanitized and cleaned up
11/15/02	Pacific West Corp.	Outfall on Sand	150	5 Gal.	24	146	101 Main Street	Huntington Beach	101 Main Street	Grease Interceptor	Grease	Possible Lack of Maintenance Grease	Pond at Outfall to Ocean	None	N/A	Yes	None
11/19/02	Private Property Owner	No	0	42	122	0	2046 E Wilshire Ave	Fullerton	Private Lateral	Private 4" lateral cleanout	Toilet Debri	Toilet Debri	N/A	N/A	All sewage was returned to sanitary sewer system	N	Jorge Gonzalez, acting sanitation specialist observed sewage around lateral cleanout. Cleanout was not overflowing at the time. Advised resident to call private plumber. City crew washed down and vacuumed area and returned all sewage to sewer system.

11/21/02	Private Property	N	120	120	60	0	361-371 Oak Place	Brea	Sewer	Manhole	Don't Know	NA	NA	NA	n/a	Y	This was a private property spill.
11/23/02	Private Property	n/a	15	0	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
11/25/02	Private	No	0	1500	0	0	1068 Rutland	Newport Beach	Cleanout	Cleanout	Unknown (possible roots)	See Remarks	n/a	n/a	n/a	yes	Cleanout overflow - OCH care Agncy closed Upper Newpor Bay Water
11/30/02	Denny's Resturant	yes	165	35	0	0	n/a	n/a	Line blockage	Line Blockage	Line blockage	n/a	Santa Ana River	Pacific Ocean	n/a	yes	(Not in originally submitted OCHCA report or Region 8 reports. Listed in OCHCA Beach Closure report)
12/2/02	Private Property	Unknown	100	10	110	90	2300 Main Street, east of Von Karman	Irvine	Private Lateral Sewer	Clean out	Blockage from Misc. debris	N/A	N/A	N/A	Native surrounding soil	Y on 12/02/2002 at 03:00:00 PM	NA
12/3/02	Private	Unknown	150	100	0	0	Big Canyon Golf Course	Newport Beach	n/a	n/a	Roots and grease	See Remarks	n/a	n/a	n/a	yes	Overflow on Big Canyon Golf Course
12/3/02	Richard Darling	Yes, OCFC-Sunset Channel	180	90	190	90	16490 Bolsa Chica	Huntington Beach	16490 Bolsa Chica	Cleanout in Parking Lot	Unknown at the time, turned out to be a separation in the pipe.	Unknown at the time, turned out to be a separation in the pipe.	OCFC Sunset Channel	Christiana Bay, Huntington Harbor	N/A	Yes	None
12/4/02	HB Elks Lodge	HB Central Park which was dry.	218	100	250	118	7711 Talbert Ave.	Huntington Beach	7711 Talbert Ave.	Manhole cover in Parking Lot	Grease	Possible Lack of Maintenance Grease	HB Central Park which was dry.	None	Storm Drain Pipe	Yes	None
12/4/02	Richard Darling	Yes, OCFC-Sunset Channel	480	400	490	90	16490 Bolsa Chica	Huntington Beach	16490 Bolsa Chica	Cleanout in Parking Lot	Unknown at the time, turned out to be a separation in the pipe.	Unknown at the time, turned out to be a separation in the pipe.	OCFC Sunset Channel	Christiana Bay, Huntington Harbor	N/A	Yes	None
12/5/02	Private	No	500	100	0	0	1433 Superior Ave.	Newport Beach	Private system	Private system	Unknown	See Remarks	n/a	n/a	n/a	yes	Plumber onsite removed blockage in private system as CNB news arrive on site (Beach House Appartments. Reported in OCHCA Beach Closure Report, not in originally submitted OCHCA report)
12/10/02	Private Property	n/a	0	0	0	0	1770 W. La Habra	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
12/11/02	Private Lateral Yucatan Grill Rest.	no	900	900	1500	0	12147 Seal Beach Blvd	Seal Beach	private lateral	private lateral clean out	grease	grease blockage	n/a	n/a	n/a	yes	n/a
12/20/02	Private	n/a	640	1625	0	0	San Canyon & Burt Rd.	Irvine	n/a	n/a	Unknown	Unknown	n/a	n/a	n/a	n/a	
12/20/02	PRIVATE PROPERTY OWNER - APT COMPLEX	n/a	100	0	0	0	7330 CERRITOS AVE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE	n/a	n/a	n/a	n/a	n/a	n/a
12/28/02	Private: Property Management Group, 1398 N. Mako Ln.	No	425	75	275	425	1398 N. Mako Lane	Anaheim	Near 1398 N. Mako Lane	Manhole	Grease and Roots	Grease and roots blocking flow	Carbon Creek	Pacific Ocean		YES	Property Management Group, Jerry O'Donnell, (714) 408-3469 headquarters.
12/31/02	El Toro Bravo Restaurant, 739 VI 19th St. Costa Mesa, CA 92027	N	0	480	300	0	El Toro Bravo restaurant @ 739 West 19th St	Costa Mesa, CA	Grease/commeal plugged EI Toro Bravo lateral line forcing SSO out of cidemout cover and into th parking lot where it was contained, returned to sewer system. Field Crew manager of SSO status - asked manager to clean cleanout.	El Toro Bravo restaurant cleanout, located in the parking loc, percolated area pickhole 2 inches in height. Field crew remained in parking ontained in parking lot and returned sewer system.	El Toro Bravo restaurant cleanout, located in the parking lot, percolated raw sewage out of pickhole 2 inches in height. Field crew remained in area to ensure sewage was contained in parking lot and returned to sewer system.	El Toro Bravo restaurant cleanout, located in the parking lot, percolated raw sewage out of pickhole 2 inches in height.	NĂ	NA.	Contained SSO flush water were disposed of into the cleanout and into the sewer system.	Y	Gresse/commeel plugged EI Toro Bravo lateral line forcing SSO out of desnout over and into the parking lot. Field Crew informed EI Toro Bravo manager of SSO status - asked manager to clean cleanout. Approximately 480 gallons of SSO spilled out of clean
Totals	104		35,193	21,622	27,827	11,311											
2003																	
1/2/03	PRIVATE PROPERTY OWNER	n/a	150	150	0	0	7326 CERRITOS AVENUE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE - PLASTIC BAGS, PATCHING COMPOUND, HEAVY GREASE	n/a	n/a	n/a	n/a	n/a	n/a
1/5/03	Private	N	50	50	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
1/6/03	Private Property	n/a	300	300	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a	n/a	n/a	Yes	n/a
1/6/03	Private Property	N/A	5	0	0	0	1621 FOOTHILL BLVD.	Unincorporated County of Orange	Private lateral line	Clean out	Unknown	N/A	N/A	N/A	Native soil	Y, 1/6/2003 16:12	Fences and location prevented OCSD staff from cleaning up the spill. Vacant lot properly owner was unknown, staff told the neighbor who reported the spill to contact OCSP's Engineering Dept. to try and figure out who the owner is and contact them to repo

1/7/03	Rubios Restaurant	No	50	50	750	0	16672 Beach Blvd. Suite# 101	Huntington Beach	16672 Beach Blvd. Suite# 101	Grease Trap	Lack of Maintenance	Lack of Maintenance/Grease trap had not been cleaned out for over a year.	None	None	Parking Lot	Yes	None
1/8/03	Private Property	Unkown	40	20	100	0	1101 Packers Circle	Tustin	Private lateral line	Manhole	Grease clog	N/A	Peter's Canyon Wash	Newport Back Bay	Unknown	Y 1/8/2003 1:25:00 AM	ECM, Collections, and Communications staff will be sending a letter to the Home Owners Association to notify owner of problem and the need to implement preventative maintenance schedule to ensure no future SSOs.
1/9/03	PACIFIC WEST MGMT CO.	n/a	450	0	0	0	12057 BEACH BLVD.	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE - GREASE	n/a	n/a	n/a	n/a	n/a	n/a
1/12/03	Private Property - Royal Holiday Mobil Park	No	0	0	0	0	215 S. Sullivan Street	Santa Ana	Private - unknown	Clean out	Grease blockage	Grease blockage	None	None	Contained on private property - sewage was recovered Minute Man Pumping Company	Yes	
1/14/03	Private Property	n/a	0	0	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a	n/a	n/a	Yes	n/a
1/16/03	Private Spill: Rodi Properties	No	0	175	275	1	12th Street	Seal Beach	Private property; parking lot behind restaurant	Cleanout	Grease	Restaurant grease interceptor had stoppage	n/a	n/a	City Sewer System	Yes	n/a
1/16/03	Freeway Industrial Park	Yes	2080	450	1070	1630	7402 Edinger	Huntington Beach	7402 Edinger	Cleanout	Lack of Maintenance	Lack of Maintenance/Grease/Crew Reported that grease logs were coming out into main sewer line	Murdy Channel	East Wintersburg Channel and Bolsa Chica	N/A	Yes	None
1/16/03	Private Property	N/A	0	0	0	0	14436 SAND BROOK DR.	Tustin	Private lateral line	Bathtub	Unknown	N/A	N/A	N/A	Bathtub		OCSD staff inspected OCSD lines and found them running normal. At the request of the readent staff showed him the structure at both ends of the line segment in first of his property. The resident was informed that this was his responsibility to clear t
1/18/03	Private		4680	0	0	0	WINDROW COMMUNITY PARK	IRVINE	N/A	LINE BREAK	LINE BREAK	STREET, CURB, GUTTER AND INTO STORM DRAIN	N/A	N/A	N/A	Yes	May be R-9
1/20/03	Private	n/a	0	0	0	0	3955 Alton Pkwy.	Irvine	n/a	n/a	Grease	Grease	n/a	n/a	n/a	n/a	
1/20/03	Private	n/a	3	0	0	0	6692 Ridge Park Rd.	Newport Beach	n/a	n/a	Paper	Paper	n/a	n/a	n/a	n/a	
1/23/03	Private	n/a	300	0	0	0	19752 Macarther Blvd.	Irvine	n/a	n/a	Unknown	Unknown	n/a	n/a	n/a	n/a	
1/23/03	Private	N	179	179	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
1/26/03	Private	n/a	360	0	0	0	50 Eastshore	Irvine	n/a	n/a	Grease	Grease	n/a	n/a	n/a	n/a	
1/27/03	Private Property	n/a	50	50	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a	n/a	n/a	Yes	n/a
1/28/03	Florida Gardens Apartments	No	50	30	45	20	18832 Florida	Huntington Beach	18832 Florida	Cleanout	Lack of Maintenance	Lack of Maintenance - Blockage cause by debris and Toilet Paper	None	None	Adams Pump Station which is on diversion to the sewe		None
1/29/03	Private Property	N/A	0	0	0	0	1102 Hyde Park Dr.	Unincorporated County of Orange	Private lateral line	Bathtub and toilet	Roots in private lateral line	N/A	N/A	N/A	Bathtub and toilet	Y, already onsite when OCSD arrived	OCSD will CCTV entire Hyde Park Dr. line segments to investigate house lateral conditions for root intrusion. Resident was sent a letter explaining the cause of the swage backup into his home (roots in his lateral) so he could file an insurance claim.
1/29/03	Private	N	192	192	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
1/30/03	Private Spill	Unknown	1000	0	0	0	3435 Newport Blvd.	Newport Beach	n/a	n/a	Grease, Paper products	See Remarks	n/a	n/a	n/a	yes	(Pavillons Supermarket) Blockage of paper products, feminine hygiene products, grease. (Originally marked as unknown for surface water. Reported on OCHCA Beach Closure Report)
2/2/03	FAIRCREST APARTMENTS	n/a	10,400	8,000	0	0	FERN AND CERRITOS	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE	n/a	n/a	n/a	n/a	n/a	n/a
2/4/03	Private (KFC)	No	0	5	105	0	150 W Orangethorpe Ave	Fullerton	Private Lateral	Lateral Cleanouts an Grease Interceptor	dGrease	Lateral was plugged upon arrival. Likely cause-grease, possibly toilet debris. KFC personnel rodded and cleared unknown blockage in lateral.	N/A	N/A		Yes	Upon arrival, City crew observed solidfiled gresse in curb and gutter area and on private property at Kentucky Fried Chicken (KFC), KFC personnel on site informed City crew lateral was blocked. Crew continued inspection and observed gresse trap full and
2/6/03	Private Property	N/A	2	0	0	0	Vacant lot between 1621 Foothill Blvd. and 1651 Foothill Blvd.	Unincorporated County of Orange	Private Lateral	Private Cleanout	Unknown	Unknown	N/A	N/A	Soaked into surrounding native soil.	Y; 2/6/2003 3:50:00 PM	NA
2/9/03	Coral Cay HOA	Yes	55	5	25	55	16832 Coral Cay	Huntington Beach	16832 Coral Cay	Manhole	Grease	Grease/Lack of Maintenance	Harbor Channel	Pacific Ocean	N/A	Yes	None
2/22/03	Private	n/a	0	0	0	0	24681 Shadowfax	Lake Forest	n/a	n/a	Roots	Roots	n/a	n/a	n/a	n/a	
2/24/03	Private	N	75	75	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
2/25/03	Private Property	yes	3000	2000	0	0	1440 W. Lambert Rd.	La Habra	Line Blockage	Line Blockage	Grease	Grease line blockage	San Gabriel River	Pacific Ocean	n/a	Yes	(Not listed in originally submitted OCHCA report. Listed in the OCHCA Beach Closure Report. Not indicated as private spill in Region 8 report)

										1			1				
2/27/03	Private Property	na	25	180	180	25	2097 E Orangethorpe Placentia	Placentia	private lateral line	clean out	Grease	Grease build up	na	na	storm drain	yes	Yorba Linda Water district Responded and cleaned up the spill also picked up the wash water. This spill was located on priviate property.
3/1/03	PRIVATE PROPERTY OWNER - BURGER KING	n/a	300	100	0	0	12550 BEACH BLVD.	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE	n/a	n/a	n/a	n/a	n/a	n/a
3/7/03	Private	N	200	200	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
3/10/03	Private Business	No	0	10	60	0	150 S. Harbor Blvd.	Fullerton	Private grease trap manhole	Private grease trap manhole	Grease	Full grease trap	N/A	N/A		Yes	City crews Gonzalez, Hernandez and Rangel were called out to contain a private grease trap spill at Knowlwood restaurant. Grease and sewage spilled out of interceptor manhole onto surrounding sidewalk and parking lot to the rear of building. Crews conta
3/12/03	Private - PCM Mgt. Co. View Point North Comm. Assoc.	No	750	300	350	750	7807 East Viewrim Drive	Anaheim	Near 7807 East Viewrim Drive	Private Manhole	Grease	The sewer line was obstructed by grease.	Santa Ana River	N/A	N/A	YES	The property where the spill occurred is private property. The city had no responsibility for the spill and responded only to assist in the containment to prevent additional sewage from reaching our storm water catch basin system.
3/12/03	Private	N	15	15	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
3/13/03	Private Property	na	350	400	400	750	112 N Bradford Ave Placentia	Placentia	private lateral line	Broken latteral line	roots	roots from tree	na	na	storm drain	yes	Bradford Senior homes hired contractor to repair latteral line City to charge back time and matterals for spill
3/18/03	Daniel Moran, Investors Property Services	No	0	240	300	0	1212 S. Bristol Street, Santa Ana, CA	Santa Ana	Private Spill	Clean out	Grease/Private Spill: There are several restaurants located in the shopping center that maybe dumping grease in the lateral.	There are several restaurants located in the shopping cente that maybe dumping grease in the lateral.	None	None	Sewage was picked up using a vaccum truck and returned to the sewer system.	Yes	This was a private spill handled by Orange County Health.
3/27/03	Private	n/a	0	0	0	0	20 Goodyear	Irvine	n/a	n/a	Rocks	Rocks	n/a	n/a	n/a	n/a	
3/28/03	Private Property	N/A	0	0	0	0	1777 MITCHELL	Tustin	Private Sewer line	Manhole	Blockage Misc. debris	N/A	N/A	N/A	Street, sand berm	Y; 3/28/03 5:37PM	N/A
4/3/03	Private (resident)	No	0	15	75	0	745 N Euclid	Fullerton	Private lateral between driveway and connection to main	Private 4" lateral ocleanout in driveway approach	Unknown	Unknown	N/A	N/A	All sewage was returned to sewer system	Yes	City crews Hernandez, Rangel, Davidison and Anzaldo responded to a report of a plugged lateral. When they arrived, sewage was observed seeping out of resident's private cleanout into gutter area. City crews contained the sewage, washed down, vacuumed and
4/4/03	Valley View Center, private property	Yes	540	210	275	0	7811 Valley View St.	La Palma	Private lateral	Private lateral cleanout	Grease	Grease blockage on private property as well as debris	Moody Creek	San Gabriel River		Y	Private contractor sanitized and cleaned up
4/7/03	Private Lateral Sharam Afshani	no	500	500	1500	0	Grease Interceptor 4348 Katella	Los Alamitos	private lateral	private grease interceptor	grease	grease blockage	n/a	n/a	n/a	yes	Grease interceptor was at a low point in the system and was not the cause.
4/17/03	Private Property	N	0	0	0	0	13071 ST MARK ST	Santa Ana	Private lateral	Private Clean out	Blockage Misc. debris	N/A	Soaked into ground	N/A	Soaked into ground	4/17/2003 8:47 AM	N/A
4/18/03	Private	n/a	2	0	0	0	4 Gillman	Irvine	n/a	n/a	Roots	Roots	n/a	n/a	n/a	n/a	
4/18/03	Private Property	n/a	0	0	0	0	2220 S. Monte Vista	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
4/20/03	Private Property	N	3	0	0	3	1091 OLD IRVINE BLVD.	Tustin	Private lateral	Private Clean out	Blockage Grease clog	N/A	Soaked into ground	N/A	U	4/20/2003 3:15 PM	N/A
4/21/03	Private Property	no	0	0	0	0	1400 Magnolia St. Westminster	Westminster	cleanout	cleanout	grease	grease	n/a	n/a			This spill occurred on private property. The private security guard who called the spill into the Westminister PD reported the spill had been occurring for at least 24 to 48 hours, but the property owners had instructed him not to report it to anyone. He
4/29/03	Private Property	n/a	200	200	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
5/1/03	Private	n/a	60	0	0	0	3 Burroughs	Irvine	n/a	n/a	Unknown	Unknown	n/a	n/a	n/a	n/a	
5/1/03	Private	Yes	0	25	0	0	2751 Coast Hwy.	Newport Beach	Grease Trap	Grease Trap	Unknown	See Remarks	Pacific Ocean	n/a	n/a	yes	Grease trap was overflowing. 5 gallons per minute.
5/1/03	Elis Nourafchan	No	900	900	1100	0	6905 Warner Ave.	Huntington Beach	6905 Warner Ave.	Cleanout	Grease and debris blockage	Grease buildup from a number of restaurants in the complex.	None	None	Put back into the sewer system.	Yes	
5/6/03	666 West 18th St Newport Mesa Townhome, Costa Mesa, CA 92626	N	0	165	100	0	SSO spilled out of lateral line cleanout at 666 W 18th St, Costa Mesa	Costa Mesa, CA	Location is in a residential neighborhood. SSO spilled out of lateral line cleanout at 666 W18th St, Costa Mesa. Lateral line blocked with roots and paper.	line cleanout at 666	Lateral line blocked with roots and paper.	Lateral line blocked with root and paper.	³ NA	NA	Contained SSO and flush water were returned to/disposed of into the sewer system.	Y 5/06/2003 1045hrs	Approximately 155 gallons of SSO spilled out of private lateral line cleanout located at 868 West 18th St, Costa Mesa, Field Crew fully contained SSO in public right of way. Crew vactored SSO, flushed SSO with fresh water and disposed of SSO and flush wat
5/6/03	Private	N	10	10	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	

5/7/03	700 N. Valley Street	Yes	200	20	30	200	700 N. Brookhurst Street	Anaheim	On Gramercy Avenue, eas of Brookhurst Street	Private sewer clean out at Mobile Gas Station	Paper towels obstructing the flow.	Paper towels were obstructing the sewer line which caused the overflow.	Carbon Creek	N/A	N/A	YES	The owner of the Mobile Gas station, Morteza Yassini stated there was a small flow spilling from the clean out on 55/03 at 11 p.m. At the time, he assumed it was just water since the clean out had a lid that stated "Water" on it. Operations Crew Superv
5/7/03	Private Property	N	0	0	0	0	BLACK ANGUS RESTAURANT, BROOKHURST ST. & TALBERT IN FOUNTAIN	Fountain Valley	Lateral	Cleanout	Blockage Grease clog	N/A	Fountain Valley Channel to the Talbert Channel	N/A	Unknown	5/7/2003 8:45 AM	NA
5/9/03	Private Property	N	0	0	0	0	CANYON TERRACE RD &	Unincorporated County of Orange	Lateral	Cleanout	Blockage Root obstruction in lateral line	N/A	None	N/A	Unknown	N	NA
5/12/03	8265 Maureen Condominium Complex	no	0	30	0	0	8265 Maureen Midway City	Midway City	cleanout	cleanout	debris	debris on private property	n/a	n/a	Returned to sewer system		Spill reported to District by property management company. Spill on private property.
5/15/03	Private Property	n/a	0	0	0	0	1232 N. Palm	La Habra	n/a	Septic Tank	n/a	n/a	n/a	n/a	n/a	n/a	
5/15/03	Private Property	N	0	0	0	0	HIDEAWAY DR. & NEWPORT BLVD.	Unincorporated County of Orange	Lateral	Cleanout	Blockage Misc. debris	N/A	Contained in Storm Drain/Channel. Red Hill Channel	N/A	Contained in Storm Drain/Channel	5/15/2003 Unknown	NA
5/15/03	Private Property	N	20	30	30	0	7100 KNOTT AVE.	Buena Park	Lateral	Cleanout	Blockage Root obstruction in lateral line	N/A	Fullerton Creek Channel	N/A	Unknown	5/15/2003 7:20 PM	NA
5/19/03	Private Property	n/a	50	0	0	0	n/a	Orange	n/a	Pump Malfunct.	Pump Malfunct.	n/a	n/a	n/a	n/a	Yes	n/a
5/20/03	Private Property	n/a	0	30	0	0	n/a	Orange	n/a	n/a	Roots	n/a	n/a	n/a	n/a	Yes	n/a
5/26/03	Huntington by the Sea MHP	Yes	960	40	40	920	21851 Newland Ave.	Huntington Beach	21851 Newland # 2-8	At hookup for the Coaches	Grease and debris blockage	Grease and debris from a lack of maintenance.	CTalbert Marsh	Pacific Ocean		Yes	
6/6/03	Private	Ν	25	25	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
6/7/03	West Bay Café	No	40	40	40	0	6600 Admiralty Drive	Huntington Beach	6600 Admiralty Drive	Cleanout	Grease	Grease from Café caused blockage.	None	None	Catch Basin	Yes	None
6/9/03	Private Property	n/a	0	0	0	0	331 Eunice Cr.	La Habra	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
6/11/03	Kikuya Japanese Rest.	Yes	90	50	150	40	8052 Adams	Huntington Beach	Front of Restaurant on sidewalk	Manhole	Grease	Grease causes blockage in line, Lack of Maintenance	OC Flood Control D01	None	None	Yes	None
6/11/03	Private Property	Unknown	35	0	75	95	11407 ARROYO AVE	Unincorporated County of Orange	8-inch private property lateral	manhole	Blockage Grease clog	N/A	Hicks Canyon	Unknown	N/A	Y, 6/12/2003 11:29 PM	The field report states that it did enter a storm drain. However, after talking to Victo Hermelin, he stated that it actually did not enter a storm drain. The spill had been contained in the gutter, which dried up, so it was not recovered via vactor tr
6/13/03	Condominium Complex	no	50	325	0	0	Kramer & Stonehedge Lane Westminster	Westminster		manhole	grease	grease in sewer line	Wintersburg Channel	n/a	Returned to sewer system	yes	Spill reported by Westminster PD. Spill on private property
6/18/03	Private Party	No	0	400	60	0	409 N. Jeanine Drive	Anaheim	Near 409 N. Jeanine Drive	Private cleanout	Trash / Debris	Debris blocking the flow of sewer line.	N/A	N/A	Spill ponded. Did not reach storm drain.	YES	The City of Anaheim responded to assist in the containment of the spill from a private clean-out. Sewage did not enter the storm drain.
6/30/03	Trailer Park run by Del Almo	no	0	80	0	0	9702 Bolsa Ave. Westminster	Westminster		manhole	grease	grease in sewer line on private property	^e n/a	n/a	Returned to sewer system	yes	Spill on private property
6/30/03	Private Property	n/a	150	150	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
7/1/03	Private Property Owner: 278 N. Wilshire Street	Yes	590	10	20	590	278 N. Wilshire Street	Anaheim	Near 278 N. Wilshire Street	Private Manhole	Swale in sewer lateral	Swale in pipe allowed debris to settle and accumulate resulting in blockage	Carbon Creek	N/A	N/A	Yes	Property Management was very difficult to get a hold of, however, the delay in their response will result in a large bill being issued to them for cost recovery, in conjunction with the notice of violation. Copy of this report was provided to OC Health C
7/8/03	Private Property	n/a	0	0	0	0	141 S. Idaho	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
7/9/03	Private Property	N	0	0	0	0	11772 HIGH VIEW DRIVE	Unicorporated County of Orange	Private sewer line	Bathtub and toilet	U	U	N/A	N/A	N/A	N	OCSD line was running freely. No sewer spill in the area.
7/14/03	Private Property Owners (4) of shared lateral.	No	20	40	340	20	1320 S. State College Boulevard	Anaheim	Near 1320 S. State College Boulevard	Private Cleanout	Grease	Grease buildup obstructing sewer flow.	N/A	N/A	Ponded in SD	Yes	Unusual situation as there are four (4) properties served by a single lateral. Based on observations it was clear the cause of the blockage was excessive grease. The only grease bearing operation is the Restaurant at 1258 S. State College Boulevard. Ho
7/17/03	Private Property: Paradise Pier Hotel 1717 Harbor Boulevard	Yes	100	200	1000	100	1717 Disneyland Drive	Anaheim	Near 1717 Disneyland Drive	Private Cleanout		Overflow caused by buildup of paper towels in sewer line.	f East GG Channel	Bolsa Chica	NA	Yes	Disney was very forthcoming in providing the appropriate information, as well as notifying proper City and other agency staff for this incident. For many reasons, Disney has focused a great deal of effort on preventing any similar spills in the future an
7/23/03	Private Property: Mandas Konstantinos - 910 S. Euclid Street	No	50	10	210	50	910 S. Euclid Street	Anaheim	Near 910 S. Euclid Street	Private Cleanout	Grease	Grease buildup obstructing sewer flow.	N/A	N/A	Ponded in SD	Yes	City was notified of al leak of some kind at 2:00 am on 7/23/03, however upon arriving on scene there was no spill. A follow up inspection later that morning revealed a slow leak from the cleanout.

7/25/03	Private Property: Crown Point Homeowners Association	No	13167	798	998	13167	400 Crown Point Drive	Anaheim	Near 400 Crown Point Drive	Private sewer manhole on Crown Point Drive	Roots	Roots obstructed the sewer flow.	N/A	N/A	It is suspected that a sump area in Cal Trans Right of Way received the spill.	Yes	Spill could not be found at Santa Ana channel where it would empty into. It is suspected that a sump area in Cal Trans Right of Way received the spill.
7/25/03	Little Saigon Village	no	0	0	0	0	10161 Bolsa Ave. Westminster	Westminster		cleanout	grease	grease in sewer line on private property	storm drain on Bolsa Ave.	n/a	Returned to sewer system	yes	Spill on private property
7/30/03	Private - Albertsons Inc	No	0	200	600	0	455 N State College Blvd	Fullerton	Private lateral	Private lateral cleanout in parking lot	Rags	Rags in lateral connection	N/A	N/A		Yes	Reynoso, Hemandez, Miller, Rangel, and supervisor Rosebarry responded to report of server overflow in the parking lot of Sav-on. Original notification was made to Cit Fire Dept., who contained the spill in the gutter and notified the Police Dept (Rocco)
7/30/03	Private	N	110	110	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
8/1/03	Private		2500	0	0	0	MAIN & MAC ARTHUR	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN TO LANE CHANNEL.	N/A	N/A	N/A	Yes	
8/3/03	Private	Yes	180	0	0	0	#7 ASPEN TREE LANE	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN TO SAN JOAQUIN CHANNEL.	SAN JOAQUIN CHANNEL	N/A	N/A	Yes	May be R-9
8/7/03	The Saywitz Co. 4740 Von Karman, Suite 100, Newport Beach, Ca 92660	NO	150	150	250	0	7712 Cypress Ave., Huntington Beach Ca.	Huntington Beach	Property owners lateral at 7712 Cypress Ave., Huntington Beach Ca.	Clean out cover	Grease and debris.	A buildup of grease and debris in the lateral, probaly caused by insufficent maintenance.	None	None	Spill was contained at the gutter in front of location, vacuumed up and placed back into the sewer.	Yes	
8/13/03	Private Property	N	0	0	0	0	12523 HINTON WAY	Unicorporated County of Orange	Per Roy Parrino the problem was on Private Property and the problem stemmed from their clean- out. There was no spill and the residents were told to contact a plumber and not to run any water.		N/A	NA	None	None	None	N	None
8/13/03	Richard Lee PO Box 2142, Huntington Beach, Ca 92647	NO	120	120	220	0	7872 Stark Ave., Huntington Beach Ca.	Huntington Beach	Property owners lateral at 7872 Stark Ave., Huntington Beach Ca.	Cleanout cover	Grease	A buildup of grease in the lateral, probably caused by insufficent maintenance.	None	None	Spill was contained at the storm drain, and the five gallons that got into the storm drain was vacuumed up using city equipment and placed back into the sewer system.	yes	
8/20/03	Private Property	n/a	0	150	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
8/24/03	Hannam Market, private property	No	0	50	55	0	4875 La Palma Ave.	La Palma	Private lateral	Manhole	Grease	Grease blockage on private property	N/A	N/A	Returned to sewer system	Y	Private contractor sanitized and cleaned up
8/25/03	Private Party	No	200	50	1000	0	2508 West Chain Street	Anaheim	Near 2508 West Chain Street	Sinkhole in Street	Break	Pipe failure allowed sewage to seep into the ground	N/A	N/A	Seeped into the ground	YES	Report of possible sinkhole first came to the City at 4:45 PM on August 25, 2003. Subsequent investigation on August 27 indicated a water leak, however further investigation on August 28 revealed the water was in fact sewage. The sewage in the sinkhole wa
8/28/03	Private Property	U	0	0	0	0	18802 BARDEEN AV	Irvine	SBCO 420 Charlie Ambriz to evaluate the problem. Spill was in the residential property.	N/A	N/A	N/A	None	None	None	N	None
8/28/03	Private Property	N	0	0	0	0	12691 BROWNING AVE	Unicorporated County of Orange	Call out Div. 420 Standby Charlie Ambriz. 08/29/03 00:22 Charlie reported that OCSD line was flowing clearly. Problem was at home owner's building sewer.	Bath tub and toilet	U	NA	None	None	None	N	None
9/4/03	Private Property	N	0	0	0	0	17792 McFadden	Tustin	Blockage was determined to be in private property	Toilets backed up in Shopping Center Area	U	N/A	N/A	N/A	N/A	N	N/A
9/12/03	Private Property	n/a	0	0	0	0	1061 N. Euclid St.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
9/15/03	Private Property	n/a	150	100	0	0	n/a	Orange	n/a	n/a	Roots	n/a	n/a	n/a	n/a	Yes	n/a
9/15/03	Private		19	20	0	0	2451 ELDEN AVE	COSTA MESA	N/A	LINE BREAK	LINE BREAK	STREET, CURB AND GUTTER AND INTO STORM DRAIN.	N/A	N/A	N/A	Yes	N/A
9/18/03	Private Property	n/a	0	0	0	0	630 N. Beach Blvd.	La Habra	n/a	Washrack	n/a	n/a	n/a	n/a	n/a	n/a	
9/28/03	Private	No	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	

9/30/03	American Properties, P.O. Box 3895, Newport Beach (949) 363-7255	No	0	30	50	0	718 N. Lacy Street	Santa Ana	Private lateral	Sewer lateral clean out	Roots: Private spill, plumber pulled out roots/paper.	Private spill, plumber pulled out roots and paper.	None	None	Returned to sewer system	Yes	
9/30/03	Private	No	5	5	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
10/1/03	George Conzalez (714) 957- 2529 - Private	No	0	540	1800	0	1128 S. Bristol St.	Santa Ana	Private lateral	6* clean out	Grease - Spill was a combination of large amounts of grease and the lateral is a 6° line that connects to a 4° lateral at the pl This lateral serves a market and a laundromat, this lateral should be a 6° all the way to the sewer main.	laundromat, this lateral should be a 6" all the way to the sewer main.	None	None	Returned to sewer system	Yes	
10/1/03	Private Property	Unknown	0	0	0	0	Jamboree at Big Canyon Golf Course	Newport Beach	Private manhole	Private manhole	Roots and debris	See Remarks	n/a	n/a	n/a	yes	Opened manhole and cleared roots and debris over 10 ft deep manhole. Private manhole. Private property: Sea Island Community Association.
10/2/03	Private- William Lyon Property Management	No	30	210	20	0	5601 E. Orangethorpe Ave	Anaheim	5601 E. Orangethorpe Ave	Private Manhole	Roots	Roots obstructed sewer flow, causing the overflow at the manhole	Santa Ana River	N/A	N/A	YES	Mark Williams of OCHCA responded to the scene and informed the property owner of the seriousness of the situation
10/3/03	George Gonzalez (714) 957- 2529 - Private	No	0	180	680	0	1128 S. Bristol St.	Santa Ana	Private lateral	Clean out	Grease - Cause of overflow was the same as the spill on 10/01/03, large amounts of grease	Cause of overflow was the same as the spill on 10/01/03, large amounts of grease.	None	None	Returned to sewer system	Yes	
10/7/03	George Gonzalez (714) 957- 2529 - Private	No	0	120	420	0	1128 S. Bristol St.	Santa Ana	Private lateral	Clean out	Grease - Large amounts of grease from market.	Large amounts of grease in market.	None	None	Returned to sewer system	Yes	
10/10/03	Private Property	Ν	0	0	0		2501, 2511 & 2521 W. SUNFLOWER AVE	SANTA ANA	U	U	U	U	N/A	N/A	N/A	N	N/A
10/13/03	Private	No	115	115	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
10/14/03	Private N	No	0	60	0	0	701 OCEAN	SEAL BEACH	N/A	LINE BREAK	LINE BREAK	ALL SEWAGE WAS CONTAINED ON SITE AND RETURNED TO SEWER.	N/A	N/A	RETURNED TO SEWER	Yes	N/A
10/22/03	Private	No	0	180	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
10/25/03	Seacliff Health Care Center	Sewage needed to travel a mile and a half with many other storm drain inlets entering pipe before it entered a County Channel.	400	375	795	25	18811 Florida Street	Huntington Beach	Parking lot of Seacliff Health Care Center, 1881 Florida St	Four inch clean out.	Debris clogged private lateral	Buildup of debris in line probably caused by insufficient maintenance.	County channel at Adams Ave and Beach Blvd.	Talbert Marsh	The sewage needed to travel about a mile and a half before it entered the County channel at Adams Ave. west of Beach Blvd	Yes	
10/27/03	Solteros Apartment maint. personnel at 17301 Keelson Ln. Huntington Beach.	No	25	25	45	0	17301 Keelson Lane	Huntington Beach	Front yard of Solteros Apartment complex at 17301 Keelson Ln	Four inch clean out.	Tree roots clogged private lateral.	Roots from tree clogged apartment complexes sewer lateral.	None	None	Spill was contained at the gutter, vacuumed up and placed into the sewer system.	Yes	
10/28/03	Private Property	Yes, possibly spill went into nearby creek.	0	0	0	0	JAMBOREE RD.	Newport Beach	8-inch clean out on private property	Clean out	Grease, other and debris	N/A	Nearby Creek	N/A	NA	Y	NA
10/30/03	Private	Yes	17	21	300	0	1708 Peppertree Ln in alley behind apartments	Fullerton	Private lateral	Private lateral cleanout	Roots and debris	Root intrusion into 6 inch sewer lateral through defective joint	Brea Creek Channel	Pacific Ocean		Yes	Crews responded to private lateral overflow. Overflow was intermittent between 0 and 3 gpm. City crews contained spill, cleared blockage, washed down and vacumed area. Due to normal irrigation run-off and storm drain flow, crews were unable to contain
10/30/03	Private Property	n/a	0	100	0	0	n/a	Orange	n/a	n/a	Grease/Roots/Paper	n/a	n/a	n/a	n/a	Yes	n/a
10/30/03	Private	Yes	24	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
10/31/03	Private Property	N	0	50	50	0	2000 JAMBOREE RD	Newport Beach	8-inch force main on private property	Force main	Failed pipe	8-inch force main failure	N/A	N/A	Sanitary Sewer System	Y	This spill began on 10/31/2003 and after initial containment on the evening of 10/31/2003, the spill resultaced on 11/01/2003. CCSD responded to spill on 11/01/2003 to find that the cause of the spill was a broken 8-inch force main line. Containment was
11/1/03	Private	No	0	1,000	0	0	McArthur Blvd.	Newport Beach	Private force main	Private force main	Private forcemain was broken	See Remarks	n/a	n/a	n/a	yes	Private force main was broken Located Big Canyon Villas HOA.
11/4/03	Private Property	Ν	0	0	0	0	17792 McFadden Ave	Tustin	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Resident Called in to report toilet back up. Spill was private property responsibility

11/12/03	Private Party	n/a	40	305	0	0	10201 Valley View	Cypress	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/15/03	Private	No	55	55	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/17/03	5665 E La Palma	Yes	2700	100	200	500	5665 E. La Palma Avenue	Anaheim	5665 E. La Palma Avenue	Private cleanout	Paper Towels	Paper towels obstructed the flow of the sanitary sewer line causing it to overflow.	Santa Ana River	N/A		Yes	The majority of the sewage remaining on the surface of the parking lot was collected during a washdown with the City's vactor truck. However, due to a misdiagnosis of where the spill cutlet to the nearby channel, the washdown of the parking lot (intended
11/18/03	540 North Euclid	No	20	19	50	0	540 North Euclid Avenue	Anaheim	540 North Euclid	Private sewer manhole	Grease	Grease obstructed the flow of the sanitary sewer line causing it to overflow	N/A	N/A	Spill Ponded in Catch Bas	in Yes	
11/20/03	Dr. Charles Kenyon, at his private residence.	None	55	55	105	0	17075 Roundhill Dr.	Huntington Beach	Private homeowners latera at 17075 Roundhill Dr.	I Broken lateral line.	Tree roots clogged sewer lateral line.	Private party tree roots clogged and broke their sewer lateral. City's Water Dept. dug hole checking out complaint of broken water line found broken sewer pipe.	None	None	Sewage was vacuumed u and put into the sewer system.	P Yes	Problem spot was in street homeowners sewer lateral. Residence is upstream on a hil explaining some pressure.
11/25/03	Private Property	n/a	450	50	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a	n/a	n/a	Yes	n/a
11/29/03	777 Convention Way	No	50	0	50	0	Hotel Way East of 777 Convention Way	Anaheim	777 Convention Way	Private sewer manhole	Grease	Grease released by Anaheim Hilton obstructed the flow of the sanitary sewer line causing the overflow	N/A	N/A	Spill Ponded in Catch Bas	in Yes	
12/2/03	Private property owner	No	100	1600	1600	0	1758 W. Sumac Lane	Anaheim	1758 W. Sumac Lane	Clean out in laundry room	Roots	Roots clogged the sewer latteral	East Garden Grove Channel	N/A	N/A	YES	Property owner was initially unresponsive to the City's and OCHCA's calls notifying him of the situation. Owner finally arrived onscene and obtained the services of a private plumber 8 hours after initial contact.
12/5/03	Private	lo	0	75	0	0	CAMPUS & CARLSON	IRVINE	N/A	LINE BREAK	LINE BREAK	ALL SEWAGE WAS CONTAINED.	N/A	N/A	N/A	Yes	N/A
12/8/03	Private Property	n/a	0	0	0	0	321 S. Idaho St.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
12/9/03	Bill Jarjour, owner of Hilltop Liquor	YES	1500	25	45	1475	815 Indianapolis Ave.	Huntington Beach	Private homeowners latera at 815 Indianapolis Ave.	I Private clean out	Grease	Grease clogged homeowners lateral line	Orange County Flood Control Channel DO-1	Talbert Marsh	Sewage was vacuumed u and put into the sewer system.	P Yes	Difference of opinion by homeowner and person notifying city of spill as to length spill flowed. Location was next to bus stop see picture.
12/10/03	Private property owner	Yes	300	500	200	0	6103 Morningview Drive	Anaheim	6103 Morningview Drive	Private Cleanout PC192423	Roots	Roots clogged the sewer line and caused a overflow	Santa Ana River	N/A	N/A	YES	
12/12/03	Private property owner	No	0	125	200	0	1616 West Katella Avenue	Anaheim	1616 West Katella Avenue	Private Cleanout	Metal from broken grate	Metal from broken grate fell into latteral and obstructed the flow, causing the overflow	N/A	N/A	Vacuumed by private contractor and disposed o in sewer	f YES	This incident started with a complaint of odor which was the result of flow coming from an outdoor trash compactor. The owner/operator of the compactor, Food 4 less, was required to stop this flow, and moved the compactor to do so. However, in moving it,
12/15/03	Tritz Professional Management Services Inc.	YES	943	470	570	473	4171 Andros	Huntington Beach	Private eight-inch sewer line at 4171 Andros Ave.	Private sewer manhole	Grease and roots	Grease and roots caused the private homeowners sewer system to clog.	Huntington Harbor	Huntington Harbor		YES	
12/16/03	Private Property	Ν	0	7	257	0	11481 Skyline Drive	Santa Ana	4" Sewer Lateral	Clean out	Blockage, Misc. debris	N/A	N/A	N/A	N/A	Y (via spill notification e- mail)	N/A
12/22/03	Private	No	5	5	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
12/22/03	Private	No	12	12	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
12/26/03	Hugh Roberts	NO	200	200	300	0	705 Jay Circle	Huntington Beach	Private homeowners latera at 705 Jay Cir.	I Private clean out	Grease	Grease clogged homeowners lateral line	None	None	Sewage was vacuumed u and put into the sewer system.	YES	
12/27/03	Private Property	Ν	50	100	250	50	17231 E. 17th Street	Tustin	8" Sewer Lateral	Manhole	Blockage, Grease clog	N/A	Santa Ana River	N/A	N/A	Y; Called 12/27/2003 9:05:00 PM	N/A
12/28/03	Complex,private property	No	0	15	20	0	7002 Moody St.	La Palma	Private lateral	Private lateral cleanout	Blockage	Blockage	N/A	N/A	Returned to sewer syster	n N	Private contractor sanitized and cleaned up
12/29/03	Richard LI, owner of the apartments	Yes	2312	200	300	2112	7872 Stark Street.	Huntington Beach	Private homeowners latera at 7872 Stark Street	Private clean out	Grease	Grease clogged apartment complex lateral line	East Garden Grove Winter Burge Channel (C-05)	Bolsa Chica Ecological Reserve		Yes	Agnes Do from the Orange County Health Care Agency was on scene and wrote a report.
12/31/03	Richard Beachler	No	75	75	100	0	6571 Sabbicas Cir.	Huntington Beach	Private homeowners latera at 6571 Sabbicas Cir.	I Private clean out		Tree roots in private sewer lateral	None	None	Sewage was vacuumed u and put into the sewer system.	P Yes	
Totals	141		55,805	25,473	20,235	23,051											
2004																	

1/4/04	Private Property Owner	Yes	600	0	0	0	1415 W. Ball Rd.	Anaheim	1415 W. Ball Rd.	Private Manhole	Grease	Grease obstructed the flow of the Sanitary Sewer Line causing it to overflow	Westminster	N/A	N/A	Yes	The Anaheim Fire Department responded initially. Then Streets and Sanitation was called out and responded. Spill duration was estimated at 1 hour as the property manger found the sewer manhole flowing out heavily. Fire said that the spill was 3 inches abo
1/12/04	La Palma Hospital, private property	No	O	300	500	0	7901 Walker Street	La Palma	Private lateral	Private lateral cleanouts	Grease blockage on private property as well as debris	Grease blockage on private y property as well as debris	N/A	N/A	Returned to sewer system	Y	Private contractor sanitized and deaned up
1/13/04	The Lodge, a Food Service Establishment (FSE) at The Camp. 2937 Bristol St, Costa Mesa, CA	N	100	100	200	100	The Lodge is one of 3 Food Service Establishments FSE3) at The Camp address; Interceptor for The Lodge was blocked, forcing the SSO out of a vent hole at 2937 Bristol St.	Costa Mesa, CA	The Lodge is one of 3 Food Service Establishments FSEs) at The Camp address: Interceptor for The Lodge was blocked, forcing the SSO out of a vent hole at 2937 Bristol St.	blocked, forcing the	District Field Craw	EDistrict Field Crew verified SE FSE grease blocked The Lodge interceptor.	Santa Ana-Delhi Channel	None	100 gais of SSO entered storm drain leading to the Santa Ana-Dehih Channel, 100 gais SSO were contained. Vactored SSO and flush water were returned to District Main Line at the Corporate Yard.	Y 1/13/04 1712 hrs	OCSD informed CMSD of the SSO at the Food Service Establishment (FSE) known as The Lodge at 2537 Britisti St. District Crew arrived, contained the SSO, discussed corrective action with The Lodge employees, called the City of Costa Mesa National Pollutant
1/17/04	Private Property Owner	No	560	1600	500	0	1630 W. Katella Ave.	Anaheim	1630 W. Katella Ave.	Private Cleanout	Grease	Grease obstructed the flow of the Sanitary Sewer Line causing it to overflow	Westminster	N/A	N/A	Yes	Second spill in 15 months
1/17/04	Brea	N	300	50	50	0	105 W. lambert Rd.	Brea	unknown	intercepter	unknown	NA	NA	NA	n/a	Y	The property management and Alexander Soles from OC Health dept were on site at time of the sewer stoppage.
1/17/04	Brea	N	0	300	350	0	730 Imp. Hwy.	Brea	unknown	intercepter	unknown	na	NA	NA	n/a	Y	The property management and Alexander Soles from OC Health dept were on site at time of the sewer stoppage. Apartment management phone # 714.990.0151
1/21/04	Private	No	52	55	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
1/21/04	Private Lateral St. Hedwig School	no	50	50	300	0	11482 Los Alamitos Blvd.	Los Alamitos	private lateral	private lateral clean out	roots	tree root blockage	n/a	n/a	n/a	no	n/a
1/26/04	Coastline West Management Service	No	50	50	55	0	1035 12th Street	Huntington Beach	1035 12th Street	Sewer clean out pipe on private property	Roots	Apartment complex sewage line clogged with roots.	None	None	City sewer system.	Yes	
1/31/04	Private Property	No	0	100	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
2/2/04	Rick Trucios, homeowner.	no	300	200	250	100	782 Little Harbor	Huntington Beach	Private homeowners later at 782 Little Harbor	al Roots caused a private sewer lateral to plug.	Tree roots clogged lateral line	Private party tree roots d clogged sewer line and caused sewage to spill out of homeowners association manhole.	None	None	Sewage was vacuumed up and put into the sewer system.	Yes	Private cleanup company (Aladdin Emergency Services) contacted the City about the spill otherwise we might not have known.
2/2/04	Dr. Wayne Brown rental property owner.	No	100	100	150	0	214 9th St. in alley	Huntington Beach	Private homeowners later at 214 9th St.	^{al} Private sewer lateral	Broken sewer lateral.	Private broken sewer lateral caved in soil around it causing a blockage to overflow onto public property.	None	None	Sewage was vacuumed up and put into the sewer system.	Yes	
2/3/04	Private Property Owner	No	0	0	0	0	3133 Pearl Dr	Fullerton	Private lateral for kitchen area	Private lateral cleanout	Unknown	Unknown	N/A	N/A		Yes	Emergency night crew Jennings responded to report of lateral blockage at apartment on 2304. Advised resident to call a plumber, no follow up needed. Sanitation crews responded on 2/604 to check main line and found lateral problem had not been resolve
2/9/04	Seaside Village Condo. Homeowners Association	No, all sewage that went into the storm drain system went to a storm water pump station that was being diverted into the sewer system.	1512	1512	1612	0	2100 Admiral Lane	Huntington Beach	1213 Admiral Lane, a private sewer lift station.	Private sewer manhole.	Problems with private lift station.	Private lift station was not working properly causing sewage to spill out of three manholes.	None	None	Sewage on site was vacuumed up and put into the sewer system. Sewage in storm drain system was diverted into the sewer system at the storm water pump station.	Yes	This condo complex has had problems before with their sewer lift station. Each time they say problem is lixed. Mr. Billard said the sewage had been splitting out of the manholes for three days.
2/12/04	Norms Restaurant	No	400	400	900	0	16572 Beach Blvd.	Huntington Beach	Norms Restaurant 16572 Beach Blvd.	Cleanout drain.	Grease and food debris.	Grease and food debris from Norms clogged the sewer lateral causing sewage to come out of their cleanout pipe.	None	None	Sewage was vacuumed up and put into the sewer system.	Yes	Due to a construction project adjacent to the catch basin, sandbags existed at the catch basin prior to this SSO.
2/19/04	Private	No	5	5	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
2/19/04	Private	No	50	50	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
2/19/04	Private	No	30	30	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
2/24/04	Private Property Owner	No	50	100	500	0	2610 E Katella Ave.	Anaheim	2610 E. Katella Ave.	Private cleanout and private clarifier	Grease	Grease formation caused the sanitary sewer line to overflow	Santa Ana River			Yes	The staff at Orange County offices (located next door to J.T. Schmidt's) noticed the flow of water at 10:30 and notified the restaurant manager. Private plumber arrived by 11:00 AM to clear blockage and City of Anaheim was notified at 11:15 AM. Anaheim In
2/25/04	Rossmoor/Los Alamitos Area Sewer Dist.	no	500	490	1500	0	3642 Katella	Los Alamitos	private lateral	private lateral clean out	grease	grease blockage	n/a	na/	storm drain	yes	n/a
3/3/04	Private Property	Ν	120	120	200	0	2540Country Hills Rd.	Brea	A-04	Manhole	unknown	NA	NA	NA	n/a	Y	Apartment Manager Kathy Hill (714)9905626

	Sycamore Canyon										_	Roots obstructed private clean					Private plumber did not arrive until 9:35 pm and had difficulty with their equipment.
3/7/04	Townhomes	Yes	800	200	200	0	8282 E. Oak Ridge Circle	Anaheim	8282 E. Oak Ridge Circle	Private clean out	Roots	out	Santa Ana River		N/A	Yes	Obstruction was finally cleared at 3am. Private plumber and City Staff worked to washdown and clean affected area.
3/19/04	Parkview One Homeowners	Yes	960	60	1000	0	6518 E. Camino Vista	Anaheim	6518 E. Camino Vista	Private Sewer Manhole	Roots	Roots obstructed private sewer line.	City Golf Course	Santa Ana River	N/A	Yes	The spill was not reported for an estimated 2 days, due to the fact that the residents of this complex did not identify this spill as being sewage.
3/22/04	Private Spill	No	300	200	0	0	4525 W. Coast Hwy	Newport Beach	n/a	n/a	Grease spill at ChronicTaco	See Remarks	n/a	n/a	n/a	yes	Containment setup at storm drain. Vacuum truck clean up spill, grease and stop overflow.
3/22/04	Pacific Mobile Home Park	No	30	30	80	0	Pacific Mobile Home Park, 80 Huntington St.	Huntington Beach	Sewer clean out pipe	Mobile Home	Sewer pipe was clogged.	In ground sewage hook-up pipe for Mobile Home was clogged causing sewage to back-up and overflow.	None	None	Vacuumed up and put into the sewage system.	Yes Control #04-1562	Private property owner hired Emergency Services Restoration Company to do all the clean up
3/25/04	Private Property	n/a	25	225	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
4/7/04	Private Property	No	100	40	0	100	164 Yorba Linda	Placentia	Priavate property lateral	lateral line	grease	grease	na	na	Storm drain	yes	Spill was caused by grease from business located on Kraemer / Yorba Linda in a priavate parking lot and ran through the parking lot ending up on Bradford Ave.
4/4/04	CMSD	Y	2475	525	300	0	1599 Superior Ave / 700 Block of West 16th St;	Costa Mesa, CA	Root balls blocked private sewer lateral forcing SSO out of private cleanout; possible root entry point at Ductile Iron Pipe fitting to lateral on private property;	private cleanout; possible root entry point at Ductile Iron	Root balls blocked private sewer lateral forcing SSO out of private cleanout;	Root balls blocked private sewer lateral forcing SSO out of private cleanout;	Newport Beach Harbor	None	Vactored SSO and rinse water were disposed of in the sanitary sewer system at the Corporate Yard;	Y; 4/05/2004 @ 1545 hrs	Root balls blocked private sever lateral forcing SSQ out of private deamout; possible nod entry point at Ductile inon Pipe Itting to lateral on private property; Olen Properties Property Manage at PS Solvenizer at called for two plumbing companies to dear the SSQ blareril blockage; First company unable to dear lateral with rotary cutile plade- but removed or out dusters from lateral: Second company used a min hydrojet to clarer remaining blockage; Diatrict Field Crew recommended the Property Manager wide the lateral: (or of Cotata Mass NPDE'S Manager also on-alie and took photos; CMSD Crew dammed storm drain, vactored and disposed of the contained SSQ and rines water into the District samilary sever system at the Corporate Yant; Photographs were taken and are attached.
4/12/04	Foodland Market	No	100	50	0	0	910 S. Euclid St.	Anaheim	910 S. Euclid St.	Private Cleanout	Grease	Grease caused obstruction.	Ponded in SD	N/A	N/A	Yes	Meetings have been held with representatives from Foodland.
4/12/04	Private Business	No	0	8	200	0	814 Williamson Ave	Fullerton	Private Lateral	Private Lateral Cleanout	Unknown		N/A	N/A	N/A	Yes	City crews responded to report of sewage seeping out of cleanout. City crews assisted private business to contained intermittent overflow at a sump box approximately 100 from cleanout. City crews rodded private lateral to clear blockage. All sewage wa
4/13/04	Private		3000	0	0	0	NEWPORT COAST DR	NEWPORT BEACH	N/A	LINE BREAK	LINE BREAK	STORM DRAIN	N/A	N/A	N/A	Yes	NA
4/15/04	City of Anaheim / Anaheim Fire Station #9	Yes	150	50	200	0	6300 Nohl Ranch Rd.	Anaheim	6300 Nohl Ranch Rd.	Sewer Lateral Cleanout	Construction damaged the lateral and allowed roots to invade sewer line	Roots	Flood Control Channel	Santa Ana River	N/A	Yes	NA
4/29/04	Orange County Head Start, INC.	No	5	5	0	0	14422Hammon Ln.	Huntington Beach	Drain pipe connecting to Grease Interceptor.	Grease Interceptor	Broken drain pipe.	Broken drain pipe connecting to Grease Interceptor.	None	None	Spill was contained at the grease interceptor vacuumed up and placed back into the sewer system	Yes	Drain pipe for grease interceptor in the parking lot broke and caused the asphalt to cave in. West Duke Plumbing took care of the pipe repair and clean up.
5/17/04	Private Property	n/a	25	25	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a	n/a	n/a	Yes	n/a
5/19/04	Private	No	10	10	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
5/22/04	C & C Property Management Group	No	5	50	50	0	411 N. Park Vista St.	Anaheim	411 N. Park Vista St.	Private cleanout in alley	Grease	Grease caused private lateral to become blocked and to back up.	Ponded in CB	N/A	N/A	Yes	
5/29/04	Private Property	U	0	0	0	0	17502 17TH STREET	Tustin	Sewer Line	Manhole	Blockage	Grease clog	U	U	U	Y; 5/30/2004	N/A
6/10/04	2349 W. La Palma Ave., Anaheim	No	10	40	500	0	2349 W. La Palma Ave.	Anaheim	2349 W. La Palma Ave.	Private Manhole	Sewer lateral offset	Private stormdrain installed may have offset the Sewer lateral, allowing a cell phone to block the restricted line.	Ponded in SD	N/A	N/A	Yes	Apparent delay in notification to RWQCB was due to the fact that the spill had apparently not left the site when City Staff arrived. However, after interviewing onsite personnel, it was discovered that the spill had left the site but the water was volunta
6/16/04	Sushi Ya	No	100	75	100	175	50 Centerpointe Dr.	La Palma	Private lateral	Private lateral cleanout	Grease	Grease interceptor failure.	N/A	N/A	Recovered sewage was returned to sewer system. Remainder was soaked into soil on private property.	۰Y	Private contractor sanitized and cleaned up
6/21/04	1331 E. Katella Ave., Anaheim 92805 (714) 978- 8088	No	182	250	200	0	1221 E. Katella Ave.	Anaheim	1221 E. Katella Ave.	Private clean out	Grease	Grease obstructed the flow of the Sanitary Sewer Lateral causing it to overflow	Ponded in SD	N/A	N/A	Yes	
6/21/04	AAA Management 661-252- 9035	No	50	0	1000	0	5600 E. Santa Ana Cyn Rd.	Anaheim	5600 E. Santa Ana Cyn Rd.	Private property clean out in parking lot	Grease	Grease obstructed the flow of the Sanitary Sewer Lateral causing it to overflow	Santa Ana River	Santa Ana River	N/A	Yes	
6/23/04	Private Property	n/a	500	0	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
6/24/04	Private Spill	Unknown	400	100	0	0	500 Superior	Newport Beach	n/a	n/a	Unknown	See Remarks	n/a	n/a	n/a	yes	Vactor setup dirt berm@catch basin. Vacuum setup @ manhole to stop SSO.

6/25/04	Terry Stoia 8130 Orangewood Ave., Stanton, CA 90680	No	0	20	50	0	604 W. Provential Dr.	Anaheim	604 W. Provential Dr.	Private cleanout	Grease	Grease obstructed the flow of the Sanitary Sewer Lateral causing it to overflow	N/A	N/A	N/A	Yes	
6/28/04	Private property owner	No	0	35	2000	0	305 N Harbor on Wilshire side	Fullerton	Private lateral from 305 N Harbor Blvd	Private lateral cleanout on Wilshire Ave	Roots and debris	Possible roots from parkway tree. To be determined	N/A	N/A	N/A	Yes	City crews responded to report of overflow on sidewalk. Flow was contained at 239 W Wilshire Ave. City crews cleared root and debris blockage in private lateral from businesses at 305 & 315 N Harbor. Crews washed down and vacuumed approximately 35 gall
6/28/04	Noble Mgmt. Company, 747 W. Katella Avenue, Orange, CA 92867	No	150	200	0	350	325 S. Flower Street - Private Spill	Santa Ana	clean out on lateral	Clean out	Blockage/Private Property: Large amount of paper and grease flowing from clean out.	Large amount of paper and grease flowing from clean out.	None	None	Sewage was returned to sewer system.	Yes	
6/29/04	Private Property	No	90	60	0	30	1300 Kraemer	Placentia	Private property lateral	lateral line	grease	grease	na	na	Storm drain	no	Spill was caused by grease from business located 1300 Kraemer in a priavate parking lot and ran through the parking lot ending ending up on Kraemer blvd.
7/11/04	Golden West Property Management Inc. (714) 491- 9005	Yes	3024	0	50	3024	Behind 6101 Morningside Drive	Huntington Beach	Grease blockage inside of eight inch private sewer line.	Manhole	Grease blockage	Grease buildup from a lack of maintenance.	Bolsa Chica Wetlands	None, all sewage stayed in wetland area.		Yes	Sewage flowes from 200 residents through this line. All upstream sewer lines were cleaned 7/19/04. These lines will be put on a scheduled cleaning.
7/12/04	Private Spill	No	600	0	0	0	1000 Dove St.	Newport Beach	Private cleanout	Private cleanout	Grease & Paper Products	See Remarks	n/a	n/a	n/a	yes	Setup vactor on Dove to catch & contain overflow from private cleanout at driveway.
7/12/04	Private Property	n/a	100	50	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
7/12/04	Private	No	45	45	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/13/04	Private Property	n/a	50	150	0	0	n/a	Orange	n/a	n/a	Paper	n/a	n/a	n/a	n/a	Yes	n/a
7/15/04	Private Property	U	0	0	0	0	On Canyon Terrace Rd which is just below residents house @10372 Crawford Canyon Rd.	Unincorporated County of Orange	u	Cleanout	U	u	U	υ	U	Y; 7/15/2004 5:40:00 PM	N/A
7/17/04	Private Property	n/a	25	75	0	0	n/a	Orange	n/a	n/a	Grease/unknown	n/a	n/a	n/a	n/a	Yes	n/a
7/21/04	Private Property	n/a	150	50	0	0	n/a	Orange	n/a	Broken Line	Broken Line	n/a	n/a	n/a	n/a	Yes	n/a
7/29/04	1743 S. Clementine (Extended Stay America)	Yes	260	1100	300	200	1742 S. Clementine Street	Anaheim	1742 S. Clementine Street	Private Manhole	Cloth and other debris	Cloth and debris clogged pipeline, causing sewage to overflow.	Bolsa Chica	N/A	Bolsa Chica	Yes	
8/4/04	Private	No	30	30	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
8/5/04	Private Party	yes	20	180	0	0	4901 Lincoln Ave.	Cypress	n/a	n/a	n/a	n/a	Coyote Creek	n/a	n/a	n/a	
8/12/04	Private property owner	No	0	20	200	0	741 W Commonwealth Ave	Fullerton	Private lateral	Lateral cleanout near sidewalk	Unknown		N/A	N/A	N/A	Yes	City Vactor crew observed lateral cleanout from small business complex overflowing onto City street. Crews stopped and set up Vactor vacuum at 770 W Commonwealth Are to contain spill. The City's lateral crew responded and cleared blockage in lateral to
8/29/04	Private		9450	0	0	0	DEWBERRY / SANDBURG	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN.	N/A	N/A	N/A	Yes	N/A
9/5/04	Broadmoor Huntington Harbour HOA	Yes	50	0	100	100	6905 Warner Ave.	Huntington Beach	Private sewer lateral at 3251 Moritz Drive.	Cleanout	Grease and debris blockage	Grease and debris buildup from two condo units sharing plumbing pipes.	Huntington Harbour	Pacific Ocean		Yes	Spill was reported to Huntington Beach Police Dept. they referred spill to wrong Dept. Wastewater arrived at spill two hours after reported time and sewage flow was stopped.
9/7/04	Private Property	No	0	0	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
9/9/04	Private	n/a	10	0	0	0	25361 Commerce Center Dr.	Lake Forest	n/a	n/a	Wood and concrete	e Wood and concrete	n/a	n/a	n/a	n/a	
9/11/04	Prudential Real Estate	Yes	276	200	450	76	21851 Newland Ave.	Huntington Beach	Private sewer lateral at 7931 Stark Ave.	Cleanout	Tree roots	Tree roots clogged sewer lateral for an eight unit residential complex	Wintersburg Channel, CO5	Bolsa Chica Wetlands		Yes	
9/13/04	James Estrella - Facility Manager	No	5	10	10	0	1628 South Anaheim Way	Anaheim	1628 South Anaheim Way	Private cleanout	Foreign objects	Foreign objects clogged sewe line	Ponded in SD	N/A	NA	Yes	The flow was intermittent resulting in an estimated rate of 10 gal/hr
9/21/04	Lincoln Inn, Kelly Erickson - Maint. Manager	Yes	100	0	100	0	2748 W. Lincoln Avenue	Anaheim	2748 W. Lincoln Avenue	Private cleanout	Feminine hygiene products	Feminine hygiene products got lodged in line.	Carbon Creek	N/A	NA	Yes	Hotel cleared blockage with their own equipment and proceeded to wash the spill into the onsite drop links before City Staff arrived onsite. Hotel Management was informed that the spill had to be contained onsite and City had to be contacted in the event.
9/21/04	Private Property	Y	0	400	0	0	15701 TUSTIN VILLAGE WAY	Unincorporated County of Orange	4" clean out	Clean out	Blockage	Misc. debris	Peters Canyon Wash	Peters Canyon Wash	Peters Canyon Wash	Y; 9/21/2004 9:05:00 AM	CITY OF TUSTIN TOOK PHOTOS & WILL FORWARD THEM TO OCSD. TOTAL SPILL LESS THAN 1,000 GALLONS PER FIELD OBSERVATION.
9/22/04	Private Property	No	0	0	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
9/23/04	Casa Management, 13526 E. Calora, Covina, CA 91724 (818) 468-2507, Patricia Hodura	No	720	670	1220	50	1317 S. Standard	Santa Ana	Praivate lateral	4" clean out	Paper/Grease/Private Property	Large amounts of paper and a grease geing dumped in sewer by residents and lack o a routine maintenance program.	fNone	None	Returned to sewer system	Yes	Cecilia Flores, Code Enforcement - 667-2710 contacted PWA-Agency regarding spil on 9/23/04 @ 11:00 am.

Image																		
Image: Problem No.	9/24/04	Private*	No	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
Interpression Norme Norme<	9/27/04	unit apartment complex,	N	500	1500	500	500	584 W Hamilton Street	Costa Mesa, CA	City Property, 10 unit apartment complex, Costa	Pacific City Property, 10 unit apartment complex, Costa Mesa; SSO spilled from private backyan	Pacific City Property, 10 unit apartment complex, was d blocked with	Property, 10 unit apartment complex, was blocked with	None	None	water were disposed of in the District sanitary sewer		grease; SSO spilled from private backyard cleanout; CMSD Field Crew dammed SSO in street and curb and at the SD; vactored and disposed of the contained
Image Number Number <td>10/7/04</td> <td>Private Property</td> <td>N</td> <td>10</td> <td>0</td> <td>0</td> <td>0</td> <td>7621 TRASK AV</td> <td>Westminster</td> <td>8" sewer line</td> <td>Manhole</td> <td>Blockage</td> <td>Grease Clog</td> <td>N/A</td> <td>N/A</td> <td>Soaked into ground</td> <td>Y</td> <td>Div.420 to check. No storm drain info. is known at this time. P.797 J-7. Small spill at 7621Trask Ave. is contained on private property. Approx. 10 gallons,</td>	10/7/04	Private Property	N	10	0	0	0	7621 TRASK AV	Westminster	8" sewer line	Manhole	Blockage	Grease Clog	N/A	N/A	Soaked into ground	Y	Div.420 to check. No storm drain info. is known at this time. P.797 J-7. Small spill at 7621Trask Ave. is contained on private property. Approx. 10 gallons,
Image: biology of the state	10/8/04	Wendy's Restaurant	No	10	20	0	0	2011 East La Palma Avenue	Anaheim		Private manhole	Grease	Grease clogged sewer line	Santa Ana River	N/A	Ponded in SD	Yes	Any washdown was performed by Restaurant staff under supervision of OCHCA.
Image: Note in the state interpretation of the state interpretation o	10/8/04	Private	No	150	150	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
Interview Weak	10/14/04	Private Property	n/a	50	25	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
Image: Normal state	10/21/04	 Ralph Woebkey 2180 E. Lincoln Ave., Santa Ana 	Yes	690	690	2660	690	2307 S. Bristol St.	Santa Ana	Private lateral	Clean out	Grease	located in the shopping center that maybe discharging	Upper Newport Bay	Upper Newport Bay	N/A	Yes	State ID #04-5506
Longen System L <thl< th=""> L <thl< th=""> L L <thl<< td=""><td>10/26/04</td><td>Private Property</td><td>n/a</td><td>40</td><td>25</td><td>0</td><td>0</td><td>n/a</td><td>Orange</td><td>n/a</td><td>n/a</td><td>Grease</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>Yes</td><td>n/a</td></thl<<></thl<></thl<>	10/26/04	Private Property	n/a	40	25	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
Instrument Instrum	10/29/04	Private party lateral blocked with roots;	N	1	6	31	1	690 West Hamilton St	Costa Mesa, CA	lateral; SSO spilled from private lateral cleanout at 690 West Hamilton St;	lateral; SSO spilled from private lateral cleanout at 690 Wes Hamilton St; Fully	private lateral; SS spilled from privat lateral cleanout at 690 West Hamilto	e SSO spilled from private lateral cleanout at 690 West n Hamilton St; Fully contained;	None	None	25 gals of rinse water were disposed of in the District	Y; 11/01/2004 @ 1625 hrs;	Hamilton St; Fully contained; Private owner obtained services of plumber and cleaned out the roots blocking the lateral line; Crew remained on-site until blockage
Note:Note:Not: <th< td=""><td>11/1/04</td><td>Private party lateral blocked with grease;</td><td>N</td><td>0</td><td>50</td><td>100</td><td>0</td><td>200 East 17th St.</td><td>Costa Mesa, CA</td><td>lateral cleanout approximately 10 feet from</td><td>private lateral cleanout approximately 10 fee from the curb; Greas interceptor appeared not have been maintained as evidenced from rusted bolts and cover, leading to</td><td>e Grease blocked th interceptor and th</td><td>e lateral cleanout at 200 E 17th</td><td>None</td><td>None</td><td>and 50 gallons of rinse water were disposed of in</td><td>Y; 11/01/2004 @ ~1625 hrs;</td><td>Grease interceptor appeared to not have been maintained as evidenced from rusted bolts and cover, leading to grease blockage; District Crew blocked Storm</td></th<>	11/1/04	Private party lateral blocked with grease;	N	0	50	100	0	200 East 17th St.	Costa Mesa, CA	lateral cleanout approximately 10 feet from	private lateral cleanout approximately 10 fee from the curb; Greas interceptor appeared not have been maintained as evidenced from rusted bolts and cover, leading to	e Grease blocked th interceptor and th	e lateral cleanout at 200 E 17th	None	None	and 50 gallons of rinse water were disposed of in	Y; 11/01/2004 @ ~1625 hrs;	Grease interceptor appeared to not have been maintained as evidenced from rusted bolts and cover, leading to grease blockage; District Crew blocked Storm
11404 Soft Cast Vilage No 0 600 0 0 (Dit N Decked Decked No Returned to serving to returned Test 11564 Robers and Vilage No No No Returned to serving to returned No No Returned to serving to returned No	11/1/04	Private	No	22	22	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11:504 Probability problem N D S <td>11/4/04</td> <td>South Coast Village</td> <td>No</td> <td>0</td> <td>600</td> <td>600</td> <td>0</td> <td>1001 W. MacArthur</td> <td>Santa Ana</td> <td>Unclear</td> <td>Drain in laundry roon</td> <td>n Roots</td> <td></td> <td>N/A</td> <td>N/A</td> <td>Returned to sewer system</td> <td>Yes</td> <td></td>	11/4/04	South Coast Village	No	0	600	600	0	1001 W. MacArthur	Santa Ana	Unclear	Drain in laundry roon	n Roots		N/A	N/A	Returned to sewer system	Yes	
Index <th< td=""><td>11/5/04</td><td></td><td>N</td><td>0</td><td>50</td><td>100</td><td>0</td><td>2424 University Drive</td><td>Newport Beach</td><td>lateral cleanout in a recently built sidewalk in</td><td>private lateral cleanout in a recently built sidewalk in Newport Beach;</td><td></td><td></td><td>None</td><td>None</td><td>and 50 gallons of rinse water were disposed of in the District sanitary sewer</td><td>Y 11/05/04 @ 1440 hrs</td><td>to Back Bay; Vactored 50 gallons of SSO and 50 gallons of rinse water were disposed of in the District sanitary sewer system; District Crew estimated SSO via</td></th<>	11/5/04		N	0	50	100	0	2424 University Drive	Newport Beach	lateral cleanout in a recently built sidewalk in	private lateral cleanout in a recently built sidewalk in Newport Beach;			None	None	and 50 gallons of rinse water were disposed of in the District sanitary sewer	Y 11/05/04 @ 1440 hrs	to Back Bay; Vactored 50 gallons of SSO and 50 gallons of rinse water were disposed of in the District sanitary sewer system; District Crew estimated SSO via
111004 100	11/5/04	Private		150	0	0	0	STANFORD AT NELSON	GARDEN GROVE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN.	N/A	N/A	NA	Yes	N/A
11/1004 Not No O <th< td=""><td>11/5/04</td><td>Private</td><td>No</td><td>110</td><td>100</td><td>0</td><td>0</td><td>n/a</td><td>Garden Grove</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td></td></th<>	11/5/04	Private	No	110	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
Index <th< td=""><td>11/8/04</td><td>Private Property</td><td>N</td><td>0</td><td>0</td><td>0</td><td>0</td><td>1541 FOOTHILL BL</td><td>Santa Ana</td><td>U</td><td>U</td><td>Other</td><td>U</td><td>N/A</td><td>N/A</td><td>Soaked into ground</td><td>Y; 11/8/2004 10:46:00 AM</td><td>N/A</td></th<>	11/8/04	Private Property	N	0	0	0	0	1541 FOOTHILL BL	Santa Ana	U	U	Other	U	N/A	N/A	Soaked into ground	Y; 11/8/2004 10:46:00 AM	N/A
$\begin{array}{ c c c c c c c c c c c c c c c c c c c$	11/10/04	Private	No	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/1/2/04 Anaheim Hilton Yes 880 20 400 0 777 Convention Way Anaheim 777 Convention Way Private Manhole and Cleanout Grease Grease blocked sever line, causing sewage to overflow. Anaheim Barber Channel NA Anaheim Barber Channel Yes moning which is what the flow estimate is based on. There is clear evidence that despite the large flow carried by the 15' line which was obstructed, the actual	11/11/04	Private	No	100	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/1/2/04 Private No 100 100 0 0 n/a garden Grove n/a	11/12/04	Anaheim Hilton	Yes	880	20	400	0	777 Convention Way	Anaheim	777 Convention Way		Grease	Grease blocked sewer line, causing sewage to overflow.		N/A	Anaheim Barber Channel	Yes	morning which is what the flow estimate is based on. There is clear evidence that despite the large flow carried by the 15" line which was obstructed, the actual
	11/12/04	Private	No	100	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	

11/13/04	Private Property	n/a	25	225	0	0	- /-	Orange	- 1-	- 1-	Grease	- (-	- (-	- 1-	- (-	¥	- (-
							iva	-	iva	iva		iva.	iva	iva	liva	105	1ua
11/13/04	Private	No	360	360	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/15/04	Private	n/a	250	0	0	0	#1 Federation Way	Irvine	Private manhole	Private manhole	n/a	Private manhole, unknown blockage	n/a	n/a	n/a	n/a	
11/15/04	Private	No	150	150	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/17/04	Private	No	0	50	0	0	108 30TH STREET	NEWPORT BEACH	N/A	LINE BREAK	LINE BREAK	ALL SEWAGE WAS RECOVERED.	N/A	N/A	N/A	Yes	N/A
11/19/04	Private	No	10	10	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/22/04	Private Property	No	0	0	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
11/23/04	Private Property	Ν	0	0	0	0	171 FIRST ST.	Tustin	U	U	Blockage	Misc. debris	N/A	N/A	N/A	Y; 11/23/2004 4:09:00 PM	N/A
11/24/04	FV	no	120	120	0	0	16175 Harbor Blvd	Fountain Valley			FOG accumulatio	n grease - no grease interceptor	r N/A	N/A	All material removed & depositied in sewer line	yes	NA
11/26/04	Private	n/a	1080	0	0	0	22 Pergola	Irvine	Private manhole	Private manhole	Roots	Private manhole, roots in line	n/a	n/a	n/a	n/a	
12/10/04	Private Property	Ν	0	0	0	0	4516 CHAPMAN AVE	Orange	NA	Manhole	U	U	NA	NA	NA	U	NA
12/10/04	Private	No	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
12/11/04	Woo Chung. 9944 Garden Grove Blvd., Garden Grove	No	20	80	100	0	2801 W. Ball Road	Anaheim	2801 W. Ball Road	Private Cleanouts	Grease	Roots blocked pipeline, causing sewage to overflow.	Ponded in SD	N/A	N/A	Yes	Apparently very little sewage actually reached the storm drain as it tended to pond on-site. Freants informed us that a plumber had worked at this location before and removed a large amount of roots. However, on this occasion hard evidence of discharging
12/11/04	Private	No	150	150	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
12/13/04	Private Property	No	0	25	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
12/14/04	Private	No	100	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	Yes, but did not enter the storm drain channel. Contained at storm drain outlet to channel.
12/16/04	Royale Health Care Center	Yes	300	1600	1600	300	1027 W. Central Ave.	Santa Ana	Private sewer line	Pick hole of manhole	Grease	Large amounts of grease deposits from poor maintenance program	Upper Newport Bay	None	Returned to sewer system	Yes	State ID #04-6597
12/19/04	Albertson's	n/a	0	200	0	0	3049 E. PCH, CDM	Newport Beach	Cleanout. Blockage on private lateral.	Cleanout	Blockage in privat lateral		n/a	n/a	n/a	yes	Kitty litter used to build control dykes to contained flow from cleanout. Overflow from supermarket. Parking lot was shuddown from one end to another to stop cars from driving thru puddles of sewage in lot. OCHD (Contort) and RWQCB (OES) called. Convin
12/20/04	Private Property	Ν	0	0	0	0	2355 MAIN ST	Irvine	U	Manhole	Blockage	Other Debris	NA	NA	NA	Y; 12/20/2004 4:00:00 PM	NA
12/21/04	Ron Marshall, Manager of Mr. Stox restaurant	Yes	188	100	400	0	1105 E. Katella Avenue	Anaheim	1105 E. Katella Avenue	Private cleanout	Paper Towels	Paper Towels blocked pipeline, causing sewage to overflow.	Bolsa Chica	N/A	N/A	Yes	OCHCA visited the location to determine if there were any issues inside the restaurant.
12/21/04	Private Property	n/a	100	150	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
12/28/04	Private Property	Ν	0	0	0	0	13071 ST MARKS DR	Santa Ana	4"	Clean-out	Blockage	Root obstruction in lateral line	NA	NA	Soaked into ground	Y; 12/28/2004 12:45:00 PM	Spoke with Mike Fennessy, OCHCA, and requested his staff to inspect the site since OCSD manhole/line is in the Private Property yard.
12/29/04	Private Property	Yes	50	25	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
12/30/04	Private Property	Ν	0	0	0	0	10120 SUNRISE LN	Unincorporated Count of Orange	^{ly} 4"	Clean-out	Blockage	Other Debris	NA	NA	NA	Y	NA
Totals	113		34,917	17,693	21,868	5,796											
2005																	
1/2/05	7232 Edinger shopping center	Yes	70	980	1,480	70	7232 Edinger	Huntington Beach	City's 8 inch sewer line	Manhole cover pick holes	Grease	Grease from a private shopping center lateral flowed into City's main line.	I Murdy Channel	East Garden Grove Winterburg Channel		Yes	
1/2/05	George Galanoues owner of apartment complex	Yes	2,100	900	1,400	2,100	2208 Delaware St.	Huntington Beach	Private sewer lateral	Private 4 inch sewer clean out pipe.	Grease	Grease buildup in private sewer lateral.	Huntington Beach Channel	Talbert Channel at Brookhurst St.		Yes	There were several different estimates from residents in the complex stating when the sewage started flowing above ground.

1/3/05	Private Property	N	0	0	0	0	1462 FOOTHILL BLVD	Santa Ana	4° Clean out	Clean out	Blockage	Misc. debris	NA	NA	NA	U	NA
1/3/05	Private	No	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
1/4/05	Lake Summit Association	Yes	60	40	500	0	920 S. Ridgecrest Circle	Anaheim	Near 920 S. Ridgecrest Circle	Private Manhole	Grease	Grease blocked pipeline, causing sewage to overflow.	Santa Ana River	Pacific Ocean	N/A	Yes	Spill appeared to be flowing at a far greater rate than 50 gph. However, the sewer line that was obstructed only serves 20 homes and a typical flow at 10 am would likely be approximately 50 gph. Therefore, the additional flow is suspected to be from Inflo
1/13/05	Wonson Kim, owner, Fullerton Inn Hotel	Yes	700	200	3000	0	2601 W Orangethorpe - Fullerton Inn Hotel	Fullerton	Private lateral @ 2601 W Orangethorpe	Private lateral cleanout	Debris, paper	City lateral rod crew cleared unknown blockage from upstream	Ash Channel to Fullerton Creek Channel	Pacific Ocean		Yes	City sewer crews noticed sewage flow from driveway at small hotel. City crews set up vactor vacuum at downstream catch basin while waiting for additional crews. City rodding crews and additional combo truck responded, cleared private lateral, washed down
1/13/05	Gene Opfic homeowner of 8472 Arnett Dr.	NO	0	15	15	0	8472 Arnett Dr.	Huntington Beach	Sewer lateral	Sewer clean out pipe	Grease	Grease buildup in private sewer lateral. Renter at property removed clean out cap because owner would not repair.	None	None		Yes	Renter at property called City, because owner would not fix the problem. City contracted the property owner that called a plumber to repair.
1/14/05	Pavilions Von's	No	0	700	0	0	Von's Pavilon	Newport Beach	n/a	n/a	Grease logs & grease in pipe	See Remarks	n/a	n/a	n/a	yes	Vactor used to vacuum up sewage flow. Flow did not enter drain.
1/14/05	Private Property	n/a	50	50	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
1/15/05	Private	No	3500	3500	0	0	10200 Chapman	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
1/17/05	Private	n/a	123	0	0	0	14400 Culver Dr.	Irvine	Grease Trap	Grease Trap	Grease	Grease Trap overflow	n/a	n/a	n/a	n/a	
1/17/05	Private		20	0	0	0	250 CHANNEL ROAD	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	GUTTER	N/A	N/A	N/A	Yes	N/A
1/19/05	Property Owner	Yes	60	100	200	60	3041 S. Bristol	Santa Ana	Private lateral	4" clean out	Paper/Grease/Private Property	Build up of paper and grease	Santa Ana/Alton Channel	None	N/A	Yes	None
1/19/05	Property Owner	No	0	0	0	0	201 E. 4th Street	Santa Ana	Private lateral	4" clean out	Grease	Plumber said there was grease in the lateral	None	None	N/A	No	None
1/24/05	Private Property	n/a	0	0	0	0	311 W. LAMBERT RD.	La Habra	n/a	Private lateral	n/a	n/a	n/a	n/a	n/a	n/a	
1/25/05	Victoria Townhouse Apartments	Yes	1050	7500	500	0	2256 W. Lincoln Ave.	Anaheim	2256 W. Lincoln Ave.	Private Manhole	Grease & Roots	Roots and grease blocked pipeline, causing sewage to overflow.	Coyote Creek	San Gabriel River	N/A	Yes	Property owner called private plumber at 2:00 PM but did not show up until 6:00 PM. City crews cleared the obstruction at 5:45 PM. Plumber would not have been able to clear blockage anyway, since he did not have the equipment to do so. Attached are two vo
1/27/05	Private Property	N	20	0	0	0	1722 MITCHELL	Tustin	4" Clean out	Clean out	Blockage	Grease clog	NA	NA	NA	U	NA
1/31/05	Private		0	0	0	0	4362 LINCOLN	CYPRESS	N/A	N/A	BLOCKAGE - UNKNOWN		N/A	N/A	N/A	Yes	N/A
2/4/05	Private Property	Ν	0	0	0	0	1581 N. FOOTHILL BLVD	Unincorporated County of Orange	NA	GROUND	U	U	NA	NA	NA	Y; 2/4/2005 4:30:00 PM	NA
2/7/05	Private		0	0	0	0	233 CARNATION	NEWPORT BEACH	N/A	N/A	UNKNOWN	ON-SITE	N/A	N/A	N/A	Yes	N/A
2/8/05	1310 W. Pearl St.	No	0	60	300	0	1310 W. Pearl St.	Anaheim	1310 W. Pearl St.	Private Cleanouts	Grease & Paper Towels	Grease and paper towels blocked pipeline, causing sewage to overflow.	N/A	N/A	N/A	Yes	
2/10/05	Private	No	5	5	0	0	11418 Knott	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
2/14/05	Private Property	Ν	0	0	0	0	10511 EASTER HILL DR.	Unincorporated County of Orange	U	U	U	U	NA	NA	NA	NA	Arrived on site at 10:50am. Checked OCSD M/H. All lines were flowing normal. We set up flush truck and ran customer line 319 feet, bringing back nothing. Gated community, customer was not home.
2/17/05	Private	n/a	30	0	0	0	20041 Osterman St.	Lake Forest	Cleanout	Cleanout	n/a	4" private cleanout-blockage	n/a	n/a	n/a	n/a	
2/20/05	El Pollo Loco	No	20	20	20	0	969 S. Euclid St.	Anaheim	969 S. Euclid St.	Private cleanout and Private Manhole	Grease or possibly other.	Grease blocked pipeline, causing sewage to overflow.	N/A	N/A	N/A	Yes	Upon arrival, spoke with the Manager of Little Caesar's Pizza (Maria) that initially reported the spill at neighboring business, El Pollo Loco. City staff then went to check city's main line and found it to be flowing well. I contacted the assistant manage
2/20/05	Private Property	n/a	0	0	0	0	1360 W. LAMBERT RD	La Habra	n/a	n/a	Grease	n/a	n/a	n/a	n/a	n/a	
2/20/05	Private		50	0	0	0	905 IDAHO ST.	LA HABRA	N/A	N/A	GREASE	MANHOLE TO CURB AND GUTTER TO STORM DRAIN.	N/A	N/A	N/A	Yes	N/A
2/23/05	Carl's Jr	No	40	40	60	0	5012 La Palma Ave.	La Palma	Private Lateral	Manhole	Grease	Grease blockage from private property and sedement	N/A	N/A	Returned to sewer s	ystem Y	Private contractor sanitized and cleaned up
2/26/05	FV	no	50	500	600	50	Euclid & Edinger	Fountain Valley	Between building & street cleanouts		grease build up	grease	NA	NA	Vaccumed spill	yes	Inspectd OCSD trunk line, they were flowing free and clear. Assisted City of Fountain Valley w/vactor. Health Dept responded at 7:00pm and shut down the restaurant that was contributing to the spill.
2/26/05	Private		500	0	0	0	13011 NEWPORT	TUSTIN	N/A	N/A	BLOCKAGE - UNKNOWN	STORM DRAIN	N/A	N/A	N/A	Yes	N/A

2/28/05	Richard Li property owner	YES	200	175	375	25	7872 Stark St.	Huntington Beach	Private sewer lateral	Private sewer lateral clean out at 7873 Stark St.	Grease	Buildup of grease in private sewer lateral.	East Garden Grove Winterburg Channel	Bolsa Chica wetlands		YES	Only one tenant home doing laundry at the time of the spill.
3/1/05	Private	Yes	0	0	0	0	453 SUMMERFIELD CIRCLE	ANAHEIM	N/A	N/A	GREASE	STORM DRAIN -> EAST GARDEN GROVE WINTERSBERG CHANNEL - > LOWER BOLSA	WINTERSBERG CHANNEL	N/A	N/A	Yes	NA
3/5/05	Private		40	0	0	0	540 FREEDOM	ORANGE	N/A	N/A	BLOCKAGE - UNKNOWN	STORM DRAIN/STREET	N/A	N/A	N/A	Yes	N/A
3/7/05	Private	No	842	842	0	0	10022 Garden Grove Blvd.	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
3/8/05	MBJ Property Management	Yes	290	400	2000	0	2500 E Chapman Ave @ St College	Fullerton	Private lateral to the rear of 2506 E Chapman Ave	Private lateral cleanout	Unknown		Fullerton Creek Channel	Pacific Ocean		Yes	City crews responded to private lateral overflow from cleanout to the rear of 2506 E Chapman Ave. Sewage was flowing down alley swale to storm drain inlet in approach to alley off St College Bivd. City crews contained flow at storm drain and several are
3/10/05	Private	No	64	64	0	0	12572 Harbor	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
3/12/05	Private Property	Yes	700	200	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
3/14/05	Private	No	30	30	0	0	9691 Garden Grove Blvd.	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
3/16/05	Private Property	No	0	60	0	0	10488 Valley View	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
3/16/05	Denny's Restaurant	N	0	60	160	0	105 East 17th St	Costa Mesa, CA	Denny's Restaurant grease interceptor not maintained/cleaned; - District Crew Fully Contained SSO in parking lot and vactored;	Denny's Restaurant grease interceptor not maintained/cleaned; - District Crew Fully Contained SSO in parking lot and vactored;	Denny's Restauran grease interceptor not maintained/cleaneo ; - District Crew Fully Contained SSO in parking lot and vactored;	Denny's Restaurant grease interceptor not maintainad/cleaned; - District Crew Fully Contained SSO in parking lot and vactored;	None	None	Vactored 60 gallons of SSC and 100 gallons of rinse water were disposed of in the District sanitary sewer system;	Y; 3/16/2005	OC Environmental representative Mile (714-433-6120) called SSO in to CMSD: OC Environmental and down Denvy's Restaurant due to the SSO from the grease interreport: Estimated 60 gallons SSO from single pickhole in a cleanout; Crew contained SSO; SSO did n
3/20/05	Private	Yes	350	150	0	0	745 DOVER	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	PRIVATE CLEAN OUT TO PARKING LOT TO STORM DRAIN TO NEWPORT BAY	Newport Bay	N/A	N/A	Yes	N/A
3/20/05	Private	No	631	631	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
3/22/05	Private Property	n/a	0	4	0	0	n/a	Orange	n/a	Cleanout Cap Rmvd	Cleanout Cap Rmvd	n/a	n/a	n/a	n/a	Yes	n/a
3/26/05	Private	No	5	0	0	0	2212 S. MONTE VISTA	LA HABRA	N/A	N/A	BLOCKAGE - UNKNOWN	ALL DISCHARGE CONTAINED ON SITE.	N/A	N/A	N/A	Yes	N/A
3/29/05	Private	No	175	175	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
4/1/05	Private Property	n/a	200	250	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
4/1/05	Private	No	14	14	0	0	8042 Garden Grove Blvd.	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
4/5/05	Private Property	No	0	100	0	0	8810 San Antonio	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
4/5/05	Private	No	2020	2020	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
4/7/05	FV	no	45	45	0	0	17099 Brookhurst Street	Fountain Valley	private property sewer lateral		grease blockage	grease blockage private sewerlateral	NA	NA	Private company removal OCSD	yes	NA
4/9/05	FV	no	150	100	0	0	18030 Brookhurst	Fountain Valley	unknown		grease blockage	sewage line back up at lowest point	East Valley Channel	NA	Roto-rooter,sandbags vactor jet removal	yes	Grease interceptor maintenance needed.
4/12/05	Private	No	200	100	50	0	1770 Harbor Blvd. Anaheim	Anaheim	1770 Harbor Blvd. Anaheim	Private clean out	Grease / Break in sewer line	Grease caused blockage. Pipeline broken during cleanout process	N/A	N/A	Contained and collected by vactors Disposed into sewe	/ ar	Video showed evidence of a break. Repairs are required by July 2
4/13/05	Private Property	Ν	50	0	0	50	1505 CLEARVIEW LN	Unincorporated County of Orange	4*	Cleanout	Blockage	Root obstruction pushed in from connecting line	Soaked into ground	Soaked into ground	Soaked into ground	Y; 4/13/2005 3:50:00 PM	Private Property
4/18/05	Private	No	75	75	0	0	11072 Magnolia	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
4/19/05	Business Properties Management Company	No	300	300	0	0	10132 Adams Ave.	Humtiogton Beach	Private business complex sewer line.	Private property manhole	Grease	Sewer line had grease and debris blocking the line.	None	None	All storm water in the area goes to the Meredith storm water pump station, that is being diverted to the City's sewer system.	Yes	This shopping center has at least five FSE's. They are on a sewer cleaning maintenance program, but will be making this program more frequent.
4/23/05	Private Property	Ν	0	1300	1460	0	1171 PACKERS CIR	Tustin	8"	Manhole	Blockage	Grease clog	Contained in Storm Drain/Channel	Contained in Storm Drain/Channel	Contained in Storm Drain/Channel	Y; 4/23/2005 4:55:00 PM	Private Property

															1		
4/25/05	Private Property	n/a	0	0	0	0	515-523 HEATHER AVE	La Habra	n/a	n/a	Grease & Roots	n/a	n/a	n/a	n/a	n/a	
4/26/05	Private Property	n/a	0	0	0	0	1232 N. PALM	La Habra	n/a	Septic Tank	n/a	n/a	n/a	n/a	n/a	n/a	
4/29/05	Private Property	n/a	0	0	0	0	119 1/2 LEORA ST	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
4/29/05	Private		100	0	0	0	6300 REGIO	BUENA PARK	N/A	LINE BREAK	LINE BREAK	STORM DRAIN.	N/A	N/A	N/A	Yes	N/A
5/4/05	Private	Yes	50	0	0	0	1773 W. Lincoln Ave.	Anaheim	1773 W. Lincoln Ave. Anaheim	Private clean out	Grease	Grease caused obstruction.	Carbon Creek	N/A	Carbon Creek	Yes	The spill had occurred intermittently over the 24 hours prior to City Staff arrival. A clear link, which Bakery management acknowledged, was made between the excessive amounts grease in the manhole and the obstruction which caused the spill.
5/7/05	Private		0	0	0	0	4941 LA PALMA AVENUE	LA PALMA	N/A	N/A	GREASE	GUTTER TO STORM DRAIN	N/A	N/A	N/A	Yes	N/A
5/7/05	Hannam Matket	No	10	100	370	0	4800 La Palma Ave.	La Palma	Private Lateral	Manhole	Grease	Grease blockage from private property	N/A	N/A	Returned to sewer system	Y	Private contractor sanitized and cleaned up
5/9/05	Private Property	n/a	0	0	0	0	2212 S. MONTE VISTA ST.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
5/13/05	Private	No	79	79	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
5/15/05	FV	no	30	30	0	0	9037 Garfield	Fountain Valley	private property sewer lateral		grease build up	grease blockage private sewe lateral	er NA	NA	vaccumed & returned to sewer	yes	NA
5/16/05	Mesa Verde Town Homes;	N	40	60	160	40	666 West 19th St	Costa Mesa, CA	Roots in private lateral line of Newport Mesa Town Homes caused SSO to spill from cleanout;	Roots in private lateral line of Newport Mesa Town Homes caused SSO to spill from cleanout;	Roots in private lateral line of Newport Mesa Town Homes caused SSO to spill from cleanout;	Roots in private lateral line of Newport Mesa Town Homes caused SSO to spill from cleanout;	Miles of storm drain leading to Newport Bay;	None	Lost SSO due to it soaking into the ground and evaporation - estimate 40 gallons;	Y; 5/16/05 @ 1600 hrs;	One District Crew contained SSO (upon arrival) from further entering the Storm Dani (SD) until private plumber arrived to clear private lateral line of roots; Distric called ou C&R plumbing to clean the line; SD used as additional containment vessel; C
5/19/05	Private Property	No	0	60	0	0	7758 Knott Ave	Buena Park	n/a	n/a	Paper	n/a	n/a	n/a	n/a	n/a	n/a
5/20/05	FV	no	25	25	0	0	16275 Harbor Blvd	Fountain Valley	private property sewer lateral		blockage	clogged sewer lateral not grease interceptor	NA	NA	OCSD	yes	NA
5/23/05	Private	No	119	119	0	0	12991 Rosewood	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
5/23/05	Private Property	N	0	15	15	0	1451 NISSON RD	Unincorporated County of Orange	Septic Tank	Manhole	Blockage	Misc. debris	NA	NA	NA	Y; 5/23/2005 3:35:00 PM	NA
5/24/05	Private	n/a	20	0	0	0	Jeffrey/Walnut	Irvine	Grease interceptor	Grease interceptor	Grease	Grease interceptor overflow- Chinese Restaurant	n/a	n/a	n/a	n/a	
5/27/05	Private	no	0	20	200	200	1731 W. Katella Ave. Anaheim	Anaheim	1731 Katella Ave Anaheim	Private clean out	Paper towels and grease	Paper towels and grease caused obstruction.	N/A	N/A	N/A	Yes	
5/27/05	Watt Properties Management Company	No	25	25	25	0	8965 Atlanta Ave.	Huntington Beach	Private sewer pipe.	Sewer cleanout located on private property.	Broken sewer pipe.	Broken sewer pipe at an isolation valve located in a shopping center.	None	None	City sewer system.	Yes	All storm water in this area is being diverted into the sewer system.
5/29/05	Private	Yes	3000	1200	200	200	801 N. Loara Street Anaheim	Anaheim	801 N. Loara Street Anaheim	Private clean out	Rags	Blockage caused by rags clogging lateral line.	Carbon Creek	Crecent Retarding Basin	Crecent Retarding Basin	Yes	
5/30/05	Private	No	451	451	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
5/31/05	Private	n/a	100	0	0	0	17605 Harvard	Irvine	Grease interceptor	Grease interceptor	Grease	Grease interceptor overflow- Ralphs	n/a	n/a	n/a	n/a	
5/31/05	City of La Palma	No	0	15	40	0	7822 Walker Street	La Palma	Lateral line	Cleanout	Blockage	Roots	N/A	N/A	Emergency Services removes contamonated soil and water off site	Y	Private contractor sanitized and cleaned up
5/31/05	Private Property	n/a	100	250	0	0	1040 Katella	Orange	n/a	Grse/Brkn Equip	Grse/Brkn Equip	n/a	n/a	n/a	n/a	Yes	n/a
6/1/05	Pacific West Management Corp.	No	300	300	500	0	5971 Warner Ave.	Huntington Beach	Private sewer line	Private system clean out.	Grease blockage	Grease blockage from restaurants in business complex.	East Garden Grove Wintersburg Channel	The Bolsa Chica Wetlands.		Yes	A clitzen reported sewage spilling from this same clean out earlier in the day, but we could not see any evidence of this. If the spill did occur earlier in the day than an unknown amount of sewage could have made it into the E Garden Grove Wintersburg C
6/3/05	Private	No	28	28	0	0	12158 Brookhurst	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
6/4/05	Private	No	0	20	50	50	1384 S. Gilbuck St.	Anaheim	1384 S. Gilbuck St.	Private clean out	Roots	Roots caused obstruction.	N/A	N/A		Yes	The volume of the spill was likely larger than the 20 gallons that were cleaned up. However, since the leak was very slow and ponded in street over a couple day, evaporation accounts for the remaining approximately 100 gallons.
6/6/05	Private	No	0	40	200	200	175 S. Harbor Blvd.	Anaheim	175 S. Harbor Blvd.	Private clean out	Grease	Grease caused obstruction.	N/A	N/A		Yes	NA
6/6/05	FV	no	15	15	0	0	11707 Edinger Ave	Fountain Valley	just past interceptor at lateral		grease build up	lack of interceptor maintenance	NA	NA	Cleaned by private company	yes	NA
L	1						1	1	I	1	t		i	i	1	1	

6/10/05	Private	Yes	100	800	200	200	537 N. Magnolia Ave.	Anaheim	537 N. Magnolia Ave.	Private clean out and private manhole	Pump shut down	Pump shut down caused obstruction	Coyote Creek	N/A		Yes	The property owner/imanager contacted a pump company (Orange County Pumping) who corrected the problem with the pump station. The area is front of the building was used by the City staff, however, other areas along the side of the building-not-accessable
6/13/05	Private	No	75	75	0	0	10212 Westminster	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
6/17/05	Private Property	n/a	75	40	0	0	2127 Quincy	Orange	n/a	n/a	Pumped to St.	n/a	n/a	n/a	n/a	Yes	n/a
6/18/05	Private Property	Yes	100	0	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
6/20/05	Vons Market	Yes	50	25	0	0	1000 Bayside Dr.	Newport Beach	n/a	n/a	Grease	See Remarks	Pacific Ocean	n/a	n/a	yes	Water Crew built a berm to contain the overflow to and called for a vactor to clean up the spill. Vactor remained onsite until the blockage was clearned.
6/20/05	Private Property	N	300	100	300	200	13102 NEWPORT BLVD	Tustin	8" Private Sewer	Private Manhole	Grease	Blockage	Peters Canyon Wash	NA	Peters Canyon Wash	Y; 6/20/2005 4:15:00 PM	Sherrell Brown called divsion 420; Jeff Peterson is sending crew - Don Cleveland and Duane Smith to respond. Dindo Carrillo notified right away and called the Health Department. Mr. Fennessy of the Health Dept is responding.
6/21/05	Private	n/a	20	0	0	0	17 E. Yale Loop	Irvine	Cleanout	Cleanout	Grease	Private clean-out grease	n/a	n/a	n/a	n/a	
6/22/05	Private Property	N	676	636	886	40	13102 NEWPORT BLVD	Tustin	8" Private Sewer	Private Manhole	Grease	Blockage	Peters Canyon Wash	NA	Peters Canyon Wash	Y; 6/22/2005 8:25:00 AM	City of Tustin on site called in spill. Sent OCSD crew with vactor truck to assist. Truck vactored up a total of 500 galons, including 250 galons of wash water. Spill was approx. 250 galons. All was cleaned up at 1pm. Private plumber was called & He
6/28/05	Private	No	360	350	200	200	1151 N. Euclid St	Anaheim	1151 N. Euclid St	Private clean out	Grease	Grease caused obstruction.	N/A	N/A		Yes	N/A
6/29/05	Private Property	n/a	0	0	0	0	1300 W.LAMBERT RD	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
6/30/05	FV	no	70	70	0	0	17075 Bushard	Fountain Valley	private property sewer lateral		grease build up	private lateral	NA	NA	Vaccumed & returned to sewer	yes	NA
7/1/05	Private		0	0	0	0	2735 W. COAST HWY.	NEWPORT BEACH	N/A	N/A	GREASE	N/A	N/A	N/A	N/A	Yes	N/A
7/7/05	Private	No	2	200	500	2	627 North Euclid Street	Anaheim	627 North Euclid Street	Private clean out	Grease	Grease caused obstruction	N/A	N/A		Yes	N/A
7/11/05	Private Property	N	0	0	0	0	10072 FOX SPRING RD	Unincorporated County of Orange	U	Septic tank	Other	Other	NA	NA	Soaked into ground	Y; 7/11/2005 12:20:00 PM	NA
7/17/05	Private Property	n/a	0	0	0	0	1800 W. WHITTIER BL.	La Habra	n/a	Grease Interceptor	Grease	n/a	n/a	n/a	n/a	n/a	
7/19/05	Pacific Comm.	No	450	2800	0	0	1000 Dove St.	Newport Beach	Private Cleanout	Private Cleanout	Grease & Paper Products	See Remarks	n/a	n/a	n/a	yes	Burmed the gutter before the storm drain then set up the vactor before the burm. Notified the owne to call a plumber because it is a private clean out.
7/23/05	Private		0	4	0	0	1016 IRVINE AVENUE	NEWPORT BEACH	N/A	N/A	PAPER	PARKING LOT/DRIVEWAY	N/A	N/A	N/A	Yes	N/A
7/24/05	Private	n/a	50	0	0	0	19211 Jasper Hill Rd.	Portola Hills	Cleanout	Cleanout	Asphalt debris	Asphalt blocked line-cleanout overflowed	n/a	n/a	n/a	n/a	
7/26/05	America	Unknown	0	50	0	0	3601 Jamboree Rd	Newport Beach	Grease interceptor	Grease interceptor	Grease, near the grease interceptor.	See Remarks	n/a	n/a	n/a	yes	Fire Dept. built a berm at the nearest catchbasin, Gen. Serv. StormDrain crew responded with a vactor to vacuum contained material, code enforcement took pictures & cited the Property Mgmt. Co. America West Properties, Cit#12005-0734.
7/27/05	Private	No	0	900	600	0	2108 E. Lincoln Ave.	Anaheim	2108 E. Lincoln Ave.	Private clean out	Grease	Grease caused obstruction	Ponded in gutter	N/A		Yes	Mark Williams from County Environmental Health Services arrived on site at 12:25 PM to investigate and assist. Spill did not reach underground storm drain system because sandbags and filter fabric were already blocking catch basin in street, since constr
7/29/05	Costa Mesa Sanitary District	N	0	5	55	0	584 Hamilton St	Costa Mesa, CA	Grease blocked private lateral line in a multifamily residential development forcing SSO out of private property cleanout;	Grease blocked private lateral line in : multifamily residentia development forcing SSO out of private property cleanout;	I residential development	Grease blocked private lateral line in a multitamily residential development forcing SSO out of private property cleanout;		None;	Vactored SSO was disposed of in the District Sanitary Sewer System;	Y; 8-04/05 @ 1420 hrs;	SSO trickled from private lateral cleanout onto private property and to the street and nearby storm drain (SD) which acted as a containment vessel; Crew blocked SD and vactored SO while private plumber (Coast General Plumbing) was en route to the site; C
8/2/05	Private lateral Tony Romas	Yes	20	100	200	0	1300 S Harbor Blvd	Fullerton	Private lateral	lateral cleanout	Paper		Discharge basin at Riverside Frwy	Unknown		Yes	The City's emergency crew responded to report of sso from private deanout. City crew contained sewage at storm drain, dispatched sewer on call crews. Restaurant called private plumber. There was no overflow inside facility. City crews washed down and
8/4/05	Private Property	n/a	0	0	0	0	821 CORTO WAY	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
8/5/05	Private		65	0	0	0	8699 HILLCREST	BUENA PARK	N/A	N/A	CLEAN-OUT CAP MISSING	CLEAR WATER TO STORM DRAIN.	N/A	N/A	N/A	Yes	N/A
8/9/05	Private		0	50	0	0	1101 N. BAYFRONT	NEWPORT BEACH	N/A	N/A	PAPER	ALLEYWAYS	N/A	N/A	N/A	Yes	N/A
8/13/05	Sabatino's	No	0	10	0	0	251 Shipyard Way	Newport Beach	Holding tank	Holding tank	Grease	See Remarks	n/a	n/a	n/a	yes	Used vactor to sack out a 4'x4'x4' deep holding tank that was full and keeping the sewage from the bag.

	1	1	1				1		1		1		1			1	
8/14/05	Private		0	5	0	0	1311 W. BAY	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	ALLEY	N/A	N/A	N/A	Yes	N/A
8/14/05	Private		0	2	0	0	1817 BEDFORD ROAD	NEWPORT BEACH	N/A	N/A	ROOTS	GUTTER	N/A	N/A	N/A	Yes	N/A
8/16/05	Private	n/a	20	0	0	0	6503 Quail Hill	Irvine	Effluent line	Effluent line	Plug	Plug left in effluent line from grease trap	n/a	n/a	n/a	n/a	
8/16/05	Private Property	n/a	0	63	0	0	274 N Glassell	Orange	n/a	BckFlw Mlfnct/Grs	BckFlw Mlfnct/Grs	n/a	n/a	n/a	n/a	Yes	n/a
8/16/05	Private		0	0	0	0	6885 WARNER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE	STORM DRAIN WITH DIVERSION.	N/A	N/A	N/A	Yes	N/A
8/16/05	Private Property	N	0	0	0	0	1771 LA LOMA DR.	Unincorporated County of Orange	Private Lateral	Cleanout	Blockage	Root obstruction in lateral line	Soaked into ground	NA	Soaked into ground	Y; 8/16/2005 11:30:00 AM	Div.420 arrived at site to find private property spill at homeowners clean-out. They ran the line/manhole downstream of property and cleaned out some roots. H owever, lateral is blocked with roots on homeowers property at 4in. cleanout. Homeowner is not
8/17/05	Private Property	n/a	0	0	0	0	n/a	Orange	n/a	n/a	Grease/ Vandalism	n/a	n/a	n/a	n/a	Yes	n/a
8/22/05	Private Property	No	0	30	0	0	5317 Humbolt	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
8/23/05	Private	No	0	15	0	0	28232 BEACH BLVD.	HUNTINGTON BEACH	N/A	N/A	ROOTS	CONTAINED IN CURB AND GUTTER	N/A	N/A	N/A	Yes	N/A
9/6/05	Private Property	n/a	500	1000	0	0	n/a	Orange	n/a	Cleanout Cap Rmvd	Cleanout Cap Rmvd	n/a	n/a	n/a	n/a	Yes	n/a
9/7/05	Private		2340	0	0	0	30 SCENIC BLUFF	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN TO CREEK	N/A	N/A	N/A	Yes	May be R-9
9/13/05	Private Property	N	15	0	0	0	19511 HOLIDAY LN	Unincorporated County of Orange	4-in lateral line	Clean-out	Blockage	Root obstruction in lateral line	NA	NA	Soaked into ground	Y; 9/13/2005 12:45:00 PM	NOT OCSD PROBLEM
9/18/05	Private	No	0	100	0	0	310 S. JEFFERSON	PLACENTIA	N/A	N/A	BLOCKAGE - UNKNOWN	STAYED ON SITE	N/A	N/A	N/A	Yes	N/A
9/19/05	Private	No	61	61	0	0	10012 Westminster	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
9/23/05	FV	no	48	28	0	0	11045 Warner Ave	Fountain Valley	private property sewer lateral		grease build up	private lateral, multilpe restaurants	NA	NA	OCSD	yes	NA
9/24/05	Private	Yes	2160	1200	200	0	1199 N. Euclid Street	Anaheim	1199 N. Euclid Street	N/A	Grease	Grease caused spill	Fullerton Creek	San Gabriel River		Yes	OCHCA assisted onscene and washdown was performed by a private party.
9/27/05	Private Property	n/a	0	0	0	0	500 Teakwood Ave.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
10/3/05	Private	No	970	100	300	0	2138 W. Brownwood Ave.	Anaheim	2138 W. Brownwood Avenue	N/A	Grease/Break	Grease and/or Break caused the obstruction	Carbon/Creek	N/A	Ponded in Storm Drain	Yes	This was an unusual spill due to the fact that we never were able to contact the owner by phone (or by any other method). HCA investigated contact information and City Code Enforcement as well as Utilities Billing were unable to obtain a good phone number
10/10/05	Private	No	215	215	0	0	9855 Hewitt	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
10/16/05	Private Property	N	0	300	400	0	10250 BEACH BLVD. Fair Crest Apartments	Stanton	NA	Manhole	Blockage	Grease Clog	NA	NA	NA	Y; 10/16/2005 10:40:00 AM	
10/18/05	Private		400	425	0	0	18555 YORBA LINDA BLVD	. YORBA LINDA	N/A	N/A	BLOCKAGE - UNKNOWN	CURB & GUTTER -> STORM DRAIN	N/A	N/A	N/A	Yes	N/A
10/19/05	Private	No	64	64	0	0	10072 Westminster	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
10/20/05	Private	Yes	29	50	0	0	17199 BLUEWATER LANE	HUNTINGTON BEACH	N/A	N/A	ROOTS & GREASE	MANHOLE TO SIDEWALK TO BULKHEAD TO BAY WATER	N/A	N/A	N/A	Yes	NA
10/24/05	Private	No	5	45	40	0	732 N. East Street	Anaheim	732 N. East Street	N/A	Roots	Roots caused obstruction	Carbon Creek	N/A	Ponded in Storm Drain	Yes	N/A
10/24/05	Private Property	n/a	25	15	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
10/25/05	Private	Yes	20	10	0	0	behind 2235 Pacific Dr	Newport Beach	Broken pipe	Broken pipe	Broken pipe on the hillside that was discharging sewage.	See Remarks	n/a	n/a	n/a	yes	Setup beam and vactor on Bayside Dr, used two flagmen for traffic control. Contacted Michael Bayer at 2235 Pacific Dr. to advise him he had a problem.

11/3/05	Costa Mesa Sanitary Distr	ict N	0	45	100	5	2520 Kincaid Drive	Costa Mesa, CA	Unknown blockage blocked private lateral line in a multifamily residential complex at Fairview State Hospital forcing SSO out private property M/H;	residential complex at	Unknown blockage blocked private lateral line in a mutifamily residential complex at Fairview State Hospital;	Unknown blockage blockad private lateral line in a multifamily residential complex at Fairview State Hospital;	None;	None;	Vactored SSO was disposed of in the District Sanitary Sewer System;	Y; 11-17/05 @ 1650 hrs;	Unknown blockage blocked private latered line in a multifamily residential complex an Fainwee State Hoophal forcing SSO aut of private property MH: Danied crew blocked SD, vactored SSO from the street, curb and SD; flushed the area with freah rinse w
11/3/05	Private Property	n/a	0	0	0	0	1750 W.Lambert Rd.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
11/4/05	Private Party	no	0	15	0	0	4001 Orange Ave	Cypress	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/5/05	Private Property	no	0	10	0	0	14636 Goldenwwest Ave Westminster	Westminster		cleanout	n/a	na	Westminster Channel	n/a	Returned to sewer system	no	Spill reported by Westminster City water standby.
11/6/05	Private	No	0	80	0	0	1530 PLACENTIA	NEWPORT BEACH	N/A	N/A	GREASE	CONTAINED ON SITE	N/A	N/A	N/A	Yes	NA
11/8/05	Private	No	0	0	0	0	20142 MCKINLEY LANE	HUNTINGTON BEACH	N/A	LINE BREAK	LINE BREAK	SOAKED INTO SOIL	N/A	N/A	N/A	Yes	N/A
11/9/05	Private Property	n/a	0	0	0	0	550 W. La Habra BL	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
11/10/05	Private	No	20	20	0	0	9802 Katella	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/14/05	Private Property	n/a	0	100	0	0	426 W. Almond Ave.	Orange	n/a	Building basement and Railroad right of way	Grease/Roots	Building basement and Railroad right of way	n/a	n/a	n/a	Yes	n/a
11/14/05	Private Property	N	0	0	0	0	13502 SUSSEX PLACE	Unincorporated County of Orange	8-inch lateral	U	Blockage	Misc. debris	NA	NA	NA	Y; 11/14/2005 4:00:00 PM	None
11/18/05	Private	No	121	121	0	0	8042 Garden Grove Blvd.	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/20/05	Private		0	20	0	0	1101 PINE STREET	HUNTINGTON BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	N/A	N/A	N/A	Yes	NA
11/25/05	Private	n/a	225	0	0	0	26652 Portola Pkwy	Foothill Ranch	Private lateral	Private lateral	n/a	Blockage in lateral between interceptor and main line	n/a	n/a	n/a	n/a	
11/28/05	Private - Tony Roma's Restaurant	Yes	160	30	50	0	1300 S Harbor Blvd	Fullerton	Private lateral	Private lateral cleanout	Grease, debris		Discharge basin at 91 Frwy/ S Harbor Blvd	Unknown		Yes	Emergency night crew responded to private lateral overflow all Tony Romas. Crew placed sand bags around storm drain. Sewer on call crew responded, cleared greese blockage in lateral to stop overflow, cleaned area. Follow up activities will b performed
11/28/05	Private	No	355	355	0	0	12851 Haster	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
12/2/05	Private Property	n/a	0	0	0	0	1233 W. La Habra Bl.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
12/4/05	Private	n/a	1000	0	0	0	Lake Forest & Rockfield	Lake Forest	n/a	n/a	Grease	Grease blockage	n/a	n/a	n/a	n/a	
12/9/05	Private		0	0	0	0	2085 N. HIGHLAND	ORANGE	N/A		BLOCKAGE - UNKNOWN	N/A	N/A	N/A	N/A	Yes	NA
12/14/05	Private	Yes	143	2	0	0	8052 ADAMS	HUNTINGTON BEACH	N/A	N/A	GREASE	STORM DRAIN -> TALBERT CHANNEL (DIVERTED TO SEWER SYSTEM)	TALBERT CHANNEL	N/A	N/A	Yes	NA
12/14/05	Private	No	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
12/16/05	Private	No	45	45	0	0	13946 Erin	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
12/19/05	Private Property	N	0	0	0	0	1451 NISSON RD	Tustin	Septic tank	Septic tank	u	U	NA	NA	υ	U	OCSD responded to this Private Property spill in an assistance capacity to the city of Tustin.
12/20/05	Private		0	0	0	0	2208 DELAWARE	HUNTINGTON BEACH	N/A	LINE BREAK	LINE BREAK	N/A	N/A	N/A	N/A	Yes	N/A
12/25/05	Private Property	N	100	0	150	0	11021 GOLD STAR LN	Unincorporated County of Orange	8*	Manhole	Blockage	Roots in Main Line	NA	NA	Soaked into ground	Y; 12/25/2005 10:45:00 AM	Control 1 was notified by homeowner and Control 1 contacted Larry Honeybourne. Larry Honeybourne contacted OCSD of the spill.
12/27/05	Private	No	0	5	0	0	18302 GOTHARD	HUNTINGTON BEACH	N/A	N/A	ROOTS	VACUMMED UP FROM GUTTER	N/A	N/A	N/A	Yes	NA
12/29/05	Private	No	2	2	0	0	10240 Westminster	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
12/30/05	Private Property	Ν	1780	1180	1780	600	1777 MITCHELL AV	Tustin	8*	Manhole	Blockage	Grease clog	Peters Canyon Wasl	n NA	NA	Y; 12/30/2005 3:30:00 PM	Previous Private Property spill occurred at same location on 3/28/03. Initial visual estimate at spill location was 900 gallons.

Totals	163		32,557	36,530	19,841	4,292											
2006																	
1/3/06	Private Spill Kobe Restaurant	Yes, OC Flood Control Basin	120	50	200	0	3001 Old Ranch Parkway	Seal Beach	private sewer main line at 3001 Old Ranch Parkway	Restaurant clean-out	Grease	Restaurant had grease interceptor cleaned 3 days prior to overflow. Cleaning may have forced grease into their main line.	Bixby Storm Channe	ł n/a	Los Alamitos Basin	Yes	na
1/6/06	Private Property	n/a	0	3500	0	0	n/a	Orange	n/a	n/a	Roots	n/a	n/a	n/a	n/a	Yes	n/a
1/6/06	Merit Management Group (Armstrong Ranch) 800- 428-5588	Yes	540	200	500	340	3301 S. Sheffield	Santa Ana	Private property sewer system	Starter pot	Grease/ Construction/ Private Property	Combination of construction debri and grease was the cause of the spill.	Santa Ana/ Delhi Channel	Upper Newport Bay	Upper Newport Bay	Yes	
1/7/06	Private	No	0	120	0	0	1200 PACIFIC COAST HIGHWAY	HUNTINGTON BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	CLEAN OUT TO PARKING GARAGE FLOOR TO CONTAINED.	N/A	N/A	N/A	Yes	NA
1/8/06	Private Party	no	0	40	0	0	8641 Moody Street	Cypress	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
1/9/06	Private	Yes	30	90	40	0	1721 Claudina Avenue	Anaheim	1721 Claudina Avenue	Private Cleanout	Roots	Roots caused obstruction	Los Alamitos	Bolsa Chica		Yes	N/A
1/9/06	Private	No	0	120	50	0	407 State College Blvd	Anaheim	407 State College Blvd.	Private Cleanout	Grease	Grease caused the obstruction	N/A	N/A		Yes	Owner and or manager of location was unavailable to City staff. Workers of the restaurant did not have or would not release his information. Code enforcement as well as Streets & Sanitation staff left contact information for the owner.
1/10/06	Private	No	0	40	50	0	407 State College Blvd	Anaheim	407 State College Blvd.	Private Cleanout	Grease	Grease caused the obstruction	N/A	N/A		Yes	N/A
1/10/06	Private		0	0	0	0	104 EDINGER	HUNTINGTON BEACH	N/A	N/A	GREASE	N/A	N/A	N/A	N/A	Yes	NA
1/10/06	Private		0	0	0	0	1200 PACIFIC COAST HIGHWAY	HUNTINGTON BEACH	N/A	LINE BREAK	LINE BREAK	N/A	N/A	N/A	N/A	Yes	N/A
1/10/06	Private	No	0	0	0	0	2321 S. BRISTOL	SANTA ANA	N/A	N/A	BLOCKAGE - UNKNOWN	CONTAINED IN PARKING LOT	N/A	N/A	N/A	Yes	N/A
1/10/06	Private		0	500	0	0	5812 EDINGER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE & DEBRIS	PARKING LOT	N/A	N/A	N/A	Yes	N/A
1/10/06	Private Property	Ν	0	0	0	0	12322 EL ROY DR	Unincorporated County of Orange	Private property lateral	Clean-out	Blockage	Roots in lateral	NA	NA	Soaked into ground	Y; 1/10/2006 1:31:00 PM	NOTIF. DIV. 420 JOHN GONZALES AND HAD CREW TO SITE. CREW ONLY FOUND DRIED PAPER ON PRIVATE PROPERTY. CREW USED VACTOR THUCK, LINE IN STEFTI SI RUNNING OK. CREW IS CONTACTING CALLER AS THEIR CLEAN-OUT NEEDS CLEANING OUT. AREA WAS RINSED DOWN.
1/11/06	Property Manager for 174 Placentia Ave, Costa Mes CA property;	6 a, N	20	154	254	20	779 Shalimar Dr;	Costa Mesa, CA	Roots blocked multifamily residential lateral causing overflow from an uncapped cleanout;	Uncapped cleanout;	Roots in private lateral line;	Roots blocked multifamily residential lateral causing overflow from an uncapped cleanout;	None;	None;	City of Costa Mesa crew vactored SSO and rinse water and disposed of the wastewater in the District sanitary sewer system;	Y; 1/13/06 @ 1605 hrs;	Private readent of facility reported event to CMSD and CMSD Maintenance Supervisor, in turn; Estimated 174 gallon SSO flowed from an uncapped private property cleanout; Estimate 20 gallons SSO trickled into storm drain (SD); Estimate 5% SSO evaporated p
1/11/06	Private	No	229	229	0	0	12342 Brookhurst	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
1/16/06	Private	Yes	2050	250	1000	0	453 W. Summerfield Circle	Anaheim	453 W. Summerfield Circle	Private Cleanout	Grease	Grease caused the obstruction	East GG Wintersburg	N/A		Yes	This is the first clear instance of a repeat spill in many years. This will require higher level enforcement to ensure this does not happen again.
1/20/06	Maru Sushi Food Service Establishment manager;	N	0	260	360	0	1500 Adams Ave;	Costa Mesa, CA	Estimated 260 gallon SSO spilled from private property grease intercepto (GI);	Estimated 260 gallon SSO spilled from grease-blocked private property grease interceptor (GI);	Grease blocked GI;	Estimated 260 gallon SSO spilled from grease-blocked private property grease interceptor (GI);	None;	None;	City of Costa Mesa crew vactored SSO and rinse water and disposed of the wastewater in the District sanitary sewer system;	Y; 1/23/06 @ 1650 hrs;	City of Costa Mesa Code Enforcement called event in to Comm Citr, District Marienance Supervisor, in turn: National Plant Services, inc contractor response crew dammed cleanout and Storm Drain (SD) upon arrival; SSO did not enter SD; Estimated 260 gallon
1/20/06	Private		250	100	0	0	9882 ADAMS BLVD	HUNTINGTON BEACH	N/A	N/A	GREASE	CLEAN OUT TO PARKING LOT TO CURB AND GUTTER TO STORM DRAIN.	N/A	N/A	N/A	Yes	N/A
1/24/06	Private	No	0	1000	0	0	12705 NEWBROOK	STANTON	N/A	N/A	BLOCKAGE - UNKNOWN	ALL DISCHARGE WAS RECOVERED AND RETURNED TO SEWER SYSTEM.	N/A	N/A	Sewer system	Yes	NA
1/25/06	Private Property	n/a	0	3	0	0	n/a	Orange	n/a	Cleanout Cap Rmvd	Cleanout Cap Rmvd	n/a	n/a	n/a	n/a	Yes	n/a
1/25/06	Private		0	0	0	0	1205 NEWBROOK	STANTON	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	N/A	N/A	N/A	Yes	N/A
1/25/06	Private	No	0	0	0	0	770 S. PLACENTIA AVENUE	PLACENTIA	N/A	N/A	BLOCKAGE - UNKNOWN	CURB/GUTTER -> COLLECTION	N/A	N/A	N/A	Yes	N/A

1/26/06	Private Property	n/a	0	5	0	0	154 S.WALLACE ST.	La Habra	0/9	Cleanout	0/9	n/a	n/a	0/9	0/9	0/9	
				5					iva		nva	Iva	nva	iva	iva	rva	
1/27/06	Private Property	n/a	0	1	0	0	1671 DORWOOD AVE.	La Habra	n/a	Cleanout	n/a	n/a	n/a	n/a	n/a	n/a	
1/27/06	Private	No	0	2000	0	0	4600 BISON AVENUE (UCI)	IRVINE	N/A	N/A	BLOCKAGE - UNKNOWN	PONDED IN A PIT ON CAMPUS SITE.	N/A	N/A	N/A	Yes	N/A
1/28/06	Private	n/a	11900	0	0	0	17650 Rosa Drew Lane	Irvine	n/a	n/a	Roots	Roots	n/a	n/a	n/a	n/a	
1/28/06	Private	Yes	10800	0	0	0	5238 MICHELSON	IRVINE	N/A	N/A	ROOTS	MASON CREEK AND SAN DIEGO CREEK TO UPPER NEWPORT BAY	MASON CREEK AND SAN DIEGO CREEK	UPPER NEWPORT BAY	N/A	Yes	May be R-9
1/30/06	Private	No	740	2500	1000	0	627 N. Euclid Street	Anaheim	627 N. Euclid Street	Private Cleanout	Grease and Break	Grease and break caused obstruction	ponded in Anaheim	Carbon Creek		Yes	HCA requested that the property manager perform disinfection of the affected area on private property. Although I is not common practice, the City allowed this work to proceed under HCA supervision and with the vactor truck fully containing the spill dow
2/2/06	Private	no	0	0	0	0	5175 Calzado	Laguna Woods	Private lateral	n/a	Calcium buildup	Calcium buildup in private residence lateral	n/a	n/a	Contained on site	yes	Intermittent overflow occurring at cleanout only when homeowner used the water and was completely contained to dirt area. District's staff used Hydrocleaner unit to break the blockage and cleaned small amount of debris around cleanout. Video inspection
2/2/06	Private	No	202	202	0	0	8519 Edgebrook	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
2/3/06	Private	No	2360	2500	1000	0	627 N. Euclid St.	Anaheim	627 N. Euclid St.	Private cleanout	Grease and Break	Grease and break caused obstruction	Ponded in	Carbon Creek		Yes	N/A
2/4/06	Private Property	N	50	0	0	0	1621 EDINGER AVE.	Tustin	υ	Cleanout	Blockage	Other	U	NA	υ	Y; 2/4/2006 7:23:00 PM Jenny McBride Heath Specialist 714 433-6150.	Div. 420 was sent to the location to determine the nature of problem and was requested to standby until Orange County Health department arrived on scene. Spill was on private property.
2/5/06	Private Spill - Michael Brinkman (949) 650-9100	No	0	20	30	0	825 E. Chestnut - Private Property	Santa Ana	Private Property	Clean out	Cause unknown - private property	Ran out of parking structure, down driveway to street - cause unknown	None	None	None	Yes	Fire Dept. reported spill to both OC Health/Regional Board
2/7/06	Private	No	160	2000	1000	0	627 N. Eulid St.	Anaheim	627 N. Euclid St.	Private cleanout	Assumed to be grease and break, but discovered to be a metal disk	metal disk caused spill	Ponded in	Carbon Creek		Yes	The property manager, Jim Kitby, was very cooperative and responsive to the spill on February 7. He promised to have a sandbag barrier constructed at the drive entry where the majority of the sewage left the property, in order to capture and contain any
2/7/06	Private	n/a	10	0	0	0	23344 El Toro Rd.	Lake Forest	n/a	n/a	Grease	Grease blockage	n/a	n/a	n/a	n/a	
2/8/06	Private Property	n/a	0	20	0	0	828 N. Glassell	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
2/10/06	Private Property in Leisure World	na	20	<50	250	0	Nassau & Brookline Drive	Seal Beach	Main line, Oakmont	Manhole, Brookline Dr.@Nassau Dr.	Grease	n/a	n/a	n/a	n/a	n/a	Private Property Spill
2/15/06	Private	No	120	30	200	0	2080 S. Harbor Blvd.	Anaheim	2080 S. Harbor Blvd.	Private cleanout	Grease	Grease caused obstruction	N/A	N/A		Yes	N/A
2/15/06	Private - Calvin Sekhon, property owner (714) 878- 1540	Yes	700	100	1000	0	2309 W Valencia	Fullerton	Private lateral	3 lateral cleanouts on property	Debris, grease		Fullerton Creek Channel	Pacific Ocean		Yes	Crews responded to private overflow from three cleanout locations within apartment complex. Only crews contained SSO at private drain in parking area. City crews set up vactor vacuum in gutter, cleaned blockage to stop overflow, washed down and vacuumed
2/16/06	FV	no	75	2	0	0	17815 Newhope Street	Fountain Valley	private property sewer lateral		unknown	possible paper towel in toilet	East Valley Channel 05	NA		yes	NA
2/16/06	Private - Calvin Sekhon, property owner (714) 878- 1540	Yes	587	200	1000	0	2309 W Valencia	Fullerton	Private lateral	3 lateral cleanouts on property	Debris, grease	Private lateral line was not completely cleared from previous blockage	Fullerton Creek Channel	Pacific Ocean		Yes	Crews responded to private overflow from three cleanout locations within apartment complex. Only crews contained SSO at private drain in parking area. City crews set up vactor vacuum in gutter, private plumber responded and cleared blockage to stop over
2/16/06	Brookside Apts	No	0	180	80	0	5600 Orangethorpe Avenue	La Palma	Private Lateral	Cleanout	Grease & Blockage	Grease blockage from private property and sedement	N/A	N/A	Returned to the system	Y	Private contractor sanitized and cleaned up
2/16/06	Private Property	Ν	0	0	0	0	19246 Fairhaven Extension near Panorama Place.	Unincorporated County of Orange	U	U	Blockage	Root obstruction in lateral line	NA	NA	Soaked into ground	Y; 2/16/2006 2:52:00 PM	HCA Michael Fennessy contacted, HCA going to site. Problem belongs to homeowner and HCA will follow-up.
2/17/06	Lordon Management Company (626-967-7921, x3316), @ 1275 Center Court Drive, Covina, CA 91724; FAX: 626-966- 3918)	N	0;	82	132	0;	760 West 16th St;	Costa Mesa, CA	Grease, roots, rocks and debris blocked private lateral in a parking lot causing overflow from a cleanout;	Grease, roots, rocks and debris blocked private lateral in a parking lot causing overflow from an uncapped cleanout;	Grease, roots, rocks and debris blocked private lateral in a parking lot causing overfloo from an uncapped cleanout;	Grease, roots, rocks and debris blocked private lateral in a parking lot causing overflow from an uncapped cleanout;	None;	None;	District line cleaning contractor, NPSI, dammed SD, vactored SSO and rinse water and disposed o the wastewater in the District sanitary sewer system;	f Y; 2/21/06 @ 1250 hrs;	Visually estimated \$2 galon SSO flowed from one private property cleanout. Estimate Some SSO tracked into Storm Drain (SD) used as a containment vessel; Recovered/acticented \$2 galons; District maintenance supervisor and line cleaning contractor, Nation

Image: Note of the state of																		
1210 1210 12	2/17/06	Brookside Apts	No	0	202	80	0	5600 Orangethorpe Avenue	La Palma	Private Lateral	Cleanout	Grease & Blockag	Grease blockage from private property and sedement	N/A	N/A	Returned to the system	Y	Private contractor sanitized and cleaned up
And Series And Ser	2/23/06	Private	No	0	50	200	50	917 W. Lodge Ave.	Anaheim	917 W. Lodge Ave.	Private cleanout			ponded onsite	and in street		Yes	respond in a timely manner, resulting in the property manager and his assistant clearing the drain with own tools. City vactor onsite to washdown and dispose of
Image	2/23/06	Company (626-967-7921, x3316), @ 1275 Center Court Drive, Covina, CA 91724; FAX: 626-966-	N	0	35	85	0	760 West 16th St;	Costa Mesa, CA	blocked private lateral in a parking lot causing	blocked private later in a parking lot causing overflow from	al blocked private lateral in a parking m lot causing overflo	private lateral in a parking lot	None;	None;	contractor, (NPSI), and City of Costa Mesa crew dammed SD, vactored SSO and rinse water and disposed of the wastewater	Y; 3/1/06 @ 1120 hrs;	Supervisor; Repeat similar event to 2/17/06; Visually estimated 82 gallon SSO flowed from one private property cleanout; Estimate Some SSO trickled into storm
interpretation interpretatio	2/25/06	Private	n/a	100	0	0	0	113 Rockwood St.	Irvine	n/a	n/a	n/a	Unknown blockage	n/a	n/a	n/a	n/a	
100 Mat M	2/25/06	Private		100	0	0	0	107 ROCKWELL	IRVINE	N/A	N/A	BLOCKAGE - UNKNOWN	CONTAINED IN PLANTER.	N/A	N/A	N/A	Yes	May be R-9
Image: Section of the secting of the secting of the sectio	2/26/06	Private	No	40	40	500	0	1040 N. Magnolia Ave.	Anaheim	1040 N. Magnolia Ave.	Private cleanout	Break	Break caused obstruction	Ponded in street	Fullerton Creek		Yes	also the reporting party, did all that was possible at the time to address the spill and
Ant Name Name <	3/1/06	Private Party	no	0	200	0	0	5940 Cerritos Ave.	Cypress	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
Image Image <th< td=""><td>3/4/06</td><td>Private</td><td>Yes</td><td>113</td><td>150</td><td>100</td><td>0</td><td>501 N State College Blvd (Chipotle Grill)</td><td>Fullerton</td><td>Private lateral</td><td></td><td>Debris, grease</td><td></td><td></td><td>Pacific Ocean</td><td></td><td>Yes</td><td>restaurants. Health Care agency was on scene. Crews cleared blockage to stop overflow, some grease retrieved on rodding equipment. City crews washed down</td></th<>	3/4/06	Private	Yes	113	150	100	0	501 N State College Blvd (Chipotle Grill)	Fullerton	Private lateral		Debris, grease			Pacific Ocean		Yes	restaurants. Health Care agency was on scene. Crews cleared blockage to stop overflow, some grease retrieved on rodding equipment. City crews washed down
And No. N	3/7/06	Private	Yes	500	40	20	0	105 E. Leatrice Ln.	Anaheim	105 E. Leatrice Ln.	Private cleanout	Vandalism	Vandalism caused spill	Los Alamitos	Garden Grove		Yes	This spill was reported to have been flowing for several days by the tenants. The odor in the area and the volume of solids near the spill bears this out. However, the property owner was very responsive in taking care of the obstruction as well as aid
Image: Note of the state of the s	3/14/06	Private	No	30	20	500	0	777 Convention Way	Anaheim	777 Convention Way	Private cleanout	Grease	Grease caused obstruction	Ponded in	storm drain		Yes	grease discharged to the sewer, and implemented a fairly successful sewer line cleaning program, the problem with sewer spills persists. Therefore, despite the
And Ref.	3/19/06	Private	No	3	3	0	0	13556 Robin Court	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
Algebra Viral <	3/20/06	Private Property Denny's Rest.	No	30	30	100	0	4232 Katella	Los Alamitos	private lateral	private grease interceptor	grease	grease blockage	n/a	n/a	n/a	n/a	n/a
And All and Al	3/23/06	Private	Yes	255	1500	500	0	3170 W. Lincoln Ave.	Anaheim	3170 W. Lincoln Ave.	Private cleanout	Grease	Grease caused obstruction	Carbon Creek	N/A		Yes	There was a delay, however, in clearing the sewer line, since the "snake" that the first plumber used was not effective in clearing the obstruction. The second
32306 1950 Ves. 20 190 800 0 $65 \times 1560 \times 1060 \times 1060$	3/23/06	Private Property	n/a	0	450	0	0	1538 E. Chapman	Orange	n/a	n/a	unknown	n/a	n/a	n/a	n/a	Yes	n/a
Property Name 20 85 205 205 157-B Neyport Birdly Costs Mess, CA C	3/29/06	1955 W North, Malrose Park, Illinois 60160 contact:Barbara Mott 708-	Yes	20	180	800	0	455 N State College Blvd (Sav-On)	Fullerton	Private lateral	3 lateral cleanouts in parking lot	Debris	Plumber cleared approx 10' of thick substance from line	f Fullerton Creek Channel	Pacific Ocean		Yes	& Chapman Ave. Lateral cleanouts in parking lot were seeping with small amount of flow into gutter area down to catch basin. Flow was contained in parking lot with
4/E006 Private Yes 140 0 40 0 969 S. Euclid St. Anahem 969 S. Euclid St. Private cleanout Grease and tool bits not concernence Los Alamitos Bolta Chica Yes On Ball Road it raveled west approximately 250 yards where it entered the catch baain located at 779 W. Ball Road. on the north side of Ball Road. 4/E006 Private Yes 4/00 0 00 PS S. Euclid St. Anahem 969 S. Euclid St. Private cleanout Grease and tool bits not concernence Los Alamitos Bolta Chica Yes On Ball Road it raveled west approximately 250 yards where it entered the catch baain located at 779 W. Ball Road. on the north side of Ball Road. 4/6006 Private Yes 4/00 0 0 750 SLATER AVENUE HUNTINGTON BEACHINA NA GREASE FOR AFEW DAYS - INCLOSURE SLOADS AT HUNTINGTON EXPRANCE NA Yes NA NA NA NA Yes NA NA NA NA NA NA NA	3/30/06	B Newport Blvd (Triangle Square), Costa Mesa, CA	N	20	85	205	20	1875-B Newport Blvd;	Costa Mesa, CA	commercial lateral causing overflow from two of three	Two of three parking lot cleanouts;	commercial lateral causing overflow from two of three	lateral causing overflow from	None;	None;	vactored SSO and rinse water and disposed of the wastewater in the District		Estimate 20 gallons SSO trickled into storm drain (SD) used as a containment vessel; Recovered/Vactored 85 gallons; City of Costa Mesa crew vactored SSO an
4/6006 Yes 4/00 200 0 0 7850 SLATER AVENUE HUNTINGTON BEACHINA NA REAS PARK LAKE- VILL FORM NA NA SOLIC ELOSUBE SIGNS AT HUNTINGTON PARK LAKE- VILL FORM NA NA SOLIC ELOSUBE SIGNS AT HUNTINGTON NA NA SOLIC ELOSUBE SIGNS AT HUNTINGTON NA NA <td>4/6/06</td> <td>Private</td> <td>Yes</td> <td>140</td> <td>0</td> <td>40</td> <td>0</td> <td>969 S. Euclid St.</td> <td>Anaheim</td> <td>969 S. Euclid St.</td> <td>Private cleanout</td> <td>Grease and food</td> <td>Grease and food caused obstruction</td> <td>Los Alamitos</td> <td>Bolsa Chica</td> <td></td> <td>Yes</td> <td>On Ball Road it traveled west approximately 250 yards where it entered the catch</td>	4/6/06	Private	Yes	140	0	40	0	969 S. Euclid St.	Anaheim	969 S. Euclid St.	Private cleanout	Grease and food	Grease and food caused obstruction	Los Alamitos	Bolsa Chica		Yes	On Ball Road it traveled west approximately 250 yards where it entered the catch
47706 Private No 98 98 00 0 12188 Brookhust Garden Grove n/a	4/6/06	Private	Yes	400	200	0	0	7850 SLATER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE	PARK LAKE - WILL POST SOME CLOSURE SIGNS AT DRAIN ENTRY TO LAKE FOR A FEW DAYS - INCIDENTAL CONTACT	CENTRAL PARK	N/A	NA	Yes	NA
	4/7/06	Private	No	98	98	0	0	12188 Brookhurst	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	

4/10/06	The Lodge Food Servi Establishment (FSE);	ce	N	0	10	60	0	2937 Bristol Street;	Costa Mesa, CA	Grease primarily and some debris blocked private lateral; SSO flowed from private MH on private property;	Private MH;	Grease primarily and some debris blocked private lateral;	Grease primarily and some debris blocked private lateral;	None	None	City of Costa Mesa crew vactored SSO and rinsewater and disposed of the wastewater in the CMSD sanitary sewer system;	Y; via FAX: 4/10/06 @ 1730 hrs	AB&R Plumbing called CMSD Maintenance Supervisor, Estimated 10 gallon SSO Howed from private Methole (HH) on private property into Curb City of Costa Mes and CMSD Maintenance Supervisor dammed Storm Dirain (SD) - fully contained; City of Costa Mesa cr
4/11/06	Private	Yes		15	160	0	0	7402 EDINGER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE	STORM DRAIN -> FLOOD CONTROL CHANNEL (EAST GARDEN GROVE WINTERSBERG CHANNEL)	WINTERSBERG	N/A	N/A	Yes	NA
4/17/06	Private Property		n/a	0	25	0	0	3340 E. Collins	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
4/24/06	Private	No		0	400	0	0	23691 ROCKFIELD	LAKE FOREST	N/A	LINE BREAK	LINE BREAK	SEWAGE CONTAINED ON SITE.	N/A	N/A	N/A	Yes	May be R-9
4/24/06	Private Health Care C	anter	Yes	630	0	0	0	RXR easement behind 2800 N Harbor	Fullerton	Private lateral	Lateral cleanout	Grease, debris		Brea Creek dirt channel		Sewage soaked into dirt channel	Yes	Crews responded, contained, and cleared blockage in private lateral to stop flow. Private plumber responded to follow up with clean up activities. All sewage soaked into the dirt channel near railroad easement. Skilled Healthcare Center will be added t
4/25/06	Private			50	100	0	0	21372 BROOKHURST	HUNTINGTON BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	STORM DRAIN	N/A	N/A	N/A	Yes	NA
5/7/06	Private		n/a	30	0	0	0	17575 Harvard Ave. (Corner Bakery)	Irvine	n/a	n/a	Grease	Grease blockage	n/a	n/a	n/a	n/a	
5/8/06	Private Property		n/a	0	0	0	0	730 W.5TH STREET	La Habra	n/a	Private lateral	n/a	n/a	n/a	n/a	n/a	n/a	
5/8/06	Private	No		0	300	0	0	23691 ROCKFIELD	LAKE FOREST	N/A	LINE BREAK	LINE BREAK	SEWAGE CONTAINED ON SITE.	N/A	N/A	N/A	Yes	May be R-9
5/9/06	Private Party		no	0	20	0	0	6336 Orange Ave.	Cypress	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
5/9/06	Private - Sav On/Alber Store # 9598	tsons	No	0	20	400	0	455 N State College	Fullerton	Private lateral	Lateral cleanout in parking lot	6" lateral connection to 4" lateral cleanout wye	new 6" lateral from building was connected to existing 4" lateral line. problem appears to be at offset in connection	N/A	N/A	All sewage was vacuumed and returned to the sanitary sewer system	N/A	City sewer crews working in the area observed lateral deanout in parking lot appeared wet. Crews set up Carnel at site and notified store manager who called privitel plumber. Correspondence with Sav On has been ongoing due to a previous overflow. Proper
5/9/06	Private Property		N	0	0	0	0	1942 OMEGA DR	Unincorporated County of Orange	Lateral line	υ	Blockage	Root obstruction in lateral line	NA	NA	U	NA	NA
5/10/06	Private		No	0	80	0	0	1365 Knollwood Circle	Anaheim	1365 Knollwood Circle	sample box	Lack of capacity and build up of fibers on sewer lateral	Lack of capacity caused obstruction	N/A	N/A	N/A	Yes	Sewer spills have been experienced at this location in the past, under similar circumstances. However, there has not been a spill in over three years.
5/11/06	Private		No	59	59	0	0	12912 Magnolia	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
5/15/06	Private		No	95	5	0	0	1755 W. La Palma Ave.	Anaheim	1755 W. La Palma Ave.	Private cleanout	Grease	Grease caused obstruction	Coyote Creek	dry detention basis	N/A	Yes	N/a
5/17/06	Private		No	22	22	0	0	8903 Hewitt Place	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
5/18/06	Private Property		No	0	60	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
5/22/06	PetSmart Store - Priv. party;	ate	N	25	25	25	25	620 W 17th St - PetSmart Store lateral cleanout;	Costa Mesa, CA;	Private on-site PetSmart lift station failed - well contained large volume of wastewater;	Private on-site PetSmart lift station failed - well contained large volume of wastewater;	Private on-site PetSmart lift station failed - well contained large volume of wastewater;	Private on-site PetSmart lift station failed - well contained large volume of wastewater;	None;	None;	SSO vactored and disposed of into the CMSD sanitary sewer system;	Y; 523-06 @ 1930hrs;	Visual estimate of wastewater in SD and from path from the PetSmart cleanout to the SD and the curb; 15 gallons lost to SD; 10 gallons evaporated; 25 gallons vactored; Private on-site PetSmart lift station failed - well contained large volume of wastewa
5/23/06	Private		No	300	100	200	0	1731 W. Katella Ave.	Anaheim	1731 W. Katella Ave.	Private cleanout	Grease and paper	Grease and paper caused obstruction	Anaheim Barber Channel	Bolsa Chica	N/A	Yes	MA
5/24/06	Private		No	60	160	500	0	905 E. Vermont Ave.	Anaheim	905 E. Vermont Ave.	Private cleanout	Toilet left running into tank	Toilet left running into tank caused obstruction	Ponded in SD	N/A	N/A	Yes	Because the spill flowed a significant distance before reaching the catch basin, it is believed that a significant portion of the spill was contained and collected before it was discharged into the catch basin.
5/27/06	Private	No		0	0	0	0	10001 N. FLOWER STREET	SANTA ANA	N/A	LINE BREAK	LINE BREAK	CONTAINED ON SPILL LOCATION	N/A	N/A	N/A	Yes	N/A

5/30/06	FV		no	75	70	0	0	16155A-16175 Harbor Blvd	Fountain Valley	private property sewer lateral		grease build up	private	NA	NA	Catch basin & gutter vaccumed & returned to OCSD	yes	NA
6/5/06	Private		No	128	128	0	0	10761 Palma Vista	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
6/5/06	Sterling Shopping manager, Ross Ca	Center, Inon.	Yes	360	200	700	160	17436 Beach Blvd., Sterling shopping center	Huntington Beach	Blockage was in the private lateral line of the shopping center.	Pick hole of the clean out cover.	Grease blockage.	Grease and debris blocked the private lateral line.	Jefferson City Channel	County Ocean View Channel to the Wintersburg Channel then the Bolsa Chica Wetlands.		Yes	
6/6/06	Private	No		0	100	0	0	441 GOLDENROD AVENUE	NEWPORT BEACH	N/A	N/A	ROOTS	CURB & GUTTER (CONTAINED AND CLEANED UP)	N/A	N/A	N/A	Yes	N/A
6/8/06	Private		No	10	10	15	10	2936 W. Lincoln Ave., #3	Anaheim	2936 W. Lincoln Ave., #3	Private cleanout	break	Break casued obstruction	N/A	N/A	N/A	Yes	The discharge from this property was actually from two sources. One was the kitchen of the house at the southwest corner of the property, and the other was from regular parking (of and loading dock washout from the northern portion of the property, which
6/8/06	La Palma Hospital property	private	No	0	90	110	0	7901 Walker Street	La Palma	Private Lateral	Manhole	Unknown Blockage	Blockage from private propert	tyN/A	N/A	Hauled away by OC Pumping	Y	Private contractor sanitized and cleaned up
6/11/06	Private		Yes	600	1800	20	600	8000 Naples Ln.	Anaheim	8000 Naples Ln.	Private cleanout	roots	Roots caused obstruction	Santa Ana River	N/A	N/A	Yes	N/A
6/12/06	Private			200	1800	0	0	3101 W. PACIFIC COAST HIGHWAY	NEWPORT BEACH	N/A	N/A	PUMP STATION FAILURE	STORM DRAIN -> NEWPORT BAY AT "MARINER MILE" MARINA DOCKS (3101 W. COAST HIGHWAY)	N/A	N/A	N/A	Yes	MA
6/14/06	Private	No		0	0	0	0	10631 LOS ALAMITOS	LOS ALAMITOS	N/A	LINE BREAK	LINE BREAK	SEWAGE DISCHARGED SUBSURFACE AND INTO DECORATIVE KOI POND.	N/A	N/A	N/A	Yes	NA
6/23/06	PRIVATE SSO at Apartment comple Maple St;	at 2257	N	0	10	20	0	2257 Maple Street;	Costa Mesa, CA;	Small SSO flow from uncapped private cleanout in a 4-plex;	Small SSO flow from uncapped private cleanout in a 4-plex;	Small SSO flow from uncapped private cleanout in a 4-plex;	Small SSO flow from uncapped private cleanout in a 4-plex;	None;	None;	Commercial plumber vacuumed SSO and rinse water and disposed of the wastewater in a MH in the CMSD sanitary sewer system;	Y; 6/26/06 @ 1825 hrs;	PRIVATE SSO at Apartment complex at 2257 Maple St: City of Costa Mesa and CMSD Maintenance Supervisor blocked Storm Drain (SD) around the corner from the driveway site. Commercial plumber vacuumed SSO and rinse water and disposed of the wastewater in a
6/24/06	City of Huntington	Beach	None	250	200	400	50 Gallons	17732 Goldenwest Street	Huntington Beach	Park Bench Café, 17732 Goldenwest Street	Private sewer lateral cleanout cap.	Grease and debris blockage.	Grease and debris buildup in the private sewer lateral.	None	None	Was put into the sewer system and some soaked into the grass.	Yes	The Park Bench Caté is in a City park, the problem cleanout pipe is next to a large low grass area. All sewage was confined to this aera.
6/26/06	Restaurant at the e of the Newport Pie		No	0	0	0	0	Restaurant at the end of the Newport Pier	Newport Beach	Pipe joint	Pipe hangers holding ABS piping under the pier failed due to rust & corrosion, the piping dropped & a joint pulled apart.	Pipe joint separation	See Remarks	n/a	n/a	n/a	Yes	City of Newport Basch lift station crew turned water off to Restaurant immediately and advised restaurant manager of the problem. Utilities office called Environmental Health Services and RWCCD.
6/27/06	Rainbow Disposal, hauler.	trash	None	150	150	250	0	17121 Nichols Street	Huntington Beach	Blockage was in the private lateral line on Rainbow property.	Clean out pick hole.	Grease and debris blockage.	Grease and debris buildup in the private sewer lateral.	None	None	Was put into the sewer system.	Yes	
7/3/06	PRIVATE SSO at Apartment comple Tustin Ave, manag South Coast Prop Management Co (2602-Voice, 714-4 FAX);	ed by ty 14-444-	N	25	75	150	25	1741 Tustin Ave;	Costa Mesa, CA;	Blockage in PRIVATE lateral line on PRIVATE property;	PRIVATE MANHOLE (MH) on private property at 1740 Tustin Ave;	Unknown blockage in PRIVATE lateral line on PRIVATE property;	Unknown blockage in PRIVATE lateral line on PRIVATE property;	None;	None;	City of Costa Mesa vactore SSO in public ROW curb and gutter and disposed of SSO and rinsewater in CMSD sanitary sewer system at the Corporate Yard;	Y; 7/03/06 @ 1325 hrs;	PRIVATE SSO at Apartment complex at 1741 Tustin Ave, managed by South Coast Property Management Co (714-444-2802-Voice, 714-444-3802-FAX); Estimated 100 galon PRIVATE SpO flow contained in private drive and curb; District crew dammed SD; PRIVATE plumber
7/4/06	Private Property		n/a	0	200	0	0	315 Bedford	Orange	n/a	n/a	Grease	n/a	n/a	n/a	n/a	Yes	n/a
7/4/06	Private	No		0	20	0	0	1723 E. OCEANFRONT	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	CURB & GUTTER - CONTAINED BY CITY CREV	N/A	N/A	N/A	Yes	N/A
7/6/06	Private			30	370	0	0	745 DOVER	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	PPO CLEAN OUT TO PARKING LOT TO STORM DRAIN.	N/A	N/A	N/A	Yes	N/A
7/7/06	Private Property O	vner	No	0	20	400	0	Zlings / Revolucion Restaurants, 209 N Harbor Blvd (Rear driveway)	Fullerton	Private Grease Interceptor	Interceptor lid	Grease blockage in private lateral		N/A	N/A	N/A		City crews responded to report of grease interceptor overflowing behind restaurant complex. Crews contained and vacuumed overflow until blockage was cleared. Zinga and Revolucion restaurant's shared interceptor had been pumped within the past 3 months.
7/8/06	Private		N/A	300	800	500	0	1590 W. Palm Lane	Anaheim	1590 W. Palm Lane	Private cleanout	Grease	Grease caused obstruction	Westminster	Channel	N/A	Yes	Property management was very responsive in obtaining a private plumber to clear obstruction.

7/10/06	Private Property	Ν	0	0	0	0	17672 ORANGE TREE LAN	E Tustin	4-inch	Bathroom	Blockage	Unknown	NA	NA	NA	Y; 7/10/2006 10:10:00 PM	RWQCB was contacted with their after hours number and was left a voice message. Control 1 was contacted and spoke to John (Environmental Health).
7/11/06	Silk Thai Cuisine Restaurant	No	10	10	210	0	19690 Beach Blvd., Newland Shopping Center	¹ Huntington Beach	Slik Thai Restaaurant in the Newland Shopping Center.	Cover of grease interseptor	Grease blockage	Phill's Plumbing while repairing the grease interceptor at The Silk Thai Restaurant 10 gallons of sewage spilled.	None	None	All sewage was put into the sewer system.	Yes	
7/12/06	Private	No	0	1620	4500	0	3534 W. Ball Road	Anaheim	3534 W. Ball Road	Private cleanout	Unknown	Unknown	N/A	N/A	N/A	Yes	N/A
7/12/06	PRIVATE SSO from PRIVATE 4* force main from PRIVATE lift station at 960 West 16th St;	N	2	15	65	2	960 West 16th St;	Costa Mesa, CA;	PRIVATE lift station 4* force main on PRIVATE property found to have a 3/16* hole in the plastic underground pipe;	PRIVATE lift station 4" force main on PRIVATE property found to have a 3/16" hole in the plastic underground pipe;	PRIVATE lift station 4" force main on PRIVATE property found to have a 3/16" hole in the plastic underground pipe;	PRIVATE lift station 4* force main on PRIVATE property found to have a 3/16* hole in the underground pipe; Undetermined cause for the 3/16* hole;	None;	None;	City of Newport Beach (CNB) crew vacuumed SSC and rinse water and disposed of the wastewater in the CNB sanitary sewer system;	Y; 7/12/06 @ 1125 hrs;	PRIVATE SSO occurred from PRIVATE 4" force main from PRIVATE lift station at 960 West 16th St. Mess Consolidate Water District dammed Storm Drain (SD) while executing potential water line leak and plugged 4" force main hole with a bolt City of Newpor
7/13/06	Private	No	44	44	0	0	11812 Poes	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/17/06	Private Property	Yes	50	100	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
7/26/06	Private	No	144	144	0	0	12905 Palm	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
7/27/06	Pacific West Management Corporation, property manager Sharon Ference 714-433-7300	No	100	100	200	0	6941 Warner Avenue	Huntington Beach	Don Ramon's Mexican Restaurant in this shopping center.	Sewer lateral clean out cover.	Grease blockage	Grease blockage in the private sewer lateral down stream of the Don Ramon's Restaurant.	e None	None	All sewage was put into the sewer system.	Yes	
7/28/06	Pacific Coast Properties (PCP) Management for 12- unit apartment complex located at 584 West Hamilton (Beth - Office 714- 378-1366, Cell - 714-331- 7847);	N	20	80	180	20	584 West Hamilton Street;	Costa Mesa, CA;	Blockage in PRIVATE lateral line on PRIVATE property;	Cleanout (CO) on PRIVATE property;	Grease and debris blockage in PRIVATE lateral line on PRIVATE property;	Grease and debris blockage in PRIVATE lateral line on PRIVATE property;	None;	None;	City of Costa Mesa vactore SSO in public ROW curb and gutter and disposed of SSO and rinsewater in CMSD sanitary sewer system at the Corporate Yard;	Y; 7/28/06 @ 1700 hrs;	PRIVATE SSO called in to City of Costa Mesa Comm Center - Fire Dept and PD responded for potential hazardoua materials spill and traffic control: CMSD Staff encountered SSO while traveling home from work; Pacific Coast Properties (PCP) Management for 12-
7/30/06	Private	No	220	120	100	0	1919 W. Coronet Ave	Anaheim	1919 W. Coronet Ave	Private cleanout	Break	Break caused obstruction	ponded	storm drain	N/A	yes	N/A
8/3/06	Earl Benton 714-964-7697, home address 20271 Meander Lane, HB 92646.	No	20	20	170	0	4932 Kona Dr.	Huntington Beach	4932 Kona Dr., sewer line inside of apartment building.	The discharge pipe for the washing machine.	Grease blockage	Grease blockage in private sewer lateral line.	None	None	All the wash water and sewage was vacuumed up and put into the City's sewer system.	Yes	The owner of this four unit appartment complex does not do much maintenance or upkeep on this property.
8/5/06	Private	N/A	1000	5300	6000	1000	1250 S. Brookhurst St.	Anaheim	1250 S. Brookhurst St.	Private cleanout	Roots, break, unknown	Unknown cause of obstruction, possibly roots or a break in the line.	Anaheim Barber Channel	Bolsa Chica	N/A	Yes	Private plumber was unable to clear obstruction with snake. Another plumber with a jetter was called in, after several hours of delays, to eventually clear obstruction.
8/5/06	Private	Yes	300	0	0	0	24401 MUIRLANDS	LAKE FOREST	N/A	N/A	GREASE	GREASE INTERCEPTOR TO PARKING LOT TO STORM DRAIN TO SAN DIEGO CREEK (DRY).	SAN DIEGO CREEH (DRY)	< _{N/A}	N/A	Yes	May be R-9
8/11/06	A.K.A. Japanese Restaurant 714-374-9600 and Cavallino Italian Restaurant 714-536-6665	No	55	55	155	0	8082 Adams Ave.	Huntington Beach	Between private manhole and City manhole at 8082 Adams Ave.	Pick holes of manhole cover.	Grease blockage	Grease buildup from two food service establishments.	None	None	All the wash water and sewage was vacuumed up and put into the City's sewer system.	Yes	
8/14/06	Private Property	No	0	100	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
8/20/06	Private Property	Yes	100	100	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
8/20/06	FV	no	10	10	0	0	9102 Edinger Avenue	Fountain Valley	private property sewer lateral		grease	private sewer lateral	NA	NA	OCSD	no	NA
8/27/06	Private	No	215	215	0	0	12905 Palm	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
8/31/06	El Taco Mexican Restaurant owner (213-249-0756);	N	0	30	80	0	2101 Harbor Blvd;	Costa Mesa, CA;	Grease blocked PRIVATE lateral line from El Toro Mexican Restaurant;	Grease blocked PRIVATE lateral line from EI Toro Mexican Restaurant;	Grease blocked PRIVATE lateral line from El Toro Mexican Restaurant;	Grease blocked PRIVATE lateral line from El Toro Mexican Restaurant;	None;	None;	City of Costa crew vactored SSO from curb and gutter and returmed/disposed of SSO in District sanitary sewer system;	Y; 8/31/06 @ 1445 hrs;	El Taco Mexican Restaurant overer (213-249-0756) called District Maintenance Supervisor, District Maintenance Supervisor called @ 1100 hrs, blocked SD @ 1112 hrs, called City of Costa Mesa Public Services to send a Vactor and clean the Public ROW, flush s
9/8/06	Earl Benton, 20271 Meander Ln., HB 92646	No	5	5	105	0	4932 Kona Dr.	Huntington Beach	Lateral sewer line of 4932 Kona Dr.	Sewer discharge pipe in the laundry room.	Grease and root blockage	Grease and root blockage of private sewer line.	None	None	All sewage was put into the City sewer system.	Yes	From the looks of this four unit complex the owner, Eral Benton, does not maintain the property very well.
		-				-		-		-	-		-	-	-	-	

9/9/06	PRIVATE FACILITY - Coast Alcohol & Drug Program Facility;		N	25	25	100	25	2212 Placentia Ave;	Costa Mesa, CA;	PRIVATE lateral blocked with debris;	PRIVATE lateral blocked with debris;	PRIVATE lateral blocked with debris;	SSO flow from PRIVATE lateral blocked with debris from 8-unit apt complex to rear facility sump pump operated intermittently;	None;	None;	Up to 25 gallons of SSO was contained in the SD and evaporated; Costa Mesa Public Services vactored public ROW and disposed of SSO and rinsewater in the CMSD Sanitary Sewer system;	Y ; 9/10/06 @ 0935 hrs;	City of Costa Mesa Comm Center called SSO in to District Maintenance 8 Supervisor: District Maint Supervisor blocked Storm Drain (SD) @ 1534 hrs and turned of findity sump pump; Costa Mesa Public Services vactored public right of way (ROW) and returned/
9/15/06	FV		no	20	20	0	0	18774 Brookhurst Street	Fountain Valley	roots in private lateral		grease	roots in private lateral	NA	NA	OCSD	no	NA
9/17/06	Private		No	395	395	0	0	10191 Lampson	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
9/21/06	Private		No	30	20	500	0	537 N. Magnolia Ave.	Anaheim	537 N. Magnolia Ave.	Private cleanout	Grease	Grease caused obstruction	Catch basin	Carbon Creek	N/A	Yes	A previous spill occurred at this address on 6/10/06. The spill occurred when the sewage lift pump failed, partially as a result of the failure to implement the corrective actions required in the first Compliance Order, and partially due to new condition
9/23/06	Private			0	0	0	0	4672 PLUMOSA DRIVE	YORBA LINDA	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	N/A	N/A	N/A	Yes	NA
9/26/06	Private Property		N	0	0	0	0	13626 ESTERO CIR	Tustin	Clean out	Clean out	Blockage	Misc. debris	NA	NA	NA	Y; 9/26/2006 7:27:00 PM	Notifications were made to Control One and RWQCB. Corwin Brown from Health Care was asked to assist in speaking with Apartment Complex Manager so they would call the plumber.
9/28/06	Nora Balikciagli, owne the Moble Gas Station	er of 1	No	25	25	45	0	2002 Beach Blvd.	Huntington Beach	Lateral sewer line of 2002 Beach Blvd.	Private sewer clean out cover.	Debris blockage	2002 Beach Blvd. Is a gas station. It is suspected that vandals put to much debris into the toilets.	None	None	All sewage was put into the City sewer system.	Yes	
9/28/06	Private	Yes		25	0	0	0	Grant Street	Newport Beach	n/a	n/a	n/a	n/a	Nwport Slough	Santa Ana River	n/a	yes	(Listed only on the OCHCA Beach Closure Report)
10/4/06	PRIVATE SSO - Apar Owner/Manager Ed G 714-926-3805;		N	288	0	0	288	779 Shalimar Drive;	Costa Mesa, CA;	PRIVATE PROPERTY cleanout in rear of propert in alley;	PRIVATE PROPERTY cleanout in rear of property in alley;	Root in lateral line in front of facility blocked lateral line which runs under the 4 unit apartment complex;	Root in lateral line in front of facility blocked lateral line which runs under the 4 unit apartment complex; Later verified with private CCTV;	None'	None;	Estimated 288 gallons SSO not recoverable due to evaporation and entry into the SD;	Y; 10/0406 @	City of Costa Mesa Code Enforcement Officer Tim Sun notified Diatrict Maintenance Buspervisor, PRIVATE SSD - Apartment Owner/Manager Ed Glinka - 714-925- 3805 is the responsible pany; A continuing facility lateral problem caused an estimated 288 gallons
10/5/06	Private	No		0	20	0	0	703 POPPY	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	YARD -> CURB & GUTTER - > ALL FLOW CONTAINED	N/A	N/A	N/A	Yes	NA
10/12/06	Private		n/a	300	0	0	0	3955 Alton Pkwy Olive Garden	Irvine	Private lateral	Private lateral	n/a	Blockage in customer's latera	n/a	n/a	n/a	n/a	
10/16/06	Private	Yes		200	0	0	0	610 NEWPORT CENTER DRIVE	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	SEWAGE DISCHARGED TO STORM DRAIN AND INTO NEWPORT BAY	NEWPORT BAY	N/A	N/A	Yes	NA
10/19/06	Private	No		0	8	0	0	23472 LOS ADORNOS	UNINCORPORATED COUNTY	N/A	N/A	ROOTS	ALL DISCHARGE WAS CAPTURED AND RETURNED TO SEWER.	N/A	N/A	RETURNED TO SEWER	Yes	N/A
10/21/06	Private			0	0	0	0	1139 / 1125 CERRITOS DR	FULLERTON	N/A	N/A	BLOCKAGE - UNKNOWN	PRIVATE CLEANOUT TO PRIVATE PROPERTY TO DIRT TRACK TO STORM DRAIN.	N/A	N/A	N/A	Yes	NA
10/30/06	Private			0	0	0	0	710 WASHINGTON AVENUE	SANTA ANA	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	N/A	N/A	N/A	Yes	N/A
11/3/06	Joe's Crab		Unknown	0	20	0	0	2607 W. Coast Hwy	Newport Beach	Blocked Grease intercepto	or Grease interceptor	Blocked Grease Interceptor	See Remarks	Pacific Ocean	n/a	n/a	yes	Met vactor, called for sand to build a berm around the grease that overflowed from the Restaurant interceptor. Contacted workers inside restaurant to call for a plumber/pump truck and informed them they would not be allowed to open until the problem was t
11/6/06	Private		Yes	1000	1520	1000	0	967 S. Euclid St.	Anaheim	927 S. Euclid St. interceptor	Private cleanout	Grease and settlable food solids	Grease and solids build up in interceptor and caused obstruction	Catch basin	Anahiem Barber Channel/ Huntington Harbor	N/A	Yes	A previous spill occurred at this address but not from this same line. Implementing a program to prevent the discharge of solids to the interceptor as well as a more frequent inspection and/or cleaning program should resolve this situation.
11/6/06	Market Broiler Restau	rant	No	500	500	800	0	20111 Brookhurst Street	Huntington Beach	Broken sewer pipe three feet under the concrete slab of the Market Broiler building.	Concrete slab and sewer clean out cover.	Broken sewer pipe under the concrete slab.	Old sewer line had a break in it.	None	None	All liquid was put into the City sewer system.	Yes	
11/8/06	Private		No	162	162	0	0	11072 Magnolia	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/9/06	Private Property		No	0	100	225	0	614-616 E. Pine Street	Santa Ana	Unknown	Clean out on property	Unknown	Plumber who cleared the line was not sure of what caused the backup.	None	None	Sewage was picked p with Vac truck and returned to sewer system	Yes	None
11/11/06	Private			100	0	0	0	602 CHAPMAN	PLACENTIA	N/A	NA	BLOCKAGE - UNKNOWN	PARKING LOT -> CURB AND GUTTER (NO BACK UP INTO RESTAURANTS ACCORDING TO CITY CREW)	N/A	N/A	N/A	Yes	Resturant
11/12/06	Private		No	531	531	0	0	12186 Solarno	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	

11/12/06	Private Property	U	0	0	0	0	1192 MITCHELL	Tustin	24 inch	Manhole	Blockage	Misc. debris	NA	NA	NA	Y; 11/12/2006 11:50:00 AM	Dindo made regulatory notifications after receiving the spill notification made at 1130 hour. John Ralls (OCHCA) was asked to assist by speaking with apartment manager to call a plumber. ROMD was also notified by Control One.
11/13/06	Private	No	162	162	0	0	11072 Magnolia	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
11/15/06	Private	n/a	0	10	0	0	52 Leesburg	Irvine	Private lateral	Private lateral	roots	Blockage in customer's latera (roots)	^{il} n/a	n/a	n/a	n/a	
11/15/06	Dominic J. Manna owner of this office building	No	25	25	75	0	17122 Beach Blvd.	Huntington Beach	Sewer lateral pipe at 17122 Beach Blvd.	Sewer clean out cover.	Plugged sewer lateral.	Roots and debris in the private sewer lateral.	None	None	All liquid was put into the City sewer system.	Yes	Owner of this office building was very cooperative and helpful.
11/16/06	Service First Management Corporation, property manager Encs Werner 714- 963-5555 ext. 378.	No	3,500	3,500	4,100	0	17742 Beach Bivd.	Huntington Beach	Beach Medical Associates Center, 17742 Beach Blvd. lateral sewer pipe.	Sewer clean out cover.	Plugged sewer lateral.	Roots and debris in the private sewer lateral. The landscaping parallel to this private sewer lateral has about the Ficus trees planted in it. The plumbing company pulle out many roots from this sewer lateral. These roots restricted the sewage flow an	u None d	None	All liquid was put into the City sewer system.	Yes	Property Manager Erica Werner cell phone 949-683-7184.
11/20/06	Service First Management Corporation, property manager Erica Werner 714- 963-5555 ext. 378.	No	1,200	1,200	1,500	0	17742 Beach Blvd.	Huntington Beach	Beach Medical Associates Center, 17742 Beach Blvd. lateral sewer pipe.	Sewer clean out cover.	Plugged sewer lateral.	Roots and debris in the private sewer lateral. Plumbe on 11/16/06 did not get all roots cut and removed from the sewer system.	er None	None	All liquid was put into the City sewer system.	Yes	Property Manager Erica Werner cell phone 949-683-7184.
11/22/06	Private		0	0	0	0	235 W. LINCOLN	ORANGE	N/A	N/A	BLOCKAGE - UNKNOWN	SANTIAGO APARTMENTS - BY TRASH AREA NEXT TO LAUNDRY ROOM	N/A	N/A	N/A	Yes	N/A
11/25/06	Private Property	No	405	0	0	0	1001 W. Stevens	Santa Ana	Private lateral	Private clean out	Grease	Grease in private lateral	Santa Ana Delhi Channel	None	Upper Newport Bay	Yes	None
11/25/06	Private		0	0	0	0	24371 EL TORO ROAD	LAKE FOREST	N/A	N/A	GREASE	CURB & GUTTER -> STORM DRAIN	¹ N/A	N/A	N/A	Yes	May be R-9
11/28/06	Der Wagenmeister owner, Richard (949-633-8033);	N	98	0	0	200	722 West 16th St;	Costa Mesa, CA;	Owner cleaned roots from lateral and pushed in roots into Main Line, 400ft (Drop MH) and 140ft from situs address;	due to lack of backwater prevention	Pushed in tree roots from private property lateral;	Pushed in tree roots from private property lateral;	SD leads to Upper Newport Bay - too fa away for SSO to reach it;	r _{None;}	Wastewater flowed East with owner Rinsewater 250 to SD; Unrecoverable;	0 f ¥; 1 1/28-06 ⊛ 1620hrs;	Der Wagenmeister owner, Richard (949-633-6033) reported PRIVATE SSO to CMSD: CMSD Crew unable to exter private propert yn. Vachor SSO and RimareWater, Wastewater flowd with owner Rinsewater 250ft to SD; Unrecoverable PRIVATE PROPERTY SSO due to lack of
11/30/06	Private	Yes	400	500	500	0	1830 W. Romneya Drive	Anaheim	Pump Station at N/W corner of Euclid and Romneya	Private manhole	pump station failure	A sensor which monitors the level of sewage in the wet wel failed	II Catch basin	Fullerton Creek/Coyote Creek	N/A	Yes	This was an unusual spill as it was caused by a failure of a private pump station. This failure is unlikely to occur again, however we will require assurances from the owner/operator to ensure this.
12/1/06	Private	No	10	40	0	0	415 Old Newport Blvd.	Newport Beach	Lateral	Lateral	Roots from the lateral before the CMSD mainline.	See Remarks	n/a	n/a	Returned to system	Yes	Call for hydroflusher and vactor built erm at private storm drain box and set up vactor. Beamed storm rain box and used hydro to flush curb and gutter to storm drain at Hospital Road to Newport Bivd. returend to parking lot and vacuumed at private stor
12/7/06	Charles Dunn Management Company, Laura Tarbutton Property manager	No	450	450	650	0	6918 Warner Avenue	Huntington Beach	6918 Warner Avenue	Clean out cover behind the Subway Sandwich shop.	Grease blockage	Grease blockage in the privat lateral sewer line.	^{le} None	None	City sewer system.	Yes	
12/11/06	Casa Linda Condos & Montero Planning	No	350	0	o	0	300 E. Chestnut Street, 92701	Santa Ana	At pump lift station.	Pump lift station	Private lift station	The City responded to check City sewer main and found no problems. The spill was coming from the parking garage at 300 E. Chestnut. Montero Plumbing was working on the lift station pumps.	Santa Ana Delhi Channel	Upper Newport Bay	NA	Yes	None
12/14/06	Private Property owner 2630 W Porter	No	0	200	500	0	2630 W Porter - behind apartments in Alley	Fullerton	Private lateral	Lateral cleanout	Unknown		N/A	N/A	Contained in alley	Yes	City sewer crews working in the area noticed overflow in alley. Crews set up comb truck vacuum and contained/vacuumed sewage until water service was shut off to stop flow. Private plumber responded to clear blockage. Crews washed down/vacuumed area.
12/19/06	Private Property owner, CVS Pharmacy	Yes	100	200	All	0	455 N State College Blvd	Fullerton	Private lateral	Lateral cleanout	Lateral defect, debris	6" lateral from building connects to old 4" lateral at sidewalk area creating offset	Fullerton Creek Channel	Pacific Ocean		Yes	City crews responded to private overflow in CVS (formerly Sav-On) parking lot. Water crew responded to shut off water service to stop overflow. Store manager was not aware of problem prior to our arrival. Private plumber was dispatched and responded to
12/20/06	Private	Yes	100	200	0	0	CHAPMAN/STATE COLLEGE	FULLERTON	N/A	N/A	CONSTRUCTION DEBRIS	PARKING LOT CLEAN OUT TO STREET, CURB AND GUTTER TO STORM DRAIN TO FULLERTON CHANNEL.	FULLERTON CHANNEL	N/A	N/A	Yes	NA
12/22/06	Private	Yes	10	0	0	0	1151 N. Euclid St.	Anaheim	1151 N. Euclid lateral in alley behind building	Private cleanout	Grease	Grease caused obstruction	Catch basin	Fullerton Creek/Coyote Creek	N/A	Yes	A previous spill occurred at this location. If routine cleaning and Kitchen BMPs can not prevent spills, an iterceptor will be required,.

12/23/06.	Private	Yes	100	200	0	0	3435 Newport Blvd.	Newport Beach	Grease trap	Grease trap	Grease from their grease trap.	See Remarks	n/a n/a	n/a		Grease trap from Pavillions Market overflowing. Fire crew and Monica from Health Dept. already on scene. Set up vacuum truck in parking lot. Spoke with the Manager at the market and told him he needs to get a plumber out. Health Dept. shut down the Market
12/27/05	City of Santa Ana	No	450	200	250	200	300 W. Second St.	Santa Ana	H09-028	Manhole cover	Grease	No maintenance program caused grease build-up and resulted in flow back-up	None None	Sewage was contained removed with Vactor	and Yes	Affected areas were cleaned up by Aladdin Emergency Clean-up Service. Increase maintenance from the Plaza del Sol Apartment complex.
12/28/06	Private	Yes	200	400	200	0	537 N. Magnolia Ave.	Anaheim	Pump Station Failure	Private manhole	pump station failure	pumps are believed to have burned out	Catch basin Carbon Creek	N/A	¥	This was an unusual spill since it is the third at this location, however, since it was caused by something different each time it has occurred, the order will focus on times that may not have been satisfied in previous orders and items that would help pr
12/30/06	Private		0	0	0	0	4232 KATELLA	LOS ALAMITOS	N/A	N/A		STREET -> CURB & GUTTER	N/A N/A	N/A	Yes	Denny's resturant
12/30/06	Private	yes	100	2000	2000	2000	2704 W. Ball Road	Anaheim	lateral from last manhole in complex to street	Private cleanout	perhaps roots or a	Grease alone or in conjunction with a break or roots caused the obstruction	Catch basin anaheim barber channel	N/A	Yes	
Totals	168		49,782	48,071	39,236	4,985										
Totals	689		208,254	149,389	129,007	49,435										

APPENDIX C

Modified Master Private Property Spills 2002–2006 Sorted by Cause

Date SSO is First Reported to Responding Agency	Cause	Responsible Party	SSO Volume Lost (Gallons)	Recovered SSO Volume (Gallons)	Recovered wash Water & Sewage Contaminated Water Volume	Lost Wash Water & Sewage Contaminated Water Volume	Location of overflow: Street	Location of overflow: City	Location of potential blockage or problem poin	Description of component from which spill occurred	Likely cause of SSO	Overflow Cause - Detailed Description	Remarks
Unknown													
4/15/02	0	Private Property	0	0	0	0	12622 Kingsview Rd.	Unincorporated County of Orange	4" Sewer Line	υ	Blockage	υ	NA
4/23/02	0	Private Property	1281	150	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a
5/2/02		Sunbridge Care Center For Fullerton, private property	20	60	0	0	2800 N Harbor Blvd	Fullerton	Private lateral	Private lateral cleanou	Unknown blockage on private property	N/A	Private four inch sewer lateral backed up and vented out of cleanout on private proper Sewage flowed onto City easement and a small amount of sewage entered the storm drain. City crews responded and contained spill. City crews notified maintenance ma from Subridge to have plumber ordisnake private sewer lateral. Advised to call Emergency Service Restoration for cleanup.
5/13/02	0	RS Properties Mgt. Private property	30	90	40	0	4050 W Franklin Ave	Fullerton	Private lateral	Private lateral cleanou	Unknown blockage on private property	N/A	Private four inch sewer lateral backed up and vented out of cleanout on private proper The city contained sewage. The Management Co called private plumber (Rick the Happy Plumber) to clear blockage. The City washed down and vacuumed sewage an returned it to the sewer system. Contact the Health Dept for their recommendations to the Management Co
5/27/02	0	Private Property	0	0	0	0	na	na	na	na	na	na	California Pizza Kitchen. Not listed in supplied OCHCA report or on Region 8 reports
6/21/02	0	Private Property	0	0	0	0	2220 S. Monte Vista	La Habra	n/a	n/a	n/a	n/a	
6/28/02	0	Private Property	0	0	0	0	631 S. Palm	La Habra	n/a	n/a	n/a	n/a	
7/6/02	0	Costa Mesa Sanitary District	300	300	500	0	1936 Wallace, Costa Mesa, CA	Costa Mesa, CA	Private Lateral	Private Lateral Cleanout	Blockage in Private lateral line	NA	Sewage from private residential lateral spilled into street when private contractor clear residential lateral and cleanout. All sewage contained in street. Approx 2.5 gpm into street * 120 minutes yields 200 gals spilled. Field crew dammed sewage spill, vactore up sewage, flushed street with fresh water and vactored up all flush water. Spill and flush water returned to sewer system. No sewage reached storm drain, channels, or surface waters.
7/10/02	0	Private	1215	1215	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/15/02	0	Private Property	0	0	0	0	1841 VON KARMAN	Irvine Buisness Complex	Private lateral	Indoors	N/A	N/A	Walt reports blockage cleared before his arrival, plumber at location. OCSD lines are running free and clear. No assistance needed.
7/21/02	0	Private	1500	0	0	0	East Shore & East Yale Loop	Irvine	n/a	n/a	n/a	Unknown	
7/23/02	0	Private	98	98	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/30/02	0	Private	10	10	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/30/02	0	Private	150	150	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/30/02	0	Private	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/30/02	0	Private	450	120	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/30/02	0	Private	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/30/02	0	Private	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/31/02	0	Private	165	165	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
8/1/02	0	Private	50	50	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
8/3/02	0	Private Property	0	0	0	0	2220 S. Monte Vista	La Habra	n/a	n/a	n/a	n/a	

8/3/02	0	Private Property	0	0	0	0	2220 MONTE VISTA AVE VISTA APARTMENTS	La Habra	N/A	N/A	N/A	N/A	CALLED LA HABRA POLICE TO CONTACT WATER DEPT. ALSO CALLED OUT DIV. 420 STANDBY. UPON ARRIVAL, STANDBY VERIFIED THAT CITY OF LA HABRA HAD CONTAINED THE SSO, SSO NO LONGER FLOWING, AND NO FLOW WAS GOING TO PUBLIC STREET. PROBLEM CONTAINED ON PRIVATE PROPERT
9/16/02	0	Private	100	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
9/19/02	0	PWA-City of Santa Ana	600	300	900	600	2101 S. Pacific Ave.	Santa Ana	Private lateral	4" clean out	Private property spill, cause of overflow unknown.	Private property spill, cause of overflow unknown.	
9/21/02	0	Private Property	87	0	0	0	16th Street	Seal Beach	residential sewer lateral	lateral sewer line	n/a	blockage	n/a
9/30/02	0	Private	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
9/30/02	0	Private	54	54	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
10/5/02	0	Private	30	30	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
10/17/02	0	Private	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
10/22/02	0	Private	20	0	0	0	7 Holland	Irvine	n/a	n/a	n/a	Unknown	
10/22/02	0	Private Property	0	0	0	0	301 Mountain View	La Habra	n/a	n/a	n/a	n/a	
10/22/02	0	PRIVATE PROPERTY OWNER-JIM YOUNG 761- 5872	1,000	0	0	0	9021 STACIE LANE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE	n/a	n/a
10/25/02	0	Private	5	0	0	0	21212 Bake Pkwy.	Lake Forest	n/a	n/a	n/a	Unknown	
10/26/02	0	Private Property	2	0	0	0	12421 Mystic Lane	Unincorporated County of Orange	Sewer	Clean-out	N/A	N/A	STANDBY CHARLIE AMBRIZ RESPONDED. HE CHECKED OCSD LINES AND ALL WERE FLOWING NORMAL. HE DETERMINED THAT SPILL BELONGED TO PRIVATE PROPERTY OWNER. THEY WERE NOTIFIED TO CALL A PLUMBER.
11/1/02	0	Private Property	0	0	0	0	2300 E. Lambert	La Habra	n/a	n/a	n/a	n/a	
11/11/02	0	Private	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/13/02	0	Seebreeze Management Company	N/A	N/A	N/A	N/A	410 Lake Street	Huntington Beach	410 Lake Street	Cleanout	Maintenance Crew	Maintenance Crew was cleaning sewer lines and allowing the sewage to flow down the drain.	None
11/21/02	0	Private Property	120	120	60	0	361-371 Oak Place	Brea	Sewer	Manhole	Don't Know	NA	This was a private property spill.
11/30/02	0	Denny's Resturant	165	35	0	0	n/a	n/a	Line blockage	Line Blockage	Line blockage	n/a	(Not in originally submitted OCHCA report or Region 8 reports. Listed in OCHCA Beach Closure report)
12/5/02	0	Private	500	100	0	0	1433 Superior Ave.	Newport Beach	Private system	Private system	Unknown	See Remarks	Plumber onsite removed blockage in private system as CNB news arrive on site
12/10/02	0	Private Property	0	0	0	0	1770 W. La Habra	La Habra	n/a	n/a	n/a	n/a	
12/20/02	0	Private	640	1625	0	0	San Canyon & Burt Rd.	Irvine	n/a	n/a	Unknown	Unknown	
12/20/02	0	PRIVATE PROPERTY OWNER - APT COMPLEX	100	0	0	0	7330 CERRITOS AVE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE	n/a	n/a
1/5/03	0	Private	50	50	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
1/6/03	0	Private Property	300	300	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a

1/803 0 Private Property 5 0 0 1621 FOOTHILL BLVD. Unincorporated County Private lateral line Clean out Unknown NA Property or constraints 1/803 0 PACIFIC WEST MGMT CO. 450 0 0 100 12057 BEACH BLVD. STANTON LINE BLOCKAGE n/a LINE BLOCKAGE n/a n/a n/a 1/1/1/03 0 Private Property 0 0 0 n/a or ange n/a	SD staff inspected OCSD lines and found them running normal. At the request of resident staff showed him the structure at both ends of the line segment in front of property. The resident was informed that this was his responsibility to clear the
1/1903 0 PACIFIC WEST MOMITOD. 450 0 0 0 0 1/2057 BEACH BEVD. STANTON Lifter BLOCKAGE rrad GREASE rrad Inal	SD staff inspected OCSD lines and found them running normal. At the request of resident staff showed him the structure at both ends of the line segment in front of property. The resident was informed that this was his responsibility to clear the
1/1603 0 Private Property 0 0 0 0 0 1/436 SAND BROOK DR. Tustin Private lateral line Bathtub Unknown NA OCSD state the reside his property line	SD staff inspected OCSD lines and found them running normal. At the request of resident staff showed him the structure at both ends of the line segment in front of property. The resident was informed that this was his responsibility to clear the
1/16/03 0 Private Property 0 0 0 0 14436 SAND BROOK DR. Tustin Private lateral line Bathub Unknown NA the reside his properties of the properties	resident staff showed him the structure at both ends of the line segment in front of property. The resident was informed that this was his responsibility to clear the
1/23/03 0 Private 300 0 0 0 19752 Macanther Blvd. Irvine n/a n/a Unknown Unknown	
1/23/03 0 Private 179 179 0 0 n/a Garden Grove n/a n/a n/a n/a	
1/27/03 0 Private Property 50 50 0 0 n/a Orange n/a n/a n/a n/a	
1/29/03 0 Private 192 192 0 0 n/a Garden Grove n/a n/a n/a	
22/03 0 FAIRCREST APARTMENTS 10,400 8,000 0 0 FERN AND CERRITOS STANTON LINE BLOCKAGE n/a LINE BLOCKAGE n/a n/a	
2/6/03 0 Private Property 2 0 0 0 Vacant lot between 1621 Bivd. Bivd. and 1651 Foothill Unincorporated County Private Lateral Private Cleanout Unknown Unknown NA	
2/24/03 0 Private 75 75 0 0 n/a n/a n/a n/a	
3/1/03 0 PRIVATE PROPERTY OWNER - BURGER KING 300 100 0 0 12550 BEACH BLVD. STANTON LINE BLOCKAGE n/a LINE BLOCKAGE n/a	
3/7/03 0 Private 200 200 0 0 n/a Garden Grove n/a n/a n/a	
3/12/03 0 Private 15 0 0 n/a Garden Grove n/a n/a n/a	
4/3/03 0 Private (resident) 0 15 75 0 745 N Euclid Pullerton Private lateral between driveway and connection to driveway and conn	crews Hernandez, Rangel, Davidson and Anzaldo responded to a report of a gged lateral. When they arrived, sewage was observed seeping out of resident's ate cleanout into guiter area. City crews contained the sewage, washed down, uned and returned to sever system. Resident to hite private plumber to clear lin /s main was flowing fine. Resident had reported blockage on 4/2/03, no overflow ured at that time, resident was to hire plumber.
4/18/03 0 Private Property 0 0 0 0 2220 S. Monte Vista La Habra n/a n/a n/a	
5/1/03 0 Private 60 0 0 0 3 Burroughs Irvine n/a n/a Unknown Unknown	
5/6/03 0 Private 10 10 0 0 n/a Garden Grove n/a n/a n/a	
5/15/03 0 Private Property 0 0 0 1232 N. Palm La Habra n/a Septic Tank n/a	
6/6/03 0 Private 25 25 0 0 n/a Garden Grove n/a n/a n/a n/a	
6/9103 0 Private Property 0 0 0 0 331 Eurice Cr. La Habra n/a n/a n/a n/a	
7/8/03 0 Private Property 0 0 0 141 S. Idaho La Habra n/a Cleanout n/a N/a	
7/9/03 0 Private Property 0 0 0 0 11772 HIGH VIEW DRIVE Unicorporated County o Private sewer line Bathub and toilet U U OCSD line	SD line was running freely. No sewer spill in the area.
7/30/03 0 Private 110 110 0 0 n/a Garden Grove n/a n/a n/a	

8/13/03	0	Private Property	0	0	0	0	12523 HINTON WAY	Unicorporated County o Orange	Per Roy Parrino the problem was on Private Property and the problem stemmed from their clean-out. There was no spill, and the residents were told to contact a plumber and not to run any water.	N/A	N/A	N/A	None
8/28/03	0	Private Property	0	0	0	0	18802 BARDEEN AV	Irvine	SBCO 420 Charlie Ambriz to evaluate the problem. Spill was in the residential property.	N/A	N/A	N/A	None
8/28/03	0	Private Property	0	0	0	0	12691 BROWNING AVE	Unicorporated County o Orange	Call out Div. 420 Standby Charlie Ambriz. 08/29/03 00:22 Charlie reported that OCSD line was flowing dearly. Problem was at home owner's building sewer.	Bath tub and toilet	U	N/A	None
9/4/03	0	Private Property	0	0	0	0	17792 McFadden	Tustin	Blockage was determined to be in private property	Toilets backed up in Shopping Center Area	U	N/A	N/A
9/12/03	0	Private Property	0	0	0	0	1061 N. Euclid St.	La Habra	n/a	Cleanout	n/a	n/a	
9/18/03	0	Private Property	0	0	0	0	630 N. Beach Blvd.	La Habra	n/a	Washrack	n/a	n/a	
9/28/03	0	Private	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
9/30/03	0	Private	5	5	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
10/10/03	0	Private Property	0	0	0	0	2501, 2511 & 2521 W. SUNFLOWER AVE	SANTA ANA	U	υ	U	U	N/A
10/13/03	0	Private	115	115	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
10/22/03	0	Private	0	180	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
10/30/03	0	Private	24	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/4/03	0	Private Property	0	0	0	0	17792 McFadden Ave	Tustin	N/A	N/A	N/A	N/A	Resident Called in to report toilet back up. Spill was private property responsibility
11/12/03	0	Private Party	40	305	0	0	10201 Valley View	Cypress	n/a	n/a	n/a	n/a	
11/15/03	0	Private	55	55	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/25/03	0	Private Property	450	50	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a
12/8/03	0	Private Property	0	0	0	0	321 S. Idaho St.	La Habra	n/a	Cleanout	n/a	n/a	
12/22/03	0	Private	5	5	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
12/22/03	0	Private	12	12	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
12/28/03	0	Complex,private property	0	15	20	0	7002 Moody St.	La Palma	Private lateral	Private lateral cleanou	Blockage	Blockage	Private contractor sanitized and cleaned up
1/17/04	0	Brea	300	50	50	0	105 W. lambert Rd.	Brea	unknown	intercepter	unknown	NA	The property management and Alexander Soles from OC Health dept were on site at time of the sewer stoppage.
1/17/04	0	Brea	0	300	350	0	730 Imp. Hwy.	Brea	unknown	intercepter	unknown	na	The property management and Alexander Soles from OC Health dept were on site at time of the sewer stoppage. Apartment management phone # 714.990.0151
1/21/04	0	Private	52	55	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	

							1		1	1		1	
1/31/04	0	Private Property	0	100	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
2/3/04	0	Private Property Owner	0	0	0	0	3133 Pearl Dr	Fullerton	Private lateral for kitchen area	Private lateral cleanou	Unknown	Unknown	Emergency night crew Jennings responded to report of lateral blockage at apartment en 2/3/04. Advised resident to call a plumber, no follow up needed. Sanitation crews responded on 2/6/04 to check main line and found lateral problem had not been resolved. Cit/ Qode Enforcement and QC Health Dept were called. City crews remained on scene to contain if necessary until water was shut off and Code Enforcement and Health personnel arrived. Small amount of grey water reached sidewalk area. Overflow remained in landscape area surrounding building. Owner and plumber were called and responded to take care of the problem. Code enforcement an Health Dept supervised dry cleanup, Health Dept recommended adding some lime wh scarifying.
2/19/04	0	Private	5	5	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
2/19/04	0	Private	50	50	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
2/19/04	0	Private	30	30	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
3/3/04	0	Private Property	120	120	200	0	2540Country Hills Rd.	Brea	A-04	Manhole	unknown	NA	Apartment Manager Kathy Hill (714)9905626
3/22/04	0	Pacific Mobile Home Park	30	30	80	0	Pacific Mobile Home Park, 80 Huntington St.	Huntington Beach	Sewer clean out pipe	Mobile Home	Sewer pipe was clogged.	In ground sewage hook-up pipe for Mobile Home was clogged causing sewage to back-up and overflow.	Private property owner hired Emergency Services Restoration Company to do all the
3/25/04	0	Private Property	25	225	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
4/12/04	0	Private Business	0	8	200	0	814 Williamson Ave	Fullerton	Private Lateral	Private Lateral Cleanout	Unknown		City crews responded to report of sewage seeping out of cleanout. City crews assisted private business to contained intermittent overflow at a sump box approximately 100° from cleanout. City crews rodded private lateral to clear biockage. All sewage was confined to drivway, swale area and sump to as tindustrial area of Williamson. City crews washed down and vacuumed area and sump.
5/17/04	0	Private Property	25	25	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a
5/19/04	0	Private	10	10	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
6/24/04	0	Private Spill	400	100	0	0	500 Superior	Newport Beach	n/a	n/a	Unknown	See Remarks	Vactor setup dirt berm@catch basin. Vacuum setup @ manhole to stop SSO.
7/12/04	0	Private	45	45	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/15/04	0	Private Property	0	0	0	0	On Canyon Terrace Rd which is just below residents house @ 10372 Crawford Canyon Rd.	Unincorporated County of Orange	U	Cleanout	U	U	N/A
8/4/04	0	Private	30	30	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
8/5/04	0	Private Party	20	180	0	0	4901 Lincoln Ave.	Cypress	n/a	n/a	n/a	n/a	
8/12/04	0	Private property owner	0	20	200	0	741 W Commonwealth Ave	Fullerton	Private lateral	Lateral cleanout near sidewalk	Unknown		City Vactor crew observed lateral cleanout from small business complex overflowing onto City street. Crews stopped and set up Vactor vacuum at 770 W Commonwealth Ave to contain spill. The City's lateral crew responded and cleared blockage in lateral to stop overflow. City crews washed down and vacuumed sewage on street, sidewalk, a cut. On 8-16-04, property owner was notified of problem and lateral responsibilities. Owner had recently had lateral cleaned and video inspected. We advised owner to ha treanst keep a close eye on the problem and immediately call a plumber if another problem occurs, but to call the City immediately if cleanout overflows so our crews car contain spill until plumber arrives. Owner was cooperative.
9/7/04	0	Private Property	0	0	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
9/22/04	0	Private Property	0	0	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a

9/24/04	0	Private*	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	Private spill in Midway Sanitary District juristiction. GGSD crews were first responders and acted in a support role only.
10/8/04	0	Private	150	150	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/1/04	0	Private	22	22	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/5/04	0	Private	110	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/8/04	0	Private Property	0	0	0	0	1541 FOOTHILL BL	Santa Ana	U	U	Other	U	N/A
11/10/04	0	Private	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/11/04	0	Private	100	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/12/04	0	Private	100	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/13/04	0	Private	360	360	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/15/04	0	Private	250	0	0	0	#1 Federation Way	Irvine	Private manhole	Private manhole	n/a	Private manhole, unknown blockage	
11/15/04	0	Private	150	150	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/19/04	0	Private	10	10	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/22/04	0	Private Property	0	0	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
11/23/04	0	Private Property	0	0	0	0	171 FIRST ST.	Tustin	U	U	Blockage	Misc. debris	N/A
12/10/04	0	Private Property	0	0	0	0	4516 CHAPMAN AVE	Orange	NA	Manhole	U	υ	NA
12/10/04	0	Private	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
12/11/04	0	Private	150	150	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
12/13/04	0	Private Property	0	25	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
12/14/04	0	Private	100	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	Yes, but did not enter the storm drain channel. Contained at storm drain outlet to channel.
12/19/04	0	Albertson's	0	200	0	0	3049 E. PCH, CDM	Newport Beach	Cleanout. Blockage on private lateral.	Cleanout	Blockage in private lateral	See Remarks	Kitty litter used to build control dykes to contained flow from cleanout. Overflow from supermarket. Parking lot was shutdown from one end to another to stop cars from driving thru puddles of sewage in lot. OCHD (Contor11) and RWQCB (OES) called. Corwin Brown and Monica Mazur cabled back from OCHD. OES Control is si WH6650 Plumber called by Henry the Mgr. from Albertson's to clear blockage from private later Vacuum unit 5503 and hydro Unit 5517 used to clean up parking lot.
12/29/04	0	Private Property	50	25	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
1/3/05	0	Private	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
1/15/05	0	Private	3500	3500	0	0	10200 Chapman	Garden Grove	n/a	n/a	n/a	n/a	
1/17/05	0	Private	20	0	0	0	250 CHANNEL ROAD	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	GUTTER	N/A
1/24/05	0	Private Property	0	0	0	0	311 W. LAMBERT RD.	La Habra	n/a	Private lateral	n/a	n/a	
1/31/05	0	Private	0	0	0	0	4362 LINCOLN	CYPRESS	N/A	N/A	BLOCKAGE - UNKNOWN		N/A
2/4/05	0	Private Property	0	0	0	0	1581 N. FOOTHILL BLVD	Unincorporated County of Orange	NA	GROUND	U	U	NA

	1												
2/7/05	0	Private	0	0	0	0	233 CARNATION	NEWPORT BEACH	N/A	N/A	UNKNOWN	ON-SITE	NA
2/10/05	0	Private	5	5	0	0	11418 Knott	Garden Grove	n/a	n/a	n/a	n/a	
2/14/05	0	Private Property	0	0	0	0	10511 EASTER HILL DR.	Unincorporated County of Orange	υ	U	υ	υ	Arrived on site at 10:50am. Checked OCSD M/H. All lines were flowing normal. We set up flush truck and ran customer line 319 feet, bringing back nothing. Gated community, customer was not home.
2/17/05	0	Private	30	0	0	0	20041 Osterman St.	Lake Forest	Cleanout	Cleanout	n/a	4" private cleanout-blockage	
2/26/05	0	Private	500	0	0	0	13011 NEWPORT	TUSTIN	N/A	N/A	BLOCKAGE - UNKNOWN	STORM DRAIN	NA
3/5/05	0	Private	40	0	0	0	540 FREEDOM	ORANGE	N/A	N/A	BLOCKAGE - UNKNOWN	STORM DRAIN/STREET	N/A
3/7/05	0	Private	842	842	0	0	10022 Garden Grove Blvd.	Garden Grove	n/a	n/a	n/a	n/a	
3/8/05	0	MBJ Property Management	290	400	2000	0	2500 E Chapman Ave @ St College	Fullerton	Private lateral to the rear of 2506 E Chapman Ave	Private lateral cleanou	Unknown		City crews responded to private lateral overflow from cleanout to the rear of 2506 E Chapman Ave. Sewage was flowing down alley swale to storm drain inlet in approach alley off St College Bivd. City crews contained flow at storm drain and several areas in the alley. Vactor vacuum was set up to vacuum sewage while crews cleared blockage City crews cleared blockage with rodding equipment. City crews washed down alley swale and vacuumed all sewage and returned to sanitary sewer system. MBJ propent management company was notified at 9:45 by Round Table Pizza to have private plumber respond. Private plumber had not responsibilities and has recently hired private plumber to video and assess lateral for possible replacement.
3/10/05	0	Private	64	64	0	0	12572 Harbor	Garden Grove	n/a	n/a	n/a	n/a	
3/12/05	0	Private Property	700	200	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
3/14/05	0	Private	30	30	0	0	9691 Garden Grove Blvd.	Garden Grove	n/a	n/a	n/a	n/a	
3/16/05	0	Private Property	0	60	0	0	10488 Valley View	Buena Park	n/a	n/a	n/a	n/a	n/a
3/20/05	0	Private	350	150	0	0	745 DOVER	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	PRIVATE CLEAN OUT TO PARKING LOT TO STORM DRAIN TO NEWPORT BAY	N/A
3/20/05	0	Private	631	631	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
3/26/05	0	Private	5	0	0	0	2212 S. MONTE VISTA	LA HABRA	N/A	N/A	BLOCKAGE - UNKNOWN	ALL DISCHARGE CONTAINED ON SITE.	N/A
3/29/05	0	Private	175	175	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
4/1/05	0	Private	14	14	0	0	8042 Garden Grove Blvd.	Garden Grove	n/a	n/a	n/a	n/a	
4/5/05	0	Private Property	0	100	0	0	8810 San Antonio	Buena Park	n/a	n/a	n/a	n/a	n/a
4/5/05	0	Private	2020	2020	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
4/18/05	0	Private	75	75	0	0	11072 Magnolia	Garden Grove	n/a	n/a	n/a	n/a	
4/26/05	0	Private Property	0	0	0	0	1232 N. PALM	La Habra	n/a	Septic Tank	n/a	n/a	
4/29/05	0	Private Property	0	0	0	0	119 1/2 LEORA ST	La Habra	n/a	Cleanout	n/a	n/a	
5/9/05	0	Private Property	0	0	0	0	2212 S. MONTE VISTA ST.	La Habra	n/a	Cleanout	n/a	n/a	
5/13/05	0	Private	79	79	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
5/20/05	0	FV	25	25	0	0	16275 Harbor Blvd	Fountain Valley	private property sewer latera	1	blockage	clogged sewer lateral not grease interceptor	NA

-		1						1	1	r			
5/23/05	0	Private	119	119	0	0	12991 Rosewood	Garden Grove	n/a	n/a	n/a	n/a	
5/30/05	0	Private	451	451	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
6/3/05	0	Private	28	28	0	0	12158 Brookhurst	Garden Grove	n/a	n/a	n/a	n/a	
6/13/05	0	Private	75	75	0	0	10212 Westminster	Garden Grove	n/a	n/a	n/a	n/a	
6/17/05	0	Private Property	75	40	0	0	2127 Quincy	Orange	n/a	n/a	Pumped to St.	n/a	n/a
6/18/05	0	Private Property	100	0	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
6/29/05	0	Private Property	0	0	0	0	1300 W.LAMBERT RD	La Habra	n/a	Cleanout	n/a	n/a	
7/11/05	0	Private Property	0	0	0	0	10072 FOX SPRING RD	Unincorporated County of Orange	U	Septic tank	Other	Other	NA
8/4/05	0	Private Property	0	0	0	0	821 CORTO WAY	La Habra	n/a	Cleanout	n/a	n/a	
8/14/05	0	Private	0	5	0	0	1311 W. BAY	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	ALLEY	NA
8/22/05	0	Private Property	0	30	0	0	5317 Humbolt	Buena Park	n/a	n/a	n/a	n/a	n/a
9/18/05	0	Private	0	100	0	0	310 S. JEFFERSON	PLACENTIA	N/A	N/A	BLOCKAGE - UNKNOWN	STAYED ON SITE	N/A
9/19/05	0	Private	61	61	0	0	10012 Westminster	Garden Grove	n/a	n/a	n/a	n/a	
9/27/05	0	Private Property	0	0	0	0	500 Teakwood Ave.	La Habra	n/a	Cleanout	n/a	n/a	
10/10/05	0	Private	215	215	0	0	9855 Hewitt	Garden Grove	n/a	n/a	n/a	n/a	
10/18/05	0	Private	400	425	0	0	18555 YORBA LINDA BLVD.	YORBA LINDA	N/A	N/A	BLOCKAGE - UNKNOWN	CURB & GUTTER -> STORM DRAIN	NA
10/19/05	0	Private	64	64	0	0	10072 Westminster	Garden Grove	n/a	n/a	n/a	n/a	
11/3/05	0	Costa Mesa Sanitary District	0	45	100	5	2520 Kincaid Drive	Costa Mesa, CA	Unknown blockage blocked private lateral line in a multifamily residential complex at Fairview State Hospital forcing SSO out of private property M/H;	blocked private lateral line in a multifamily residential complex at	Unknown blockage blocked private lateral line in a multifamily residential complex at Fairview State Hospital;	Unknown blockage blocked private lateral line in a multifamily residential complex at Fairview State Hospital;	Unknown blockage blocked private lateral line in a mutifamily residential complex at Fairview State Hospital forcing SSO out of private property MH: District crew blocked SD, vactored SSO from the street, curb and SD; flushed the area with fresh rinse wate District Staff contacted Fairview State Hospital Manager (Shanon, 7):14545-0421 contact plumber and increase frequency of lateral line cleaning; Private plumber removed lateral line blockage; vactored SSO was disposed of in the District Santary Sever System; Pictures were taken and are attached;
11/3/05	0	Private Property	0	0	0	0	1750 W.Lambert Rd.	La Habra	n/a	Cleanout	n/a	n/a	
11/4/05	0	Private Party	0	15	0	0	4001 Orange Ave	Cypress	n/a	n/a	n/a	n/a	
11/5/05	0	Private Property	0	10	0	0	14636 Goldenwwest Ave Westminster	Westminster		cleanout	n/a	na	Spill reported by Westminster City water standby.
11/9/05	0	Private Property	0	0	0	0	550 W. La Habra BL	La Habra	n/a	Cleanout	n/a	n/a	
11/10/05	0	Private	20	20	0	0	9802 Katella	Garden Grove	n/a	n/a	n/a	n/a	
11/18/05	0	Private	121	121	0	0	8042 Garden Grove Blvd.	Garden Grove	n/a	n/a	n/a	n/a	
11/20/05	0	Private	0	20	0	0	1101 PINE STREET	HUNTINGTON BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	NA
11/25/05	0	Private	225	0	0	0	26652 Portola Pkwy	Foothill Ranch	Private lateral	Private lateral	n/a	Blockage in lateral between interceptor and main line	

	1		I										
11/28/05	0	Private	355	355	0	0	12851 Haster	Garden Grove	n/a	n/a	n/a	n/a	
12/2/05	0	Private Property	0	0	0	0	1233 W. La Habra Bl.	La Habra	n/a	Cleanout	n/a	n/a	
12/9/05	0	Private	0	0	0	0	2085 N. HIGHLAND	ORANGE	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	N/A
12/14/05	0	Private	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
12/16/05	0	Private	45	45	0	0	13946 Erin	Garden Grove	n/a	n/a	n/a	n/a	
12/19/05	0	Private Property	0	0	0	0	1451 NISSON RD	Tustin	Septic tank	Septic tank	U	U	OCSD responded to this Private Property spill in an assistance capacity to the city of Tustin.
12/29/05	0	Private	2	2	0	0	10240 Westminster	Garden Grove	n/a	n/a	n/a	n/a	
1/7/06	0	Private	0	120	0	0	1200 PACIFIC COAST HIGHWAY	HUNTINGTON BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	CLEAN OUT TO PARKING GARAGE FLOOR TO CONTAINED.	N/A
1/8/06	0	Private Party	0	40	0	0	8641 Moody Street	Cypress	n/a	n/a	n/a	n/a	
1/10/06	0	Private	0	0	0	0	2321 S. BRISTOL	SANTA ANA	N/A	N/A	BLOCKAGE - UNKNOWN	CONTAINED IN PARKING LOT	NA
1/11/06	0	Private	229	229	0	0	12342 Brookhurst	Garden Grove	n/a	n/a	n/a	n/a	
1/24/06	0	Private	0	1000	0	0	12705 NEWBROOK	STANTON	N/A	N/A	BLOCKAGE - UNKNOWN	ALL DISCHARGE WAS RECOVERED AND RETURNED TO SEWER SYSTEM.	NA
1/25/06	0	Private	0	0	0	0	1205 NEWBROOK	STANTON	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	NA
1/25/06	0	Private	0	0	0	0	770 S. PLACENTIA AVENUE	PLACENTIA	N/A	N/A	BLOCKAGE - UNKNOWN	CURB/GUTTER -> COLLECTION	N/A
1/26/06	0	Private Property	0	5	0	0	154 S.WALLACE ST.	La Habra	n/a	Cleanout	n/a	n/a	
1/27/06	0	Private Property	0	1	0	0	1671 DORWOOD AVE.	La Habra	n/a	Cleanout	n/a	n/a	
1/27/06	0	Private	0	2000	0	0	4600 BISON AVENUE (UCI)	IRVINE	N/A	N/A	BLOCKAGE - UNKNOWN	PONDED IN A PIT ON CAMPUS SITE.	NA
2/2/06	0	Private	202	202	0	0	8519 Edgebrook	Garden Grove	n/a	n/a	n/a	n/a	
2/4/06	0	Private Property	50	0	0	0	1621 EDINGER AVE.	Tustin	U	Cleanout	Blockage	Other	Div. 420 was sent to the location to determine the nature of problem and was requested to standby until Orange County Health department arrived on scene. Spill was on private property.
2/5/06	0	Private Spill - Michael Brinkmai (949) 650-9100	0	20	30	0	825 E. Chestnut - Private Property	Santa Ana	Private Property	Clean out	Cause unknown - private property	Ran out of parking structure, down driveway to street - caus unknown	Fire Dept. reported spill to both OC Health/Regional Board
2/16/06	0	FV	75	2	0	0	17815 Newhope Street	Fountain Valley	private property sewer latera	1	unknown	possible paper towel in toilet	NA
2/25/06	0	Private	100	0	0	0	113 Rockwood St.	Irvine	n/a	n/a	n/a	Unknown blockage	
2/25/06	0	Private	100	0	0	0	107 ROCKWELL	IRVINE	N/A	N/A	BLOCKAGE - UNKNOWN	CONTAINED IN PLANTER.	May be R-9
3/1/06	0	Private Party	0	200	0	0	5940 Cerritos Ave.	Cypress	n/a	n/a	n/a	n/a	
3/7/06	0	Private	500	40	20	0	105 E. Leatrice Ln.	Anaheim	105 E. Leatrice Ln.	Private cleanout	Vandalism	Vandalism caused spill	This spill was reported to have been flowing for several days by the tenants. The odo the area and the volume of solids near the spill bears this out. However, the property owner was very responsive in taking care of the obstruction as well as aiding in the cleanup.

3/19/06	0	Private	3	3	0	0	13556 Robin Court	Garden Grove	n/a	n/a	n/a	n/a	
3/23/06	0	Private Property	0	450	0	0	1538 E. Chapman	Orange	n/a	n/a	unknown	n/a	n/a
4/7/06	0	Private	98	98	0	0	12188 Brookhurst	Garden Grove	n/a	n/a	n/a	n/a	
4/25/06	0	Private	50	100	0	0	21372 BROOKHURST	HUNTINGTON BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	STORM DRAIN	N/A
5/8/06	0	Private Property	0	0	0	0	730 W.5TH STREET	La Habra	n/a	Private lateral	n/a	n/a	
5/9/06	0	Private Party	0	20	0	0	6336 Orange Ave.	Cypress	n/a	n/a	n/a	n/a	
5/11/06	0	Private	59	59	0	0	12912 Magnolia	Garden Grove	n/a	n/a	n/a	n/a	
5/17/06	0	Private	22	22	0	0	8903 Hewitt Place	Garden Grove	n/a	n/a	n/a	n/a	
5/18/06	0	Private Property	0	60	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
5/24/06	0	Private	60	160	500	0	905 E. Vermont Ave.	Anaheim	905 E. Vermont Ave.	Private cleanout	Toilet left running into tank	Toilet left running into tank caused obstruction	Because the spill flowed a significant distance before reaching the catch basin, it is believed that a significant portion of the spill was contained and collected before it was discharged into the catch basin.
6/5/06	0	Private	128	128	0	0	10761 Palma Vista	Garden Grove	n/a	n/a	n/a	n/a	
6/8/06	0	La Palma Hospital, private property	0	90	110	0	7901 Walker Street	La Palma	Private Lateral	Manhole	Unknown Blockage	Blockage from private property	Private contractor sanitized and cleaned up
7/3/06	0	PRIVATE SSO at Apartment complex at 1741 Tustin Ave, managed by South Coast Property Management Co (714 444-2602 Voice, 714-444-3602 FAX);	25	75	150	25	1741 Tustin Ave;	Costa Mesa, CA;	Blockage in PRIVATE latera	property at 1740 Tustin	in PRIVATE lateral	Unknown blockage in PRIVATI lateral line on PRIVATE property;	PRIVATE SSO at Apartment complex at 1741 Tustin Ave, managed by South Coast Property Management Co (714-444-2602-Voice, 714-444-3602-FAX); Estimated 100 gallon PRIVATE SSO flow contained in private drive and curb; District crew dammed SD; PRIVATE Istoraci, City of Costa Meas vactored SSO in public ROW curb and guiter and disposed of SSO and rinswater in CMSD sanitary sever system at the Corporate Yard; Apartment complex needs to Increase the frequency of cleaning PRIVATE lateral lines; Photographs were taken and are attached;
7/4/06	0	Private	0	20	0	0	1723 E. OCEANFRONT	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	CURB & GUTTER - CONTAINED BY CITY CREW	N/A
7/6/06	0	Private	30	370	0	0	745 DOVER	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	PPO CLEAN OUT TO PARKING LOT TO STORM DRAIN.	NA
7/10/06	0	Private Property	0	0	0	0	17672 ORANGE TREE LANE	Tustin	4-inch	Bathroom	Blockage	Unknown	RWQCB was contacted with their after hours number and was left a voice message. Control 1 was contacted and spoke to John (Environmental Health).
7/12/06	0	Private	0	1620	4500	0	3534 W. Ball Road	Anaheim	3534 W. Ball Road	Private cleanout	Unknown	Unknown	N/A
7/13/06	0	Private	44	44	0	0	11812 Poes	Garden Grove	n/a	n/a	n/a	n/a	
7/17/06	0	Private Property	50	100	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
7/26/06	0	Private	144	144	0	0	12905 Palm	Garden Grove	n/a	n/a	n/a	n/a	
8/14/06	0	Private Property	0	100	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
8/20/06	0	Private Property	100	100	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
8/27/06	0	Private	215	215	0	0	12905 Palm	Garden Grove	n/a	n/a	n/a	n/a	
9/17/06	0	Private	395	395	0	0	10191 Lampson	Garden Grove	n/a	n/a	n/a	n/a	
9/23/06	0	Private	0	0	0	0	4672 PLUMOSA DRIVE	YORBA LINDA	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	NA

9/28/06	0	Private	25	0	0	0	Grant Street	Newport Beach	n/a	n/a	n/a	n/a	(Listed only on the OCHCA Beach Closure Report)
10/5/06	0	Private	0	20	0	0	703 POPPY	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	YARD -> CURB & GUTTER -> ALL FLOW CONTAINED	NA
10/12/06	0	Private	300	0	0	0	3955 Alton Pkwy Olive Garden	Irvine	Private lateral	Private lateral	n/a	Blockage in customer's lateral	
10/16/06	0	Private	200	0	0	0	610 NEWPORT CENTER DRIVE	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	SEWAGE DISCHARGED TO STORM DRAIN AND INTO NEWPORT BAY	NA
10/21/06	0	Private	0	0	0	0	1139 / 1125 CERRITOS DR	FULLERTON	N/A	N/A	BLOCKAGE - UNKNOWN	PRIVATE CLEANOUT TO PRIVATE PROPERTY TO DIRT TRACK TO STORM DRAIN.	NA
10/30/06	0	Private	0	0	0	0	710 WASHINGTON AVENUE	SANTA ANA	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	N/A
11/8/06	0	Private	162	162	0	0	11072 Magnolia	Garden Grove	n/a	n/a	n/a	n/a	
11/9/06	0	Private Property	0	100	225	0	614-616 E. Pine Street	Santa Ana	Unknown	Clean out on property	Unknown	Plumber who cleared the line was not sure of what caused the backup.	None
11/11/06	0	Private	100	0	0	0	602 CHAPMAN	PLACENTIA	N/A	N/A	BLOCKAGE - UNKNOWN	PARKING LOT -> CURB AND GUTTER (NO BACK UP INTO RESTAURANTS ACCORDING TO CITY CREW)	Resturant
11/12/06	0	Private	531	531	0	0	12186 Solarno	Garden Grove	n/a	n/a	n/a	n/a	
11/13/06	0	Private	162	162	0	0	11072 Magnolia	Garden Grove	n/a	n/a	n/a	n/a	
11/15/06	0	Dominic J. Manna owner of this office building	25	25	75	0	17122 Beach Blvd.	Huntington Beach	Sewer lateral pipe at 17122 Beach Blvd.	Sewer clean out cover	Plugged sewer lateral.	Roots and debris in the private sewer lateral.	Owner of this office building was very cooperative and helpful.
11/22/06	0	Private	0	0	0	0	235 W. LINCOLN	ORANGE	N/A	N/A	BLOCKAGE - UNKNOWN	SANTIAGO APARTMENTS - BY TRASH AREA NEXT TO LAUNDRY ROOM	NA
12/14/06	0	Private Property owner 2630 W Porter	0	200	500	0	2630 W Porter - behind apartments in Alley	Fullerton	Private lateral	Lateral cleanout	Unknown		City sewer crews working in the area noticed overflow in alley. Crews set up combo truck vacuum and contained/vacuumed sewage until water service was shut off to stop flow. Private plumber responded to clear blockage. Crews washed down/vacuumed area.
Totals	253		40,890	37,918	10,885	630							
Grease													
4/2/02	1	Private	0	0	0	0	2325 E. PCH	Newport Beach	Grease Interceptor	Grease Interceptor	Unknown	See Remarks	Grease interceptor was overflowing (Brio Rest)
4/18/02	1	PRIVATE PROPERTY OWNER	150	150	0	0	9010 STACIE LANE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE - GREASE	n/a	n/a
4/27/02	1	Private Property -Beachwalk Condominiums	675	350	0	0	19801 Shorecliff Lane	Huntington Beach	In the street at 19801 Shorecliff Lane.	4" Clean Out Lid	Grease	A buildup of grease in the line, probably caused by insufficient maintenance.	

	-												
6/6/02	1	Private Property	340	240	580	0	4117 W. McFadden Avenue	Santa Ana	Private Property	Clean out	Grease - Private Property. City of Santa Ana installed a siphon to make way for a storm drain system on the lateral. Spill occurred due to grease build up.	The City of Santa Ana installed a siphon to make way for a storm drain system on the lateral, the siphon backed up due to grease.	
6/17/02	1	Private Property -Beachwalk Condominiums	45	45	50	0	19771 Coastline Lane	Huntington Beach	In the street at 19771 Coastline Lane.	Manhole lid	Grease	A buildup of grease in the line, probably caused by insufficient maintenance.	
6/25/02	1	Private Property - Owner not known	375	375	575	0	421 E. 16th Street	Santa Ana	Private Property	Clean out	Grease and paper	Grease and paper	
6/30/02	1	Private Property	300	0	0	0	3rd St & French St.	Santa Ana	Private property lateral	Cleanout	Blockage Grease	Not applicable - Not OCSD SSO	Called Don Cleveland to respond and evaluate, due to no response from Santa Ana Public Works. Don Cleveland arrived at this location at 1015 hour. City of Santa Ana, Fire Department rived on stile before Sam. A private plumber also responded to the sile to relieve the blockage in the private properly line that was causing flocking in the apartment complex. At about 3: Tisam o relieve the flocking in the plumber opened the cleanou which allowed the sewage to flow diffile and into the stort driving. The Fire Department was able to contain the spill within about 15 lin. and calculated the flow or to be 10 gallons per minute. They conservatively settimated the anound of the spill to storm drinin to be about 300 gallons (15 min x 10 gpm x 2 for conservancy) Health Cale was onsite by 10 Joan and PFRN, Karen Ashty, scon after. Haz Mata Iso responder. City of Santa Ana Public Works arrived between 11-11:20am and cleaned the savagi in the street was avactor and street sweeper. The plumber had Minute Man Pumping clean up the sewage in the parking lot. OCSD staff remained onsite until 11:45am. H
7/2/02	1	Hamilton Pacific	50	750	0	0	15622 Brookhurst Westminster	Westminster			grease	grease on private property	
7/22/02	1	Trans Pacific Management Services - Private Property	50	50	150	0	17152 Pacific Coast Highway	Huntington Beach	17152 Pacific Coast Highway	Laundry Room Drain	Grease, Debris	Appears to be lack of maintenance - grease and debris was found blocking the line.	Cleanup was delayed because of lack of a representative from management company. Cleanup was halted until a board member approved the work.
7/25/02	1	Costa Mesa Sanitary District	25	25	1000	0	Marie Callender's:363 East 17th St, Costa Mesa, CA	Costa Mesa, CA	Private Lateral	Private Lateral Cleanout	Blockage: Grease ir private lateral	NĄ	Marie Callender's private lateral blocked with grease; Rescue Rooter opened a 4° cleanout to clear the line; When opened, sewage spilled out from the sidewalk cleanout onto the street and curb for approx 10 minutes while contractor cleared the lateral line Field crew blocked downstream strom drain to provide additional containment. See photos. District crew hydro-rodded the District Main line to break up any grease alisologid init of trom the lateral; Storm drain was powolecked to contain any sewage withh it and all sewage was contained. District vactored up street and curb spill, vactored ou the storm drain containment for interwater, rinsed the street with fresh water and vactored up the rinsewater. See photos.
8/22/02	1	PWA-City of Santa Ana	90	450	450	90	2502 W. Seventeenth St.	Santa Ana	Private property	Clean out	Grease combined with surgical gloves (dental office)	Grease combined with surgical gloves (dental office)	
9/16/02	1	CITY OF ANAHEIM	200	200	300	0	1511 N. Euclid Ave.	Anaheim	Clean out at back alley of 'Super Torta'	private clean out	grease; possible lint	grease and possible lint	
9/17/02	1	El Pollo Loco Restaurant, 1941 Harbor Bivd, Costa Mesa, CA 92626	0	0	0	0	1941 Harbor Blvd	Costa Mesa, CA	Grease blocked El Pollo Loco grease trap and cleanout.	El Pollo Loco grease trap and cleanout in sidewalk between facility and drive-thru.	Grease blocked EI Polio Loco grease trap and cleanout	Grease blocked El Pollo Loco grease traja and deanout, causing overflow across sidewalk, across drive thru, intr alley down Bernard St gutter and into Harbor Bivd storm drain.	Grease blocked EI Polio Loco grease trap and cleanout, causing overflow across sidewalk, across drive thru, into alley down Bernard St gutter and into Harbor Bhd sto drain. EI Polio Loco contractor cleared grease trap and facility inside lines, but overflow flushed as described. Most importants its the follow-up. Revisit to EI Polio Loco on 9-24 02 - Iuli cooperation from managers with documents/records review. Emphasized clean grease trap maintenance and proper flushing – Provided coxy of 'vater's Caulity Guidelines for Exterior Restaurant Cleaning Operations' (OC Storrwater Program) and "Restaurant Owner's Guide for Grease Control' (CMSD). Further Follow-up Action: District is redistributing both puidse with a 'Vanning Notice' attached to all District restaurants. Prost-activity photograph taken of site relating cleaned area, with only vehicular road grime in drive-thru, alley and streets. El Polio Loco contractor & District vactored flush & storm drain.
10/9/02	1	Hannam Market, private property	0	0	0	0	4875 La Palma Ave.	La Palma	Private lateral	Manhole	Grease blockage or private property	Grease blockage on private property	Private contractor sanitized and cleaned up

10/12/02	1	Harbor Breeze Apartments	5,400	100	600	0	4841 Heil	Huntington Beach	4841 Heil	Cleanout-Manhole	Grease	Grease had built up in the line, probably due to lack of maintenance	
10/17/02	1	Private: Twin Pines Apts.	5028	4800	8800	5028	2880 W. Ball Road	Anaheim	Blockage in lateral	private clean outs	Grease buildup	Grease buildup	Sewage was vacuumed up downstream in storm drain sump area in the City of Stanto Vaccuming continued until little or no flow was observed entering sump area.
10/17/02	1	Koo Koo Roo Restaurant, 212 E 17h St, Costa Mesa, CA 92627	120	120	170	0	17th St between Orange Avenue and Westminster	Costa Mesa, CA	Koo Koo Roo Restaurant lateral , biccked with grease and paper towels	Koo Koo Roo Restaurant lateral cleanout	Grease and paper towels blocked Koo Koo Roo Restauran lateral.	Grease and paper towels blocked Koo Koo Roo Restaurant lateral, causing SSO into E 17th St curb and gutter.	Main line running clear; Koo Koo Roo contracted plumber cleaned out private lateral; grease blockage cleared from lateral line into District Main Line; Crew contained SSO upon arrival, vactored SSO, flushed area with 50 gals fresh water and vactored up rine after. Koo Koo Roo manager showed documentation of lateral cleaning 3 months earlier; Field Crew advised Koo Koo Roo manager to clean out lateral more frequently- every 6 weeks - to prevent another occurrence. Field Crew ran Main Line to ensure unclogged greese did not block main line. Crew turther advised Koo Koo Roo manager to instal a greese tano. Staff is re-sending 2 brochures: CMSD "Restaurant Owner's Guide for Greese Control" and "Warning" and CC "Water Quality Guidelines for Exterior Restaurant Cleaning Operations." Also informed Koo Koo Roo employees of need to properly dispose of paper towels in the trash and not in the sewer system.
10/18/02	1	Private Property - Mr. Wilson	800	200	200	800	210 S. Newhope Street	Santa Ana	Private Lateral	Private lateral clean or	Grease: Build up of utgrease in private lateral.	Build up grease in private lateral.	
10/19/02	1	Private: Twin Pines Apts.	1776	1500	3000	1776	2880 W. Ball Road	Anaheim	Blockage in sewer lateral at appartment complex	private clean-out	Grease buildup	Grease buildup	Sewage was vacuumed up downstream in storm drain sump area in the City of Stanto Vaccuming continued until little or no flow was observed entering sump area.
10/25/02	1	Betty Chamberlin	375	10	160	0	317 21st	Huntington Beach	317 21st	Cleanout	Cleanout Cap was blocking flow	Grease had built up in the line, probably due to lack of maintenance	
11/1/02	1	Mark Montgomery	308	308	458	0	21372 Brookhurst	Huntington Beach	Southwest Corner of Property	Sewer Cleanout	Debris, Roots, Grease	Possible Lack of Maintenance, Debris and Grease	None
11/3/02	1	Archstone Huntington Beach	830	50	100	780	8925 Rockcreek	Huntington Beach	8925 Rockcreek	Manhole	Grease	Possible Lack of Maintenance- Grease	None
11/5/02	1	Yousef Ibrahim	551	100	600	451	7232 Edinger	Huntington Beach	7232 Edinger	Manhole	Grease	Chunks of Asphalt	None
11/6/02	1	Private-City owned facility	0	100	0	0	1 Newport Pier	Newport Beach	Cleanout	Cleanout under Lifeguard Headquarters was overflowing	Sand and grease	See Remarks	Cleanout under Lifeguard Headquarters was overflowing
11/6/02	1	Private Property - Sullivan Mgmt Group Inc.	150	650	800	150	751 S. Harbor Blvd	Santa Ana	20' S. of manhole where lateral connects to sewer system.	6" sewer clean out.	Grease build up caused by lack of routine maintenance program.	Grease build up caused by lac of routine maintenance program.	
11/6/02	1	Private Property	0	100	50	0	9191 Bolsa Ave Westminster	Westminster	grease interceptor	grease interceptor	grease	grease interceptor not properly serviced	
11/11/02	1	Private Lateral Tony Romas Rest.	800	700	1500	0	3642 Katella	Los Alamitos	private lateral	private lateral clean ou	ugrease	grease blockage	n/a
11/13/02	1	Private Lateral Tony Romas Rest.	500	500	1500	0	3642 Katella	Los Alamitos	private lateral	private lateral clean ou	ugrease	incomplete hydroflush	n/a
11/14/02	1	Private Party, Maguroya Japanese Restaurant located ir the Yorba Station shopping center.	100	100	200	0	Yorba Station Shopping Center 18242 Imperial Hwy	Yorba Linda	Grease interceptor outside and behind restaurant	plugged interceptor device	grease	cooking grease in unmaintaine grease interceptor.	This was a private property overflow. The local health services agency addressed the restaurant management.
11/15/02	1	Carl's Jr,private property	0	20	0	0	5012 La Palma Ave.	La Palma	Private lateral	Private lateral cleanou	Grease blockage or private property	Grease blockage on private property	Private contractor sanitized and cleaned up
11/15/02	1	Pacific West Corp.	150	5	24	146	101 Main Street	Huntington Beach	101 Main Street	Grease Interceptor	Grease	Possible Lack of Maintenance- Grease	None
11/23/02	1	Private Property	15	0	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
12/4/02	1	HB Elks Lodge	218	100	250	118	7711 Talbert Ave.	Huntington Beach	7711 Talbert Ave.	Manhole cover in Parking Lot	Grease	Possible Lack of Maintenance- Grease	None

			-										
12/11/02	1	Private Lateral Yucatan Grill Rest.	900	900	1500	0	12147 Seal Beach Blvd	Seal Beach	private lateral	private lateral clean ou	Igrease	grease blockage	n/a
12/31/02		El Toro Bravo Restaurant, 739 W 19th St. Costa Mesa, CA 92627	0	480	300	0	El Toro Bravo restaurant @ 739 West 19th St	Costa Mesa, CA	Grease/commeal plugged E Toro Bravo lateral line forcing SSO out of cleanout cover and into the parking li where it was contained, returned to sever system. Field Crew informed E1 Toro Bravo manager of SSO status - asked manager to clean cleanout.	located in the parking lot, percolated raw sewage out of pickhole 2 inches in height. Field crew remained in	percolated raw sewage out of pickhole 2 inches in baiabt. Eigld grow		Grease/commeal plugged EI Toro Bravo lateral line forcing SSO out of cleanout cover and into the parking lot. Field Crew informed EI Toro Bravo manager of SSO status - asked manager to clean cleanout. Approximately 480 gallons of SSO spilled out of cleanout into EI Toro Bravo parking Iot. Field Crew neuroler dnanger flut/lo contained SSO in parking lot; After Rescue Rooter unblocked lateral line, manager flushed parki lot with fresh water. SSO and fluta water were disposed of into the sever system. Field Crew remained on site to ensure raw sewage was contained, parking lot was flushed and both sewage and flushwater were disposed of in the sever system. Staft Called property owner, OCHCA, RWOCB, Office of Emergency Services, Costa Mesa Building Inspectros. EI Toro Bravo manger information of need to perform period lateral line maintenance; Staff provided copy of "Restaurant Owner's Quide For Grease Control, "Sewage Spills Ref Cuide' to manager. Digital photos were taken. Staff i working with City of Costa Mesa (CCM) Building representatives to clarify interpretation of CCM Ordinance 97-20 and BuildingNPDES reporting requirements.
1/7/03	1	Rubios Restaurant	50	50	750	0	16672 Beach Blvd. Suite# 101	Huntington Beach	16672 Beach Blvd. Suite# 101	Grease Trap	Lack of Maintenance	Lack of Maintenance/Grease trap had not been cleaned out for over a year.	None
1/8/03	1	Private Property	40	20	100	0	1101 Packers Circle	Tustin	Private lateral line	Manhole	Grease clog	N/A	ECM. Collections, and Communications staff will be sending a letter to the Home Owners Association to notify owner of problem and the need to implement preventative maintenance schedule to ensure no future SSOs.
1/12/03	1	Private Property - Royal Holida Mobil Park	0	0	0	0	215 S. Sullivan Street	Santa Ana	Private - unknown	Clean out	Grease blockage	Grease blockage	
1/16/03	1	Private Spill: Rodi Properties	0	175	275	1	12th Street	Seal Beach	Private property; parking lot behind restaurant	Cleanout	Grease	Restaurant grease interceptor had stoppage	n/a
1/16/03	1	Freeway Industrial Park	2080	450	1070	1630	7402 Edinger	Huntington Beach	7402 Edinger	Cleanout	Lack of Maintenance	Lack of Maintenance/Grease/Crew Reported that grease logs were coming out into main sewer line	None
1/20/03	1	Private	0	0	0	0	3955 Alton Pkwy.	Irvine	n/a	n/a	Grease	Grease	
1/26/03	1	Private	360	0	0	0	50 Eastshore	Irvine	n/a	n/a	Grease	Grease	
1/30/03	1	Private Spill	1000	0	0	0	3435 Newport Blvd.	Newport Beach	n/a	n/a	Grease, Paper products	See Remarks	(Pavillons Supermarket) Blockage of paper products, feminine hygiene products, grease. (Originally marked as unknown for surface water. Reported on OCHCA Beach Closure Report)
2/4/03	1	Private (KFC)	0	5	105	0	150 W Orangethorpe Ave	Fullerton	Private Lateral	Lateral Cleanouts and Grease Interceptor	Grease	Lateral was plugged upon arrival. Likely cause-grease, possibly toilet debris. KFC personnel rodded and cleared unknown blockage in lateral.	Upon arrival, City crew observed solidified grease in curb and gutter area and on private property at Kentucky Fried Chicken (KFC). KFC personnel on site informed City crew lateral was blocked. Crew continued inspection and observed grease trap full and lateral deanouts till but not overflowing at the time. Area was wet from recent washdown by KFC personnel preventing City crew from pinpointing overflow source. KFC plumbers arrived and cleared blockage in lateral. Service arrived to clean grease trap. City crew washed down, steam cleaned and vacuumed area. 5 gallons of grease were removed and transported to OCSD plant. Code enforcement to follow up.
2/9/03	1	Coral Cay HOA	55	5	25	55	16832 Coral Cay	Huntington Beach	16832 Coral Cay	Manhole	Grease	Grease/Lack of Maintenance	None
2/25/03	1	Private Property	3000	2000	0	0	1440 W. Lambert Rd.	La Habra	Line Blockage	Line Blockage	Grease	Grease line blockage	(Not listed in originally submitted OCHCA report. Listed in the OCHCA Beach Closure Report. Not indicated as private spill in Region 8 report)
2/27/03	1	Private Property	25	180	180	25	2097 E Orangethorpe Placenti	aPlacentia	private lateral line	clean out	Grease	Grease build up	Yorba Linda Water district Responded and cleaned up the spill also picked up the wash water. This spill was located on priviate property.
3/10/03	1	Private Business	0	10	60	0	150 S. Harbor Blvd.	Fullerton	Private grease trap manhole	Private grease trap manhole	Grease	Full grease trap	City crews Gonzalez, Hernandez and Rangel were called out to contain a private grease trap spill at Knowlwood restaurant. Grease and sewage spilled out of interceptor manhole onto surrounding sidewalk and parking lot to the rear of building. Grews contained spill with drit. Building owner, Code Enforcement. Police Dept. and Health Dept were notified. JC grease buyers was called to clean interceptor. City crews washed down, vacuumed and returned all sewage to sewer system.
3/12/03	1	Private - PCM Mgt. Co. View Point North Comm. Assoc.	750	300	350	750	7807 East Viewrim Drive	Anaheim	Near 7807 East Viewrim Drive	Private Manhole	Grease	The sewer line was obstructed by grease.	The property where the spill occurred is private property. The city had no responsibility for the spill and responded only to assist in the containment to prevent additional sewage from reaching our storm water catch basin system.

							0						
3/18/03	1	Daniel Moran, Investors Property Services	0	240	300	0	1212 S. Bristol Street, Santa Ana, CA	Santa Ana	Private Spill	Clean out	Grease/Private Spill There are several restaurants located in the shopping center that maybe dumping grease in the lateral.	There are several restaurants located in the shopping center that maybe dumping grease in the lateral.	This was a private spill handled by Orange County Health.
4/4/03	1	Valley View Center, private property	540	210	275	0	7811 Valley View St.	La Palma	Private lateral	Private lateral cleanou	Grease	Grease blockage on private property as well as debris	Private contractor sanitized and cleaned up
4/7/03	1	Private Lateral Sharam Afshani	500	500	1500	0	Grease Interceptor 4348 Katella	Los Alamitos	private lateral	private grease interceptor	grease	grease blockage	Grease interceptor was at a low point in the system and was not the cause.
4/20/03	1	Private Property	3	0	0	3	1091 OLD IRVINE BLVD.	Tustin	Private lateral	Private Clean out	Blockage Grease clog	N/A	NA
4/21/03	1	Private Property	0	0	0	0	1400 Magnolia St. Westminste (14000 Magnolia - no 1400)	Westminster	cleanout	cleanout	grease	grease	This spill occurred on private property. The private security guard who called the spill into the Westminister PD reported the spill had been occurring for at least 24 to 48 hours, but the property owners had instructed him not to report it to anyone. He eventually reported to spill, but because it had been occurring for an undetermined amount of time, it was impossible for our crew to accurately assess how much sewage was spilled and how much secared into the storm drain. Our field crew immediately called the OCHCA, and Jeff Warren responded.
4/29/03	1	Private Property	200	200	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n⁄a
5/1/03	1	Private	0	25	0	0	2751 Coast Hwy.	Newport Beach	Grease Trap	Grease Trap	Unknown	See Remarks	Grease trap was overflowing. 5 gallons per minute.
5/1/03	1	Elis Nourafchan	900	900	1100	0	6905 Warner Ave.	Huntington Beach	6905 Warner Ave.	Cleanout	Grease and debris blockage	Grease buildup from a number of restaurants in the complex.	
5/7/03	1	Private Property	0	0	0	0	BLACK ANGUS RESTAURANT, BROOKHURST ST. & TALBERT IN FOUNTAIN VALLEY.	Fountain Valley	Lateral	Cleanout	Blockage Grease clog	N/A	N/A
5/26/03	1	Huntington by the Sea MHP	960	40	40	920	21851 Newland Ave.	Huntington Beach	21851 Newland # 2-8	At hookup for the Coaches	Grease and debris blockage	Grease and debris from a lack of maintenance.	
6/7/03	1	West Bay Café	40	40	40	0	6600 Admiralty Drive	Huntington Beach	6600 Admiralty Drive	Cleanout	Grease	Grease from Café caused blockage.	None
6/11/03	1	Kikuya Japanese Rest.	90	50	150	40	8052 Adams	Huntington Beach	Front of Restaurant on sidewalk	Manhole	Grease	Grease causes blockage in line Lack of Maintenance	None
6/11/03	1	Private Property	35	0	75	95	11407 ARROYO AVE	Unincorporated County of Orange	8-inch private property lateral	manhole	Blockage Grease clog	N/A	The field report states that it did enter a storm drain. However, after talking to Victor Hermelin, he stated that it actually did not enter a storm drain. The spill had been contained in the gutter, which dried up, so it was not recovered via vactor truck. Shoud remove OCSD logo's on covers from private property manholes.
6/13/03	1	Condominium Complex	50	325	0	0	Kramer & Stonehedge Lane Westminster	Westminster		manhole	grease	grease in sewer line	Spill reported by Westminster PD. Spill on private property
6/30/03	1	Trailer Park run by Del Almo	0	80	0	0	9702 Bolsa Ave. Westminster	Westminster		manhole	grease	grease in sewer line on private property	Spill on private property
6/30/03	1	Private Property	150	150	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
7/1/03	1	Private Property Owner: 278 N. Wilshire Street	590	10	20	590	278 N. Wilshire Street	Anaheim	Near 278 N. Wilshire Street	Private Manhole	Swale in sewer lateral		Property Management was very difficult to get a hold of, however, the delay in their response will result in a large bill being issued to them for cost recovery, in conjunction with the notice of violation. Cory of this report was provided to OC Health Care on 7/2/03 for follow-up. Previously issued as 278 N. Pearl, however correct address is actually 278 N. Wilshire.)

7/14/03	1	Private Property Owners (4) of shared lateral.	20	40	340	20	1320 S. State College Boulevard	Anaheim	Near 1320 S. State College Boulevard	Private Cleanout	Grease	Grease buildup obstructing sewer flow.	Unusual situation as there are four (4) properties served by a single lateral. Based on observations it was clear the cause of the blockage was excessive grease. The only grease bearing operation is the Restaurant at 1258 S. State College Boulevard. However, because all four properties discharge to this line, the responsibility for the spill as well as the routine maintenance must be shared.
7/23/03	1	Private Property: Mandas Konstantinos - 910 S. Euclid Street	50	10	210	50	910 S. Euclid Street	Anaheim	Near 910 S. Euclid Street	Private Cleanout	Grease	Grease buildup obstructing sewer flow.	City was notified of al leak of some kind at 2:00 am on 7/23/03, however upon arriving on scene there was no spill. A follow up inspection later that morning revealed a slow leak from the cleanout.
7/25/03	1	Little Saigon Village	0	0	0	0	10161 Bolsa Ave. Westminster	Westminster		cleanout	grease	grease in sewer line on private property	Spill on private property
8/7/03	1	The Saywitz Co. 4740 Von Karman, Suite 100, Newport Beach, Ca 92660	150	150	250	0	7712 Cypress Ave., Huntingtor Beach Ca.	Huntington Beach	Property owners lateral at 7712 Cypress Ave., Huntington Beach Ca.	Clean out cover	Grease and debris.	A buildup of grease and debris in the lateral, probaly caused by insufficent maintenance.	
8/13/03	1	Richard Lee PO Box 2142, Huntington Beach, Ca 92647	120	120	220	0	7872 Stark Ave., Huntington Beach Ca.	Huntington Beach	Property owners lateral at 7872 Stark Ave., Huntington Beach Ca.	Cleanout cover	Grease	A buildup of grease in the lateral, probably caused by insufficent maintenance.	
8/20/03	1	Private Property	0	150	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
8/24/03	1	Hannam Market, private property	0	50	55	0	4875 La Palma Ave.	La Palma	Private lateral	Manhole	Grease	Grease blockage on private property	Private contractor sanitized and cleaned up
10/1/03	1	George Gonzalez (714) 957- 2529 - Prívate	0	540	1800	0	1128 S. Bristol St.	Santa Ana	Private lateral	6° clean out	6" line that connects to a 4" lateral at the p/l. This lateral serves a market and a laundromat, this	Cause of spill was a combination of large amounts of greases and the lateral is a 6° line that connects to a 4° latera at the p/l. This lateral serves a market and laundromat, this lateral should be a 6° all the wa to the sewer main.	
10/3/03	1	George Gonzalez (714) 957- 2529 - Private	0	180	680	0	1128 S. Bristol St.	Santa Ana	Private lateral	Clean out	Grease - Cause of overflow was the same as the spill on 10/01/03, large amounts of grease.	Cause of overflow was the same as the spill on 10/01/03, large amounts of grease.	
10/7/03	1	George Gonzalez (714) 957- 2529 - Private	0	120	420	0	1128 S. Bristol St.	Santa Ana	Private lateral	Clean out	Grease - Large amounts of grease from market.	Large amounts of grease in market.	
10/28/03	1	Private Property	0	0	0	0	JAMBOREE RD.	Newport Beach	8-inch clean out on private property	Clean out	Grease, other and debris	N/A	N/A
11/18/03	1	540 North Euclid	20	19	50	0	540 North Euclid Avenue	Anaheim	540 North Euclid	Private sewer manhole	Grease	Grease obstructed the flow of the sanitary sewer line causing it to overflow	
11/29/03	1	777 Convention Way	50	0	50	0	Hotel Way East of 777 Convention Way	Anaheim	777 Convention Way	Private sewer manhole	Grease	Grease released by Anaheim Hilton obstructed the flow of the sanitary sewer line causing the overflow	
12/9/03	1	Bill Jarjour, owner of Hilltop Liquor	1500	25	45	1475	815 Indianapolis Ave.	Huntington Beach	Private homeowners lateral at 815 Indianapolis Ave.	Private clean out	Grease	Grease clogged homeowners lateral line	Difference of opinion by homeowner and person notifying city of spill as to length spill flowed. Location was next to bus stop see picture.
12/26/03	1	Hugh Roberts	200	200	300	0	705 Jay Circle	Huntington Beach	Private homeowners lateral at 705 Jay Cir.	Private clean out	Grease	Grease clogged homeowners lateral line	

12/27/03	1	Private Property	50	100	250	50	17231 E. 17th Street	Tustin	8" Sewer Lateral	Manhole	Blockage, Grease clog	N/A	NA
12/29/03	1	Richard LI, owner of the apartments	2312	200	300	2112	7872 Stark Street.	Huntington Beach	Private homeowners lateral at 7872 Stark Street	Private clean out	Grease	Grease clogged apartment complex lateral line	Agnes Do from the Orange County Health Care Agency was on scene and wrote a report.
1/4/04	1	Private Property Owner	600	0	0	0	1415 W. Ball Rd.	Anaheim	1415 W. Ball Rd.	Private Manhole	Grease	Grease obstructed the flow of the Sanitary Sewer Line causing it to overflow	The Anaheim Fire Department responded initially. Then Streets and Sanitation was called out and responded. Spill duration was estimated at 1 hour as the property many found the sewer manhole flowing out heavily. Fire said that the spill was 3 inches above the manhole when they arrived. When Streets and Sanitation arrived, the spill had stopped as the water supply had been shut off.
1/12/04	1	La Palma Hospital, private property	0	300	500	0	7901 Walker Street	La Palma	Private lateral	Private lateral cleanouts	Grease blockage on private property as well as debris	Grease blockage on private property as well as debris	Private contractor sanitized and cleaned up
1/13/04	1	The Lodge, a Food Service Establishment (FSE) at The Camp, 2337 Bristol St, Costa Mesa, CA	100	100	200	100	The Lodge is one of 3 Food Service Establishments FSEs) at The Camp address; Intercoptor for The Lodge was blocked, forcing the SSO out of a vent hole at 2937 Bristol St.	Costa Mesa, CA	The Lodge is one of 3 Food Service Establishments FSEs) at The Camp address, Interceptor for The Lodge was blocked, forting the SSO at of a venthole <i>z</i> 2337 Bristol St.	Establishments FSEs) at The Camp address; Interceptor for The Lodge was blocked,	District Field Crew verified FSE grease blocked The Lodge interceptor.	District Field Crew verified FSE grease blocked The Lodge interceptor.	CCSD Informed CMSD of the SSO at the Food Service Establishment (FSE) known as The Lodge at 2937 Bristol St. District Crew arrived; contained the SSO, discussed corrective action with The Lodge employees, called the City of Costa Mesa National Pollutant Discharge Elimination System (NPDES) manager to the site and ensured The Lodge arranged for a plumber to elean out the Grease Interceptor. The Grease Interceptor cover appeared to be rusted closed and had not been opened for a long tir The site management company (Remm Group) directed the tenard. (The Lodge) to implement a quarterly interceptor cleaning program. CMSD added the site to the District FSE contractor follow-up visits and compliance. The site appears to have experienced overflows in the past as evidenced by the drive markings and The Lodge manager had not addressed the apparent overflows. The District Ploy is to backchar the responsible party for private SSOs to which the District must provide resources to control. Photos were taken and are attached.
1/17/04	1	Private Property Owner	560	1600	500	0	1630 W. Katella Ave.	Anaheim	1630 W. Katella Ave.	Private Cleanout	Grease	Grease obstructed the flow of the Sanitary Sewer Line causing it to overflow	Second spill in 15 months
2/12/04	1	Norms Restaurant	400	400	900	0	16572 Beach Blvd.	Huntington Beach	Norms Restaurant 16572 Beach Blvd.	Cleanout drain.	Grease and food debris.	Grease and food debris from Norms clogged the sewer lateral causing sewage to com- out of their cleanout pipe.	Due to a construction project adjacent to the catch basin, sandbags existed at the catch basin prior to this SSO.
2/24/04	1	Private Property Owner	50	100	500	0	2610 E Katella Ave.	Anaheim	2610 E. Katella Ave.	Private cleanout and private clarifier	Grease	Grease formation caused the sanitary sewer line to overflow	The staff at Orange County offices (located next door to J.T. Schmidt's) noticed the flo of water at 10:30 and notified the restaurant manager. Private plumber arrived by 11:0 AM to clear blockage and City of Anaheim was notified at 11:15 AM. Anaheim In
2/25/04	1	Rossmoor/Los Alamitos Area Sewer Dist.	500	490	1500	0	3642 Katella	Los Alamitos	private lateral	private lateral clean ou	grease	grease blockage	n/a
3/22/04	1	Private Spill	300	200	0	0	4525 W. Coast Hwy	Newport Beach	n/a	n/a	Grease spill at ChronicTaco	See Remarks	Containment setup at storm drain. Vacuum truck clean up spill, grease and stop overflow.
4/7/04	1	Private Property	100	40	0	100	164 Yorba Linda	Placentia	Priavate property lateral	lateral line	grease	grease	Spill was caused by grease from business located on Kraemer / Yorba Linda in a priavate parking lot and ran through the parking lot ending up on Bradford Ave.
4/12/04	1	Foodland Market	100	50	0	0	910 S. Eudid St.	Anaheim	910 S. Euclid St.	Private Cleanout	Grease	Grease caused obstruction.	Meetings have been held with representatives from Foodland.
5/22/04	1	C & C Property Management Group	5	50	50	0	411 N. Park Vista St.	Anaheim	411 N. Park Vista St.	Private cleanout in alley	Grease	Grease caused private lateral t become blocked and to back up.	
5/29/04	1	Private Property	0	0	0	0	17502 17TH STREET	Tustin	Sewer Line	Manhole	Blockage	Grease clog	NA
6/16/04	1	Sushi Ya	100	75	100	175	50 Centerpointe Dr.	La Palma	Private lateral	Private lateral cleanou	Grease	Grease interceptor failure.	Private contractor sanitized and cleaned up
6/21/04	1	1331 E. Katella Ave., Anaheim 92805 (714) 978-8088	182	250	200	0	1221 E. Katella Ave.	Anaheim	1221 E. Katella Ave.	Private clean out	Grease	Grease obstructed the flow of the Sanitary Sewer Lateral causing it to overflow	

1 Mode sequence and service 0<		
- $ -$		
42504 1 Register HA Greegener 0 20 90 0 64.W. Provenite Dr. Avalema 64.W. Provenite Dr. Provise Genoral Genoral Sensitivity Sever Lease and avalet Genoral 62504 1 Note Mayr. Company, 777 105 200 0 300 530 525 f. Flower Steler - Provise Set A Set A Genoral Genoral BecaugePrivise genoral of Logical Avalet Genoral		
62804 1 1 0deb Myr. Corregar, YA W Odd 19 20 20 30 30 305 S25 S. Plawer Stread - Private Statut Chan out on lateral Chan out merces Prepare transmission		
Octan 1 Private Property 30 00 00 30 130 Private Private Private period period <th per<="" td=""><td></td></th>	<td></td>	
7/1104 1 Management Inc. (74) 491- 3024 3024 0 50 3024 Behind 6101 Morningisde Drive Huntargon Beach olgit in Brithmanoc. Manhole olgit in Brithmanoc. Grease Blockage olgit in Brithmanoc. Offention Blockage olgit in Brithmanoc. Offentin Blockage olgit in	n a priavate parkii /d.	
1 Private Spill 600 0 0 0 100 Dove St. Newport Beach Private Ceanout Private Ceano	ewer lines were	
Image: Note of the second o	nout at driveway.	
Image: Note of the state o		
9/5/04 1 Broadmody multington Hundrog 50 0 100 100 6905 Warner Ave. Huntington Beach Private sever natural at 325 Cleanout Stream of the set and death significant Stream of the set and the		
9/2304 1 Calora, Covina, CA 91724 (Holura 720 670 1220 50 1317 S. Standard Santa Ana Praivate lateral 4° clean out Paper/GreasePrivagresse geing dumped in sew of e Poperty On 9/23/04 @ 11:00 am.	pill to wrong Dep ge flow was stopp	
Private lateral at Pacific City Property, Pacific City Protection and at the SD; vactored and disposed of the com	ncy regarding spill	
Pacific City Property, 10 unit 9/27/04 1 apartment complex, City of 500 500 500 500 584 W Hamilton Street 564 W Hamilton Street Costa Mesa, CA 9/27/04 1 apartment complex, Costa Mesa Costa Mesa	rew dammed SSC ained SSO and ri gallons of total down 600 ft path fic City Property 1 arrier) service to District upon	
10/7/04 1 Private Property 10 0 0 0 7621 TRASK AV Westminster Notified	spill at 7621Trask	
10/804 1 Wendy's Restaurant 10 20 0 0 2011 East La Palma Avenue Anaheim 2011 East La Palma Avenue Private manhole Grease Grease clogged sewer line Any washdown was performed by Restaurant staff under supervision	on of OCHCA.	
10/14/04 1 Private Property 50 25 0 0 n/a Orange n/a n/a Grease n/a n/a		
10/21/04 1 New Mark Merill Companies - Ralph Woekey 2180 E E Lincoln Ave., Santa Ana 92806 690 690 2660 690 2307 S. Bristol St. Santa Ana Private lateral Clean out Grease There are several restaurants located in the shopping center that maybe discharging greases into the severe system.		
10/26/04 1 Private Property 40 25 0 0 n/a Orange n/a n/a Grease n/a n/a		

11/1/04	1	Private party lateral blocked with grease;	0	50	100	0	200 East 17th St;	Costa Mesa, CA	SSO spilled from private lateral cleanout approximately 10 feet from the curb;	SSO spilled from private lateral cleanou approximately 10 feet from the curb; Grease interceptor appeared t not have been maintained as evidenced from rusted bolts and cover, leading to grease blockage;	t d Grease blocked the interceptor and the private lateral;	Grease blocked the private lateral cleanout at 200 E 17th St; Fully contained;	SSO spilled from private lateral cleanout approximately 10 feet from the curb; Grease interceptor appeared to not have been maintained as evidenced from rusted bolts and cover, leading to grease blockage; District Crew blocked Storm Drain (SD) with rubber mats to fully contain SSO. District Crew estimated SSO via visual pool estimated to be 50 gallons = 3 galmin x 60 minutes; Private owner obtained services of plumber and cleaned out the lateral line - need to follow up to ensure interceptor is cleaned; placed site on maintenance program; Photographs were not taken;
11/12/04	1	Anaheim Hilton	880	20	400	0	777 Convention Way	Anaheim	777 Convention Way	Private Manhole and Cleanout	Grease	Grease blocked sewer line, causing sewage to overflow.	This spill was observed on Wednesday flowing only for a couple hours in the morning which is what the flow estimate is based on. There is clear evidence that despite the large flow carried by the 15° line which was obstructed, the actual amount of sewage spilled was not large compared with the flow. This is because there is an overflow by- pass of the siphons where the obstruction occurred, which allowed a limited flow to continue in the sever. Also, it appears that the spill only occurred at peak flow (morning primarily) and was not substantial based on location and minimal solids deposition.
11/13/04	1	Private Property	25	225	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
11/24/04	1	FV	120	120	0	0	16175 Harbor Blvd	Fountain Valley			FOG accumulation	grease - no grease interceptor	NA
12/16/04	1	Royale Health Care Center	300	1600	1600	300	1027 W. Central Ave.	Santa Ana	Private sewer line	Pick hole of manhole	Grease	Large amounts of grease deposits from poor maintenance program	State ID #04-6597
12/21/04	1	Private Property	100	150	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
1/2/05	1	7232 Edinger shopping center	70	980	1,480	70	7232 Edinger	Huntington Beach	City's 8 inch sewer line	Manhole cover pick holes	Grease	Grease from a private shopping center lateral flowed into City's main line.	
1/2/05	1	George Galanoues owner of apartment complex	2,100	900	1,400	2,100	2208 Delaware St.	Huntington Beach	Private sewer lateral	Private 4 inch sewer clean out pipe.	Grease	Grease buildup in private sewe lateral.	There were several different estimates from residents in the complex stating when the sewage started flowing above ground.
1/4/05	1	Lake Summit Association	60	40	500	0	920 S. Ridgecrest Circle	Anaheim	Near 920 S. Ridgecrest Circle	Private Manhole	Grease	Grease blocked pipeline, causing sewage to overflow.	Spill appeared to be flowing at a far greater rate than 50 gph. However, the sewer line that was obstructed only serves 20 homes and a typical flow at 10 am would likely be approximately 50 gph. Therefore, the additional flow is suspected to be from Inflow and Infiltration. Sewage flowing from the manhole was very clear in appearance, further supporting this suspicion.
1/13/05	1	Gene Opfic homeowner of 8472 Amett Dr.	0	15	15	0	8472 Arnett Dr.	Huntington Beach	Sewer lateral	Sewer clean out pipe	Grease	Grease buildup in private sewe lateral. Renter at property removed clean out cap becaus owner would not repair.	Renter at property called City, because owner would not fix the problem. City contacted the property owner that called a plumber to repair.
1/14/05	1	Pavilions Von's	0	700	0	0	Von's Pavilon	Newport Beach	n/a	n/a	Grease logs & grease in pipe	See Remarks	Vactor used to vacuum up sewage flow. Flow did not enter drain.
1/14/05	1	Private Property	50	50	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
1/17/05	1	Private	123	0	0	0	14400 Culver Dr.	Irvine	Grease Trap	Grease Trap	Grease	Grease Trap overflow	
1/19/05	1	Property Owner	60	100	200	60	3041 S. Bristol	Santa Ana	Private lateral	4" clean out	Paper/Grease/Priva e Property	Build up of paper and grease	None
1/19/05	1	Property Owner	0	0	0	0	201 E. 4th Street	Santa Ana	Private lateral	4" clean out	Grease	Plumber said there was grease in the lateral	None
1/27/05	1	Private Property	20	0	0	0	1722 MITCHELL	Tustin	4" Clean out	Clean out	Blockage	Grease clog	NA
2/8/05	1	1310 W. Pearl St.	0	60	300	0	1310 W. Pearl St.	Anaheim	1310 W. Pearl St.	Private Cleanouts	Grease & Paper Towels	Grease and paper towels blocked pipeline, causing sewage to overflow.	

2/20/05	1	El Pollo Loco	20	20	20	0	969 S. Euclid St.	Anaheim	969 S. Euclid St.	Private cleanout and Private Manhole	Grease or possibly other.	Grease blocked pipeline, causing sewage to overflow.	Upon arrival, spoke with the Manager of Little Caesar's Pizza (Maria) that initially reported the spill at neighboring business, El Pollo Loco. City staff then went to check city's main line and found it to be flowing well. I contacted the assistant manager at El Pollo Loco and informed him of the servage that was coming out of a clean-out on his property and running onto the sidewalk. He immediately contacted his plumber and the plumber was on site at 3:40 PM and had the blockage opened at 3:55 PM. City staff contained and cleaned up spill.
2/20/05	1	Private Property	0	0	0	0	1360 W. LAMBERT RD	La Habra	n/a	n/a	Grease	n/a	
2/20/05	1	Private	50	0	0	0	905 IDAHO ST.	LA HABRA	N/A	N/A	GREASE	MANHOLE TO CURB AND GUTTER TO STORM DRAIN.	N/A
2/23/05	1	Carl's Jr	40	40	60	0	5012 La Palma Ave.	La Palma	Private Lateral	Manhole	Grease	Grease blockage from private property and sedement	Private contractor sanitized and cleaned up
2/26/05	1	FV	50	500	600	50	Euclid & Edinger	Fountain Valley	Between building & street cleanouts		grease build up	grease	Inspectd OCSD trunk line, they were flowing free and clear. Assisted City of Fountain Valley wivactor. Health Dept responded at 7:00pm and shut down the restaurant that was contributing to the spill.
2/28/05	1	Richard Li property owner	200	175	375	25	7872 Stark St.	Huntington Beach	Private sewer lateral	Private sewer lateral clean out at 7873 Star St.	Grease	Buildup of grease in private sewer lateral.	Only one tenant home doing laundry at the time of the spill.
3/1/05	1	Private	0	0	0	0	453 SUMMERFIELD CIRCLE	ANAHEIM	N/A	N/A	GREASE	STORM DRAIN -> EAST GARDEN GROVE WINTERSBERG CHANNEL -> LOWER BOLSA	N/A
3/16/05	1	Denny's Restaurant	0	60	160	0	105 East 17th St	Costa Mesa, CA	Denny's Restaurant grease interceptor not maintained/cleaned; - District Crew Fully Contained SSO in parking lot and vactored;	Denny's Restaurant grease interceptor not maintained/cleaned District Crew Fully contained SSO in parking lot and vactored;	Denny's Restaurant grease interceptor not maintained/cleaned District Crew Fully Contained SSU Contained SSU contained SSU parking lot and vactored;	Denny's Restaurant grease interceptor not maintained/cleaned; - District Crew Fully Contained SSO in parking lot and vactored;	OC Environmental representative Mike (714-433-6120) called SSO in to CMSD; OC Environmental shut down Denny's Restaurant due to the SSO from the grease interceptor; Estimated 60 gallons SSO from single pickhole in a deanout; Crew contained SSO; SSO did not enter the storm drain (SD); District crew vactored approximately 60 gal of SSO and 100 gals of rinse water; Crew disposed of vactored SSO and rinsewater into District sanitary sewer; District Orew estimated SSO to be 60 gals – 5 gal/min x 120 mixutes; Denny's Restaurant grease interceptor not maintained/cleaned; - District Crew Fully Contained SSO in parking lot and vactored; District crew arrived on site nearring Denny's engloyees obtained a plumber to clean out the grease interceptor; District back-charged Denny's Restaurant for the services provided; District crew ensured Denny's Restaurant tor the services provided; District crew ensured Denny's Restaurant for the services provided; District crew ensured Denny's Restaurant for the services provided; District crew ensured Denny's Restaurant for the services provided; District crew ensured Dathiments (FSE) inspections, permitting and grease interceptor maintenance; Photos were taken and are attached;
4/1/05	1	Private Property	200	250	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
4/7/05	1	FV	45	45	0	0	17099 Brookhurst Street	Fountain Valley	private property sewer later	a	grease blockage	grease blockage private sewerlateral	NA
4/9/05	1	FV	150	100	0	0	18030 Brookhurst	Fountain Valley	unknown		grease blockage	sewage line back up at lowest point	Grease interceptor maintenance needed.
4/12/05	1	Private	200	100	50	0	1770 Harbor Blvd. Anaheim	Anaheim	1770 Harbor Blvd. Anaheim	Private clean out	Grease / Break in sewer line	Grease caused blockage. Pipeline broken during cleanou process	Video showed evidence of a break. Repairs are required by July 2
4/19/05	1	Business Properties Management Company	300	300	0	0	10132 Adams Ave.	Humtiogton Beach	Private business complex sewer line.	Private property manhole	Grease	Sewer line had grease and debris blocking the line.	This shopping center has at least five FSE's. They are on a sewer cleaning maintenance program, but will be making this program more frequent.
4/23/05	1	Private Property	0	1300	1460	0	1171 PACKERS CIR	Tustin	8"	Manhole	Blockage	Grease clog	Private Property
5/4/05	1	Private	50	0	0	0	1773 W. Lincoln Ave.	Anaheim	1773 W. Lincoln Ave. Anaheim	Private clean out	Grease	Grease caused obstruction.	The spill had occurred intermittentity over the 24 hours prior to City Staff arrival. A clear link, which Bakery management acknowledged, was made between the excessive amounts grease in the manhole and the obstruction which caused the spill.
5/7/05	1	Private	0	0	0	0	4941 LA PALMA AVENUE	LA PALMA	N/A	N/A	GREASE	GUTTER TO STORM DRAIN	NA
5/7/05	1	Hannam Matket	10	100	370	0	4800 La Palma Ave.	La Palma	Private Lateral	Manhole	Grease	Grease blockage from private property	Private contractor sanitized and cleaned up
5/15/05	1	FV	30	30	0	0	9037 Garfield	Fountain Valley	private property sewer later	21	grease build up	grease blockage private sewer lateral	NA

5/24/05	1	Private	20	0	0	0	Jeffrey/Walnut	Irvine	Grease interceptor	Grease interceptor	Grease	Grease interceptor overflow- Chinese Restaurant	
5/31/05	1	Private	100	0	0	0	17605 Harvard	Irvine	Grease interceptor	Grease interceptor	Grease	Grease interceptor overflow- Ralphs	
5/31/05	1	Private Property	100	250	0	0	1040 Katella	Orange	n/a	Grse/Brkn Equip	Grse/Brkn Equip	n/a	n/a
6/1/05	1	Pacific West Management Corp.	300	300	500	0	5971 Warner Ave.	Huntington Beach	Private sewer line	Private system clean out.	Grease blockage	Grease blockage from restaurants in business complex.	A citizen reported sewage spilling from this same clean out earlier in the day, but we could not see any evidence of this. If the spill did occur earlier in the day than an unknown amount of sewage could have made it into the E Garden Grove Wintersburg C
6/6/05	1	Private	0	40	200	200	175 S. Harbor Blvd.	Anaheim	175 S. Harbor Blvd.	Private clean out	Grease	Grease caused obstruction.	N/A
6/6/05	1	FV	15	15	0	0	11707 Edinger Ave	Fountain Valley	just past interceptor at latera		grease build up	lack of interceptor maintenance	a NA
6/20/05	1	Vons Market	50	25	0	0	1000 Bayside Dr.	Newport Beach	n/a	n/a	Grease	See Remarks	Water Crew built a berm to contain the overflow to and called for a vactor to clean up t spill. Vactor remained onsite until the blockage was clearned.
6/20/05	1	Private Property	300	100	300	200	13102 NEWPORT BLVD	Tustin	8" Private Sewer	Private Manhole	Grease	Blockage	Sherrell Brown called divsion 420; Jeff Peterson is sending crew - Don Cleveland and Duane Smith to respond. Dindo Carrillo notified right away and called the Health Department. Mr. Fennessy of the Health Dept is responding.
6/21/05	1	Private	20	0	0	0	17 E. Yale Loop	Irvine	Cleanout	Cleanout	Grease	Private clean-out grease	
6/22/05	1	Private Property	676	636	886	40	13102 NEWPORT BLVD	Tustin	8" Private Sewer	Private Manhole	Grease	Blockage	City of Tustin on site called in spill. Sent OCSD crew with vactor truck to assist. Truck vactored up a total of 500 galtons, including 250 galtons of wash water. Spill was approx. 250 galtons. All was cleaned up at 1pm. Private plumber was called & Health Dept. on site as well. Approx. 40 galtons was not recovered from storm drain. Elaine Yan from HCA visited spill site.
6/28/05	1	Private	360	350	200	200	1151 N. Euclid St	Anaheim	1151 N. Euclid St	Private clean out	Grease	Grease caused obstruction.	N/A
6/30/05	1	FV	70	70	0	0	17075 Bushard	Fountain Valley	private property sewer later	al	grease build up	private lateral	NA
7/1/05	1	Private	0	0	0	0	2735 W. COAST HWY.	NEWPORT BEACH	N/A	N/A	GREASE	N/A	N/A
7/7/05	1	Private	2	200	500	2	627 North Euclid Street	Anaheim	627 North Euclid Street	Private clean out	Grease	Grease caused obstruction	N/A
7/17/05	1	Private Property	0	0	0	0	1800 W. WHITTIER BL.	La Habra	n/a	Grease Interceptor	Grease	n/a	
7/19/05	1	Pacific Comm.	450	2800	0	0	1000 Dove St.	Newport Beach	Private Cleanout	Private Cleanout	Grease & Paper Products	See Remarks	Burmed the gutter before the storm drain then set up the vactor before the burm. Notified the owne to call a plumber because it is a private clean out.
7/26/05	1	America	0	50	0	0	3601 Jamboree Rd	Newport Beach	Grease interceptor	Grease interceptor	Grease, near the grease interceptor.	See Remarks	Fire Dept built a berm at the nearest catchbasin, Gen. Serv. StomDrain crew responded with a vactor to vacuum contained material, code enforcement took pictures & cited the Property Mgmt. Co. America West Properties, Cl#12005-0734.
7/27/05	1	Private	0	900	600	0	2108 E. Lincoln Ave.	Anaheim	2108 E. Lincoln Ave.	Private clean out	Grease	Grease caused obstruction	Mark Williams from County Environmental Health Services arrived on site at 12:25 PM to investigate and assist. Spill did not reach underground storm drain system because sandbags and filter fabric were already blocking catch basin in street, since constructin is underway on the Lincoln Ave2. College BHA, whering project. Additionally the obstruction occurred in the middle of the private onsite sever collection system, therefore, the focus of the remedial actions will be on those businesses upstream of the obstruction.
7/29/05	1	Costa Mesa Sanitary District	0	5	55	0	584 Hamilton St	Costa Mesa, CA	Grease blocked private lateral line in a multifamily residential development forcing SSO out of private property cleanout;	Grease blocked privat lateral line in a multifamily residential development forcing SSO out of private property cleanout;	Grease blocked private laterall ine ir a multifamit residential development forcin SSO out of private property cleanout;	line in a multifamily residential	SSO trickled from private lateral cleanoul onto private property and to the street and nearby storm drain (SD) which acted as a containment vessel; Crew blocked SD and vactored SSO while private plumber (Coast General Plumbing) was en route to the site Crew vactored sewage and rines water from site (carter, curb and SD) and disposed it in the District sanitary sewer; District Crew and Staff estimated SSO volume pooled on private property to be 45 galoties and 5 galotis stricked in in the street, curb and SD District informed Pacific City Properties (management company) of situation, recommended increased lateral cleaning frequency from quartery to b-in-mothly and backcharged management company (Pacific City Properties) for District services; Photographs were not taker;

8/13/05	1	Sabatino's	0	10	0	0	251 Shipyard Way	Newport Beach	Holding tank	Holding tank	Grease	See Remarks	Used vactor to sack out a $4^{\prime}x4^{\prime}x4^{\prime}$ deep holding tank that was full and keeping the sewage from the bag.
8/16/05	1	Private Property	0	63	0	0	274 N Glassell	Orange	n/a	BckFlw Mlfnct/Grs	BckFlw Mlfnct/Grs	n/a	n/a
8/16/05	1	Private	0	0	0	0	6885 WARNER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE	STORM DRAIN WITH DIVERSION.	N/A
8/17/05	1	Private Property	0	0	0	0	n/a	Orange	n/a	n/a	Grease/ Vandalism	n/a	n/a
9/23/05	1	FV	48	28	0	0	11045 Warner Ave	Fountain Valley	private property sewer later	al	grease build up	private lateral, multilpe restaurants	NA
9/24/05	1	Private	2160	1200	200	0	1199 N. Euclid Street	Anaheim	1199 N. Euclid Street	N/A	Grease	Grease caused spill	OCHCA assisted onscene and washdown was performed by a private party.
10/3/05	1	Private	970	100	300	0	2138 W. Brownwood Ave.	Anaheim	2138 W. Brownwood Avenue	N/A	Grease/Break	Grease and/or Break caused the obstruction	This was an unusual spill due to the fact that we never were able to contact the owner by phone (or by any other method). HCA investigated contact information and City Con Enforcement as well as Utilities Billing were unable to obtain a good phone number fo the owner. The residents of both units also did not have a phone number.
10/16/05	1	Private Property	0	300	400	0	10250 BEACH BLVD. Fair Crest Apartments	Stanton	NA	Manhole	Blockage	Grease Clog	None
10/24/05	1	Private Property	25	15	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
11/6/05	1	Private	0	80	0	0	1530 PLACENTIA	NEWPORT BEACH	N/A	N/A	GREASE	CONTAINED ON SITE	N/A
11/28/05	1	Private - Tony Roma's Restaurant	160	30	50	0	1300 S Harbor Blvd	Fullerton	Private lateral	Private lateral cleanou	nGrease, debris		Emergency night crew responded to private lateral overflow at Tony Romas. Crews placed sand bags around storm drain. Sewer on call crew responded, cleared grease blockage in lateral to stop overflow, cleaned area. Follow up activities will be performed by FOG inspection personnal. Private plumber responded for follow up. Private plumber installed new cap on cleanout to prevent discharge near storm drain inlet. General manager was informed or responsibilities and assured City staff the facility would increase their maintenance.
12/4/05	1	Private	1000	0	0	0	Lake Forest & Rockfield	Lake Forest	n/a	n/a	Grease	Grease blockage	
12/14/05	1	Private	143	2	0	0	8052 ADAMS	HUNTINGTON BEACH	N/A	NA	GREASE	STORM DRAIN -> TALBERT CHANNEL (DIVERTED TO SEWER SYSTEM)	N/A
12/30/05	1	Private Property	1780	1180	1780	600	1777 MITCHELL AV	Tustin	8"	Manhole	Blockage	Grease clog	Previous Private Property spill occurred at same location on 3/28/03. Initial visual estimate at spill location was 900 gallons.
1/3/06	1	Private Spill Kobe Restauran	120	50	200	0	3001 Old Ranch Parkway	Seal Beach	private sewer main line at 3001 Old Ranch Parkway	Restaurant clean-out	Grease	Restaurant had grease interceptor cleaned 3 days pric to overflow. Cleaning may hav forced grease into their main line.	n/a
1/6/06	1	Merit Management Group (Armstrong Ranch) 800-428- 5588	540	200	500	340	3301 S. Sheffield	Santa Ana	Private property sewer system	Starter pot	Grease/ Construction/ Private Property	Combination of construction debri and grease was the caus of the spill.	
1/9/06	1	Private	0	120	50	0	407 State College Blvd	Anaheim	407 State College Blvd.	Private Cleanout	Grease	Grease caused the obstruction	Owner and or manager of location was unavailable to City staff. Workers of the restaurant did not have or would not release his information. Code enforcement as well as Streets & Sanitation staff left contact information for the owner.
1/10/06	1	Private	0	40	50	0	407 State College Blvd	Anaheim	407 State College Blvd.	Private Cleanout	Grease	Grease caused the obstruction	N/A
1/10/06	1	Private	0	0	0	0	104 EDINGER	HUNTINGTON BEACH	N/A	N/A	GREASE	N/A	N/A
1/10/06	1	Private	0	500	0	0	5812 EDINGER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE & DEBRIS	PARKING LOT	NA
1/16/06	1	Private	2050	250	1000	0	453 W. Summerfield Circle	Anaheim	453 W. Summerfield Circle	Private Cleanout	Grease	Grease caused the obstruction	This is the first clear instance of a repeat spill in many years. This will require higher level enforcement to ensure this does not happen again.

-													
1/20/06	1	Maru Sushi Food Service Establishment manager;	0	260	360	0	1500 Adams Ave;	Costa Mesa, CA	Estimated 260 gallon SSO spilled from private property grease interceptor (GI);	Estimated 260 gallon SSO spilled from grease-blocked privati property grease interceptor (GI);	Grease blocked GI;	Estimated 260 gallon SSO spilled from grease-blocked private property grease interceptor (GI);	City of Costa Mesa Code Enforcement called event in to Comm Cit, District Maintenance Supervisor, in turn: National Plant Services, inc contractor response crew dammed cleanout and Storm Drain (SD) upon anrival; SSO did not enter SD, Estimated 260 gallon SSO spilled from grease-blocked private property grease interceptor (GI); City of Costa Mesa cerv accorde SSO and rinse water and disposed of the wastewaithr in the District sanitary sever system; District Staff and City of Costa Mesa errore SM anager counseled Maru Sushi Manager, Scott (S44) 458-5661, to increase frequency of GI cleaning, to use Best Managerent Practices (BMPs) and educate employees or proper disposal of Fats, Oils and Grease (FOG); Photos were taken;
1/20/06	1	Private	250	100	0	0	9882 ADAMS BLVD	HUNTINGTON BEACH	N/A	N/A	GREASE	CLEAN OUT TO PARKING LOT TO CURB AND GUTTER TO STORM DRAIN.	NA
1/30/06	1	Private	740	2500	1000	0	627 N. Euclid Street	Anaheim	627 N. Euclid Street	Private Cleanout	Grease and Break	Grease and break caused obstruction	HCA requested that the property manager perform disinfection of the affected area on private property. Although it is not common practice, the City allowed this work to proceed under HCA supervision and with the vactor truck fully containing the spill downstream.
2/3/06	1	Private	2360	2500	1000	0	627 N. Euclid St.	Anaheim	627 N. Euclid St.	Private cleanout	Grease and Break	Grease and break caused obstruction	NA
2/7/06	1	Private	10	0	0	0	23344 El Toro Rd.	Lake Forest	n/a	n/a	Grease	Grease blockage	
2/8/06	1	Private Property	0	20	0	0	828 N. Glassell	Orange	n/a	n/a	Grease	n/a	n/a
2/10/06	1	Private Property in Leisure World	20	<50	250	0	Nassau & Brookline Drive	Seal Beach	Main line, Oakmont	Manhole, Brookline Dr.@Nassau Dr.	Grease	n/a	Private Property Spill
2/15/06	1	Private	120	30	200	0	2080 S. Harbor Blvd.	Anaheim	2080 S. Harbor Blvd.	Private cleanout	Grease	Grease caused obstruction	NA
2/15/06	1	Private - Calvin Sekhon, property owner (714) 878-1540	700	100	1000	0	2309 W Valencia	Fullerton	Private lateral	3 lateral cleanouts on property	Debris, grease		Crews responded to private overflow from three cleanout locations within apartment complex. City crews contained SSO at private drain in parking area. City crews set up vactor vacuum in gutter, cleared blockage to stop overflow, washed down and vacuumed area. Agartment maintenance person was instructed to thoroughly clean like to prevent re-occurrence. Per residents at complex (who choose to remain anonymous) overflows occur often.
2/16/06	1	Private - Calvin Sekhon, property owner (714) 878-1540	587	200	1000	0	2309 W Valencia	Fullerton	Private lateral	3 lateral cleanouts on property	Debris, grease	Private lateral line was not completely cleared from previous blockage	Crews responded to private overflow from three cleanout locations within apartment complex. City crews contained SSD at private drain in parking area. City crews set up vactor vacuum in guiter, private plumber responded and cleared blockage to stop overflow. City crews washed down and vaccumed area. Properly owner responded a was instrued to thoroughly clean line to prevent re-occurrence. Private plumber had not cleaned entire line due to short ording equipment, extensions were acquired. City personnel, as well as Health agency personnel explained seriousness of SSD to owner of property. South Coast Plumbing video inspected line, found sags in lateral line but other major defects.
2/16/06	1	Brookside Apts	0	180	80	0	5600 Orangethorpe Avenue	La Palma	Private Lateral	Cleanout	Grease & Blockage	Grease blockage from private property and sedement	Private contractor sanitized and cleaned up
2/17/06	1	Brookside Apts	0	202	80	0	5600 Orangethorpe Avenue	La Palma	Private Lateral	Cleanout	Grease & Blockage	Grease blockage from private property and sedement	Private contractor sanitized and cleaned up
3/4/06	1	Private	113	150	100	0	501 N State College Blvd (Chipotle Grill)	Fullerton	Private lateral	Private lateral cleanou	Debris, grease		City crews responded to private lateral overflow at Chipotle Gnil/Pick up Stix restaurants. Health Care agency was on scene. Crews cleared blockage to stop overflow, scome grease retrieved on rodding equipment. City crews washed down and vacuumed area.
3/14/06	1	Private	30	20	500	0	777 Convention Way	Anaheim	777 Convention Way	Private cleanout	Grease	Grease caused obstruction	Although the Hilton has gone to substantial efforts in reducing the amount of grease discharged to the sewer, and implemented a fairly successful sewer line cleaning program, the problem with sewer spills persists. Therefore, despite the potentially high cost, structural controls (grease interceptors and/or trap) will be required to be install at appropriate locations and will be sized adequately and maintained properly.
3/20/06	1	Private Property Denny's Rest.	30	30	100	0	4232 Katella	Los Alamitos	private lateral	private grease interceptor	grease	grease blockage	n/a
L													1

									-				
3/23/06	1	Private	255	1500	500	0	3170 W. Lincoln Ave.	Anaheim	3170 W. Lincoln Ave.	Private cleanout	Grease	Grease caused obstruction	Property owner was very cooperative and reported this spill to the City themselves. There was a delay, however, in clearing the sewer line, since the 'snake' that the first plumber used was not effective in clearing the obstruction. The second plumber managed to clear the obstruction with a jetting tool.
3/30/06		Property Manager for 1875-B Newpord Blvd (Triangle Square), Costa Mesa, CA property;	20	85	205	20	1875-B Newport Blvd;	Costa Mesa, CA	Grease blocked commercia lateral causing overflow fror two of three cleanouts;		Grease blocked commercial lateral causing overflow from two of three cleanouts;	Grease blocked commercial lateral causing overflow from two of three cleanouts;	Estimated 105 gallon SSO flowed from two of three private property cleanouts; Estima 20 gallons SSO trickled into storm drain (SD) used as a containment vessel; RecoveredVactored 85 gallons; City of Costa Mesa crew vactored SSO and rinse wa and disposed of the wastewater in the District santing severe system; Grease blocked commercial lateral causing overflow from two of three cleanouts; CMSD District Maintenance Supervisor on site; City of Costa Mesa crew blocked SD and vactored wastewater in the street and cut/s while plumber was en route. Private plumber Proser cleaned lateral line; CMSD contractor, National Plant Senios, Inc., cleaned the remaining grease pushed into the District Main Line on 3-31-06 @ 0930 hours; Photos were taken and are attached;
4/6/06	1	Private	140	0	40	0	969 S. Euclid St.	Anaheim	969 S. Euclid St.	Private cleanout	Grease and food	Grease and food caused obstruction	Sewage flowed south from parking lot behind Little Caesar's Pizza to Ball Road. On E Road it traveled west approximately Z50 yards where it entered the catch basin located at 1791 W. Ball Road, on the north side of Ball Road.
4/6/06	1	Private	400	200	0	0	7850 SLATER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE	HUNTINGTON CENTRAL PARK LAKE - WILL POST SOME CLOSURE SIGNS AT DRAIN ENTRY TO LAKE FOR A FEW DAYS - INCIDENTAL CONTACT LAKE.	N/A
4/10/06	1	The Lodge Food Service Establishment (FSE);	0	10	60	0	2937 Bristol Street;	Costa Mesa, CA	Grease primarily and some debris blocked private lateral; SSO flowed from private MH on private property;	Private MH;	Grease primarily and some debris blocked private lateral;	Grease primarily and some debris blocked private lateral;	AB&R Plumbing called CMSD Maintenance Supervisor; Estimated 10 gallon SSO flowed from private Manhole (MH) on private property into Curb - City of Costa Mesa and CMSD Maintenance Supervisor drammed Storm Drain (SD) - July contained; City Costa Mesa carev vactored SSO and rines water and disposed of the waterwater in the CMSD sanitary sewer system; Visual Estimate of 10 galons pooled wastewater i rho shallow - 10 galons over 30 minutes = 3.3 galonSminute; Grease primatiy and debris blocked private lateral; Photographs were taken and are attached;
4/11/06	1	Private	15	160	0	0	7402 EDINGER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE	STORM DRAIN -> FLOOD CONTROL CHANNEL (EAST GARDEN GROVE WINTERSBERG CHANNEL)	N/A
4/17/06	1	Private Property	0	25	0	0	3340 E. Collins	Orange	n/a	n/a	Grease	n/a	n/a
4/24/06 0943	1	Private Health Care Center	630	0	0	0	RXR easement behind 2800 N Harbor	Fullerton	Private lateral	Lateral cleanout	Grease, debris		Crews responded, contained, and cleared blockage in private lateral to stop flow. Private plumber responded to follow up with clean up activities. All sewage scaked imp the dirt channel near railroad easement. Skilled Healthcare Center will be added to the City's FOG program.
5/7/06	1	Private	30	0	0	0	17575 Harvard Ave. (Corner Bakery)	Irvine	n/a	n/a	Grease	Grease blockage	
5/15/06	1	Private	95	5	0	0	1755 W. La Palma Ave.	Anaheim	1755 W. La Palma Ave.	Private cleanout	Grease	Grease caused obstruction	Na
5/23/06	1	Private	300	100	200	0	1731 W. Katella Ave.	Anaheim	1731 W. Katella Ave.	Private cleanout	Grease and paper	Grease and paper caused obstruction	N/A
5/30/06	1	FV	75	70	0	0	16155A-16175 Harbor Blvd	Fountain Valley	private property sewer laters	1	grease build up	private	NA
6/5/06		Sterling Shopping Center, manager, Ross Cannon.	360	200	700	160	17436 Beach Blvd., Sterling shopping center	Huntington Beach	Blockage was in the private lateral line of the shopping center.	Pick hole of the clean out cover.	Grease blockage.	Grease and debris blocked the private lateral line.	
6/24/06	1	City of Huntington Beach	250	200	400	50 Gallons	17732 Goldenwest Street	Huntington Beach	Park Bench Café, 17732 Goldenwest Street	Private sewer lateral cleanout cap.	Grease and debris blockage.	Grease and debris buildup in the private sewer lateral.	The Park Bench Café is in a City park, the problem cleanout pipe is next to a large low grass area. All sewage was confined to this aera.
6/27/06	1	Rainbow Disposal, trash hauler.	150	150	250	0	17121 Nichols Street	Huntington Beach	Blockage was in the private lateral line on Rainbow property.	Clean out pick hole.	Grease and debris blockage.	Grease and debris buildup in the private sewer lateral.	
7/4/06	1	Private Property	0	200	0	0	315 Bedford	Orange	n/a	n/a	Grease	n/a	n/a

7/7/06	1	Private Property Owner	0	20	400	0	Ziings / Revolucion Restaurants, 209 N Harbor Blvd (Rear driveway)	Fullerton	Private Grease Interceptor	Interceptor lid	Grease blockage in private lateral		City crews responded to report of grease interceptor overflowing behind restaurant complex. Crews contained and vacuumed overflow until blockage was cleared. Zings and Revolucion restaurant's shared interceptor had been pumped within the past 3 months as required by the City's FOG program. Blockage in tateral line assumed to be grease. The City's FOG program inspector will follow up and monitor maintenance activities to re-evaluate pumping schedule.
7/8/06	1	Private	300	800	500	0	1590 W. Palm Lane	Anaheim	1590 W. Palm Lane	Private cleanout	Grease	Grease caused obstruction	Property management was very responsive in obtaining a private plumber to clear obstruction.
7/11/06	1	Silk Thai Cuisine Restaurant	10	10	210	0	19690 Beach Blvd., Newland Shopping Center	Huntington Beach	Slik Thai Restaaurant in the Newland Shopping Center.	Cover of grease interseptor	Grease blockage	Phill's Plumbing while repairing the grease interceptor at The Silk Thai Restaurant 10 gallons of sewage spilled.	
7/27/06	1	Pacific West Management Corporation, property manager Sharon Ference 714-433-7300	100	100	200	0	6941 Warner Avenue	Huntington Beach	Don Ramon's Mexican Restaurant in this shopping center.	Sewer lateral clean ou cover.	Grease blockage	Grease blockage in the private sewer lateral down stream of the Don Ramon's Restaurant.	
7/28/06	1	Pacific Coast Properties (PCP) Management for 12-unit apartment complex located at 584 West Hamilton (Beth - Office 714-378-1366, Cell - 714-331-7847);	20	80	180	20	584 West Hamilton Street;	Costa Mesa, CA;	Blockage in PRIVATE latera	Cleanout (CO) on PRIVATE property;	Grease and debris blockage in PRIVATE lateral line on PRIVATE property;	Grease and debris blockage in PRIVATE lateral line on PRIVATE property;	PRIVATE SSO called in to City of Costa Mesa Comm Center - Fire Dept and PD responded for potential hazardous materials spill and traffic control; CMSD Staff encountered SSO while traveling home from work; Pacific Coast Properties (PCP) Management for 12-unit apartment complex located at 584 West Hamilton (Beth - Offi 714-378-1586, Cell - 714-331-7847); Biockage in PRIVATE lateral line on PRIVATE property: Estimated 60 gallons SSO contained in SD curb; City of Costa Mesa acdored SSO in public ROW curb and gutter and disposed of SSO and rinsewater in CMSD sanitary sever system at the Corporate Yard; COM dammed SD, Private [public cleanion gand install anothe CO to assist in cleaning the lateral; Photographs were taken and are attached;
8/3/06	1	Earl Benton 714-964-7697, home address 20271 Meander Lane, HB 92646.	20	20	170	0	4932 Kona Dr.	Huntington Beach	4932 Kona Dr., sewer line inside of apartment building	The discharge pipe for the washing machine.	Grease blockage	Grease blockage in private sewer lateral line.	The owner of this four unit appartment complex does not do much maintenance or upkeep on this property.
8/5/06	1	Private	300	0	0	0	24401 MUIRLANDS	LAKE FOREST	N/A	N/A	GREASE	GREASE INTERCEPTOR TO PARKING LOT TO STORM DRAIN TO SAN DIEGO CREEK (DRY).	May be R-9
8/11/06	1	A.K.A. Japanese Restaurant 714-374-9600 and Cavallino Italian Restaurant 714-536- 6665	55	55	155	0	8082 Adams Ave.	Huntington Beach	Between private manhole and City manhole at 8082 Adams Ave.	Pick holes of manhole cover.	Grease blockage	Grease buildup from two food service establishments.	
8/20/06	1	FV	10	10	0	0	9102 Edinger Avenue	Fountain Valley	private property sewer latera	-	grease	private sewer lateral	NA
8/31/06	1	El Taco Mexican Restaurant owner (213-249-0756);	0	30	80	0	2101 Harbor Blvd;	Costa Mesa, CA;	Grease blocked PRIVATE lateral line from El Toro Mexican Restaurant;	Grease blocked PRIVATE lateral line from El Toro Mexican Restaurant;	Grease blocked PRIVATE lateral line from El Toro Mexican Restaurant	Grease blocked PRIVATE lateral line from El Toro Mexican Restaurant;	El Taco Mexican Restaurant owner (213-249-0756) called District Maintenance Supervisor: District Maintenance Supervisor called @ 1100 hrs. blocked SD @ 1112 hrs. called City of Costa Mesa Public Services to send a Vatotr and clean the Public ROW, flush site with fresh water and vator site: City of Costa crew vactored SSO from curb and gutter and returmed/disposed of SSO in District samitary sever system; Grasse blocked PRIVATE lateral line from El Toro Mexican Restaurant. El Toro Mexican Restaurant owner reminded to increase frequency of cleaning grease from PRIVATE lateral line and follow PCG guidance of BMPs, training, and record keeping; Photographs were taken and are submitted with this monthly report;
9/21/06	1	Private	30	20	500	0	537 N. Magnolia Ave.	Anaheim	537 N. Magnolia Ave.	Private cleanout	Grease	Grease caused obstruction	A previous spill occurred at this address on 6/10/06. The spill occurred when the sewage lift pump failed, partially as a result of the failure to implement the corrective actions required in the first Compliance Order, and partially due to new conditions.
11/3/06	1	Joe's Crab	0	20	0	0	2607 W. Coast Hwy	Newport Beach	Blocked Grease interceptor	Grease interceptor	Blocked Grease Interceptor	See Remarks	Met vactor, called for sand to build a berm around the grease that overflowed from the Restaurant interceptor. Contacted workers inside restaurant to call for a plumber/pump truck and informed them they would not be allowed to open until the problem was taken care of. Called the Orange County Health Dept. and Regional Water Qualty Control Board.
11/6/06	1	Private	1000	1520	1000	0	967 S. Euclid St.	Anaheim	927 S. Euclid St. interceptor	Private cleanout	Grease and settlable food solids	Grease and solids build up in interceptor and caused obstruction	A previous spill occurred at this address but not from this same line. Impliementing a program to prevent the discharge of solids to the interceptor as well as a more frequent inspection and/or cleaning program should resolve this situation.
11/25/06	1	Private Property	405	0	0	0	1001 W. Stevens	Santa Ana	Private lateral	Private clean out	Grease	Grease in private lateral	None

	1			1									
11/25/06	1	Private	0	0	0	0	24371 EL TORO ROAD	LAKE FOREST	N/A	N/A	GREASE	CURB & GUTTER -> STORM DRAIN	May be R-9
12/7/06		Charles Dunn Management Company, Laura Tarbutton Property manager	450	450	650	0	6918 Warner Avenue	Huntington Beach	6918 Warner Avenue	Clean out cover behind the Subway Sandwich shop.	Grease blockage	Grease blockage in the private lateral sewer line.	
12/22/06	1	Private	10	0	0	0	1151 N. Euclid St.	Anaheim	1151 N. Euclid lateral in alley behind building	Private cleanout	Grease	Grease caused obstruction	A previous spill occurred at this location. If routine cleaning and Kitchen BMPs can no prevent spills, an iterceptor will be required
12/23/06.	1	Private	100	200	0	0	3435 Newport Blvd.	Newport Beach	Grease trap	Grease trap	Grease from their grease trap.	See Remarks	Grease trap from Pavillions Market overflowing. Fire crew and Monica from Health De already on scene. Set up vacuum truck in parking lot. Spoke with the Manager at the market and told him he needs to get a plumber out. Health Dept. shut down the Market
12/27/05	1	City of Santa Ana	450	200	250	200	300 W. Second St.	Santa Ana	H09-028	Manhole cover	Grease	No maintenance program caused grease build-up and resulted in flow back-up	Affected areas were cleaned up by Aladdin Emergency Clean-up Service. Increase maintenance from the Plaza del Sol Apartment complex.
12/30/06	1	Private	0	0	0	0	4232 KATELLA	LOS ALAMITOS	N/A	N/A	GREASE INTERCEPTOR	STREET -> CURB & GUTTER	Denny's resturant
Totals	240		73,469	59,008	73,913	26,861							
	28	Grease traps or interceptor	2,518	3,405	4,944	247							
Roots													
4/19/02	2	Private Property	10	8	8	2	18802 Bardeen Ave.	Irvine	4" Sewer Line	V-drain	Blockage	Root obstruction in lateral line & Possible Broken Lateral	NA
9/17/02	2	Private Management Company	0	0	0	0	1815 W Malvern Ave	Fullerton	Private Lateral	Private four inch cleanout	Roots and Toilet debris	Unknown	On 9/16/02 Unit 340 (emerg night crew) responded to a report of a private sewer problem, private plumber was on scene, no overflow observed. On 9/17/02 Jorge Gonzales (acting sanitation specialist) followed up by inspecting problem site and observed sewage around lateral cleanout and a small amount at curk. No sewage was overflowing at that time. Jorge Gonzales contained spill with dirt at curb and advised Management Co. to call Emergency Services for proper cleanup. Management Co. advised they had private Co. to cleanup. Jorge Gonzales informed Code Enforcement and Supervisor to follow up. Service Request #0238736
9/18/02	2	Private Sewer Lateral	20	0	0	0	Behind 1730 Raintree Rd	Fullerton	Private Lateral	Private four inch latera	Roots	Roots	City Employees Gonzalez, Bair and Miller responded with pickup truck and flatbed trus to private lateral overflow. City crew contained spill, cleared blockage, cordoned off and and scarified approximately twenty feet of bride trail. Service Request #0238767
11/2/02	2	Private	50	0	0	0	22606 Costa Bella Dr.	Lake Forest	n/a	n/a	Roots	Roots	
11/25/02	2	Private	0	1500	0	0	1068 Rutland	Newport Beach	Cleanout	Cleanout	Unknown (possible roots)	See Remarks	Cleanout overflow - OCH care Agncy closed Upper Newpor Bay Water
1/29/03	2	Private Property	0	0	0	0	1102 Hyde Park Dr.	Unincorporated County of Orange	Private lateral line	Bathtub and toilet	Roots in private lateral line		OCSD will CCTV entire Hyde Park Dr. line segments to investigate house lateral conditions for root intrusion. Resident was sent a letter explaining the cause of the sewage backup into his home (roots in his lateral) so he could file an insurance claim.
2/22/03	2	Private	0	0	0	0	24681 Shadowfax	Lake Forest	n/a	n/a	Roots	Roots	
3/13/03	2	Private Property	350	400	400	750	112 N Bradford Ave Placentia	Placentia	private lateral line	Broken latteral line	roots		Bradford Senior homes hired contractor to repair latteral line City to charge back time and matterals for spill
4/18/03	2	Private	2	0	0	0	4 Gillman	Irvine	n/a	n/a	Roots	Roots	
5/6/03		666 West 18th St Newport Mesa Townhome, Costa Mesa, CA 92526	0	165	100	0	SSO spilled out of lateral line cleanout at 666 W 18th St, Costa Mesa	Costa Mesa, CA	Location is in a residential neighborhood. SSO spilled out of lateral line cleanout a 666 W 18th St. Costa Mesa Lateral line blocked with roots and paper.	Location is in a residential neighborhood. SSO spilled out of lateral line cleanout at 666 W 18th St, Costa Mesa. Lateral line blocked with roots and paper.	Lateral line blocked with roots and paper.	Lateral line blocked with roots	Approximately 165 gallons of SSO spilled out of private lateral line cleanout located at 666 West 18th St, Costa Mesa. Field Crew fully contained SSO in public right of way. Crew vacored SSO, flushed SSO with fresh water and disposed of SSO and flush water into the sever system. Private pumber, Costa Plumbing, cleared line by cutting roots out of lateral; Digital photos were taken and are attached to this report.

5/9/03	2	Private Property	0	0	0	0	CANYON TERRACE RD & CRAWFORD CANYON RD	Unincorporated County of Orange	Lateral	Cleanout	Blockage Root obstruction in lateral line	N/A	NA
5/15/03	2	Private Property	20	30	30	0	7100 KNOTT AVE.	Buena Park	Lateral	Cleanout	Blockage Root obstruction in lateral line	N/A	NA
5/20/03	2	Private Property	0	30	0	0	n/a	Orange	n/a	n/a	Roots	n/a	n/a
7/25/03	2	Private Property: Crown Point Homeowners Association	13167	798	998	13167	400 Crown Point Drive	Anaheim	Near 400 Crown Point Drive	Private sewer manhole on Crown Point Drive	Roots	Roots obstructed the sewer flow.	Spill could not be found at Santa Ana channel where it would empty into. It is suspect that a sump area in Call Trans Right of Way received the spill.
9/15/03	2	Private Property	150	100	0	0	n/a	Orange	n/a	n/a	Roots	n/a	n/a
9/30/03	2	American Properties, P.O. Box 3895, Newport Beach (949) 363-7255	0	30	50	0	718 N. Lacy Street	Santa Ana	Private lateral	Sewer lateral clean ou	Roots: Private spill, plumber pulled out roots/paper.	Private spill, plumber pulled our roots and paper.	
10/1/03	2	Private Property	0	0	0	0	Jamboree at Big Canyon Golf Course	Newport Beach	Private manhole	Private manhole	Roots and debris	See Remarks	Opened manhole and cleared roots and debris over 10 ft deep manhole. Private manhole. Private property: Sea Island Community Association.
10/2/03	2	Private- William Lyon Property Management	30	210	20	0	5601 E. Orangethorpe Ave	Anaheim	5601 E. Orangethorpe Ave	Private Manhole	Roots	Roots obstructed sewer flow, causing the overflow at the manhole	Mark Williams of OCHCA responded to the scene and informed the property owner of the seriousness of the situation
10/27/03	2	Solteros Apartment maint. personnel at 17301 Keelson Ln Huntington Beach.	25	25	45	0	17301 Keelson Lane	Huntington Beach	Front yard of Solteros Apartment complex at 1730 Keelson Ln	Four inch clean out.	Tree roots clogged private lateral.	Roots from tree clogged apartment complexes sewer lateral.	
10/30/03	2	Private	17	21	300	0	1708 Peppertree Ln in alley behind apartments	Fullerton	Private lateral	Private lateral cleanou	Roots and debris	Root intrusion into 6 inch sewer lateral through defective joint	Crews responded to private lateral overflow. Overflow was intermittent between 0 and 3 gm. City crews contained spill, cleared blockage, washed down and vacuumed area Due to normal irrigation run-off and storm drain flow, crews were unable to contain approximately 17 gallons of sewage that entered the storm drain system prior to their arrival. Property owner video inspected lateral and found a defective joint. City instructed owner to repair defective pipe to prevent any further overflows.
11/20/03	2	Dr. Charles Kenyon, at his private residence.	55	55	105	0	17075 Roundhill Dr.	Huntington Beach	Private homeowners lateral at 17075 Roundhill Dr.	Broken lateral line.	Tree roots clogged sewer lateral line.	Private party tree roots clogged and broke their sewer lateral. City's Water Dept. dug hole checking out complaint of broken water line, found broker sewer pipe.	Problem spot was in street homeowners sewer lateral. Residence is upstream on a hil explaining some pressure.
12/2/03	2	Private property owner	100	1600	1600	0	1758 W. Sumac Lane	Anaheim	1758 W. Sumac Lane	Clean out in laundry room	Roots	Roots clogged the sewer latter	Property owner was initially unresponsive to the City's and OCHCA's calls notifying hin fol the situation. Owner finally arrived onscene and obtained the services of a private plumber 8 hours after initial contact.
12/10/03	2	Private property owner	300	500	200	0	6103 Morningview Drive	Anaheim	6103 Morningview Drive	Private Cleanout PC192423	Roots	Roots clogged the sewer line and caused a overflow	
12/31/03	2	Richard Beachler	75	75	100	0	6571 Sabbicas Cir.	Huntington Beach	Private homeowners lateral at 6571 Sabbicas Cir.	Private clean out		Tree roots in private sewer lateral	
1/21/04	2	Private Lateral St. Hedwig School	50	50	300	0	11482 Los Alamitos Blvd.	Los Alamitos	private lateral	private lateral clean ou	roots	tree root blockage	n/a
1/26/04	2	Coastline West Management Service	50	50	55	0	1035 12th Street	Huntington Beach	1035 12th Street	Sewer clean out pipe on private property	Roots	Apartment complex sewage line clogged with roots.	
2/2/04	2	Rick Trucios, homeowner.	300	200	250	100	782 Little Harbor	Huntington Beach	Private homeowners lateral at 782 Little Harbor	Roots caused a private sewer lateral to plug.	Tree roots clogged lateral line	Private party tree roots clogged sewer line and caused sewage to spill out of homeowners association manhole.	Private cleanup company (Aladdin Emergency Services) contacted the City about the spill otherwise we might not have known.
3/7/04	2	Sycamore Canyon Townhomes	800	200	200	0	8282 E. Oak Ridge Circle	Anaheim	8282 E. Oak Ridge Circle	Private clean out	Roots	Roots obstructed private clean out	Private plumber did not arrive unil 9:35 pm and had difficulty with their equipment. Obstruction was finally cleared at 3am. Private plumber and City Staff worked to washdown and clean affected area.

	1							1			1		
3/19/04	2	Parkview One Homeowners	960	60	1000	0	6518 E. Camino Vista	Anaheim	6518 E. Camino Vista	Private Sewer Manhole	eRoots		The spill was not reported for an estimated 2 days, due to the fact that the residents of this complex did not identify this spill as being sewage.
4/4/04	2	CMSD	2475	525	300	0	1599 Superior Ave / 700 Block of West 16th St;	Costa Mesa, CA	Root balls blocked private sewer lateral forcing SSO out of private cleanout; possible root entry point at Ductile Iron Pipe fitting to lateral on private property;	Root balls blocked private sewer lateral forcing SSO out of private cleanout; possible root entry point at Ductile Iron Pipe fitting to lateral or private property;	Root balls blocked private sewer lateral forcing SSO out of private cleanout;	Root balls blocked private sewer lateral forcing SSO out o private cleanout;	Root balls blocked private sewer lateral forcing SSO out of private cleanout; possible root entry point at Ductile Iron Pipe fitting to lateral on private property. Oten Properties Property Manager Jeff Schweitzer called for two plumbing companies to clear the SSO lateral blockage. First company unable to clear tateral with rotay cutting blade - but removed root clusters from lateral: Second company used a mini hydrojet to clear remaining blockages: District Field Cerw ecommended the Property Manager video the lateral: City of Costa Mesa NPDES Manager also on-site and took photos: CMSD Crew dammed storm crain, vaccored and disposed of the contained SSO and rises water into the District sanitary sewer system at the Corporate Yard; Photographs were taken and are attached.
4/15/04	2	City of Anaheim / Anaheim Fire Station #9	150	50	200	0	6300 Nohl Ranch Rd.	Anaheim	6300 Nohl Ranch Rd.	Sewer Lateral Cleanou	Construction damaged the lateral and allowed roots to invade sewer line	Roots	N/A
6/28/04	2	Private property owner	0	35	2000	0	305 N Harbor on Wilshire side	Fullerton	Private lateral from 305 N Harbor Blvd	Private lateral cleanou on Wilshire Ave	Roots and debris	Possible roots from parkway tree. To be determined	City crews responded to report of overflow on sidewalk. Flow was contained at 239 W Wilshire Ave. City crews cleared root and debris blockage in private lateral from businesses at 305 a 215 N Harbor. Crews washed down and vacuumed approximately 35 gallons of sewage combined with havy inglation run off approximately 100 feet down Wilshire Ave. gutter area. Lateral line will be video inspected to determine if roots from the parkway tree are intruding into the lateral. Area sewer mains were maintenance jetted, no problems found.
9/11/04	2	Prudential Real Estate	276	200	450	76	21851 Newland Ave.	Huntington Beach	Private sewer lateral at 793 [.] Stark Ave.	Cleanout	Tree roots	Tree roots clogged sewer latera for an eight unit residential complex	
10/29/04	2	Private party lateral blocked with roots;	1	6	31	1	690 West Hamilton St	Costa Mesa, CA	Roots blocked private latera SSO spilled from private lateral deanout at 690 West Hamilton St; Fully contained	from private lateral cleanout at 690 West		SSO spilled from private lateral	Roots blocked private lateral; SSO spilled from private lateral cleanout at 690 West Hamilton St; Fully contained; Private owner obtained services of plumber and cleaned out the roots blocking the lateral line; Crew remained on-site until blockage cleared; Vactored SSO (g tabl) and 25 gails of rises water were disposed of in the District sanitary sewer system; 9 gals SSO evaporated from earthen dam; Photographs were taken and are attached in Word format;
11/4/04	2	South Coast Village	0	600	600	0	1001 W. MacArthur	Santa Ana	Unclear	Drain in laundry room	Roots	Build up of roots in sewer latera	
11/5/04	2	Private party lateral cleanout blocked with roots;	0	50	100	0	2424 University Drive	Newport Beach	SSO spilled from private lateral cleanout in a recently built sidewalk in Newport Beach;	SSO spilled from private lateral cleanout in a recently built sidewalk in Newport Beach; Roots blocked lateral line	t Roots blocked private lateral line;	Roots blocked private lateral line at 2424 University Drive;	City of Newport Beach Crew and CMSD District Crew blocked flow in curb leading to Back Bay, Vactored 50 gallons of SSO and 50 gallons of rinse water were disposed of in the District sanitary sewer system; District Crew estimated SSO via visual pool estimated to be 50 gallons – 5.0 gallrim x 100 minutes; AB&R Plumbing responded to District for owner manager Max Yamada and cleaned roots out of the lateral; Lateral lihe also videotaped; Photographs were taken and are attached;
11/26/04	2	Private	1080	0	0	0	22 Pergola	Irvine	Private manhole	Private manhole	Roots	Private manhole, roots in line	
12/28/04	2	Private Property	0	0	0	0	13071 ST MARKS DR	Santa Ana	4"	Clean-out	Blockage	Root obstruction in lateral line	Spoke with Mike Fennessy, OCHCA, and requested his staff to inspect the site since OCSD manhole/line is in the Private Property yard.
4/13/05	2	Private Property	50	0	0	50	1505 CLEARVIEW LN	Unincorporated County of Orange	4"	Cleanout	Blockage	Root obstruction pushed in from connecting line	Private Property
5/16/05	2	Mesa Verde Town Homes;	40	60	160	40	666 West 19th St	Costa Mesa, CA	Roots in private lateral line (Newport Mesa Town Homes caused SSO to spill from cleanout;	Roots in private lateral line of Newport Mesa Town Homes caused SSC to spill from cleanout;	Roots in private lateral line of Newport Mesa Town Homes caused SSO to spill from cleanout;	Roots in private lateral line of Newport Mesa Town Homes caused SSO to spill from cleanout;	One District Crew contained SSO (upon arrival) from further entering the Storm Drain (SD) until private plumber arrived to clear private lateral line of roots; District called ou C&R plumbing to clean the line; SD used as additional containment vessel; Crew vactored severage from site and SD and disposed of in the District sanitary sever; Estimated flow rate of 20 galons per hour for 5 hours yielding an SSO of togalons; Roots in private lateral line of Newport Mesa Town Homes caused SSO to spill from cleanout; District crew vactored 60 gallons of SSO from site and storm drain and 100 galons of treh nine water used to clean the site; District informed Property Manager Cheryl Store to increase frequency of lateral line cleanout to quarterly rather than every six months; last documented occurrence was 5-6-03; Photographs were taken and an attached.
5/31/05	2	City of La Palma	0	15	40	0	7822 Walker Street	La Palma	Lateral line	Cleanout	Blockage	Roots	Private contractor sanitized and cleaned up
	•			•									

6/4/05	2	Private	0	20	50	50	1384 S. Gilbuck St.	Anaheim	1384 S. Gilbuck St.	Private clean out	Roots	Roots caused obstruction.	The volume of the spill was likely larger than the 20 gallons that were cleaned up. However, since the leak was very slow and ponded in street over a couple days, evaporation accounts for the remaining approximately 100 gallons.
8/14/05	2	Private	0	2	0	0	1817 BEDFORD ROAD	NEWPORT BEACH	N/A	N/A	ROOTS	GUTTER	N/A
8/16/05	2	Private Property	0	0	0	0	1771 LA LOMA DR.	Unincorporated County of Orange	Private Lateral	Cleanout	Blockage		Div 420 arrived at site to find private property spill at homeowners clean-out. They ran the line/manhole downstream of property and cleaned out some roots. However, lateral is blocked with roots on homeowers property at 4in. cleanout. Homeowner is not home but mays. have been left for thin to contact a private plumber before using anymore water. Spill is not flowing at present time & was determined to be a very small spill.
8/23/05	2	Private	0	15	0	0	28232 BEACH BLVD.	HUNTINGTON BEACH	N/A	N/A	ROOTS	CONTAINED IN CURB AND GUTTER	NA
9/13/05	2	Private Property	15	0	0	0	19511 HOLIDAY LN	Unincorporated County of Orange	4-in lateral line	Clean-out	Blockage	Root obstruction in lateral line	NOT OCSD PROBLEM
10/24/05	2	Private	5	45	40	0	732 N. East Street	Anaheim	732 N. East Street	N/A	Roots	Roots caused obstruction	N/A
12/25/05	2	Private Property	100	0	150	0	11021 GOLD STAR LN	Unincorporated County of Orange	8"	Manhole	Blockage	Roots in Main Line	Control 1 was notified by homeowner and Control 1 contacted Larry Honeybourne. Larry Honeybourne contacted OCSD of the spill.
12/27/05	2	Private	0	5	0	0	18302 GOTHARD	HUNTINGTON BEACH	N/A	N/A	ROOTS	VACUMMED UP FROM GUTTER	N/A
1/6/06	2	Private Property	0	3500	0	0	n/a	Orange	n/a	n/a	Roots	n/a	n/a
1/9/06	2	Private	30	90	40	0	1721 Claudina Avenue	Anaheim	1721 Claudina Avenue	Private Cleanout	Roots	Roots caused obstruction	N/A
1/10/06	2	Private Property	0	0	0	0	12322 EL ROY DR	Unincorporated County of Orange	Private property lateral	Clean-out	Blockage	Roots in lateral	NOTIF. DIV. 420 JOHN GONZALES AND HAD CREW TO SITE. CREW ONLY FOUND DRIED PAPER ON PRIVATE PROPERTY. CREW USED VACTOR TRUCK, LINE IN STEET IS RUNNING OK. CREW IS CONTACTING CALLER AS THEIR CLEAN-OUT NEEDS CLEANING OUT. AREA WAS RINSED DOWN.
1/11/06	2	Property Manager for 1746 Placentia Ave, Costa Mesa, CA property;	20	154	254	20	779 Shalimar Dr;	Costa Mesa, CA	Roots blocked multifamily residential lateral causing overflow from an uncapped cleanout;	Uncapped cleanout;	Roots in private lateral line;	Roots blocked multifamily residential lateral causing overflow from an uncapped cleanout;	Private resident of facility reported event to CMSD and CMSD Maintenance Supervisor, in turn: Estimated 174 gallon SSO flowed from an uncapped private property cleanout Estimate 20 gallons SSO trickled into storm drain (SD): Estimate 50% SSO evaporated prior to reaching SD: City of Costa Meas crew vactored SSO and frise water and disposed of the wastewater in the District sanitary sewer system; Roots blocked multifamily residential lateral causing overflow from an uncapped cleanout; CMSD Maintenance Supervisor remained on site unit commercial plumber arrived and completed lateral cleaning/removal of roots and capping the facility cleanout; CMSD Staff informed Facility Manager, EG Glinka, 714-926-3805, of need to increase lateral line cleaning frequency and keep cleanouts capped; CMSD backcharged Facility Manager for services provided; Photos were taken;
1/28/06	2	Private	11900	0	0	0	17650 Rosa Drew Lane	Irvine	n/a	n/a	Roots	Roots	
1/28/06	2	Private	10800	0	0	0	5238 MICHELSON	IRVINE	N/A	N/A	ROOTS	MASON CREEK AND SAN DIEGO CREEK TO UPPER NEWPORT BAY	May be R-9
2/16/06	2	Private Property	0	0	0	0	19246 Fairhaven Extension near Panorama Place.	Unincorporated County of Orange	U	U	Blockage	Root obstruction in lateral line	HCA Michael Fennessy contacted, HCA going to site. Problem belongs to homeowner and HCA will follow-up.

									1				
2/23/06	2	Lordon Management Company (626-967-7921, x3316), @ 1275 Gener Court Drive, Covina, CA 91724; FAX: 626- 966-3918)	0	35	85	0	760 West 16th St;	Costa Mesa, CA	Roots/paper towels blocked private lateral in a parking lo causing overflow from a cleanout;	Roots/paper towels blocked private lateral in a parking lot causing overflow from a cleanout;	Roots/paper towels blocked private lateral in a parking to causing overflow from a cleanout;	Roots/paper towels blocked private lateral in a parking lot causing overflow from a cleanout;	London Management Company reported event to CMSD and CMSD Maintenance Supervisor; Repeat similar event to 2/17/06; Visually estimated 82 gallon SSO flowed from one private property cleanout; Estimate Some SSO trickled into stom drain (SD) used as a containment vessel; Recovered/vactored & gallons; District line cleaning contractor, National Plant Services, Inc., (NPSI), and City of Costs Mesa crew performed cleanup; District maintenance supervisor and NPSI dammed Storm Drain (SD) and vactored SSO and rinse water and disposed of the wastewater in the District sanitary sever system; Private plumber arrived and removed roots/spaper towels while cleaning lateral line; Roots/spaper towels blockad private lateral in a parking lot causing overflow from a cleanout; District Maintenance to prevent flux (User SSO; Photos were taken and are attached; District backcharged London Management Company for services/resources used to manage the SSO;
5/9/06	2	Private Property	0	0	0	0	1942 OMEGA DR	Unincorporated County of Orange	Lateral line	υ	Blockage	Root obstruction in lateral line	NA
6/6/06	2	Private	0	100	0	0	441 GOLDENROD AVENUE	NEWPORT BEACH	N/A	N/A	ROOTS	CURB & GUTTER (CONTAINED AND CLEANED UP)	N/A
6/11/06	2	Private	600	1800	20	600	8000 Naples Ln.	Anaheim	8000 Naples Ln.	Private cleanout	roots	Roots caused obstruction	N/A
8/5/06	2	Private	1000	5300	6000	1000	1250 S. Brookhurst St.	Anaheim	1250 S. Brookhurst St.	Private cleanout	Roots, break, unknown	Unknown cause of obstruction, possibly roots or a break in the line.	Private plumber was unable to clear obstruction with snake. Another plumber with a jetter was called in, after several hours of delays, to eventually clear obstruction.
10/4/06		PRIVATE SSO - Apartment Owner/Manager Ed Glinka - 714-926-3905;	288	0	0	288	779 Shalimar Drive;	Costa Mesa, CA;	PRIVATE PROPERTY cleanout in rear of property in alley;	PRIVATE PROPERTY cleanout in rear of property in alley;	Root in lateral line ir front of facility blocked lateral line which runs under the 4 unit apartment complex;	Root in lateral line in front of facility blocked lateral line whic runs under the 4 unit apartmen complex; Later verified with private CCTV;	City of Costa Mesa Code Enforcement Officer Tim Sun notified District Maintenance Supervisor; PRIVATE SSO - Apartment Owner/Manager Ed Glinka - 714-926-3805 is the responsible party; A continuing facility lateral problem caused an estimated 288 galons of SSO to flow onto private property/alley over 24 hour period. Private plumfer cleaned lateral; Most of SSO evaporated while flowing to Stom Drain (SD); Estimate 288 galons SO not recoverable due to evaporation and entry into the SD; Root in lateral line in front of facility blocked lateral line which runs under the 4 unit apartment complex, later verified with private CVTV; CMSD Maintenance Supervisor and City of Costa Mesa Code Enforcement Officer Tim Sun recommended Owner/Manager CCTV line to verify roots and work with the City of Costa Mesa to possibly remove tree based on the video and repair the lateral line to prevent future SSOs; Pholographs were taken and are included;
10/19/06	2	Private	0	8	0	0	23472 LOS ADORNOS	UNINCORPORATED COUNTY	N/A	N/A	ROOTS	ALL DISCHARGE WAS CAPTURED AND RETURNED TO SEWER.	N/A
11/15/06	2	Private	0	10	0	0	52 Leesburg	Irvine	Private lateral	Private lateral	roots	Blockage in customer's lateral (roots)	
11/16/06	2	Service First Management Corporation, property manager Erica Wermer 714-963-5555 ext. 378.	3,500	3,500	4,100	0	17742 Beach Blvd.	Huntington Beach	Beach Medical Associates Center, 17742 Beach Blvd. lateral sewer pipe.	Sewer clean out cover	Plugged sewer lateral.	Roots and debris in the private sever lateral. The landscaping parallel to this private sever lateral has about ten Ficus tree planted in it. The plumbing company pulled out many roots from this sever lateral. These roots restricted the sewage flow and	Property Manager Erica Werner cell phone 949-683-7184.
11/20/06	2	Service First Management Corporation, property manager Erica Werner 714-963-5555 ext. 378.	1,200	1,200	1,500	0	17742 Beach Blvd.	Huntington Beach	Beach Medical Associates Center, 17742 Beach Blvd. lateral sewer pipe.	Sewer clean out cover	Plugged sewer lateral.	Roots and debris in the private sewer lateral. Plumber on 11/16/06 did not get all roots cut and removed from the sewer system.	Property Manager Erica Werner cell phone 949-683-7184.
11/28/06	2	Der Wagenmeister owner, Richard (949-633-8033);	98	0	0	200	722 West 16th St;	Costa Mesa, CA;	into Main Line, 400ft (Drop	PRIVATE PROPERTY SSO due to lack of backwater prevention device - property is 10° below CMSD MH cover on W 16th St;	Pushed in tree roots from private propert lateral;	Pushed in tree roots from private property lateral;	Der Wagenmeister owner, Richard (949-633-8033) reporte PRIVATE SSO to CMSD; CMSD Crew unable to enter private property to Vactor SSO and RinseWater. Wastewater flowed with owner Rinsewater 250t to SD. Unrecoverable; PRIVATE PROPERTY SSO due to lack of backwater prevention device – property is 10° below CMSD MH cover on W 16th St; CMSD recommended property owner install a backwater prevention device in lateral line to prevent future backups on private property. CCTV lateral, and remove the four trees directly over the private lateral line; Photographs were taken and are attached;

12/1/06	2	Private	10	40	0	0	415 Old Newport Blvd.	Newport Beach	Lateral	Lateral	Roots from the lateral before the CMSD mainline.	See Remarks	Call for hydroflusher and vactor built erm at private storm drain box and set up vactor. Beamed storm rain box and used hydro to flush curb and gutter to storm drain at Hospital Road to Newport Bivd. returend to parking lot and vacumed at private storm drain box until plumber arrived and cleared the blockage. Used high pressure water to clean parking lot and washed to vacuume.
Totals	68		50,169	23,472	21,881	16,344							
Debris													
4/4/02	3	Private Property	25	0	0	25	1634 La Loma Dr.	Santa Ana	4" Sewer Line	Cleanout	Blockage	Misc. debris	NA
7/6/02	3	Rich Darling - Private Property	90	60	450	0	16490 Bolsa Chica Street	Huntington Beach	In the parking lot at 16490 Bolsa Chica Street.	Clean Out	Debris	Debris built up in the line, causing the blockage.	Statements were obtained from employee's of Jon's Coffee Shop. Line was cleared before City crews arrived.
7/10/02	3	Private	480	20	0	0	25521 Commercenter	Lake Forest	n/a	n/a	Construction debris	Construction debris	
8/4/02	3	Brea	200	200	250	0	650 Tamarack	Brea	Sewer	Manhole	paper products	NA	The property management and Larry honeybourne from OC Health dept were on site at time of the sewer stoppage. Apartment management phone # 714.990.0150
8/14/02	3	Gas Station	12	12	20	0	20002 Beach Blvd.	Huntington Beach	In the sidewalk alongside 20002 Beach Blvd	Clean Out	Debris	A gas station sewer line had become plugged by paper towels.	
8/16/02	3	La Palma Hospital, private property	0	0	0	0	7901 Walker Street	La Palma	Private lateral	Manhole	Unknown blockage on private property	N/A	Private sewer lateral backed up and vented out of a manhole on private property. Sewage flowed onto City gutter and a small amount of sewage entered the storm drain. City of La Palma Public Works Duty man responded and contained spill. City staff notified maintenace dept from La Palma Hospital to have plumber jet private sewer lateral. Advised to call RL Walker for cleanup.
8/18/02	3	Private	2250	10	25	0	4752 Pearce Street	Huntington Beach	In front of 4752 Pearce Street.	Clean Out	Debris, Blockage	Blockage caused by paper in line. Problem started after a recent slip lining project, according to residents.	Orange County Health, Michael Fennessy stated he recovered samples of affected waters.
11/19/02	3	Private Property Owner	0	42	122	0	2046 E Wilshire Ave	Fullerton	Private Lateral	Private 4° lateral cleanout	Toilet Debri	Toilet Debri	Jorge Gonzalez, acting sanitation specialist observed sewage around lateral cleanout. Cleanout was not overflowing at the time. Advised resident to call private plumber. Dy crew washed down and vacuumed area and returned all sewage to sewer system.
12/2/02	3	Private Property	100	10	110	90	2300 Main Street, east of Von Karman	Irvine	Private Lateral Sewer	Clean out	Blockage from Misc debris	N/A	N/A
1/2/03	3	PRIVATE PROPERTY OWNER	150	150	0	0	7326 CERRITOS AVENUE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE - PLASTIC BAGS, PATCHING COMPOUND, HEAVY GREASE	n/a	n/a
1/20/03	3	Private	3	0	0	0	6692 Ridge Park Rd.	Newport Beach	n/a	n/a	Paper	Paper	

1/28/03	3	Florida Gardens Apartments	50	30	45	20	18832 Florida	Huntington Beach	18832 Florida	Cleanout	Lack of Maintenance	Lack of Maintenance - Blockag cause by debris and Toilet Paper	None
3/27/03	3	Private	0	0	0	0	20 Goodyear	Irvine	n/a	n/a	Rocks	Rocks	
3/28/03	3	Private Property	0	0	0	0	1777 MITCHELL	Tustin	Private Sewer line	Manhole	Blockage Misc. debris	N/A	N/A
4/17/03	3	Private Property	0	0	0	0	13071 ST MARK ST	Santa Ana	Private lateral	Private Clean out	Blockage Misc. debris	N/A	N/A
5/7/03	3	700 N. Valley Street	200	20	30	200	700 N. Brookhurst Street	Anaheim	On Gramercy Avenue, east of Brookhurst Street	Private sewer clean ou at Mobile Gas Station	Paper towels obstructing the flow.	Paper towels were obstructing the sewer line which caused the overflow.	The owner of the Mobile Gas station, Morteza Yassini stated there was a small flow spilling from the clean out on 5/5/03 at 11 p.m. At the time, he assumed it was just water since the clean out had a lid that stated "Water" on it. Operations Crew Supervisor, Clean Bowers arrived on site at approximately 145 p.m., assessed the situation and set up all necessary precautions prior to a crew arriving. By 2:10 p.m. the line was clear and overflow was corrected.
5/12/03	3	8265 Maureen Condominium Complex	0	30	0	0	8265 Maureen Midway City	Midway City	cleanout	cleanout	debris	debris on private property	Spill reported to District by property management company. Spill on private property.
5/15/03	3	Private Property	0	0	0	0	HIDEAWAY DR. & NEWPORT BLVD.	Unincorporated County of Orange	Lateral		Blockage Misc. debris	N/A	NA
6/18/03	3	Private Party	0	400	60	0	409 N. Jeanine Drive	Anaheim	Near 409 N. Jeanine Drive	Private cleanout	Trash / Debris	Debris blocking the flow of sewer line.	The City of Anaheim responded to assist in the containment of the spill from a private clean-out. Sewage did not enter the storm drain.
7/17/03	3	Private Property: Paradise Pier Hotel 1717 Harbor Boulevard	100	200	1000	100	1717 Disneyland Drive	Anaheim	Near 1717 Disneyland Drive	Private Cleanout	Paper Towels	Overflow caused by buildup of paper towels in sewer line.	Unusual situation as there are four (4) properties served by a single lateral. Based on observations it was clear the cause of the blockage was excessive grease. The only grease bearing operation is the Restaurant at 1258 S. State College Boulevard. However, because all four properties discharge to this line, the responsibility for the spill as well as the routine maintenance must be shared.
7/30/03	3	Private - Albertsons Inc	0	200	600	0	455 N State College Blvd	Fullerton	Private lateral	Private lateral cleanou in parking lot	Rags		Reynoso, Hernandez, Miller, Rangel, and supervisor Roseberry responded to report o sewer overflow in the parking lot of Sav-on. Original notification was made to City Fire Dept., who contained the spill in the gutter and notified the Police Dept (Rocco), who then notified Doug Reneau. Supervisor in the Strete Dept. Doug relayed message to Roseberry and crews were called out. Business was instructed not to use water. Property owner had private plumber respond to clear blockage. City crews washed down spill area and vacuumed all sewage and wash water and returned to sanitary sewer system. Property owner later video inspected the lateral line and is in process of repairing defect.
10/25/03	3	Seacliff Health Care Center	400	375	795	25	18811 Florida Street	Huntington Beach	Parking lot of Seacliff Health Care Center, 18811 Florida St.	Four inch clean out.	Debris clogged private lateral	Buildup of debris in line probably caused by insufficient maintenance.	
11/17/03	3	5665 E La Palma	2700	100	200	500	5665 E. La Palma Avenue	Anaheim	5665 E. La Palma Avenue	Private cleanout	Paper Towels	Paper towels obstructed the flow of the sanitary sewer line causing it to overflow.	The majority of the sewage remaining on the surface of the parking lot was collected during a washdown with the City's vactor truck. However, due to a misdiagnosis of where the spill outlet to the nearby channel, the washdown of the parking lot (intended clean "tracked sewage" and flush out remaining sewage in storm drain) this portion of the washdown was not collected.
12/12/03	3	Private property owner	0	125	200	0	1616 West Katella Avenue	Anaheim	1616 West Katella Avenue	Private Cleanout	Metal from broken grate		This incident started with a complaint of odor which was the result of flow coming from an outdoor trash compactor. The owner/operator of the compactor, Food 4 less, was required to stop this flow, and moved the compactor to do so. However, In moving It, they broke the grate which covered the sewer cleanout under the compactor, dropping metal into the lateral resulting in an obstruction and subsequently a sewer spill.
12/16/03	3	Private Property	0	7	257	0	11481 Skyline Drive	Santa Ana	4" Sewer Lateral	Clean out	Blockage, Misc. debris	N/A	NA

6/10/04	3	2349 W. La Paima Ave., Anaheim	10	40	500	0	2349 W. La Palma Ave.	Anaheim	2349 W. La Palma Ave.	Private Manhole	Sewer lateral offset	have offset the Sewer lateral,	Apparent delay in notification to RWQCB was due to the fact that the spill had apparently not left the site when City Staff arrived. However, after interviewing onsite personnel, it was discovered that the spill had left the site but the water was voluntaril shut of which stopped the spill and made it appear as if it had not left the site. The plumber that the private property owner hired not only shut of the the site. The plumber that the sever lateral. An offset was discovered and was thought to have been caused by a private stormdrain installation, completed over a year ago. This could not shown conclusively so the City performed repair.
7/13/04	3	Private Property	50	150	0	0	n/a	Orange	n/a	n/a	Paper	n/a	n/a
7/29/04	3	1743 S. Clementine (Extended Stay America)	260	1100	300	200	1742 S. Clementine Street	Anaheim	1742 S. Clementine Street	Private Manhole	Cloth and other debris	Cloth and debris clogged pipeline, causing sewage to overflow.	
9/9/04	3	Private	10	0	0	0	25361 Commerce Center Dr.	Lake Forest	n/a	n/a	Wood and concrete	Wood and concrete	
9/13/04	3	James Estrella - Facility Manager	5	10	10	0	1628 South Anaheim Way	Anaheim	1628 South Anaheim Way	Private cleanout	Foreign objects	Foreign objects clogged sewer line	The flow was intermittent resulting in an estimated rate of 10 gal/hr
9/21/04	з	Lincoln Inn, Kelly Erickson - Maint. Manager	100	0	100	0	2748 W. Lincoln Avenue	Anaheim	2748 W. Lincoln Avenue	Private cleanout	Feminine hygiene products	Feminine hygiene products gol lodged in line.	Hotel cleared blockage with their own equipment and proceeded to wash the spill into the onsite drop inlet before City Staff arrived onsite. Hotel Management was informed that the spill had to be contained onsite and City had to be contacted in the event of a spill. This requirement will be reiterated in the Compliance Order.
9/21/04	3	Private Property	0	400	0	0	15701 TUSTIN VILLAGE WAY	Unincorporated County of Orange	4" clean out	Clean out	Blockage	Misc. debris	CITY OF TUSTIN TOOK PHOTOS & WILL FORWARD THEM TO OCSD. TOTAL SPILL LESS THAN 1,000 GALLONS PER FIELD OBSERVATION.
12/20/04	3	Private Property	0	0	0	0	2355 MAIN ST	Irvine	U	Manhole	Blockage	Other Debris	NA
12/21/04	3	Ron Marshall, Manager of Mr. Stox restaurant	188	100	400	0	1105 E. Katella Avenue	Anaheim	1105 E. Katella Avenue	Private cleanout	Paper Towels	Paper Towels blocked pipeline causing sewage to overflow.	OCHCA visited the location to determine if there were any issues inside the restaurant
12/30/04	3	Private Property	0	0	0	0	10120 SUNRISE LN	Unincorporated County of Orange	4"	Clean-out	Blockage	Other Debris	NA
1/3/05	3	Private Property	0	0	0	0	1462 FOOTHILL BLVD	Santa Ana	4" Clean out	Clean out	Blockage	Misc. debris	NA
1/13/05	3	Wonson Kim, owner, Fullerton Inn Hotel	700	200	3000	0	2601 W Orangethorpe - Fullerton Inn Hotel	Fullerton	Private lateral @ 2601 W Orangethorpe	Private lateral cleanou	r Debris, paper	City lateral rod crew cleared unknown blockage from upstream	City sewer crews noticed sewage flow from driveway at small hotel. City crews set up vactor vacuum at downstream catch basin while waiting for additional crews. City rodding crew and additional combo truck responde, cleared private lateral, washed down and swept entire path along Orangethorpe and Magnolia to remove all debrs. C crew estimates approximately 700 gallons entered catch basin on Magnolia Ave. before arrival of vactor crew due to intermittent flow during the night hours. City crews Reynoso and Lambaren spoke with owner, explained the seriousness of the situation. The owner stated he called a plumber at 10:00pm in the evening and plumber never responded, so he valied until moming and called another plumber. The plumber arriv shortly after City crews arrived. Owner stated he didn't realize the seriousness of the situation. Owner was informed to call the City for containment assistance in the future start a routine maintenance program, and consider CCTV on lateral.
5/19/05	3	Private Property	0	60	0	0	7758 Knott Ave	Buena Park	n/a	n/a	Paper	n/a	r/a
5/23/05	3	Private Property	0	15	15	0	1451 NISSON RD	Unincorporated County of Orange	Septic Tank	Manhole	Blockage	Misc. debris	NA
5/27/05	3	Private	0	20	200	200	1731 W. Katella Ave. Anaheim	Anaheim	1731 Katella Ave Anaheim	Private clean out	Paper towels and grease	Paper towels and grease caused obstruction.	
5/29/05	3	Private	3000	1200	200	200	801 N. Loara Street Anaheim	Anaheim	801 N. Loara Street Anaheim	Private clean out	Rags	Blockage caused by rags clogging lateral line.	
7/23/05	3	Private	0	4	0	0	1016 IRVINE AVENUE	NEWPORT BEACH	N/A	N/A	PAPER	PARKING LOT/DRIVEWAY	NA

7/24/05	3	Private	50	0	0	0	19211 Jasper Hill Rd.	Portola Hills	Cleanout	Cleanout	Asphalt debris	Asphalt blocked line-cleanout overflowed	
8/2/05	3	Private lateral Tony Romas	20	100	200	0	1300 S Harbor Blvd	Fullerton	Private lateral	lateral cleanout	Paper		The City's emergency crew responded to report of sso from private deanout. City crew contained sewage at storm drain, dispatched sewer on call crews. Restaurant called private plumber. There was no overflow inside facility. City crews washed down and vacuumed all sewage. Private plumber cleared blockage of paper in lateral line. The City's FOG control inspector will follow up at FSE.
8/9/05	3	Private	0	50	0	0	1101 N. BAYFRONT	NEWPORT BEACH	N/A	N/A	PAPER	ALLEYWAYS	NA
11/14/05	3	Private Property	0	0	0	0	13502 SUSSEX PLACE	Unincorporated County of Orange	8-inch lateral	υ	Blockage	Misc. debris	None
2/2/06	3	Private	0	0	0	0	5175 Calzado	Laguna Woods	Private lateral	n/a	Calcium buildup	Calcium buildup in private residence lateral	Intermittent overflow occurring at cleanout only when homeowner used the water and was completely contained to drit area. District's staff used Hydrodeaner unit to break the blockage and cleaned small amount of debris around cleanout. Video inspection of lateral line revealed water deposit build up. Line was cleaned with chain cutter to remove all water deposits on 2 / 2 / 06.
2/7/06	3	Private	160	2000	1000	0	627 N. Eulid St.	Anaheim	627 N. Euclid St.	Private cleanout	Assumed to be grease and break, but discovered to be a metal disk	metal disk caused spill	The property manager, Jim Kirby, was very cooperative and responsive to the spill on February 7. He promised to have a sandbag barrier constructed at the drive entry whe the majority of the sewage left the property, in order to capture and contain any spills h the near future and prevent them from leaving the property. Additionally, the disk which likely was the cause of the recent spills should be removed within 48 hours.
2/23/06	3	Private	0	50	200	50	917 W. Lodge Ave.	Anaheim	917 W. Lodge Ave.	Private cleanout	Soap/sewer buildup	Soap/sewer buildup caused obstruction	Property manager called private plumber to clear obstruction. Plumber did not respond in a timely manner, resulting in the property manager and his assistant clearing the dra with own tools. City vactor onsite to washdown and dispose of waste water.
3/29/06		Private, Albertsons Corp, 1955 W North, Malrose Park, Illinois 60160 contact:Barbara Mott 708-492-3100	20	180	800	0	455 N State College Blvd (Sav On)	Fullerton	Private lateral	3 lateral cleanouts in parking lot	Debris	Plumber cleared approx 10° of thick substance from line	City crews responded to report of sewage in parking lot of Sav On at State College & Chapman Ave. Lateral cleanouts in parking lot were seeping with small amount of flow into gutter area down to cath basin. Flow was contained in parking lot with sandbage. City vactor crew was called for assistance with containment, private plumber was called by manager 0.5 av On. City crews remained on scene until pumber arised and dear very thick blockage in line with rodding equipment. City crews assisted plumber with jetting of problem area in line. City crews washed down and vacuumed sewage in parking lot and gutter areas. City contacted Sav On Corp office and recommended follow up activities to prevent future problems (see attachment).
5/10/06	3	Private	0	80	0	0	1365 Knollwood Circle	Anaheim	1365 Knollwood Circle	sample box	Lack of capacity and build up of fibers on sewer lateral	Lack of capacity caused obstruction	Sewer spills have been experienced at this location in the past, under similar circumstances. However, there has not been a spill in over three years.
9/9/06	3	PRIVATE FACILITY - South Coast Alcohol & Drug Program Facility;	25	25	100	25	2212 Placentia Ave;	Costa Mesa, CA;	PRIVATE lateral blocked with debris;	PRIVATE lateral blocked with debris;	PRIVATE lateral blocked with debris;	SSO flow from PRIVATE latera blocked with debris from 8-unit apt complex to rear facility sump pump operated intermittently;	City of Costa Mesa Comm Center called SSO in to District Maintenance Supervisor; District Maint Supervisor blocked Storm Drain (SD) @ 1534 hrs and turned off facility sump pump; Costa Mesa Public Services vactored public right of way (ROW) and returned/disposed of SSO into District sanitary sever system; District called C&R Drains to clear PRIVATE lateral; Up to 25 gallons of SSO was contained in the SD and evaporated; Photographs were taken and are attached;
9/26/06	3	Private Property	0	0	0	0	13626 ESTERO CIR	Tustin	Clean out	Clean out	Blockage	Misc. debris	Notifications were made to Control One and RWQCB. Corwin Brown from Health Care was asked to assist in speaking with Apartment Complex Manager so they would call the plumber.
9/28/06	3	Nora Balikciagli, owner of the Moble Gas Station	25	25	45	0	2002 Beach Blvd.	Huntington Beach	Lateral sewer line of 2002 Beach Blvd.	Private sewer clean ou cover.	Debris blockage	2002 Beach Blvd. Is a gas station. It is suspected that vandals put to much debris into the toilets.	
11/12/06	3	Private Property	0	0	0	0	1192 MITCHELL	Tustin	24 inch	Manhole	Blockage	Misc. debris	Dindo made regulatory notifications after receiving the spill notification made at 1130 hour. John Ralis (OCHCA) was asked to assist by speaking with apartment manager to call a plumber. RDMD was also notified by Control One.

12/19/06	3	Private Property owner, CVS Pharmacy	100	200	All	0	455 N State College Bivd	Fullerton	Private lateral	Lateral cleanout	Lateral defect, debris	6" lateral from building connects to old 4" lateral at sidewalk area creating offset	City crews responded to private overflow in CVS (formerly Sav-On) parking lot. Water crew responded to shu off water service to stop overflow. Store manager was not aware of problem prior to our arrival. Private plumber was dispatched and responded to clear blockage. City crews washed down and vacuumed all sewage from guiter and street, and contained overflow in parking lot. Private cleanup service was called by C to clean parking lot. Saver staff requested response by OCHA to record incident due to several prior incidents at this facility. City staff will notify CVS and require immediate repair of lateral line
12/20/06	3	Private	100	200	0	0	CHAPMAN/STATE COLLEGE	FULLERTON	N/A	N/A	CONSTRUCTION DEBRIS	PARKING LOT CLEAN OUT TO STREET, CURB AND GUTTER TO STORM DRAIN TO FULLERTON CHANNEL.	NA
Totals	57		11,583	8,200	11,234	1,635							
Grease/Roots													
6/24/02	4	Private Property	100	250	450	0	510 E. Chestnut Avenue	Santa Ana	Private Property	Clean out	Grease and Roots: Blockage on sewer lateral was caused by grease and tree roots.	Blockage on sewer lateral was caused by grease and tree roots.	
9/18/02	4	Private Property	0	0	0	0	6234 Industrial Way Westminster	Westminster			grease & roots	grease & roots on private property	
11/5/02	4	Mark Montgomery	800	350	450	450	21372 Brookhurst	Huntington Beach	Southwest Corner of Property	Sewer Cleanout	Debris, Roots, Grease	Possible Lack of Maintenance, Debris and Grease	None
12/3/02	4	Private	150	100	0	0	Big Canyon Golf Course	Newport Beach	n/a	n/a	Roots and grease	See Remarks	Overflow on Big Canyon Golf Course
12/28/02	4	Private: Property Management Group, 1398 N. Mako Ln.	425	75	275	425	1398 N. Mako Lane	Anaheim	Near 1398 N. Mako Lane	Manhole	Grease and Roots	Grease and roots blocking flow	Property Management Group, Jerry O'Donnell, (714) 408-3469 headquarters.
10/30/03	4	Private Property	0	100	0	0	n/a	Orange	n/a	n/a	Grease/Roots/Pape	n/a	n/a
12/15/03	4	Tritz Professional Management Services Inc.	943	470	570	473	4171 Andros	Huntington Beach	Private eight-inch sewer line at 4171 Andros Ave.	Private sewer manhole	Grease and roots	Grease and roots caused the private homeowners sewer system to clog.	
12/11/04	4	Woo Chung. 9944 Garden Grove Blvd., Garden Grove	20	80	100	0	2801 W. Ball Road	Anaheim	2801 W. Ball Road	Private Cleanouts	Grease	Roots blocked pipeline, causin sewage to overflow.	Apparently very little sewage actually reached the storm drain as it tended to pond on- site. Tenants informed us that a plumber had worked at this location before and removed a large amount of roots. However, on this occasion hard evidence of discharging grease to the sewer line was the primary factor for the problem.
1/25/05	4	Victoria Townhouse Apartments	1050	7500	500	0	2256 W. Lincoln Ave.	Anaheim	2256 W. Lincoln Ave.	Private Manhole	Grease & Roots	Roots and grease blocked pipeline, causing sewage to overflow.	Property owner called private plumber at 2:00 PM but did not show up until 6:00 PM. City crews cleared the obstruction at 5:45 PM. Plumber would not have been able to clear blockage anyway, since he did not have the equipment to ds so. Attached are two volume calculation forms, which use two different methods to arrive at virtually the same estimate of flow: 1800 gallons per hour. Property owner is currently disputing his responsibility for this spill.
4/25/05	4	Private Property	0	0	0	0	515-523 HEATHER AVE	La Habra	n/a	n/a	Grease & Roots	n/a	
10/20/05	4	Private	29	50	0	0	17199 BLUEWATER LANE	HUNTINGTON BEACH	N/A	N/A	ROOTS & GREASE	MANHOLE TO SIDEWALK TO BULKHEAD TO BAY WATER	N/A

11/14/05	4	Private Property	0	100	0	0	426 W. Almond Ave.	Orange	n/a	Building basement and Railroad right of way	Grease/Roots	Building basement and Railroad right of way	n/a
2/17/06	4	Lordon Management Company (626-967-7921, x3316), @ 1275 Center Court Drive, Covina, CA 91724; FAX: 626- 966-3918)	ο;	82	132	0;	760 West 16th St;	Costa Mesa, CA	Grease, roots, rocks and debris blocked private later in a parking for causing overflow from a cleanout;	Grease, roots, rocks and debris blocked aprivate lateral in a parking lot causing overflow from an uncapped cleanout;	Grease, roots, rock and debris blocked private lateral in a parking lot causing overflow from an uncapped cleanout;	blocked private lateral in a parking lot causing overflow from an uncapped cleanout;	Visually estimated 82 gallon SSO flowed from one private property cleanout: Estimate Some SSO trickled into Storm Drain (SD) used as a containment vessel; Recovered/Vactored 82 gallons; District maintenance supervisor and fine cleaning contractor, National Plant Services, Inc., dammed SD and vactored SSO and fine of where and disposed of the wastewater in the District similary server system; Private plants and debt blocked properties in the plant services in the plants and debt blocked properties and the aparting for cleaning time; Greates, notot, roots
9/8/06	4	Earl Benton, 20271 Meander Ln., HB 92646	5	5	105	0	4932 Kona Dr.	Huntington Beach	Lateral sewer line of 4932 Kona Dr.	Sewer discharge pipe in the laundry room.	Grease and root blockage	Grease and root blockage of private sewer line.	From the looks of this four unit complex the owner, Eral Benton, does not maintain the property very well.
9/15/06	4	FV	20	20	0	0	18774 Brookhurst Street	Fountain Valley	roots in private lateral		grease	roots in private lateral	NA
12/30/06	4	Private	100	2000	2000	2000	2704 W. Ball Road	Anaheim	lateral from last manhole in complex to street	Private cleanout	grease and perhaps roots or a break	Grease alone or in conjunction with a break or roots caused th obstruction	
totals	16		3,642	11,182	4,582	3,348							
Structural													
8/9/02	5	Private	0	0	0	0	5465 Alton Pkwy.	Irvine	n/a	n/a	Illegal connection to storm drain	Illegal connection to storm drain	
8/29/02	5	Jimni Service	528	100	50	0	20896 Seacoast	Huntington Beach	At the intersection of Beachcomber and Coastwatch	Manhole	Vandalism	Someone turned off power to pump station, causing the overflow.	Jimni Service cleaned up the spill and checked the pump station.
9/18/02	5	Private: Lusardi Development	0	50	50	0	Harbor Blvd. N/O Ball Rd.	Anaheim	Sewer line break at Gianne Electric, Harbor Blvd. N/O Ball Rd.	ll sewer line	Break in sewer line	Sewer line break at Giannelli Electric	
9/26/02	5	Private: Seris Regio Group	200	20	70	200	2050 Winston Rd.	Anaheim	cleanout near center of driv area at 2050 Winston Rd.	e clean out onsite	break in the private sewer lateral	broken lateral in private sewer	Property owner was notified of spill at 2:00 on 9/26/02 and was told the line would have to be cleaned immediately. Private plumber did not show up until the 27th. Due to difficulties cleaning the line it was determined there was a break in the private sewer lateral. Work to repair this line was completed on the 28th.
9/28/02	5	Private	0	0	0	0	6 LOS OLIVOS	IRVINE	N/A	LINE BREAK	LINE BREAK	STREET CURB AND GUTTER, STORM DRAIN	May be R-9
12/3/02	5	Richard Darling	180	90	190	90	16490 Bolsa Chica	Huntington Beach	16490 Bolsa Chica	Cleanout in Parking Lot	Unknown at the time, turned out to be a separation in the pipe.	Unknown at the time, turned ou to be a separation in the pipe.	None
12/4/02	5	Richard Darling	480	400	490	90	16490 Bolsa Chica	Huntington Beach	16490 Bolsa Chica	Cleanout in Parking Lot	Unknown at the time, turned out to be a separation in the pipe.	Unknown at the time, turned ou to be a separation in the pipe.	None
1/18/03	5	Private	4680	0	0	0	WINDROW COMMUNITY PARK	IRVINE	N/A	LINE BREAK	LINE BREAK	STREET, CURB, GUTTER AND INTO STORM DRAIN	May be R-9
5/19/03	5	Private Property	50	0	0	0	n/a	Orange	n/a	Pump Malfunct.	Pump Malfunct.	n/a	n/a

8/1/03	5	Private	2500	0	0	0	MAIN & MAC ARTHUR	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN TO LANE CHANNEL.	
8/3/03	5	Private	180	0	0	0	#7 ASPEN TREE LANE	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN TO SAN JOAQUIN CHANNEL.	May be R-9
8/25/03	5	Private Party	200	50	1000	0	2508 West Chain Street	Anaheim	Near 2508 West Chain Street	Sinkhole in Street	Break	Pipe failure allowed sewage to seep into the ground	Report of possible sinkhole first came to the City at 4:45 PM on August 25, 2003. Subsequent investigation on August 27 indicated a water leak, however further investigation on August 28 revealed the water was in fact sewage. The sewage in the sinkhole was vacuumed by the City, but the hole had to be widened by the City's contractor to determine the cause was pipe failure (not contractor caused). Sewage likely continued flowing to the sewer due to dirt failing into the lateral was carried away create the sinkhole. Some sewage seeped into the ground.
9/15/03	5	Private	19	20	0	0	2451 ELDEN AVE	COSTA MESA	N/A	LINE BREAK	LINE BREAK	STREET, CURB AND GUTTER AND INTO STORM DRAIN.	NA
10/14/03	5	Private	0	60	0	0	701 OCEAN	SEAL BEACH	N/A	LINE BREAK	LINE BREAK	ALL SEWAGE WAS CONTAINED ON SITE AND RETURNED TO SEWER.	N/A
10/31/03	5	Private Property	0	50	50	0	2000 JAMBOREE RD	Newport Beach	8-inch force main on private property	Force main	Failed pipe	8-inch force main failure	This spill began on 10/31/2003 and after initial containment on the evening of 10/31/2003, the spill resurfaced on 11/01/2003. CCSD responded to spill on 11/01/2003 to find that the cause of the spill was a broken 3-inch force main line. Containment was set by the City of Newport Beach and then CCSD advised the private property owner (Merit Property Management) that a vacuum outfit should be notified to vacuum up the wet well to stop the spill until the repairs are complete.
11/1/03	5	Private	0	1,000	0	0	McArthur Blvd.	Newport Beach	Private force main	Private force main	Private forcemain was broken	See Remarks	Private force main was broken Located Big Canyon Villas HOA.
12/5/03	5	Private	0	75	0	0	CAMPUS & CARLSON	IRVINE	N/A	LINE BREAK	LINE BREAK	ALL SEWAGE WAS CONTAINED.	NA
2/2/04	5	Dr. Wayne Brown rental property owner.	100	100	150	0	214 9th St. in alley	Huntington Beach	Private homeowners lateral at 214 9th St.	Private sewer lateral.	Broken sewer lateral.	Private broken sewer lateral caved in soil around it causing blockage to overflow onto publi property.	
2/9/04	5	Seaside Village Condo. Homeowners Association	1512	1512	1612	0	2100 Admiral Lane	Huntington Beach	1213 Admiral Lane, a privat sewer lift station.	Private sewer manhole	Problems with private lift station.	Private lift station was not working properly causing sewage to spill out of three manholes.	This condo complex has had problems before with their sewer lift station. Each time they say problem is fixed. Mr. Billard said the sewage had been spilling out of the manholes for three days.
4/13/04	5	Private	3000	0	0	0	NEWPORT COAST DR	NEWPORT BEACH	N/A	LINE BREAK	LINE BREAK	STORM DRAIN	N/A
4/29/04	5	Orange County Head Start, INC.	5	5	0	0	14422Hammon Ln.	Huntington Beach	Drain pipe connecting to Grease Interceptor.	Grease Interceptor	Broken drain pipe.	Broken drain pipe connecting to Grease Interceptor.	Drain pipe for grease interceptor in the parking lot broke and caused the asphalt to care in. West Duke Plumbing took care of the pipe repair and clean up.
7/21/04	5	Private Property	150	50	0	0	n/a	Orange	n/a	Broken Line	Broken Line	n/a	n/a
8/29/04	5	Private	9450	0	0	0	DEWBERRY / SANDBURG	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN.	NA
11/5/04	5	Private	150	0	0	0	STANFORD AT NELSON	GARDEN GROVE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN.	N/A
11/17/04	5	Private	0	50	0	0	108 30TH STREET	NEWPORT BEACH	N/A	LINE BREAK	LINE BREAK	ALL SEWAGE WAS RECOVERED.	N/A
3/22/05	5	Private Property	0	4	0	0	n/a	Orange	n/a	Cleanout Cap Rmvd	Cleanout Cap Rmvc	n/a	n/a
4/29/05	5	Private	100	0	0	0	6300 REGIO	BUENA PARK	N/A	LINE BREAK	LINE BREAK	STORM DRAIN.	NA
5/27/05	5	Watt Properties Management Company	25	25	25	0	8965 Atlanta Ave.	Huntington Beach	Private sewer pipe.	Sewer cleanout locater on private property.	Broken sewer pipe.	Broken sewer pipe at an isolation valve located in a shopping center.	All storm water in this area is being diverted into the sewer system.

6/10/05	5	Private	100	800	200	200	537 N. Magnolia Ave.	Anaheim	537 N. Magnolia Ave.	Private clean out and private manhole	Pump shut down	Pump shut down caused obstruction	The property owner/manager contacted a pump company (Orange County Pumping) who corrected the problem with the pump station. The area in front of the building was washed by the City staff, however, other areas along the side of the building-not- accessable
8/5/05	5	Private	65	0	0	0	8699 HILLCREST	BUENA PARK	N/A	N/A	CLEAN-OUT CAP MISSING	CLEAR WATER TO STORM DRAIN.	NA
8/16/05	5	Private	20	0	0	0	6503 Quail Hill	Irvine	Effluent line	Effluent line	Plug	Plug left in effluent line from grease trap	
9/6/05	5	Private Property	500	1000	0	0	n/a	Orange	n/a	Cleanout Cap Rmvd	Cleanout Cap Rmvc	ln/a	n/a
9/7/05	5	Private	2340	0	0	0	30 SCENIC BLUFF	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN TO CREEK	May be R-9 Gate guarded community.
10/25/05	5	Private	20	10	0	0	behind 2235 Pacific Dr	Newport Beach	Broken pipe	Broken pipe	Broken pipe on the hillside that was discharging sewage	See Remarks	Setup beam and vactor on Bayside Dr, used two flagmen for traffic control. Contacter Michael Bayer at 2235 Pacific Dr. to advise him he had a problem.
11/8/05	5	Private	0	0	0	0	20142 MCKINLEY LANE	HUNTINGTON BEACH	N/A	LINE BREAK	LINE BREAK	SOAKED INTO SOIL	NA
12/20/05	5	Private	0	0	0	0	2208 DELAWARE	HUNTINGTON BEACH	N/A	LINE BREAK	LINE BREAK	N/A	NA
1/10/06	5	Private	0	0	0	0	1200 PACIFIC COAST HIGHWAY	HUNTINGTON BEACH	N/A	LINE BREAK	LINE BREAK	N/A	NA
1/25/06	5	Private Property	0	3	0	0	n/a	Orange	n/a	Cleanout Cap Rmvd	Cleanout Cap Rmvc	in/a	n/a
2/26/06	5	Private	40	40	500	0	1040 N. Magnolia Ave.	Anaheim	1040 N. Magnolia Ave.	Private cleanout	Break	Break caused obstruction	The cause of the spill is still under investigation. The restaurant owner, who was also the reporting party, did all that was possible at the time to address the spill and investigate the problem, including hiring 2 separate plumbers. Despite having one
4/24/06	5	Private	0	400	0	0	23691 ROCKFIELD	LAKE FOREST	N/A	LINE BREAK	LINE BREAK	SEWAGE CONTAINED ON SITE.	May be R-9
5/8/06	5	Private	0	300	0	0	23691 ROCKFIELD	LAKE FOREST	N/A	LINE BREAK	LINE BREAK	SEWAGE CONTAINED ON SITE.	May be R-9
5/9/06	5	Private - Sav On/Albertsons Store # 9598	0	20	400	0	455 N State College	Fullerton	Private lateral	Lateral cleanout in parking lot	6" lateral connection to 4" lateral cleanou wye		Correspondence with Sav On has been ongoing due to a previous overflow. Property
5/22/06	5	PetSmart Store - Private party	25	25	25		620 W 17th St - PetSmart Store lateral cleanout;	Costa Mesa, CA;	Private on-site PetSmart lift station failed - well containe large volume of wastewater;	failed - well contained	Private on-site PetSmart lift station failed - well contained large volume of wastewater;	Private on-site PetSmart lift station failed - well contained large volume of wastewater;	Visual estimate of wastewater in SD and from path from the PetSmart cleanout to the SD and the curb: 15 gallons lost to SD: 10 gallons evaporated; 25 gallons vactored; Private on-site PetSmart lift station failed - well contained large volume of wastewater; PetSmart Manager (Phill Morgenthaler (949-764-9277) arranged for plumbers to repair station and clean out private lift station well/Manager closed the business for the next day to ensure repairs were completed without additional SSO occurrence; Manager informed to maintain private lift station on a regular maintenance program; SSO vactored and disposed of into the CMSD sanitary sewer system; Photographs were taken and are attached;
5/27/06	5	Private	0	0	0	0	10001 N. FLOWER STREET	SANTA ANA	N/A	LINE BREAK	LINE BREAK	CONTAINED ON SPILL LOCATION	N/A

6/8/06	5	Private	10	10	15	10	2936 W. Lincoln Ave., #3	Anaheim	2936 W. Lincoln Ave., #3	Private cleanout	break	Break casued obstruction	The discharge from this property was actually from two sources. One was the klichen of the house at the southwest corner of the property, and the other was from regular parking lot and loading dock washout from the northern portion of the property, which flows through the back yard of the residential unit.
6/12/06	5	Private	200	1800	0	0	3101 W. PACIFIC COAST HIGHWAY	NEWPORT BEACH	N/A	N/A	PUMP STATION FAILURE	STORM DRAIN -> NEWPORT BAY AT "MARINER MILE" MARINA DOCKS (3101 W. COAST HIGHWAY)	NA
6/14/06	5	Private	0	0	0	0	10631 LOS ALAMITOS	LOS ALAMITOS	N/A	LINE BREAK	LINE BREAK	SEWAGE DISCHARGED SUBSURFACE AND INTO DECORATIVE KOI POND.	NA
6/23/06	5	PRIVATE SSO at Apartment complex at 2257 Maple St;	0	10	20	0	2257 Maple Street;	Costa Mesa, CA;	Small SSO flow from uncapped private cleanout ir a 4-plex;	Small SSO flow from uncapped private cleanout in a 4-plex;	Small SSO flow from uncapped private cleanout in a 4-plex;	Small SSO flow from uncappe private cleanout in a 4-plex;	PRIVATE SSO at Apartment complex at 2257 Maple St; City of Costa Mesa and CMSD Maintenance Supervisor blocked Storm Drain (SD) around the corner from the driveway site: Commercial pubmer vacuumed SSO and rises water and disposed of the wastewater in a MH in the CMSD sanitary server system; Visual estimate of shalt pooled wastewater in private driveway and from path from the Cleanout (CO) to the curb: Small SSO flow from uncapped private cleanout in a 4-plex; Photos were taken and are attached;
6/26/06	5	Restaurant at the end of the Newport Pier	0	0	0	0	Restaurant at the end of the Newport Pier	Newport Beach	Pipe joint	Pipe hangers holding ABS piping under the pier failed due to rust & corrosion, the piping dropped & a joint pulled apart.	Pipe joint separation	See Remarks	City of Newport Beach lift station crew turned water off to Restaurant immediately and advised restaurant manager of the problem. Utilities office called Environmental Health Services and RWQCB.
7/12/06	5	PRIVATE SSO from PRIVATE 4" force main from PRIVATE lift station at 960 West 16th St;	2	15	65	2	960 West 16th St;	Costa Mesa, CA;	PRIVATE lift station 4* force main on PRIVATE property found to have a 3/16* hole in the plastic underground pipe;	PRIVATE lift station 4" force main on PRIVATE property found to have a 3/16" hole in the plastic underground pipe;	PRIVATE lift station 4* force mair on PRIVATE property found to have a 3/16* hole in the plastic underground pipe;	PRIVATE lift station 4* force main on PRIVATE property found to have 3/16* hole in the underground pipe; Undetermined cause for the 3/16* hole;	PRIVATE SSD accurred from PRIVATE 4" force main from PRIVATE lift station at 960 West 16th St; Mesa Consolidate Water District dammed Storm Drain (SD) while excavating potential water line leak and plugged 4" force main hole with a bolt; City Newport Beach (CNB) crew vacuunde SSD and rinse water and disposed of the wastewater in the CNB sanitary sever system." (Sau elsinate of forking and poloed wastewater from PRIVATE lift station 4" force main, PRIVATE lift station 4" force main nPRIVATE property found to have a 31°C hole in the plastic underground pipe; Estimated flow d15 galions over 1440 minutes – 01 gpm; City of Newport Beach (CNB) crew accumed SSD and fines water and disposed of the wastewater in the CNB sanitary sever system; Rescue Rooter (1-800-889-6956) repaired PRIVATE lift station 4" force main on PRIVATE property. Photographs were taken and are attacht
7/30/06	5	Private	220	120	100	0	1919 W. Coronet Ave	Anaheim	1919 W. Coronet Ave	Private cleanout	Break	Break caused obstruction	NA
11/6/06	5	Market Broiler Restaurant	500	500	800	0	20111 Brookhurst Street	Huntington Beach	Broken sewer pipe three fee under the concrete slab of the Market Broiler building.	Concrete slab and sewer clean out cover.	Broken sewer pipe under the concrete slab.	Old sewer line had a break in i	
11/30/06	5	Private	400	500	500	0	1830 W. Romneya Drive	Anaheim	Pump Station at N/W corner of Euclid and Romneya	Private manhole	pump station failure	A sensor which monitors the level of sewage in the wet well failed	This was an unusual spill as it was caused by a failure of a private pump station. This failure is unlikely to occur again, however we will require assurances from the owner/operator to ensure this.
12/11/06	5	Casa Linda Condos & Montero Planning	350	0	0	0	300 E. Chestnut Street, 92701	Santa Ana	At pump lift station.	Pump lift station	Private lift station	The City responded to check City sewer main and found no problems. The spill was coming from the parking garag at 300 E. Chestnut. Montero Plumbing was working on the lift station pumps.	None
12/28/06	5	Private	200	400	200	0	537 N. Magnolia Ave.	Anaheim	Pump Station Failure	Private manhole	pump station failure	pumps are believed to have burned out	This was an unusual spill since it is the third at this location, however, since it was caused by something different each time it has occurred, the order will focus on items that may not have been satisfied in previous orders and items that would help prevent future recurrances of this spill.
Totals	55		28,501	9,614	6,512	617							
Totals	689		208,254	149,394	129,007	49,435							

APPENDIX D

Modified Master Private Property Spills 2002–2006 Sorted by Property Type

Date SSO is First Reported to Responding Agency	Туре	Responsible Party	SSO Volume Lost (Gallons)	Recovered SSO Volume (Gallons)	Recovered wash Water & Sewage Contaminated Water Volume	Lost Wash Water & Sewage Contaminated Water Volume	Location of overflow: Street	Location of overflow: City	Location of potential blockage or problem point	Description of component from which spill occurred	Likely cause of SSO	Overflow Cause - Detailed Description	Remarks
Unkown													
4/15/02	0	Private Property	0	0	0	0	12622 Kingsview Rd.	Unincorporated County of Orange	4" Sewer Line	U	Blockage	U	NA
4/23/02	0	Private Property	1281	150	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a
7/10/02	0	Private	1215	1215	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/23/02	0	Private	98	98	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/30/02	0	Private	10	10	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/30/02	0	Private	150	150	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/30/02	0	Private	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/30/02	0	Private	450	120	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/30/02	0	Private	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/30/02	0	Private	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/31/02	0	Private	165	165	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
8/1/02	0	Private	50	50	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
9/16/02	0	Private	100	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
9/30/02	0	Private	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
9/30/02	0	Private	54	54	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
10/5/02	0	Private	30	30	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
10/17/02	0	Private	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
10/26/02	0	Private Property	2	0	0	0	12421 Mystic Lane	Unincorporated County of Orange	Sewer	Clean-out	N/A	N/A	STANDBY CHARLIE AMBRIZ RESPONDED. HE CHECKED OCSD LINES AND ALL WERE FLOWING NORMAL. HE DE'TERMINED THA'T SPILL BELONGED TO PRIVATE PROPERTY OWNER. THEY WERE NOTIFIED TO CALL A PLUMBER.
11/11/02	0	Private	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/23/02	0	Private Property	15	0	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
1/5/03	0	Private	50	50	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
1/6/03	0	Private Property	300	300	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a
1/6/03	0	Private Property	5	0	0	0	1621 FOOTHILL BLVD.	Unincorporated County of Orange	Private lateral line	Clean out	Unknown	N/A	Fences and location prevented OCSD staff from cleaning up the spill. Vacant lot property owner was unknown, staff told the neighbor who reported the spill to contact OCSD's Engineering Dept. to try and figure out who the owner is and contact them to repo
1/14/03	0	Private Property	0	0	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a
1/20/03	0	Private	3	0	0	0	6692 Ridge Park Rd.	Newport Beach	n/a	n/a	Paper	Paper	
1/23/03	0	Private	179	179	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	

	-										1		
1/27/03	0	Private Property	50	50	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a
1/29/03	0	Private	192	192	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
2/6/03	0	Private Property	2	0	0	0	Vacant lot between 1621 Foothill Blvd. and 1651 Foothil Blvd.	Unincorporated County of Orange	Private Lateral	Private Cleanout	Unknown	Unknown	NA
2/24/03	0	Private	75	75	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
3/7/03	0	Private	200	200	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
3/12/03	0	Private	15	15	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
4/29/03	0	Private Property	200	200	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
5/6/03	0	Private	10	10	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
5/19/03	0	Private Property	50	0	0	0	n/a	Orange	n/a	Pump Malfunct.	Pump Malfunct.	n/a	n/a
5/20/03	0	Private Property	0	30	0	0	n/a	Orange	n/a	n/a	Roots	n/a	n⁄a
6/6/03	0	Private	25	25	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
6/11/03	0	Private Property	35	0	75	95	11407 ARROYO AVE	Unincorporated County of Orange	8-inch private property lateral	manhole	Blockage Grease clog	N/A	The field report states that it did enter a storm drain. However, after talking to Victor Hermelin, he stated that it actually did not enter a storm drain. The spill had been contained in the gutter, which dreid up, so it was not recovered via vactor truck. Shoud remove OCSD logo's on covers from private property manholes.
6/30/03	0	Private Property	150	150	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
7/9/03	0	Private Property	0	0	0	0	11772 HIGH VIEW DRIVE	Unicorporated County o Orange	Private sewer line	Bathtub and toilet	U	U	OCSD line was running freely. No sewer spill in the area.
7/30/03	0	Private	110	110	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
8/13/03	0	Private Property	0	0	0	0	12523 HINTON WAY	Unicorporated County o Orange	Per Roy Parrino the problem was on Private Property and the problem stemmed from their clean-out. There was no spill, and the residents were told to contact a plumber and not to run any water.		N/A	N/A	None
8/20/03	0	Private Property	0	150	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
9/15/03	0	Private Property	150	100	0	0	n/a	Orange	n/a	n/a	Roots	n/a	n/a
9/28/03	0	Private	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
9/30/03	0	Private	5	5	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
10/13/03	0	Private	115	115	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
10/22/03	0	Private	0	180	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
10/28/03	0	Private Property	0	0	0	0	JAMBOREE RD.	Newport Beach	8-inch clean out on private property	Clean out	Grease, other and debris	N/A	NA
10/30/03	0	Private Property	0	100	0	0	n/a	Orange	n/a	n/a	Grease/Roots/Pape	n/a	n/a

10/30/03	0	Private	24	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/15/03	0	Private	55	55	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/25/03	0	Private Property	450	50	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a
12/22/03	0	Private	5	5	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
12/22/03	0	Private	12	12	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
1/21/04	0	Private	52	55	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
1/21/04	0	Private Property	0	100	0			Buena Park	n/a	n/a	n/a	n/a	n/a
							n/a						nva
2/19/04	0	Private	5	5	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
2/19/04	0	Private	50	50	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
2/19/04	0	Private	30	30	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
3/25/04	0	Private Property	25	225	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
4/13/04	0	Private	3000	0	0	0	NEWPORT COAST DR	NEWPORT BEACH	N/A	LINE BREAK	LINE BREAK	STORM DRAIN	N/A
5/17/04	0	Private Property	25	25	0	0	n/a	Orange	n/a	n/a	unknown	n/a	n/a
5/19/04	0	Private	10	10	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
6/23/04	0	Private Property	500	0	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
7/12/04	0	Private Property	100	50	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
7/12/04	0	Private	45	45	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
7/13/04	0	Private Property	50	150	0	0	n/a	Orange	n/a	n/a	Paper	n/a	n/a
7/17/04	0	Private Property	25	75	0	0	n/a	Orange	n/a	n/a	Grease/unknown	n/a	n/a
7/21/04	0	Private Property	150	50	0	0	n/a	Orange	n/a	Broken Line	Broken Line	n/a	n/a
8/4/04	0	Private	30	30	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
9/7/04	0	Private Property	0	0	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
9/22/04	0	Private Property	0	0	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
9/24/04	0	Private*	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	Private spill in Midway Sanitary District juristiction. GGSD crews were first responders and acted in a support role only.
10/8/04	0	Private	150	150	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
10/14/04	0	Private Property	50	25	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
10/26/04	0	Private Property	40	25	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
11/1/04	0	Private	22	22	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	

11/5/04	0	Private	110	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/10/04	0	Private	20	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/11/04	0	Private	100	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/12/04	0	Private	100	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/13/04	0	Private Property	25	225	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
11/13/04	0	Private	360	360	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/15/04	0	Private	150	150	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/19/04	0	Private	10	10	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
11/22/04	0	Private Property	0	0	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
12/10/04	0	Private	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
12/11/04	0	Private	150	150	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
12/13/04	0	Private Property	0	25	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
12/14/04	0	Private	100	100	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	Yes, but did not enter the storm drain channel. Contained at storm drain outlet to channel.
12/21/04	0	Private Property	100	150	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
12/29/04	0	Private Property	50	25	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
12/30/04	0	Private Property	0	0	0	0	10120 SUNRISE LN	Unincorporated County of Orange	4"	Clean-out	Blockage	Other Debris	NA
1/3/05	0	Private	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
1/14/05	0	Private Property	50	50	0	0	n/a	Orange		n/a	Grease	n/a	n/a
2/4/05	0	Private Property	0	0	0	0	1581 N. FOOTHILL BLVD	Unincorporated County of Orange	NA	GROUND	U	U	NA
3/12/05	0	Private Property	700	200	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
3/20/05	0	Private	631	631	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
3/22/05	0	Private Property	0	4	0	0	n/a	Orange	n/a	Cleanout Cap Rmvd	Cleanout Cap Rmvo	n/a	n/a
3/29/05	0	Private	175	175	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
4/1/05	0	Private Property	200	250	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
4/5/05	0	Private	2020	2020	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
4/13/05	0	Private Property	50	0	0	50	1505 CLEARVIEW LN	Unincorporated County of Orange	4"	Cleanout	Blockage	Root obstruction pushed in from connecting line	Private Property
5/13/05	0	Private	79	79	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	

										-			
5/30/05	0	Private	451	451	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
6/18/05	0	Private Property	100	0	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
7/11/05	0	Private Property	0	0	0	0	10072 FOX SPRING RD	Unincorporated County of Orange	υ	Septic tank	Other	Other	NA
8/17/05	0	Private Property	0	0	0	0	n/a	Orange	n/a	n/a	Grease/ Vandalism	n/a	n/a
9/6/05	0	Private Property	500	1000	0	0	n/a	Orange	n/a	Cleanout Cap Rmvd	Cleanout Cap Rmvo	in/a	n/a
9/13/05	0	Private Property	15	0	0	0	19511 HOLIDAY LN	Unincorporated County of Orange	4-in lateral line	Clean-out	Blockage	Root obstruction in lateral line	NOT OCSD PROBLEM
10/24/05	0	Private Property	25	15	0	0	n/a	Orange	n/a	n/a	Grease	n/a	n/a
11/14/05	0	Private Property	0	0	0	0	13502 SUSSEX PLACE	Unincorporated County of Orange	8-inch lateral	U	Blockage	Misc. debris	None
12/14/05	0	Private	0	0	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	
1/6/06	0	Private Property	0	3500	0	0	n/a	Orange	n/a	n/a	Roots	n/a	n/a
1/10/06	0	Private Property	0	0	0	0	12322 EL ROY DR	Unincorporated County of Orange	Private property lateral	Clean-out	Blockage	Roots in lateral	NOTIF. DIV. 420 JOHN GONZALES AND HAD CREW TO SITE. CREW ONLY FOUND DRIED PAPER ON PRIVATE PROPERTY. CREW USED VACTOR TRUCK, LINE INSTETI SRINNING OK. CREW IS CONTACTING CALLER AS THEIR CLEAN-OUT NEEDS CLEANING OUT. AREA WAS RINSED DOWN.
1/25/06	0	Private Property	0	3	0	0	n/a	Orange	n/a	Cleanout Cap Rmvd	Cleanout Cap Rmvo	in/a	n/a
2/25/06	0	Private	100	0	0	0	113 Rockwood St.	Irvine	n/a	n/a	n/a	Unknown blockage	
2/25/06	0	Private	100	0	0	0	107 ROCKWELL	IRVINE	N/A	N/A	BLOCKAGE - UNKNOWN	CONTAINED IN PLANTER.	May be R-9
5/9/06	0	Private Property	0	0	0	0	1942 OMEGA DR	Unincorporated County of Orange	Lateral line	U	Blockage	Root obstruction in lateral line	NA
5/18/06	0	Private Property	0	60	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
7/17/06	0	Private Property	50	100	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
8/14/06	0	Private Property	0	100	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
8/20/06	0	Private Property	100	100	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a
9/28/06	0	Private	25	0	0	0	Grant Street	Newport Beach	n/a	n/a	n/a	n/a	(Listed only on the OCHCA Beach Closure Report)
10/19/06	0	Private	0	8	0	0	23472 LOS ADORNOS	UNINCORPORATED COUNTY	N/A	N/A	ROOTS	ALL DISCHARGE WAS CAPTURED AND RETURNED TO SEWER.	NA
11/12/06	0	Private	531	531	0	0	12186 Solarno	Garden Grove	n/a	n/a	n/a	n/a	
Totals	127		17,743	16,554	75	145							
L													
Single Family													

4/4/02	1	Private Property	25	0	0	25	1634 La Loma Dr.	Santa Ana	4" Sewer Line	Cleanout	Blockage	Misc. debris	NA
9/18/02	1	Private Sewer Lateral	20	0	0	0	Behind 1730 Raintree Rd	Fullerton	Private Lateral	Private four inch latera	Roots	Roots	City Employees Gonzalez, Bair and Miller responded with pickup truck and flatbed truck to private lateral overflow. City crew contained spill, cleared blockage, cordoned off are and scanfied approximately twenty feet of bridle trail. Service Request #0238767
9/21/02	1	Private Property	87	0	0	0	16th Street	Seal Beach	residential sewer lateral	lateral sewer line	n/a	blockage	n/a
11/1/02	1	Private Property	0	0	0	0	2300 E. Lambert	La Habra	n/a	n/a	n/a	n/a	
11/2/02	1	Private	50	0	0	0	22606 Costa Bella Dr.	Lake Forest	n/a	n/a	Roots	Roots	
1/16/03	1	Private Property	0	0	0	0	14436 SAND BROOK DR.	Tustin	Private lateral line	Bathtub	Unknown	N/A	OCSD staff inspected OCSD lines and found them running normal. At the request of the resident staff showed him the structure at both ends of the line segment in front of his property. The resident was informed that this was his responsibility to clear the lateral.
1/29/03	1	Private Property	0	0	0	0	1102 Hyde Park Dr.	Unincorporated County of Orange	Private lateral line	Bathtub and toilet	Roots in private lateral line	N/A	OCSD will CCTV entire Hyde Park Dr. line segments to investigate house lateral conditions for root intrusion. Resident was sent a letter explaining the cause of the sewage backup into his home (roots in his lateral) so he could file an insurance claim.
2/22/03	1	Private	0	0	0	0	24681 Shadowfax	Lake Forest	n/a	n/a	Roots	Roots	
4/3/03	1	Private (resident)	0	15	75	0	745 N Euclid	Fullerton	Private lateral between driveway and connection to main	Private 4" lateral cleanout in driveway approach	Unknown	Unknown	City crews Hernandez, Rangel, Davidson and Anzaldo responded to a report of a plugged lateral. When they arrived, sewage was observed seeping out of resident's private cleanout into gutter area. City crews contained the sewage, washed down, vacuumed and returned to sever system. Resident to hire private plumber to clear lin City's main was flowing line. Resident had reported blockage on 4/2/03, no overflow occured at that time, resident was to hire plumber.
4/17/03	1	Private Property	0	0	0	0	13071 ST MARK ST	Santa Ana	Private lateral	Private Clean out	Blockage Misc. debris	N/A	NA
4/18/03	1	Private	2	0	0	0	4 Gillman	Irvine	n/a	n/a	Roots	Roots	
5/9/03	1	Private Property	0	0	0	0	CANYON TERRACE RD & CRAWFORD CANYON RD	Unincorporated County of Orange	Lateral	Cleanout	Blockage Root obstruction in latera line	N/A	N/A
5/15/03	1	Private Property	0	0	0	0	1232 N. Palm	La Habra	n/a	Septic Tank	n/a	n/a	
5/15/03	1	Private Property	0	0	0	0	HIDEAWAY DR. & NEWPORT BLVD.	Unincorporated County of Orange	Lateral	Cleanout	Blockage Misc. debris	N/A	NA
6/9/03	1	Private Property	0	0	0	0	331 Eunice Cr.	La Habra	n/a	n/a	n/a	n/a	
7/23/03	1	Private Property: Mandas Konstantinos - 910 S. Euclid Street	50	10	210	50	910 S. Euclid Street	Anaheim	Near 910 S. Euclid Street	Private Cleanout	Grease	Grease buildup obstructing sewer flow.	City was notified of al leak of some kind at 2:00 am on 7/23/03, however upon arriving on scene there was no spill. A follow up inspection later that morning revealed a slow leak from the cleanout.
8/3/03	1	Private	180	0	0	0	#7 ASPEN TREE LANE	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN TO SAN JOAQUIN CHANNEL.	May be R-9
8/25/03	1	Private Party	200	50	1000	0	2508 West Chain Street	Anaheim	Near 2508 West Chain Street	Sinkhole in Street	Break	Pipe failure allowed sewage to seep into the ground	Report of possible sinkhole first came to the City at 4:45 PM on August 25, 2003. Subsequent investigation on August 27 indicated a water leak, however further investigation on August 28 revealed the water was in fact sewage. The sewage in the sinkhole was vacuumed by the City, but the hole had to be widened by the City's contractor to determine the cause was pipe failure (not contractor caused). Sewage likely continued flowing to the sewer due to dirt failing into the lateral was carried away create the sinkhole. Some sewage seeped into the ground.

									Call out Div. 420 Standby				
8/28/03	1	Private Property	0	0	0	0	12691 BROWNING AVE	Unicorporated County o Orange	Charlie Ambriz. 08/29/03 00:22 Charlie reported that OCSD line was flowing clearly. Problem was at home owner's building sewer.	Bath tub and toilet	υ	N/A	None
9/12/03	1	Private Property	0	0	0	0	1061 N. Euclid St.	La Habra	n/a	Cleanout	n/a	n/a	
10/14/03	1	Private	0	60	0	0	701 OCEAN	SEAL BEACH	N/A	LINE BREAK	LINE BREAK	ALL SEWAGE WAS CONTAINED ON SITE AND RETURNED TO SEWER.	NA
11/4/03	1	Private Property	0	0	0	0	17792 McFadden Ave	Tustin	N/A	N/A	N/A	N/A	Resident Called in to report toilet back up. Spill was private property responsibility
11/20/03	1	Dr. Charles Kenyon, at his private residence.	55	55	105	0	17075 Roundhill Dr.	Huntington Beach	Private homeowners lateral at 17075 Roundhill Dr.	Broken lateral line.	Tree roots clogged sewer lateral line.	Private party tree roots clogge and broke their sewer lateral. City's Water Dept. dug hole checking out complaint of broken water line, found broke sewer pipe.	Problem spot was in street homeowners sewer lateral. Residence is upstream on a hil explaining some pressure.
12/16/03	1	Private Property	0	7	257	0	11481 Skyline Drive	Santa Ana	4" Sewer Lateral	Clean out	Blockage, Misc. debris	N/A	NA
12/26/03	1	Hugh Roberts	200	200	300	0	705 Jay Circle	Huntington Beach	Private homeowners lateral at 705 Jay Cir.	Private clean out	Grease	Grease clogged homeowners lateral line	
12/31/03	1	Richard Beachler	75	75	100	0	6571 Sabbicas Cir.	Huntington Beach	Private homeowners lateral at 6571 Sabbicas Cir.	Private clean out		Tree roots in private sewer lateral	
7/15/04	1	Private Property	0	0	0	0	On Canyon Terrace Rd which is just below residents house @10372 Crawford Canyon Rd.	Unincorporated County of Orange	U	Cleanout	U	U	NA
10/29/04	1	Private party lateral blocked with roots;	1	6	31	1	690 West Hamilton St	Costa Mesa, CA	Roots blocked private latera SSO spilled from private lateral cleanout at 690 West Hamilton St; Fully contained	from private lateral cleanout at 690 West		Roots blocked private lateral; SSO spilled from private latera cleanout at 690 West Hamilton St; Fully contained;	Roots blocked private lateral; SSO spilled from private lateral cleanout at 690 West Hamilton St; Fully contained; Private owner obtained services of plumber and cleaned out the roots blocking the lateral line; Crew remained on-site until blockage cleared; Vactored SSO (figals) and 25 gals of rines water were disposed of in the District sanitary sewer system; 9 gals SSO evaporated from earthen dam; Photographs were taken and are attached in Word format;
11/5/04	1	Private party lateral cleanout blocked with roots;	0	50	100	0	2424 University Drive	Newport Beach	SSO spilled from private lateral cleanout in a recently built sidewalk in Newport Beach;	SSO spilled from private lateral cleanou in a recently built sidewalk in Newport Beach; Roots blocked lateral line	t Roots blocked private lateral line;	Roots blocked private lateral line at 2424 University Drive;	City of Newport Beach Crew and CMSD District Crew blocked flow in curb leading to Back Bay, Vactored 50 galions of SSO and 50 galions of rinse water were disposed of in the District sanitary sewer system; District Crew estimated SSO via visual pool estimated to be 50 galions = 5 galimin x 100 minutes; RB&R Plumibing responded to District for owner manager Max Yamada and cleaned roots out of the lateral; Lateral lihe also videotaped; Photographs were taken and are attached;
11/8/04	1	Private Property	0	0	0	0	1541 FOOTHILL BL	Santa Ana	U	U	Other	U	N/A
11/17/04	1	Private	0	50	0	0	108 30TH STREET	NEWPORT BEACH	N/A	LINE BREAK	LINE BREAK	ALL SEWAGE WAS RECOVERED.	N/A
12/28/04	1	Private Property	0	0	0	0	13071 ST MARKS DR	Santa Ana	4"	Clean-out	Blockage	Root obstruction in lateral line	Spoke with Mike Fennessy, OCHCA, and requested his staff to inspect the site since OCSD manhole/line is in the Private Property yard.
1/3/05	1	Private Property	0	0	0	0	1462 FOOTHILL BLVD	Santa Ana	4" Clean out	Clean out	Blockage	Misc. debris	NA
1/13/05	1	Gene Opfic homeowner of 8472 Arnett Dr.	0	15	15	0	8472 Arnett Dr.	Huntington Beach	Sewer lateral	Sewer clean out pipe	Grease	Grease buildup in private sewe lateral. Renter at property removed clean out cap becaus owner would not repair.	Renter at property called City, because owner would not fix the problem. City contacted the property owner that called a plumber to repair.
1/17/05	1	Private	20	0	0	0	250 CHANNEL ROAD	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	GUTTER	N/A

-													
2/14/05	1	Private Property	0	0	0	0	10511 EASTER HILL DR.	Unincorporated County of Orange	U	U	υ	U	Arrived on site at 10:50am. Checked OCSD M/H. All lines were flowing normal. We set up flush truck and ran customer line 319 feet, bringing back nothing. Gated community, customer was not home.
3/26/05	1	Private	5	0	0	0	2212 S. MONTE VISTA	LA HABRA	N/A	N/A	BLOCKAGE - UNKNOWN	ALL DISCHARGE CONTAINED ON SITE.	N/A
4/5/05	1	Private Property	0	100	0	0	8810 San Antonio	Buena Park	n/a	n/a	n/a	n/a	n/a
4/26/05	1	Private Property	0	0	0	0	1232 N. PALM	La Habra	n/a	Septic Tank	n/a	n/a	
5/9/05	1	Private Property	0	0	0	0	2212 S. MONTE VISTA ST.	La Habra	n/a	Cleanout	n/a	n/a	
5/23/05	1	Private	119	119	0	0	12991 Rosewood	Garden Grove	n/a	n/a	n/a	n/a	
5/23/05	1	Private Property	0	15	15	0	1451 NISSON RD	Unincorporated County of Orange	Septic Tank	Manhole	Blockage	Misc. debris	NA
6/4/05	1	Private	0	20	50	50	1384 S. Gilbuck St.	Anaheim	1384 S. Gilbuck St.	Private clean out	Roots	Roots caused obstruction.	The volume of the spill was likely larger than the 20 gallons that were deaned up. However, since the leak was very slow and ponded in street over a couple days, evaporation accounts for the remaining approximately 100 gallons.
6/17/05	1	Private Property	75	40	0	0	2127 Quincy	Orange	n/a	n/a	Pumped to St.	n/a	n/a
7/23/05	1	Private	0	4	0	0	1016 IRVINE AVENUE	NEWPORT BEACH	N/A	N/A	PAPER	PARKING LOT/DRIVEWAY	N/A
7/24/05	1	Private	50	0	0	0	19211 Jasper Hill Rd.	Portola Hills	Cleanout	Cleanout	Asphalt debris	Asphalt blocked line-cleanout overflowed	
8/5/05	1	Private	65	0	0	0	8699 HILLCREST	BUENA PARK	N/A	N/A	CLEAN-OUT CAP MISSING	CLEAR WATER TO STORM DRAIN.	N/A
8/9/05	1	Private	0	50	0	0	1101 N. BAYFRONT	NEWPORT BEACH	N/A	N/A	PAPER	ALLEYWAYS	N/A
8/14/05	1	Private	0	5	0	0	1311 W. BAY	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	ALLEY	N/A
8/16/05	1	Private Property	0	63	0	0	274 N Glassell	Orange	n/a	BckFlw Mlfnct/Grs	BckFlw Mlfnct/Grs	n/a	n/a
8/16/05	1	Private Property	0	0	0	0	1771 LA LOMA DR.	Unincorporated County of Orange	Private Lateral	Cleanout	Blockage	Root obstruction in lateral line	Div.420 arrived at site to find private property spill at homeowners clean-out. They ran the line/manhole downstream of property and cleaned out some roots. H owever, lateral is blocked with roots on homeowers property at 4in. cleanout. Homeowner is not home but mags. have been let for him to contact a private pumber before using anymore water. Spill is not flowing at present time & was determined to be a very small spill.
9/27/05	1	Private Property	0	0	0	0	500 Teakwood Ave.	La Habra	n/a	Cleanout	n/a	n/a	
10/24/05	1	Private	5	45	40	0	732 N. East Street	Anaheim	732 N. East Street	N/A	Roots	Roots caused obstruction	NA
11/5/05	1	Private Property	0	10	0	0	14636 Goldenwwest Ave Westminster	Westminster		cleanout	n/a	na	Spill reported by Westminster City water standby.
11/8/05	1	Private	0	0	0	0	20142 MCKINLEY LANE	HUNTINGTON BEACH	N/A	LINE BREAK	LINE BREAK	SOAKED INTO SOIL	NA
11/20/05	1	Private	0	20	0	0	1101 PINE STREET	HUNTINGTON BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	NA
12/9/05	1	Private	0	0	0	0	2085 N. HIGHLAND	ORANGE	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	NA
12/19/05	1	Private Property	0	0	0	0	1451 NISSON RD	Tustin	Septic tank	Septic tank	U	U	OCSD responded to this Private Property spill in an assistance capacity to the city of Tustin.

12/25/05	1	Private Property	100	0	150	0	11021 GOLD STAR LN	Unincorporated County of Orange	8"	Manhole	Blockage	Roots in Main Line	Control 1 was notified by homeowner and Control 1 contacted Larry Honeybourne. Larry Honeybourne contacted OCSD of the spill.
1/27/06	1	Private Property	0	1	0	0	1671 DORWOOD AVE.	La Habra	n/a	Cleanout	n/a	n/a	
2/2/06	1	Private	0	0	0	0	5175 Calzado	Laguna Woods	Private lateral	n/a	Calcium buildup	Calcium buildup in private residence lateral	Intermittent overflow occurring at cleanout only when homeowner used the water and was completely contained to dirt area. District's staff used Hydrocleaner unit to break the blockage and cleaned small amount of debris around cleanout. Video inspection df lateral line revealed water deposit build up. Line was cleaned with chain cutter to remove all water deposits on 2 / 2 / 06.
3/19/06	1	Private	3	3	0	0	13556 Robin Court	Garden Grove	n/a	n/a	n/a	n/a	
5/8/06	1	Private Property	0	0	0	0	730 W.5TH STREET	La Habra	n/a	Private lateral	n/a	n/a	
5/11/06	1	Private	59	59	0	0	12912 Magnolia	Garden Grove	n/a	n/a	n/a	n/a	
5/27/06	1	Private	0	0	0	0	10001 N. FLOWER STREET	SANTA ANA	N/A	LINE BREAK	LINE BREAK	CONTAINED ON SPILL LOCATION	N/A
6/6/06	1	Private	0	100	0	0	441 GOLDENROD AVENUE	NEWPORT BEACH	N/A	N/A	ROOTS	CURB & GUTTER (CONTAINED AND CLEANED UP)	N/A
6/8/06	1	Private	10	10	15	10	2936 W. Lincoln Ave., #3	Anaheim	2936 W. Lincoln Ave., #3	Private cleanout	break	Break casued obstruction	The discharge from this property was actually from two sources. One was the kitchen of the house at the southwest corner of the property, and the other was from regular parking lot and loading dock washout from the northern portion of the property, which flows through the back yard of the residential unit.
7/4/06	1	Private	0	20	0	0	1723 E. OCEANFRONT	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	CURB & GUTTER - CONTAINED BY CITY CREW	N/A
7/10/06	1	Private Property	0	0	0	0	17672 ORANGE TREE LANE	Tustin	4-inch	Bathroom	Blockage	Unknown	RWQCB was contacted with their after hours number and was left a voice message. Control 1 was contacted and spoke to John (Environmental Health).
7/13/06	1	Private	44	44	0	0	11812 Poes	Garden Grove	n/a	n/a	n/a	n/a	
10/21/06	1	Private	0	0	0	0	1139 / 1125 CERRITOS DR	FULLERTON	N/A	N/A	BLOCKAGE - UNKNOWN	PRIVATE CLEANOUT TO PRIVATE PROPERTY TO DIRT TRACK TO STORM DRAIN.	NA
10/30/06	1	Private	0	0	0	0	710 WASHINGTON AVENUE	SANTA ANA	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	N/A
11/15/06	1	Private	0	10	0	0	52 Leesburg	Irvine	Private lateral	Private lateral	roots	Blockage in customer's lateral (roots)	
Totals	73		1,500	1,331	2,463	136							
Multi Family													
4/18/02	2	PRIVATE PROPERTY OWNER	150	150	0	0	9010 STACIE LANE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE - GREASE	n/a	n/a
4/27/02	2	Private Property -Beachwalk Condominiums	675	350	0	0	19801 Shorecliff Lane	Huntington Beach	In the street at 19801 Shorecliff Lane.	4" Clean Out Lid	Grease	A buildup of grease in the line, probably caused by insufficient maintenance.	
5/2/02	2	Sunbridge Care Center For Fullerton, private property	20	60	0	0	2800 N Harbor Blvd	Fullerton	Private lateral	Private lateral cleanou	Unknown blockage on private property	N/A	Private four inch sewer lateral backed up and vented out of cleanout on private proper Sewage flowed onto City easement and a small amount of sewage entered the storm drain. City crews responded and contained spill. City crews notified maintenance mah from Sunbridge to have plumber rod/snake private sewer lateral. Advised to call Emergency Service Restoration for cleanup.

5/13/02	2	RS Properties Mgt. Private property	30	90	40	0	4050 W Franklin Ave	Fullerton	Private lateral	Private lateral cleanou	Unknown blockage on private property	N/A	Private four inch sewer lateral backed up and vented out of cleanout on private proper The dry contained sewage. The Management Co called private plumber (Rick the Happy Plumber) to clear blockage. The City washed down and vacuumed sewage and returned it to be sewer system. Contact the Health Dept for their recommendations to the Management Co
6/6/02	2	Private Property	340	240	580	0	4117 W. McFadden Avenue	Santa Ana	Private Property	Clean out	Grease - Private Property. City of Santa Ana installed a siphon to make way for a storm drain system on the lateral. Spill occurred due to grease build up.	a siphon to make way for a storm drain system on the	
6/17/02	2	Private Property -Beachwalk Condominiums	45	45	50	0	19771 Coastline Lane	Huntington Beach	In the street at 19771 Coastline Lane.	Manhole lid	Grease	A buildup of grease in the line, probably caused by insufficien maintenance.	
6/21/02	2	Private Property	0	0	0	0	2220 S. Monte Vista	La Habra	n/a	n/a	n/a	n/a	
6/24/02	2	Private Property	100	250	450	0	510 E. Chestnut Avenue	Santa Ana	Private Property	Clean out	Grease and Roots: Blockage on sewer lateral was caused by grease and tree roots.	caused by grease and tree	
6/25/02	2	Private Property - Owner not known	375	375	575	0	421 E. 16th Street	Santa Ana	Private Property	Clean out	Grease and paper	Grease and paper	
6/30/02	2	Private Property	300	0	0	0	3rd St & French St.	Santa Ana	Private property lateral	Cleanout	Blockage Grease clog	Not applicable - Not OCSD SSO	Called Don Cleveland to respond and evaluate, due to no response from Santa Ana Public Works. Don Cleveland arrived at this location at 1015 hour. City of Santa Ana Fire Department trived onsite before 9am. A private plumber also responded to the sile to relive the blockage in the private property line that was causing flooding in the apartment complex. At about 9:15am or relivev the flooding, the plumber opened the cleanout which allowed the sewage to flow offsite and the flooding, the plumber opened the cleanout which allowed the sewage to flow offsite and the flooding. The Fire Department was able to contain the spill within about 15 in. and calculated the flow ri to be 10 gallons per minute. They conservatively estimated the amount of the spill to storm drain to be about 300 gallows (15 min x 16 gm x 2 for conservancy) Health Care was onsite by 10:30am and PFRD, Karen Ashby, soon after. Haz Mat also responded City of Santa Ana Public Works arrived between 11:1:20am and cleaned the sewage in the street w a vactor and street sweeper. The plumber had Minute Man Pumping clean up the sewage in the parking lot. OCSD staff remained onsite until 11:45am. H
7/2/02	2	Hamilton Pacific	50	750	0	0	15622 Brookhurst Westminster	Westminster			grease	grease on private property	
7/6/02	2	Costa Mesa Sanitary District	300	300	500	0	1936 Wallace, Costa Mesa, C <i>i</i>	Costa Mesa, CA	Private Lateral	Private Lateral Cleanout	Blockage in Private lateral line	NA	Sewage from private residential lateral spilled into street when private contractor clear d residential lateral and cleanout. Al sewage contained in street. Approx 2.5 gpm into street * 120 minutes yields 300 gals spilled. Field rew dammed sewage spill, vactored up sewage, flushed street with fresh water and vactored up all flush water. Spill and flush water returned to sewer system. No sewage reached storm drain, channels, or surface waters.
7/21/02	2	Private	1500	0	0	0	East Shore & East Yale Loop	Irvine	n/a	n/a	n/a	Unknown	
7/22/02	2	Trans Pacific Management Services - Private Property	50	50	150	0	17152 Pacific Coast Highway	Huntington Beach	17152 Pacific Coast Highway	Laundry Room Drain	Grease, Debris	Appears to be lack of maintenance - grease and debris was found blocking the line.	Cleanup was delayed because of lack of a representative from management company. Cleanup was halted until a board member approved the work.
8/3/02	2	Private Property	0	0	0	0	2220 S. Monte Vista	La Habra	n/a	n/a	n/a	n/a	
8/3/02	2	Private Property	0	0	0	0	2220 MONTE VISTA AVE VISTA APARTMENTS	La Habra	N/A	N/A	N/A	N/A	CALLED LA HABRA POLICE TO CONTACT WATER DEPT. ALSO CALLED OUT DIV. 420 STANDBY, UPON ARRIVAL, STANDBY VERIFIED THAT CITY OF LA HABRA HAD CONTAINED THE SSO, SSO NO LONGER FLOWING, AND NO FLOW WAS GOING TO PUBLIC STREET. PROBLEM CONTAINED ON PRIVATE PROPERT

8/4/02	2	Brea	200	200	250	0	650 Tamarack	Brea	Sewer	Manhole	paper products	NA	The property management and Larry honeybourne from OC Health dept were on site at time of the sewer stoppage. Apartment management phone # 714.990.0150
8/16/02	2	La Palma Hospital, private property	0	0	0	0	7901 Walker Street	La Palma	Private lateral	Manhole	Unknown blockage on private property	N/A	Private sewer lateral backed up and veniad out of a manhole on private property. Sewage flowed onto City guiter and a small amount of sewage entered the storm drais. City of La Palma Public Works Dup man responded and contained spill. City staff notfilder maintenance dept from La Palma Hospital to have plumber jet private sewer lateral. Advised to call RL Walker for cleanup.
8/18/02	2	Private	2250	10	25	0	4752 Pearce Street	Huntington Beach	In front of 4752 Pearce Street.	Clean Out	Debris, Blockage	Blockage caused by paper in line. Problem started after a recent slip lining project, according to residents.	Orange County Health, Michael Fennessy stated he recovered samples of affected waters.
8/29/02	2	Jimni Service	528	100	50	0	20896 Seacoast	Huntington Beach	At the intersection of Beachcomber and Coastwatch	Manhole	Vandalism	Someone turned off power to pump station, causing the overflow.	Jimni Service cleaned up the spill and checked the pump station.
9/17/02	2	Private Management Company	0	0	0	0	1815 W Malvern Ave	Fullerton	Private Lateral	Private four inch cleanout	Roots and Toilet debris	Unknown	On 9/16/02 Unit 340 (emerg night crew) responded to a report of a private sewer problem, private plumber was on scene, no overflow observed. On 9/17/02 Jorge Gonzales (acting sanitation specialist) followed up by inspecting problem site and observed sewage around tateral claenout and a small amount at curb. No sewage was overflowing at that time. Jorge Gonzales contained split with drit at curb and advised Management Co. to call Emergency Services for procer claenup. Management Co. advised they had private Co. to cleanup. Jorge Gonzales informed Code Enforcement and Supervisor to follow up. Service Request #0238736
9/19/02	2	PWA-City of Santa Ana	600	300	900	600	2101 S. Pacific Ave.	Santa Ana	Private lateral	4" clean out	Private property spill, cause of overflow unknown.	Private property spill, cause of overflow unknown.	
9/26/02	2	Private: Seris Regio Group	200	20	70	200	2050 Winston Rd.	Anaheim	cleanout near center of drive area at 2050 Winston Rd.	clean out onsite	break in the private sewer lateral	broken lateral in private sewer	Property owner was notified of spill at 2:00 on 9/26/02 and was told the line would have to be cleaned immediately. Private plumber did not show up until the 27th. Due to difficulties cleaning the line it was determined there was a break in the private sewer lateral. Work to repair this line was completed on the 28th.
9/28/02	2	Private	0	0	0	0	6 LOS OLIVOS	IRVINE	N/A	LINE BREAK	LINE BREAK	STREET CURB AND GUTTER, STORM DRAIN	May be R-9
10/12/02	2	Harbor Breeze Apartments	5,400	100	600	0	4841 Heil	Huntington Beach	4841 Heil	Cleanout-Manhole	Grease	Grease had built up in the line, probably due to lack of maintenance	
10/17/02	2	Private: Twin Pines Apts.	5028	4800	8800	5028	2880 W. Ball Road	Anaheim	Blockage in lateral	private clean outs	Grease buildup	Grease buildup	Sewage was vacuumed up downstream in storm drain sump area in the City of Stanto Vaccuming continued until little or no flow was observed entering sump area.
10/18/02	2	Private Property - Mr. Wilson	800	200	200	800	210 S. Newhope Street	Santa Ana	Private Lateral	Private lateral clean ou	Grease: Build up of Igrease in private lateral.	Build up grease in private lateral.	
10/19/02	2	Private: Twin Pines Apts.	1776	1500	3000	1776	2880 W. Ball Road	Anaheim	Blockage in sewer lateral at appartment complex	private clean-out	Grease buildup	Grease buildup	Sewage was vacuumed up downstream in storm drain sump area in the City of Stanto Vaccuming continued until little or no flow was observed entering sump area.
10/22/02	2	Private Property	0	0	0	0	301 Mountain View	La Habra	n/a	n/a	n/a	n/a	
10/22/02	2	PRIVATE PROPERTY OWNER-JIM YOUNG 761- 5872	1,000	0	0	0	9021 STACIE LANE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE	n/a	n/a
10/25/02	2	Betty Chamberlin	375	10	160	0	317 21st	Huntington Beach	317 21st	Cleanout	Cleanout Cap was blocking flow	Grease had built up in the line, probably due to lack of maintenance	
11/1/02	2	Mark Montgomery	308	308	458	0	21372 Brookhurst	Huntington Beach	Southwest Corner of Property	Sewer Cleanout	Debris, Roots, Grease	Possible Lack of Maintenance, Debris and Grease	None
11/3/02	2	Archstone Huntington Beach	830	50	100	780	8925 Rockcreek	Huntington Beach	8925 Rockcreek	Manhole	Grease	Possible Lack of Maintenance- Grease	None

11/5/02	2	Mark Montgomery	800	350	450	450	21372 Brookhurst	Huntington Beach	Southwest Corner of Property	Sewer Cleanout	Debris, Roots, Grease	Possible Lack of Maintenance, Debris and Grease	None
11/6/02	2	Private Property - Sullivan Mgmt Group Inc.	150	650	800	150	751 S. Harbor Blvd	Santa Ana	20' S. of manhole where lateral connects to sewer system.	6" sewer clean out.	Grease build up caused by lack of routine maintenance program.	Grease build up caused by lack of routine maintenance program.	
11/13/02	2	Seebreeze Management Company	N/A	N/A	N/A	N/A	410 Lake Street	Huntington Beach	410 Lake Street	Cleanout	Maintenance Crew	Maintenance Crew was cleaning sewer lines and allowing the sewage to flow down the drain.	None
11/19/02	2	Private Property Owner	0	42	122	0	2046 E Wilshire Ave	Fullerton	Private Lateral	Private 4" lateral cleanout	Toilet Debri	Toilet Debri	Jorge Gonzalez, acting sanitation specialist observed sewage around lateral cleanout. Cleanout was not overflowing at the time. Advised resident to call private plumber. City crew washed down and vacuumed area and returned all sewage to sewer system.
11/25/02	2	Private	0	1500	0	0	1068 Rutland	Newport Beach	Cleanout	Cleanout	Unknown (possible roots)	See Remarks	Cleanout overflow - OCH care Agncy closed Upper Newpor Bay Water
12/5/02	2	Private	500	100	0	0	1433 Superior Ave.	Newport Beach	Private system	Private system	Unknown	See Remarks	Plumber onsite removed blockage in private system as CNB news arrive on site (Bea House Appartments. Reported in OCHCA Beach Closure Report, not in originally submitted OCHCA report)
12/20/02	2	PRIVATE PROPERTY OWNER - APT COMPLEX	100	0	0	0	7330 CERRITOS AVE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE	n/a	n/a
12/28/02	2	Private: Property Management Group, 1398 N. Mako Ln.	425	75	275	425	1398 N. Mako Lane	Anaheim	Near 1398 N. Mako Lane	Manhole	Grease and Roots	Grease and roots blocking flow	Property Management Group, Jerry O'Donnell, (714) 408-3469 headquarters.
1/2/03	2	PRIVATE PROPERTY OWNER	150	150	0	0	7326 CERRITOS AVENUE	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE - PLASTIC BAGS, PATCHING COMPOUND, HEAVY GREASE	n/a	n/a
1/8/03	2	Private Property	40	20	100	0	1101 Packers Circle	Tustin	Private lateral line	Manhole	Grease clog	N/A	ECM, Collections, and Communications staff will be sending a letter to the Home Owners Association to notify owner of problem and the need to implement preventative maintenance schedule to ensure no future SSOs.
1/9/03	2	PACIFIC WEST MGMT CO.	450	0	0	0	12057 BEACH BLVD.	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE - GREASE	n/a	n/a
1/12/03	2	Private Property - Royal Holida Mobil Park	0	0	0	0	215 S. Sullivan Street	Santa Ana	Private - unknown	Clean out	Grease blockage	Grease blockage	
1/26/03	2	Private	360	0	0	0	50 Eastshore	Irvine	n/a	n/a	Grease	Grease	
1/28/03	2	Florida Gardens Apartments	50	30	45	20	18832 Florida	Huntington Beach	18832 Florida	Cleanout	Lack of Maintenanc	Lack of Maintenance - Blockag cause by debris and Toilet Paper	None
2/2/03	2	FAIRCREST APARTMENTS	10,400	8,000	0	0	FERN AND CERRITOS	STANTON	LINE BLOCKAGE	n/a	LINE BLOCKAGE	n/a	n/a
2/9/03	2	Coral Cay HOA	55	5	25	55	16832 Coral Cay	Huntington Beach	16832 Coral Cay	Manhole	Grease	Grease/Lack of Maintenance	None
2/25/03	2	Private Property	3000	2000	0	0	1440 W. Lambert Rd.	La Habra	Line Blockage	Line Blockage	Grease	Grease line blockage	(Not listed in originally submitted OCHCA report. Listed in the OCHCA Beach Closure Report. Not indicated as private spill in Region 8 report)
3/12/03	2	Private - PCM Mgt. Co. View Point North Comm. Assoc.	750	300	350	750	7807 East Viewrim Drive	Anaheim	Near 7807 East Viewrim Drive	Private Manhole	Grease	The sewer line was obstructed by grease.	The property where the spill occurred is private property. The city had no responsibility for the spill and responded only to assist in the containment to prevent additional sewage from reaching our storm water catch basin system.
3/13/03	2	Private Property	350	400	400	750	112 N Bradford Ave Placentia	Placentia	private lateral line	Broken latteral line	roots	roots from tree	Bradford Senior homes hired contractor to repair latteral line City to charge back time and matterals for spill
3/28/03	2	Private Property	0	0	0	0	1777 MITCHELL	Tustin	Private Sewer line	Manhole	Blockage Misc. debris	N/A	NA
4/4/03	2	Valley View Center, private property	540	210	275	0	7811 Valley View St.	La Palma	Private lateral	Private lateral cleanou	Grease	Grease blockage on private property as well as debris	Private contractor sanitized and cleaned up

4 /18032Pirkate Property000000220 S. Monte VistaIa HabraNa <th>fully contained SSO in public right of way, h water and disposed of SSO and flush er, Coast Plumbing, cleared line by cutting in and are attached to this report.</th>	fully contained SSO in public right of way, h water and disposed of SSO and flush er, Coast Plumbing, cleared line by cutting in and are attached to this report.
S/603 2 666 West 19th St Newport CA 92626 0 165 100 0 SSO spilled out of lateral line claenout at 666 W189h St, Costa Mesa, CA Location is in a residential mesidential line claenout at 966 w199h St, Costa Mesa, CA Lateral line blocked with roots and paper. Approximately 165 gallons of SSO spilled out of lateral line blocked with roots and paper. Approximately 165 gallons of SSO spilled out of lateral line blocked with Lateral line blocked with roots and paper. Approximately 165 gallons of SSO spilled out out of lateral line blocked with Lateral line blocked with roots and paper. Lateral line blocked with roots and paper. Approximately 165 gallons of SSO spilled out of lateral. 5/1203 2 8265 Maureen Condominium Complex. 0 30 0 0 8265 Maureen Midway City 21651 Newland Ave. Midway City deanout deanout debris debris on private property blockage spille apper. spille apper. 5/1203 2 Huntington by the Sea MHP 960 40 920 21651 Newland Ave. Huntington Beach 21651 Newland # 2-8 At hookup for the Coaches Grease and debris blockage Grease and debris of maintenance. Spill neoted by Meterinetee PD. Spille oppilled out of lateral.	fully contained SSO in public right of way. In water and disposed of SSO and flush er, Coast Plumbing, cleared line by cutting in and are attached to this report.
S1203 2 Complex 0 30 0 </td <td>ement company. Spill on private property.</td>	ement company. Spill on private property.
Sizbul3 2 numingion by the Sea MinP 360 40 40 320 2101 Newland Ave. numingion beach 2101 Newland # 2-8 Coaches blockage of maintenance. 6/13/03 2 Condensitive Complex 50 325 0 0 Kramer & Stonehedge Lane Mathematics mathmatics mathematics	
	private property
6/18/03 2 Private Party 0 400 60 0 409 N. Jeanine Drive Anaheim Near 409 N. Jeanine Drive Private cleanout Trash / Debris blocking the flow of sever line.	the containment of the spill from a private drain.
6/30/03 2 Trailer Park run by Del Almo 0 80 0 0 9702 Bolsa Ave. Westminster Westminster Mestminister Broperty Service	
7/1/03 2 Private Property Owner: 278 N Wilshire Street 590 10 20 590 278 N. Wilshire Street Anaheim Near 278 N. Wilshire Street Private Manhole Swale in sewer lateral Property Management was very difficult to get sponse will result in a large bill being issue settle and accumulate resulting with the notice of violation. Copy of this rept rept very lateral 7/1/03 2 Private Property Owner: 278 N. 590 10 20 590 278 N. Wilshire Street Private Manhole Swale in sewer lateral Swale in sewer lateral Swale in sewer lateral Property Management was very difficult to get sponse will result in a large bill being issue settle and accumulate resulting with the notice of violation. Copy of this rept very lateral Swale in sewer lateral Swale in se	ed to them for cost recovery, in conjunction port was provided to OC Health Care on
7/8/03 2 Private Property 0 0 0 141 S. Idaho La Habra n'a Cleanout n'a	
2 Private Property: Paradise Pier Hotel 1717 Harbor Boulevard	lockage was excessive grease. The only at 1258 S. State College Boulevard. arge to this line, the responsibility for the spill
7/25/03 2 Private Property: Crown Point Homeowners Association 13167 798 998 13167 400 Crown Point Drive Anaheim Near 400 Crown Point Drive on Crown Point Drive Private sever manhole on Crown Point Drive Roots obstructed the sever flow. Spill could not be found at Santa Ana chann that a sump area in Cal Trans Right of Way	
7/25/03 2 Little Saigon Village 0 0 0 10161 Bolsa Ave. Westminster Westminster cleanout grease in sever line on private property spill on private property	
8/7/03 2 The Saywitz Co. 4740 Von Karman, Suite 100, Newport Beach, Ca 92660 150 250 0 7712 Cypress Ave., Huntingtor Beach, Ca. Property owners lateral at 7712 Cypress Ave., Huntington Beach, Ca. Property owners lateral at 7712 Cypress Ave., Huntington Beach, Ca. Clean out cover Grease and debris. A buildup of grease and debris.	
8/13/03 2 Richard Lee PO Box 2142, Huntington Beach, Ca 92647 120 120 220 0 ⁷⁸⁷² Stark Ave., Huntington Beach Ca. Property owners lateral at 17872 Stark Ave., Huntington Cleanout cover Frequencies and the start of	
9/15/03 2 Private 19 20 0 0 2451 ELDEN AVE COSTA MESA NA LINE BREAK LINE BREAK STREET, CURB AND GUTTER AND INTO STORM NA DRAIN.	
9/30/03 2 3895, Newport Beach (949) 0 30 50 0 718 N. Lacy Street Santa Ana Private lateral Sewer lateral clean ou plumber pulled out roots/paper.	
10/2/03 2 Private-William Lyon Property 30 210 20 0 5601 E. Orangethorpe Ave Anaheim 5601 E. Orangethorpe Ave Private Manhole Roots Roots obstructed sever flow, causing the overflow at the seriousness of the situation	scene and informed the property owner of
10/10/03 2 Private Property 0 0 0 0 2501.2511 & 2521 W. SUNFLOWER AVE SANTA ANA U U U U V/A	

10/27/03	2	Solteros Apartment maint. personnel at 17301 Keelson Ln Huntington Beach.	25	25	45	0	17301 Keelson Lane	Huntington Beach	Front yard of Solteros Apartment complex at 1730 Keelson Ln	Four inch clean out.	Tree roots clogged private lateral.	Roots from tree clogged apartment complexes sewer lateral.	
10/30/03	2	Private	17	21	300	0	1708 Peppertree Ln in alley behind apartments	Fullerton	Private lateral	Private lateral cleanou	tRoots and debris	Root intrusion into 6 inch sewe lateral through defective joint	Crews responded to private lateral overflow. Overflow was intermittent between 0 and gpm. City crews contained spill, cleared blockage, washed down and vacuumed area Due to normal irrigation run-off and storm drain flow, crews were unable to contain approximately 17 gallons of sewage that entered the storm drain system prior to their arrival. Property owner video inspected lateral and found a defective joint. City instructed owner to repair defective pipe to prevent any further overflows.
10/31/03	2	Private Property	0	50	50	0	2000 JAMBOREE RD	Newport Beach	8-inch force main on private property	Force main	Failed pipe	8-inch force main failure	This spill began on 10/31/2003 and after initial containment on the evening of 10/31/2003, the spill resurfaced on 11/01/2003. OCSD responded to spill on 11/01/2003 to find that the cause of the spill was a broken #-inch force main line. Containment was set by the City of Newport Beach and then OCSD advised the private property owner (Merit Property Management) that a vacuum outfit should be notified to vacuum up the wet well to stop the spill until the repairs are complete.
11/1/03	2	Private	0	1,000	0	0	McArthur Bivd.	Newport Beach	Private force main	Private force main	Private forcemain was broken	See Remarks	Private force main was broken Located Big Canyon Villas HOA.
12/2/03	2	Private property owner	100	1600	1600	0	1758 W. Sumac Lane	Anaheim	1758 W. Sumac Lane	Clean out in laundry room	Roots	Roots clogged the sewer latter	Property owner was initially unresponsive to the City's and OCHCA's calls notifying him bit the situation. Owner finally arrived onscene and obtained the services of a private plumber 8 hours after initial contact.
12/5/03	2	Private	0	75	0	0	CAMPUS & CARLSON	IRVINE	N/A	LINE BREAK	LINE BREAK	ALL SEWAGE WAS CONTAINED.	N/A
12/8/03	2	Private Property	0	0	0	0	321 S. Idaho St.	La Habra	n/a	Cleanout	n/a	n/a	
12/9/03	2	Bill Jarjour, owner of Hilltop Liquor	1500	25	45	1475	815 Indianapolis Ave.	Huntington Beach	Private homeowners lateral at 815 Indianapolis Ave.	Private clean out	Grease	Grease clogged homeowners lateral line	Difference of opinion by homeowner and person notifying city of spill as to length spill flowed. Location was next to bus stop see picture.
12/10/03	2	Private property owner	300	500	200	0	6103 Morningview Drive	Anaheim	6103 Morningview Drive	Private Cleanout PC192423	Roots	Roots clogged the sewer line and caused a overflow	
12/15/03	2	Tritz Professional Management Services Inc.	943	470	570	473	4171 Andros	Huntington Beach	Private eight-inch sewer line at 4171 Andros Ave.	Private sewer manhole	e Grease and roots	Grease and roots caused the private homeowners sewer system to clog.	
12/28/03	2	Complex,private property	0	15	20	0	7002 Moody St.	La Palma	Private lateral	Private lateral cleanou	Blockage	Blockage	Private contractor sanitized and cleaned up
12/29/03	2	Richard LI, owner of the apartments	2312	200	300	2112	7872 Stark Street.	Huntington Beach	Private homeowners lateral at 7872 Stark Street	Private clean out	Grease	Grease clogged apartment complex lateral line	Agnes Do from the Orange County Health Care Agency was on scene and wrote a report.
1/4/04	2	Private Property Owner	600	0	0	0	1415 W. Ball Rd.	Anaheim	1415 W. Ball Rd.	Private Manhole	Grease	Grease obstructed the flow of the Sanitary Sewer Line causing it to overflow	The Anaheim Fire Department responded initially. Then Streets and Sanitation was called out and responded. Spill duration was estimated at 1 hour as the property mang found the sewer manhole flowing out heavily. Fire said that the spill was 3 inches above the manhole when they arrived. When Streets and Sanitation arrived, the spill had stopped as the water supply had been shut off.
1/17/04	2	Brea	0	300	350	0	730 Imp. Hwy.	Brea	unknown	intercepter	unknown	na	The property management and Alexander Soles from OC Health dept were on site at time of the sewer stoppage. Apartment management phone # 714.990.0151
1/26/04	2	Coastline West Management Service	50	50	55	0	1035 12th Street	Huntington Beach	1035 12th Street	Sewer clean out pipe on private property	Roots	Apartment complex sewage lin clogged with roots.	
2/2/04	2	Rick Trucios, homeowner.	300	200	250	100	782 Little Harbor	Huntington Beach	Private homeowners lateral at 782 Little Harbor	Roots caused a private sewer lateral to plug.	e Tree roots clogged lateral line	Private party tree roots clogged sewer line and caused sewage to spill out of homeowners association manhole.	Private cleanup company (Aladdin Emergency Services) contacted the City about the spill otherwise we might not have known.

2/2/04	2	Dr. Wayne Brown rental property owner.	100	100	150	0	214 9th St. in alley	Huntington Beach	Private homeowners lateral at 214 9th St.	Private sewer lateral.	Broken sewer lateral.	Private broken sewer lateral caved in soil around it causing blockage to overflow onto publi property.	
2/3/04	2	Private Property Owner	0	0	0	0	3133 Pearl Dr	Fullerton	Private lateral for kitchen area	Private lateral cleanou	Unknown	Unknown	Emergency night crew Jennings responded to report of lateral blockage at apartment en 2/3/04. Advised resident to call a plumber, no follow up needed. Sanitation crews responded on 2/8/04 to check main line and found lateral problem had not been resolved. Cit/ Code Enforcement and CO Health Dep were called. Cit/ crews remained on scene to contain if necessary unil water was shu off and Code Enforcement and Health personnel anived. Small amount of grey water reached sidewalk area. Overflow remained in landscape area surrounding building. Owner and plumber were called and responded to take care of the problem. Code enforcement at Health Dept supervised dry clearup, Health Dept recommended adding scme line wh scarifying.
2/9/04	2	Seaside Village Condo. Homeowners Association	1512	1512	1612	0	2100 Admiral Lane	Huntington Beach	1213 Admiral Lane, a private sewer lift station.	Private sewer manhole	Problems with private lift station.	Private lift station was not working properly causing sewage to spill out of three manholes.	This condo complex has had problems before with their sewer lift station. Each time they say problem is fixed. Mr. Billard said the sewage had been spilling out of the manholes for three days.
3/3/04	2	Private Property	120	120	200	0	2540Country Hills Rd.	Brea	A-04	Manhole	unknown	NA	Apartment Manager Kathy Hill (714)9905626
3/7/04	2	Sycamore Canyon Townhomes	800	200	200	0	8282 E. Oak Ridge Circle	Anaheim	8282 E. Oak Ridge Circle	Private clean out	Roots	Roots obstructed private clean out	Private plumber did not arrive until 9:35 pm and had difficulty with their equipment. Obstruction was finally cleared at 3am. Private plumber and City Staff worked to washdown and clean affected area.
3/19/04	2	Parkview One Homeowners	960	60	1000	0	6518 E. Camino Vista	Anaheim	6518 E. Camino Vista	Private Sewer Manhole	Roots		The spill was not reported for an estimated 2 days, due to the fact that the residents of this complex did not identify this spill as being sewage.
3/22/04	2	Pacific Mobile Home Park	30	30	80	0	Pacific Mobile Home Park, 80 Huntington St.	Huntington Beach	Sewer clean out pipe	Mobile Home	Sewer pipe was clogged.	In ground sewage hook-up pipe for Mobile Home was clogged causing sewage to back-up and overflow.	Private property owner hired Emergency Services Restoration Company to do all the
4/4/04	2	CMSD	2475	525	300	0	1599 Superior Ave / 700 Block of West 16th St;		Root balls blocked private sewer lateral forcing SSO out of private cleanout; possible root entry point at Ductile Iron Pipe fitting to lateral on private property;	Root balls blocked private sewer lateral forcing SSO out of private cleanout; possible root entry point at Ductile Iron Pipe fitting to lateral or private property;	Root balls blocked private sewer latera forcing SSO out of private cleanout;	Root balls blocked private sewer lateral forcing SSO out o private cleanout;	Root balls blocked private sewer lateral forcing SSO out of private deanout; possible root entry point at Ductile iron Pipe fitting to lateral on private property. Olen Properties Property Manager Jeff Schweitzer called for two plumbing companies to clear the SSO lateral blockage; Fist company unable to dear lateral with rotary cutile plada - but removed root clusters from lateral; Second company used a mini hydrojet to clear remaining blockage; District Field Crew recommended the Property Manager video the lateral; City of Costa Mesa NPDES Manager also on-site and took photos; CMSD Crew dammed storm drain, vactored and disposed of the contained SSO and rinse water inb the District samitary sever system at the Corporate Yard; Photographs were taken and are attached.
5/22/04	2	C & C Property Management Group	5	50	50	0	411 N. Park Vista St.	Anaheim	411 N. Park Vista St.	Private cleanout in alley	Grease	Grease caused private lateral to become blocked and to back up.	
6/21/04	2	1331 E. Katella Ave., Anaheim 92805 (714) 978-8088	182	250	200	0	1221 E. Katella Ave.	Anaheim	1221 E. Katella Ave.	Private clean out	Grease	Grease obstructed the flow of the Sanitary Sewer Lateral causing it to overflow	
6/21/04	2	AAA Management 661-252- 9035	50	0	1000	0	5600 E. Santa Ana Cyn Rd.	Anaheim	5600 E. Santa Ana Cyn Rd.	Private property clean out in parking lot	Grease	Grease obstructed the flow of the Sanitary Sewer Lateral causing it to overflow	
6/25/04	2	Terry Stoia 8130 Orangewood Ave., Stanton, CA 90680	0	20	50	0	604 W. Provential Dr.	Anaheim	604 W. Provential Dr.	Private cleanout	Grease	Grease obstructed the flow of the Sanitary Sewer Lateral causing it to overflow	
6/28/04	2	Noble Mgmt. Company, 747 W Katella Avenue, Orange, CA 92867	150	200	0	350	325 S. Flower Street - Private Spill	Santa Ana	clean out on lateral	Clean out	Blockage/Private Property: Large amount of paper and grease flowing from clean out.	Large amount of paper and grease flowing from clean out.	
7/11/04	2	Golden West Property Management Inc. (714) 491- 9005	3024	0	50	3024	Behind 6101 Morningside Drive	Huntington Beach	Grease blockage inside of eight inch private sewer line	Manhole	Grease blockage	Grease buildup from a lack of maintenance.	Sewage flowes from 200 residents through this line. All upstreem sewer lines were cleaned 7/19/04. These lines will be put on a scheduled cleaning.
7/29/04	2	1743 S. Clementine (Extended Stay America)	260	1100	300	200	1742 S. Clementine Street	Anaheim	1742 S. Clementine Street	Private Manhole	Cloth and other debris	Cloth and debris clogged pipeline, causing sewage to overflow.	

	1												
8/29/04 2	2	Private	9450	0	0	0	DEWBERRY / SANDBURG	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN.	NA
9/5/04 2	2	Broadmoor Huntington Harbou HOA	50	0	100	100	6905 Warner Ave.	Huntington Beach	Private sewer lateral at 3251 Moritz Drive.	Cleanout	Grease and debris blockage	Grease and debris buildup fron two condo units sharing plumbing pipes.	Spill was reported to Huntington Beach Police Dept. they referred spill to wrong Dept. Wastewater arrived at spill two hours after reported time and sewage flow was stopped.
9/11/04 2	2	Prudential Real Estate	276	200	450	76	21851 Newland Ave.	Huntington Beach	Private sewer lateral at 7931 Stark Ave.	Cleanout	Tree roots	Tree roots clogged sewer laters for an eight unit residential complex	
9/21/04		Lincoln Inn, Kelly Erickson - Maint. Manager	100	0	100	0	2748 W. Lincoln Avenue	Anaheim	2748 W. Lincoln Avenue	Private cleanout	Feminine hygiene products	Feminine hygiene products got lodged in line.	Hotel cleared blockage with their own equipment and proceeded to wash the spill into the onsite drop inlet before City Staff arrived onsite. Hotel Management was informed that the spill had to be contained onsite and City had to be contacted in the event of a spill. This requirement will be reiterated in the Compliance Order.
9/21/04 2	2	Private Property	0	400	0	0	15701 TUSTIN VILLAGE WAY	Unincorporated County of Orange	4" clean out	Clean out	Blockage	Misc. debris	CITY OF TUSTIN TOOK PHOTOS & WILL FORWARD THEM TO OCSD. TOTAL SPILL LESS THAN 1,000 GALLONS PER FIELD OBSERVATION.
9/23/04 2	2	Casa Management, 13526 E. Calora, Covina, CA 91724 (818) 468-2507, Patricia Hodura	720	670	1220	50	1317 S. Standard	Santa Ana	Praivate lateral	4" clean out	Paper/Grease/Priva e Property	Large amounts of paper and grease geing dumped in sewer by residents and lack of a routine maintenance program.	Cecilia Flores, Code Enforcement - 667-2710 contacted PWA-Agency regarding spill on 9/23/04 @ 11:00 am.
9/27/04 2	2	Pacific City Property, 10 unit apartment complex, City of Costa Mesa	500	1500	500	500	584 W Hamilton Street	Costa Mesa, CA	Private lateral at Pacific City Property, 10 unit apartment complex, Costa Mesa		Private lateral at Pacific City Property, 10 unit apartment complex, was blocked with grease;	Private lateral at Pacific City Property, 10 unit apartment complex, was blocked with grease;	Private lateral at Pacific City Property, 10 unit apartment complex, was blocked with grease; SSO spilled from private backyard cleanout; CMSD Field Crew dammed SSO in street and cut and at the SSV actioned and disposed of the contained SSO and in water into the District stantary sever system; Of the estimated 2000 galors of total SSO, 500 galo were loal in the storm drain (SD) and to evaporation down 600 ft path to SD; Coast Pluming cleand the grease blocked lateral line at Pacific City Property To unit apartment complex. District intends to contact the US postal (carrier) service to determine the best protocol for carriers to report such events to the District upon discovery in the future; Photographs were unavailable as attachments to this report;
10/7/04 2	2	Private Property	10	0	0	0	7621 TRASK AV	Westminster	8" sewer line	Manhole	Blockage	Grease Clog	1030am, Possible spill at 7621 Trask Ave. in Westminster, Notified OCSD / Div.420 to check. No storm drain info. is known at this time. P.797 J-7. Small spill at 7621 Trask Ave. is contained on private property. Approx. 10 gallons, Containment is set. NO sto drain impact. OCSD is looking for Apt. manager at this time.
11/12/04 2	2	Anaheim Hilton	880	20	400	0	777 Convention Way	Anaheim	777 Convention Way	Private Manhole and Cleanout	Grease	Grease blocked sewer line, causing sewage to overflow.	This spill was observed on Wednesday flowing only for a couple hours in the moming which is what the flow estimate is based on. There is clear evidence that despite the arge flow carried by the 15° line which was obstructed, the actual amount of sewage spilled was not large compared with the flow. This is because there is an overflow by- pass of the spihons where the destruction occurred, which allowed all mitted flow to continue in the sewer. Also, it appears that the spill only occurred at peak flow (morning primarily) and was not substantial based on location and minimal solids deposition.
1/2/05	2	George Galanoues owner of apartment complex	2,100	900	1,400	2,100	2208 Delaware St.	Huntington Beach	Private sewer lateral	Private 4 inch sewer clean out pipe.	Grease	Grease buildup in private sewe lateral.	There were several different estimates from residents in the complex stating when the sewage started flowing above ground.
1/4/05 2	2	Lake Summit Association	60	40	500	0	920 S. Ridgecrest Circle	Anaheim	Near 920 S. Ridgecrest Circle	Private Manhole	Grease	Grease blocked pipeline, causing sewage to overflow.	Spill appeared to be flowing at a far greater rate than 50 gph. However, the sewer line that was obstructed only serves 20 homes and a typical flow at 10 am would likely be approximately 50 gph. Therefore, the additional flow is suspected to be from Inflow and Infiltration. Sewage flowing from the manhole was very clear in appearance, further supporting this suspicion.
1/13/05 2	2	Wonson Kim, owner, Fullerton Inn Hotel	700	200	3000	0	2601 W Orangethorpe - Fullerton Inn Hotel	Fullerton	Private lateral @ 2601 W Orangethorpe	Private lateral cleanou	Debris, paper	City lateral rod crew cleared unknown blockage from upstream	City sewer crews noticed sewage flow from driveway at small hotel. City crews set up vactor vacuum at downstream catch basin while waiting for additional crews. City rodding crew and additional combo truck responded, cleared private lateral, washed down and swept entire path along Orangethorpe and Magnolia to remove all debris. Co crew estimates approximately 700 galors entered catch basin on Magnolia Ave. before arrival of vactor crew due to intermittent flow during the night hours. City crews Reynoso and Lambaren spoke with owner, explained the seriousness of the situation. The owner states the called a plumber at 10:00pm in the evening and plumber never responded, so he waited until morning and catled another plumber. The plumber arriv shortly after City crews arrived. Owner states the doit realize the seriousness of the situation. Owner was informed to call the City for containment assistance in the future, start a routine maintenance program, and consider CCTV on lateral.
				1									

												I	
1/24/05	2	Private Property	0	0	0	0	311 W. LAMBERT RD.	La Habra	n/a	Private lateral	n/a	n/a	
1/25/05	2	Victoria Townhouse Apartments	1050	7500	500	0	2256 W. Lincoln Ave.	Anaheim	2256 W. Lincoln Ave.	Private Manhole	Grease & Roots	Roots and grease blocked pipeline, causing sewage to overflow.	Property owner called private plumber at 2:00 PM but did not show up until 6:00 PM. City crews cleared the obstruction at 5:45 PM. Plumber would not have been able to clear blockage anyway, since he did not have the explorment to do so. Atched are two volume calculation forms, which use two different methods to arrive at virtually the same estimate of flow; 1800 gallons per hour. Property owner is currently disputing his responsibility for this spill.
1/27/05	2	Private Property	20	0	0	0	1722 MITCHELL	Tustin	4" Clean out	Clean out	Blockage	Grease clog	NA
2/7/05	2	Private	0	0	0	0	233 CARNATION	NEWPORT BEACH	N/A	N/A	UNKNOWN	ON-SITE	NA
2/8/05	2	1310 W. Pearl St.	0	60	300	0	1310 W. Pearl St.	Anaheim	1310 W. Pearl St.	Private Cleanouts	Grease & Paper Towels	Grease and paper towels blocked pipeline, causing sewage to overflow.	
2/10/05	2	Private	5	5	0	0	11418 Knott	Garden Grove	n/a	n/a	n/a	n/a	
2/17/05	2	Private	30	0	0	0	20041 Osterman St.	Lake Forest	Cleanout	Cleanout	n/a	4" private cleanout-blockage	
2/20/05	2	Private Property	0	0	0	0	1360 W. LAMBERT RD	La Habra	n/a	n/a	Grease	n/a	
2/20/05	2	Private	50	0	0	0	905 IDAHO ST.	LA HABRA	N/A	N/A	GREASE	MANHOLE TO CURB AND GUTTER TO STORM DRAIN.	N/A
2/28/05	2	Richard Li property owner	200	175	375	25	7872 Stark St.	Huntington Beach	Private sewer lateral	Private sewer lateral clean out at 7873 Star St.	Grease	Buildup of grease in private sewer lateral.	Only one tenant home doing laundry at the time of the spill.
3/1/05	2	Private	0	0	0	0	453 SUMMERFIELD CIRCLE	ANAHEIM	N/A	N/A	GREASE	STORM DRAIN -> EAST GARDEN GROVE WINTERSBERG CHANNEL -> LOWER BOLSA	NA
4/23/05	2	Private Property	0	1300	1460	0	1171 PACKERS CIR	Tustin	8"	Manhole	Blockage	Grease clog	Private Property
5/16/05	2	Mesa Verde Town Homes;	40	60	160	40	666 West 19th St	Costa Mesa, CA	Roots in private lateral line Newport Mesa Town Homes caused SSO to spill from cleanout;	Roots in private latera line of Newport Mesa Town Homes caused SSO to spill from cleanout;	Roots in private lateral line of Newport Mesa Town Homes caused SSO to spill from cleanout;	Roots in private lateral line of Newport Mesa Town Homes caused SSO to spill from cleanout;	One District Crew contained SSO (upon arrival) from further entering the Storm Drain (SD) until private plumber arrived to clear private lateral line of roots: District called ou C&R plumbing to clean the line; SD used as additional containment vessel; Crew vachored sewage from site and SD and disposed of 1 in the District calmaly sever; Seltmated flow rate of 20 gallons per hour for 5 hours yielding an SSO of 100 gallons; Roots in private lateral line of Newport Meas Town Homes caused SSO to spill from cleanou; District rew vactored 60 gallons of SSO throm site and Storm drain and 100 gallons of fresh rinse water used to clean the site; District informed Property Manager Cheryl Stone to increase frequency of lateral line cleanou to quarterly rather than evely six months; last documented occurrence was 5-6-03; Photographs were taken and an attached.
5/19/05	2	Private Property	0	60	0	0	7758 Knott Ave	Buena Park	n/a	n/a	Paper	n/a	n/a
5/29/05	2	Private	3000	1200	200	200	801 N. Loara Street Anaheim	Anaheim	801 N. Loara Street Anaheim	Private clean out	Rags	Blockage caused by rags clogging lateral line.	
6/21/05	2	Private	20	0	0	0	17 E. Yale Loop	Irvine	Cleanout	Cleanout	Grease	Private clean-out grease	
6/29/05	2	Private Property	0	0	0	0	1300 W.LAMBERT RD	La Habra	n/a	Cleanout	n/a	n/a	
7/29/05	2	Costa Mesa Sanitary District	0	5	55	0	584 Hamilton St	Costa Mesa, CA	Grease blocked private lateral line in a multifamily residential development forcing SSO out of private property cleanout;	Grease blocked privat lateral line in a multifamily residential development forcing SSO out of private property cleanout;	Grease blocked private lateral line ir a multifamily residential development forcing SSO out of private property cleanout;	Grease blocked private lateral line in a multifamily residential development forcing SSO out of private property cleanout;	SSO trickled from private lateral cleanout onto private property and to the street and nearby storm drain (SD) which acted as a containment vessel; Crew blocked SD and vactored SSO while private plumber (Coast General Plumbing) was en route to the site; Crew vactored sewage and rinse water from sile (creet, cuth and SD) and disposed of it in the District sanitary sewer; District Crew and Staff estimated SSO volume pooled son private property to be 45 galoms and 5 galoms tricked in the street, cuth and SD District informed Padific City Properties (management company) of situation, recommended increased lateral cleaning frequency from quartery to bi-monthy and backcharged management company (Pacific City Properties) for District services; Photographs were not taken;

No. No.										1	1		1	
integra integra <t< td=""><td>8/14/05</td><td>2</td><td>Private</td><td>0</td><td>2</td><td>0</td><td>0</td><td>1817 BEDFORD ROAD</td><td>NEWPORT BEACH</td><td>N/A</td><td>N/A</td><td>ROOTS</td><td>GUTTER</td><td>NA</td></t<>	8/14/05	2	Private	0	2	0	0	1817 BEDFORD ROAD	NEWPORT BEACH	N/A	N/A	ROOTS	GUTTER	NA
No. 101 1 101	8/22/05	2	Private Property	0	30	0	0	5317 Humbolt	Buena Park	n/a	n/a	n/a	n/a	n/a
unit v value v value v v v v v v v 102 2 Name 0 </td <td>9/7/05</td> <td>2</td> <td>Private</td> <td>2340</td> <td>0</td> <td>0</td> <td>0</td> <td>30 SCENIC BLUFF</td> <td>IRVINE</td> <td>N/A</td> <td>LINE BREAK</td> <td>LINE BREAK</td> <td>STORM DRAIN TO CREEK</td> <td>May be R-9 Gate guarded community.</td>	9/7/05	2	Private	2340	0	0	0	30 SCENIC BLUFF	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN TO CREEK	May be R-9 Gate guarded community.
100 12 Ref. 10 10 10 100 Ref. Ref. <thref.< th=""> <thref.< th=""> <thref.< th=""></thref.<></thref.<></thref.<>	9/18/05	2	Private	0	100	0	0	310 S. JEFFERSON	PLACENTIA	N/A	N/A		STAYED ON SITE	NA
No. No. <td>10/3/05</td> <td>2</td> <td>Private</td> <td>970</td> <td>100</td> <td>300</td> <td>0</td> <td>2138 W. Brownwood Ave.</td> <td>Anaheim</td> <td></td> <td>N/A</td> <td>Grease/Break</td> <td></td> <td>by phone (or by any other method). HCA investigated contact information and City Cote Enforcement as well as Utilities Billing were unable to obtain a good phone number for</td>	10/3/05	2	Private	970	100	300	0	2138 W. Brownwood Ave.	Anaheim		N/A	Grease/Break		by phone (or by any other method). HCA investigated contact information and City Cote Enforcement as well as Utilities Billing were unable to obtain a good phone number for
Interplant Interl	10/10/05	2	Private	215	215	0	0	9855 Hewitt	Garden Grove	n/a	n/a	n/a	n/a	
1 max 2 Max 2 Max	10/16/05	2	Private Property	0	300	400	0		Stanton	NA	Manhole	Blockage	Grease Clog	None
10200000000000000000000000000000000000	10/20/05	2	Private	29	50	0	0	17199 BLUEWATER LANE	HUNTINGTON BEACH	N/A	N/A	ROOTS & GREASE	TO BULKHEAD TO BAY	NA
11000122Cata Mess Santay Data04410052Solvais DirectCata Mess.Rest Mess Direct DirectRest Mess Direct D	10/25/05	2	Private	20	10	0	0	behind 2235 Pacific Dr	Newport Beach	Broken pipe	Broken pipe	hillside that was	See Remarks	Setup beam and vactor on Bayside Dr, used two flagmen for traffic control. Contacted Michael Bayer at 2235 Pacific Dr. to advise him he had a problem.
1 <td>11/3/05</td> <td>2</td> <td>Costa Mesa Sanitary District</td> <td>0</td> <td>45</td> <td>100</td> <td>5</td> <td>2520 Kincaid Drive</td> <td>Costa Mesa, CA</td> <td>private lateral line in a multifamily residential complex at Fairview State Hospital forcing SSO out of</td> <td>blocked private lateral line in a multifamily residential complex at Fairview State</td> <td>blocked private lateral line in a multifamily residential complex at Fairview State</td> <td>private lateral line in a multifamily residential complex</td> <td>Fairview State Hospital forcing SSO out of private property MH-I District crew blocked SD, vaccored SSO from the street, curb and SD; flushed the area with fresh rines wate District Staff contacted Fairview State Hospital Manager (Shannon, 714-545-0442) to contact plumber and increase frequency of lateral line cleaning: Private plumber removed lateral line blockage; Vacorded SSO was disposed of in the District Staffary</td>	11/3/05	2	Costa Mesa Sanitary District	0	45	100	5	2520 Kincaid Drive	Costa Mesa, CA	private lateral line in a multifamily residential complex at Fairview State Hospital forcing SSO out of	blocked private lateral line in a multifamily residential complex at Fairview State	blocked private lateral line in a multifamily residential complex at Fairview State	private lateral line in a multifamily residential complex	Fairview State Hospital forcing SSO out of private property MH-I District crew blocked SD, vaccored SSO from the street, curb and SD; flushed the area with fresh rines wate District Staff contacted Fairview State Hospital Manager (Shannon, 714-545-0442) to contact plumber and increase frequency of lateral line cleaning: Private plumber removed lateral line blockage; Vacorded SSO was disposed of in the District Staffary
1000000000000000000000000000000000000	11/3/05	2	Private Property	0	0	0	0	1750 W.Lambert Rd.	La Habra	n/a	Cleanout	n/a	n/a	
12 <t< td=""><td>11/4/05</td><td>2</td><td>Private Party</td><td>0</td><td>15</td><td>0</td><td>0</td><td>4001 Orange Ave</td><td>Cypress</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td></td></t<>	11/4/05	2	Private Party	0	15	0	0	4001 Orange Ave	Cypress	n/a	n/a	n/a	n/a	
10 <t< td=""><td>11/9/05</td><td>2</td><td>Private Property</td><td>0</td><td>0</td><td>0</td><td>0</td><td>550 W. La Habra BL</td><td>La Habra</td><td>n/a</td><td>Cleanout</td><td>n/a</td><td>n/a</td><td></td></t<>	11/9/05	2	Private Property	0	0	0	0	550 W. La Habra BL	La Habra	n/a	Cleanout	n/a	n/a	
122005 12 Private 120 <td>11/28/05</td> <td>2</td> <td>Private</td> <td>355</td> <td>355</td> <td>0</td> <td>0</td> <td>12851 Haster</td> <td>Garden Grove</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td>n/a</td> <td></td>	11/28/05	2	Private	355	355	0	0	12851 Haster	Garden Grove	n/a	n/a	n/a	n/a	
(1) <th< td=""><td>12/16/05</td><td>2</td><td>Private</td><td>45</td><td>45</td><td>0</td><td>0</td><td>13946 Erin</td><td>Garden Grove</td><td>n/a</td><td>n/a</td><td>n/a</td><td>n/a</td><td></td></th<>	12/16/05	2	Private	45	45	0	0	13946 Erin	Garden Grove	n/a	n/a	n/a	n/a	
12 Jobs 2 Private Property 11000 11000	12/20/05	2	Private	0	0	0	0	2208 DELAWARE	HUNTINGTON BEACH	N/A	LINE BREAK	LINE BREAK	N/A	NA
1/600 2 (Amstrong Ranch) 800-428- \$588 540 200 500 340 3301 S. Sheffield Santa Ana Private Property system Starter pot Private Property Construction/ private Property definition grasse was the cause 1/700 2 Private Party 0 120 0 1200 PACIFIC COAST HUNTINGTON BEACH NA NA Starter pot Private Property CleAN UIT TO PARKING CONTAINED. NA 1/8006 2 Private Party 0 400 0 8641 Moody Street Cypress n/a n/a n/a n/a NA	12/30/05	2	Private Property	1780	1180	1780	600	1777 MITCHELL AV	Tustin	8"	Manhole	Blockage	Grease clog	
17/06 2 Private 0 120 0 0 Interface Constrained NA DECORAGE - UNKNOWN GRANGE FLOOR TO CONTAINED. NA 1/8/06 2 Private Party 0 40 0 0 B641 Moody Street Cypress n/a n/a n/a n/a n/a	1/6/06	2	(Armstrong Ranch) 800-428-	540	200	500	340	3301 S. Sheffield	Santa Ana	Private property sewer system	Starter pot	Construction/	debri and grease was the caus of the spill.	
	1/7/06	2	Private	0	120	0	0	1200 PACIFIC COAST HIGHWAY	HUNTINGTON BEACH	N/A	N/A		GARAGE FLOOR TO	NA
	1/8/06	2	Private Party	0	40	0	0	8641 Moody Street	Cypress	n/a	n/a	n/a	n/a	
	1/10/06	2	Private	0	0	0	0		HUNTINGTON BEACH	N/A	LINE BREAK	LINE BREAK	N/A	N/A

1/11/06	2	Property Manager for 1746 Placentia Ave, Costa Mesa, CA property;	20	154	254	20	779 Shalimar Dr;	Costa Mesa, CA	Roots blocked multifamily residential lateral causing overflow from an uncapped cleanout;	Uncapped cleanout;	Roots in private lateral line;	Roots blocked multifamily residential lateral causing overflow from an uncapped cleanout;	Private resident of facility reported event to CMSD and CMSD Maintenance Supervisor, in turn; Estimated 174 gallon SSO flowed from an uncapped private property cleanout Estimate 20 gallons SSO trickled into storm drain (SD); Estimate 50% SSO evaporated prior to reaching SD; City of Costa Mesa crew vacored SSO and rinse water and disposed of the wastewater in the District sanitary sever system; Roots blocked multifamily residential lateral causing overflow from an uncapped cleanout; CMSD Maintenance Supervisor remained on site until commercial plumber arrived and completed lateral cleaning/removal of roots and capping the facility cleanout; CMSD Staff informed Facility Manager, Ed Glinka, 714-926-9305, of need to increase lateral line cleaning frequency and keep cleanouts capped; CMSD backcharged Facility Manager for services provided; Photos were taken;
1/16/06	2	Private	2050	250	1000	0	453 W. Summerfield Circle	Anaheim	453 W. Summerfield Circle	Private Cleanout	Grease	Grease caused the obstruction	This is the first clear instance of a repeat spill in many years. This will require higher level enforcement to ensure this does not happen again.
1/24/06	2	Private	0	1000	0	0	12705 NEWBROOK	STANTON	N/A	N/A	BLOCKAGE - UNKNOWN	ALL DISCHARGE WAS RECOVERED AND RETURNED TO SEWER SYSTEM.	N/A
1/25/06	2	Private	0	0	0	0	1205 NEWBROOK	STANTON	N/A	N/A	BLOCKAGE - UNKNOWN	N/A	N/A
1/28/06	2	Private	11900	0	0	0	17650 Rosa Drew Lane	Irvine	n/a	n/a	Roots	Roots	
1/28/06	2	Private	10800	0	0	0	5238 MICHELSON	IRVINE	N/A	N/A	ROOTS	MASON CREEK AND SAN DIEGO CREEK TO UPPER NEWPORT BAY	May be R-9
2/2/06	2	Private	202	202	0	0	8519 Edgebrook	Garden Grove	n/a	n/a	n/a	n/a	
2/7/06	2	Private	160	2000	1000	0	627 N. Eulid St.	Anaheim	627 N. Euclid St.	Private cleanout	Assumed to be grease and break, but discovered to be a metal disk	metal disk caused spill	The property manager, Jim Kirby, was very cooperative and responsive to the spill on February 7. He promised to have a sandbag barrier constructed at the drive entry whe the majority of the sewage left the property, in order to capture and contain any spills th the near future and prevent them from leaving the property. Additionally, the disk while likely was the cause of the recent spills should be removed within 48 hours.
2/8/06	2	Private Property	0	20	0	0	828 N. Glassell	Orange	n/a	n/a	Grease	n/a	n/a
2/10/06	2	Private Property in Leisure World	20	<50	250	0	Nassau & Brookline Drive	Seal Beach	Main line, Oakmont	Manhole, Brookline Dr.@Nassau Dr.	Grease	n/a	Private Property Spill
2/15/06	2	Private	120	30	200	0	2080 S. Harbor Blvd.	Anaheim	2080 S. Harbor Blvd.	Private cleanout	Grease	Grease caused obstruction	N/A
2/15/06	2	Private - Calvin Sekhon, property owner (714) 878-1540	700	100	1000	0	2309 W Valencia	Fullerton	Private lateral	3 lateral cleanouts on property	Debris, grease		Crews responded to private overflow from three cleanout locations within apartment complex. City crews contained SSO at private drain in parking area. City crews set up vactor vacuum in gutter, cleared blockage to stop overflow, washed down and vacuumed area. Apartment maintenance person was instructed to thoroughly clean like to prevent re-occurrence. Per residents at complex (who choose to remain anonymous) overflows occur often.
2/16/06	2	Private - Calvin Sekhon, property owner (714) 878-1540	587	200	1000	0	2309 W Valencia	Fullerton	Private lateral	3 lateral cleanouts on property	Debris, grease	Private lateral line was not completely cleared from previous blockage	Crews responded to private overflow from three cleanout locations within apartment complex. City crews contained SSO at private drain in parking area. City crews set up vactor vacuum in gutters, private plumber responded and cleaned blockage to stop overflow. City crews vashed down and vacuumed area. Property owner responded a was instructed to horoughly clean line to prevent re-occurrence. Private plumber had not cleaned emite line due to short odding aquipment, axensions were acquired. Cit personnel, as well as Health agency personnel explained seriousness of SSO to owner of property. South Coast Plumbing video inspected line, found sags in lateral line but other major defects.
2/16/06	2	Brookside Apts	0	180	80	0	5600 Orangethorpe Avenue	La Palma	Private Lateral	Cleanout	Grease & Blockage	Grease blockage from private property and sedement	Private contractor sanitized and cleaned up
2/16/06	2	Private Property	0	0	0	0	19246 Fairhaven Extension near Panorama Place.	Unincorporated County of Orange	U	U	Blockage	Root obstruction in lateral line	HCA Michael Fennessy contacted, HCA going to site. Problem belongs to homeowner and HCA will follow-up.

2/17/06		Lordon Management Company (626-967-7921, x3316), @ 1275 Center Court Drive, Covina, CA 91724; FAX: 626- 966-3918)	0;	82	132	0;	760 West 16th St;	Costa Mesa, CA	Grease, roots, rocks and debris blocked private latera in a parking lot causing overflow from a cleanout;	Grease, roots, rocks and debris blocked private lateral in a parking lot causing overflow from an uncapped cleanout;	Grease, roots, rocks and debris blocked private lateral in a parking lot causing overflow from an uncapped cleanout;	Grease, roots, rocks and debri blocked private lateral in a parking lot causing overflow from an uncapped cleanout;	Visually estimated 82 gallon SSO flowed from one private property cleanout; Estimate Some SSO trickled into Storm Drain (SD) used as a containment vessel; Recovered/vactored 82 gallons; District maintenance supervisor and line cleaning contractor, National Plant Services, Inc., dammed 80 and vactored SSO and rinse water and disposed of the wastewater in the District sanitary sewer system; Private plumber pushed blockage into District line while cleaning lateral line. Grease, roots, rocks and debris blocked private lateral in a parking lot causing overflow from a cleanout; Distinct Main Line previously cleaned on 12-3266. Lordon management Company (626-647-7921, v3316) informed of the need to increase private lateral line maintenance to prevent future SSOs; Photos were taken and are attached; District backcharged London Management Company for services/resources used to manage the SSO;
2/17/06	2	Brookside Apts	0	202	80	0	5600 Orangethorpe Avenue	La Palma	Private Lateral	Cleanout	Grease & Blockage	Grease blockage from private property and sedement	Private contractor sanitized and cleaned up
2/23/06	2	Private	0	50	200	50	917 W. Lodge Ave.	Anaheim	917 W. Lodge Ave.	Private cleanout	Soap/sewer buildup	Soap/sewer buildup caused obstruction	Property manager called private plumber to clear obstruction. Plumber did not respond in a timely manner, resulting in the property manager and his assistant clearing the dr with own tools. City vactor onsite to washdown and dispose of waste water.
2/23/06		Lordon Management Company (626-967-7921, x3316). @ 1275 Center Coun Drive, Covina, CA 91724; FAX: 626- 966-3918)	0	35	85	0	760 West 16th St;	Costa Mesa, CA	Roots/paper towels blocked private lateral in a parking to carring out of the second of the second of the second deanout;			Roots/paper towels blocked private laternal in a parking lot causing overflow from a cleanout;	London Management Company reported event to CMSD and CMSD Maintenance Supervisor: Repeat similar event to 2/17/06: Visually estimated 82 gallon SSO flowed from one private property cleanout: Estimate Some SSO trickled into storm drain (SD) used as a containment vessel; Recovered/Vactored 82 gallons: District line cleaning contractor, National Plant Services, Inc., (NPSI), and Cily of Costa Mesa crew performed cleanue; District maintenance supervisor and NPSI dammed Storm Drain (SD) and vactored SSO and rinse water and disposed of the vastewater in the Distric saniary severe system: Private plumber arrived and removed roots/paper towels while cleaning lateral line; Roots/paper towels blocked private lateral in a parking lot causin overflow from a cleanout; District Main Line previously cleaned on 1/2306 and on 2/17/06; Lordon Management Company (B26-967-7821, 3316) informed of the need to increase private lateral line maintenance to prevent future SSOs; Photos were taken and are attached; District backcharged London Management Company for services/resources used to manage the SSO;
3/7/06	2	Private	500	40	20	0	105 E. Leatrice Ln.	Anaheim	105 E. Leatrice Ln.	Private cleanout	Vandalism	Vandalism caused spill	This spill was reported to have been flowing for several days by the tenants. The odo the area and the volume of solids near the spill bears this out. However, the property owner was very responsive in taking care of the obstruction as well as aiding in the cleanup.
3/14/06	2	Private	30	20	500	0	777 Convention Way	Anaheim	777 Convention Way	Private cleanout	Grease	Grease caused obstruction	Although the Hilton has gone to substantial efforts in reducing the amount of grease discharged to the sewer, and implemented a fairly successful sewer line cleaning program, the problem with sewer spills pensits. Therefore, despite the potentially high cost, structural controls (grease interceptors and/or traps) will be required to be install at appropriate locations and will be sized adequately and maintained property.
4/6/06	2	Private	400	200	0	0	7850 SLATER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE	HUNTINGTON CENTRAL PARK LAKE - WILL POST SOME CLOSURE SIGNS AT DRAIN ENTRY TO LAKE FOR A FEW DAYS - INCIDENTAL CONTACT LAKE.	NA
4/17/06	2	Private Property	0	25	0	0	3340 E. Collins	Orange	n/a	n/a	Grease	n/a	n/a
4/25/06	2	Private	50	100	0	0	21372 BROOKHURST	HUNTINGTON BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	STORM DRAIN	N/A
5/9/06	2	Private Party	0	20	0	0	6336 Orange Ave.	Cypress	n/a	n/a	n/a	n/a	
5/17/06	2	Private	22	22	0	0	8903 Hewitt Place	Garden Grove	n/a	n/a	n/a	n/a	
6/5/06	2	Private	128	128	0	0	10761 Palma Vista	Garden Grove	n/a	n/a	n/a	n/a	
6/8/06	2	La Palma Hospital, private property	0	90	110	0	7901 Walker Street	La Palma	Private Lateral	Manhole	Unknown Blockage	Blockage from private property	Private contractor sanitized and cleaned up

								1	1	1	1		
6/11/06	2	Private	600	1800	20	600	8000 Naples Ln.	Anaheim	8000 Naples Ln.	Private cleanout	roots	Roots caused obstruction	N/A
6/23/06	2	PRIVATE SSO at Apartment complex at 2257 Maple St;	0	10	20	0	2257 Maple Street;	Costa Mesa, CA;	Small SSO flow from uncapped private cleanout i a 4-plex;	Small SSO flow from runcapped private cleanout in a 4-plex;	Small SSO flow from uncapped private cleanout in a 4-plex;	Small SSO flow from uncapped private cleanout in a 4-plex;	PRIVATE SSO at Apartment complex at 2257 Maple St: City of Costa Mesa and CMSD Maintenance Supervisor blocked Storm Drain (SD) around the corner from the driveway site; Commercial plumber vacuumed SSO and rinse water and disposed of the vastewater in a NH in the CMSD sanitary sever system; Visual estimate of shall pooled wastewater in private driveway and from path from the Cleanout (CO) to the curb; Small SSO flow from uncapped private cleanout in a 4-plex; Photos were taken and are attached;
7/3/06	2	PRIVATE SSO at Apartment complex at 1741 Tustin Ave, managed by South Coast Property Management Co (714 444-2602-Voice, 714-444-3602 FAX);	25	75	150	25	1741 Tustin Ave;	Costa Mesa, CA;	Blockage in PRIVATE latera line on PRIVATE property;	PRIVATE MANHOLE (MH) on private property at 1740 Tust Ave;	in PRIVATE lateral	Unknown blockage in PRIVATE lateral line on PRIVATE property:	PRIVATE SSO at Apartment complex at 1741 Tustin Ave, managed by South Coast Property Management Co (714-444-2602-Voice, 714-444-3602-FAX); Estimated 100 gallon PRIVATE SSO flow contained in private drive and curb, District crew dammed SD, PRIVATE JINDer Clearad PRIVATE Istarle; (C) of Coast Maes vactored SSO in public ROW curb and gutter; City of Costa Maes vactored SSO in public ROW curb and gutter and disposed of ISSO and insewater in CMSD sanitary sever system at the Corporate Vard; Apartment complex needs to Increase the frequency of cleaning PRIVATE Isteral lines; Photographs were taken and are attached;
7/4/06	2	Private Property	0	200	0	0	315 Bedford	Orange	n/a	n/a	Grease	n/a	n/a
7/8/06	2	Private	300	800	500	0	1590 W. Palm Lane	Anaheim	1590 W. Palm Lane	Private cleanout	Grease	Grease caused obstruction	Property management was very responsive in obtaining a private plumber to clear obstruction.
7/12/06	2	Private	0	1620	4500	0	3534 W. Ball Road	Anaheim	3534 W. Ball Road	Private cleanout	Unknown	Unknown	N/A
7/26/06	2	Private	144	144	0	0	12905 Palm	Garden Grove	n/a	n/a	n/a	n/a	
7/28/06	2	Pacific Coast Properties (PCP) Management for 12-unit apartment complex located at 564 West Hamilton (Beth - Office 714-378-1366, Cell - 714-331-7847);	20	80	180	20	584 West Hamilton Street;	Costa Mesa, CA;	Blockage in PRIVATE latera	Cleanout (CO) on PRIVATE property;	Grease and debris blockage in PRIVATE lateral lind on PRIVATE property;	Grease and debris blockage in PRIVATE lateral line on PRIVATE property;	PRIVATE SSO called in to City of Costa Mesa Comm Center - Fire Dept and PD responded for potential hazardous materials spill and traffic control: CMSD Staff encountered SSO while traveling home from work; Pacific Coast Properties (PCP) Management for 12-unit apartment complex located at 584 West Hamilton (Beh - Offi 71-437-51366, Coll : 71-4331-7847); Biokage in PNIVATE lateral inter on PRIVATE property; Estimated 80 galons SSO Concerted SSO in public ROW curb and guter and disposed of SSO and rinsewater in CMSD sanity sewer system at the Corporate Yard; CCM dammed SD, Private plumber cinand our PRIVATE lateral; PCP took plumbers advice to increase frequency of lateral cleaning and install anothe CO to assist in cleaning the lateral; Photographs were taken and are attached;
7/30/06	2	Private	220	120	100	0	1919 W. Coronet Ave	Anaheim	1919 W. Coronet Ave	Private cleanout	Break	Break caused obstruction	N/A
8/3/06	2	Earl Benton 714-964-7697, home address 20271 Meander Lane, HB 92646.	20	20	170	0	4932 Kona Dr.	Huntington Beach	4932 Kona Dr., sewer line inside of apartment building	The discharge pipe fo the washing machine.	r Grease blockage	Grease blockage in private sewer lateral line.	The owner of this four unit appartment complex does not do much maintenance or upkeep on this property.
8/5/06	2	Private	1000	5300	6000	1000	1250 S. Brookhurst St.	Anaheim	1250 S. Brookhurst St.	Private cleanout	Roots, break, unknown	Unknown cause of obstruction, possibly roots or a break in the line.	Private plumber was unable to clear obstruction with snake. Another plumber with a jetter was called in, after several hours of delays, to eventually clear obstruction.
8/27/06	2	Private	215	215	0	0	12905 Palm	Garden Grove	n/a	n/a	n/a	n/a	
9/8/06	2	Earl Benton, 20271 Meander Ln., HB 92646	5	5	105	0	4932 Kona Dr.	Huntington Beach	Lateral sewer line of 4932 Kona Dr.	Sewer discharge pipe in the laundry room.	Grease and root blockage	Grease and root blockage of private sewer line.	From the looks of this four unit complex the owner, Eral Benton, does not maintain the property very well.
9/9/06	2	PRIVATE FACILITY - South Coast Alcohol & Drug Program Facility;	25	25	100	25	2212 Placentia Ave;	Costa Mesa, CA;	PRIVATE lateral blocked with debris;	PRIVATE lateral blocked with debris;	PRIVATE lateral blocked with debris;	SSO flow from PRIVATE latera blocked with debris from 8-unit apt complex to rear facility sump pump operated intermittently;	City of Costa Mesa Comm Center called SSO in to District Maintenance Supervisor; District Maint Supervisor blocked Storm Drain (SD) @ 1534 hrs and turned off facility sump pump; Costa Mesa Public Services vactored public right of way (ROW) and returned/disposed of SSO into District sanitary sever system; District called C&R Drains to clear PRIVATE lateral; Up to 25 gallons of SSO was contained in the SD and evaporated; Photographs were taken and are attached;
9/15/06	2	FV	20	20	0	0	18774 Brookhurst Street	Fountain Valley	roots in private lateral		grease	roots in private lateral	NA
9/17/06	2	Private	395	395	0	0	10191 Lampson	Garden Grove	n/a	n/a	n/a	n/a	
9/21/06	2	Private	30	20	500	0	537 N. Magnolia Ave.	Anaheim	537 N. Magnolia Ave.	Private cleanout	Grease	Grease caused obstruction	A previous spill occurred at this address on 6/10/06. The spill occurred when the sewage lift pump failed, partially as a result of the failure to implement the corrective actions required in the first Compliance Order, and partially due to new conditions.

9/23/06	2	Private	0	0	0	0	4672 PLUMOSA DRIVE	YORBA LINDA	N/A	N/A	BLOCKAGE -	N/A	N/A
9/23/06	2	Private	U	U	0	0	4672 PLUMUSA DRIVE	TORBA LINDA	N/A	N/A	UNKNOWN	N/A	NA
9/26/06	2	Private Property	0	0	0	0	13626 ESTERO CIR	Tustin	Clean out	Clean out	Blockage	Misc. debris	Notifications were made to Control One and RWQCB. Corwin Brown from Health Care was asked to assist in speaking with Apartment Complex Manager so they would call the plumber.
10/4/06	2	PRIVATE SSO - Apartment Owner/Manager Ed Glinka - 714-926-3605;	288	0	0	288	779 Shalimar Drive;	Costa Mesa, CA;	PRIVATE PROPERTY deanout in rear of property in alley:	PRIVATE PROPERTY cleanout in rear of property in alley;	Root in lateral line ir front of facility blocked lateral line which runs under the 4 unit apartment complex;	Root in lateral line in front of facility blocked lateral line whic runs under the 4 unit apartmen complex; Later verified with private CCTV;	City of Costa Mesa Code Enforcement Officer Tim Sun notified District Maintenance Supervisor; PRIVATE SSO - Apartment Owner/Manager Ed Glinka - 714-926-3805 is the responsible party; A continuing facility lateral problem caused an estimated 288 againos GS SSO to flow onto private property/alley over a 24 hour period. Private plumber cleaned lateral; Most of SSO evaporated while flowing to Storm Drain (SD); Estimated 288 aglions SSO to recoverable due to evaporation and entry into the SD; Root in lateral line in front of facility blocked lateral line which runs under the 4 unit apartment complex, later verified with private CCTV; GMSD Maintenance Supervisor and City of Costa Mesa Code Enforcement Officer Tim Sun recommended Owner/Manager CCTV into to verify roots and work with the City of Costa Mesa to possibly remove tree based on the video and repair the lateral line to prevent future SSOs; Photographs were taken and are included;
10/5/06	2	Private	0	20	0	0	703 POPPY	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	YARD -> CURB & GUTTER -> ALL FLOW CONTAINED	NA
11/9/06	2	Private Property	0	100	225	0	614-616 E. Pine Street	Santa Ana	Unknown	Clean out on property	Unknown	Plumber who cleared the line was not sure of what caused the backup.	None
11/12/06	2	Private Property	0	0	0	0	1192 MITCHELL	Tustin	24 inch	Manhole	Blockage	Misc. debris	Dindo made regulatory notifications after receiving the spill notification made at 1130 hour. John Ralis (OCHCA) was asked to assist by speaking with apartment manager to call a plumber. RDMD was also notified by Control One.
11/22/06	2	Private	0	0	0	0	235 W. LINCOLN	ORANGE	N/A	N/A	BLOCKAGE - UNKNOWN	SANTIAGO APARTMENTS - BY TRASH AREA NEXT TO LAUNDRY ROOM	NA
11/25/06	2	Private Property	405	0	0	0	1001 W. Stevens	Santa Ana	Private lateral	Private clean out	Grease	Grease in private lateral	None
11/25/06	2	Private	0	0	0	0	24371 EL TORO ROAD	LAKE FOREST	N/A	N/A	GREASE	CURB & GUTTER -> STORM DRAIN	May be R-9
11/28/06	2	Der Wagenmeister owner, Richard (949-633-8033);	98	0	0	200	722 West 16th St;	Costa Mesa, CA;	Owner cleaned roots from lateral and pushed in roots into Main Line, 400ft (Drop MH) and 140ft from situs address;		Pushed in tree roots from private propert lateral;	Pushed in tree roots from private property lateral;	Der Wagenmeister owner, Richard (949-633-6033) reporterPRIVATE SSO to CMSD; CMSD Crew unable to enter private property to Vactor SSO and RinseWater; Wastewater flowed with owner Rinsewater 250t to SD; Unercoverable; PRIVATE PROPERTY SSO due to lack of backwater prevention device - property is 10° below CMSD MH cover on W 16th St; CMSD recommended property owner install a backwater prevention device in lateral line to prevent future backups on private property. CCTV lateral, and remove the four trees directly over the private lateral line; Photographs were taken and are attached;
12/11/06	2	Casa Linda Condos & Montero Planning	350	0	0	0	300 E. Chestnut Street, 92701	Santa Ana	At pump lift station.	Pump lift station	Private lift station	The City responded to check City sewer main and found no problems. The spill was coming from the parking garag at 300 E. Chestnut. Montero Plumbing was working on the lift station pumps.	None
12/14/06	2	Private Property owner 2630 W Porter	0	200	500	0	2630 W Porter - behind apartments in Alley	Fullerton	Private lateral	Lateral cleanout	Unknown		City sewer crews working in the area noticed overflow in alley. Crews set up combo truck vacuum and contained/vacuumed sewage until water service was shut off to stop flow. Private plumber responded to clear blockage. Crews washed down/vacuumed area.
12/27/05	2	City of Santa Ana	450	200	250	200	300 W. Second St.	Santa Ana	H09-028	Manhole cover	Grease	No maintenance program caused grease build-up and resulted in flow back-up	Affected areas were cleaned up by Aladdin Emergency Clean-up Service. Increase maintenance from the Plaza del Sol Apartment complex.

12/28/06	2	Private	200	400	200	0	537 N. Magnolia Ave.	Anaheim	Pump Station Failure	Private manhole	pump station failure	pumps are believed to have burned out	This was an unusual spill since it is the third at this location, however, since it was caused by something different each time it has occurred, the order will focus on items that may not have been satisfied in previous orders and items that would help prevent future recurrances of this spill.
12/30/06	2	Private	100	2000	2000	2000	2704 W. Ball Road	Anaheim	lateral from last manhole in complex to street	Private cleanout	grease and perhaps roots or a break	Grease alone or in conjunction with a break or roots caused th obstruction	
Totals	215		134,005	74,887	66,766	42,759							
Commercial													
4/2/02	3	Private	0	0	0	0	2325 E. PCH	Newport Beach	Grease Interceptor	Grease Interceptor	Unknown	See Remarks	Grease interceptor was overflowing (Brio Rest)
4/19/02	3	Private Property	10	8	8	2	18802 Bardeen Ave.	Irvine	4" Sewer Line	V-drain	Blockage	Root obstruction in lateral line a Possible Broken Lateral	NA
5/27/02	3	Private Property	0	0	0	0	na	na	na	na	na	na	California Pizza Kitchen. Not listed in supplied OCHCA report or on Region 8 reports
6/28/02	3	Private Property	0	0	0	0	631 S. Palm	La Habra	n/a	n/a	n/a	n/a	
7/6/02	3	Rich Darling - Private Property	90	60	450	0	16490 Bolsa Chica Street	Huntington Beach	In the parking lot at 16490 Bolsa Chica Street.	Clean Out	Debris	Debris built up in the line, causing the blockage.	Statements were obtained from employee's of Jon's Coffee Shop. Line was cleared before City crews arrived.
7/10/02	3	Private	480	20	0	0	25521 Commercenter	Lake Forest	n/a	n/a	Construction debris	Construction debris	
7/15/02	3	Private Property	0	0	0	0	1841 VON KARMAN	Irvine Buisness Complex	Private lateral	Indoors	N/A	N/A	Walt reports blockage cleared before his arrival, plumber at location. OCSD lines are running free and clear. No assistance needed.
7/25/02	3	Costa Mesa Sanitary District	25	25	1000	0	Marie Callender's:363 East 17th St, Costa Mesa, CA	Costa Mesa, CA	Private Lateral	Private Lateral Cleanout	Blockage: Grease in private lateral	NA	Marie Callender's private lateral blocked with grease; Rescue Rooter opened a 4' cleanout to clear the line; When opened, sewage spilled out from the sidewalk cleanou onto the street and curb for approx 10 minutes while contractor cleared the lateral line Field crew blocked downstream strem drain to provide additional containment. See photos. District crew hydro-rodded the District Main line to break up any grease disologid initi of trom the lateral. Strom drain was blocked to contain any sewage within it and all sewage was contained. District vactored up street and curb spill, vactored ou the storm drain containment for insewater, rinesed the street with fresh water and vactored up the rinsewater. See photos.
8/9/02	3	Private	0	0	0	0	5465 Alton Pkwy.	Irvine	n/a	n/a	Illegal connection to storm drain	Illegal connection to storm drai	
8/14/02	3	Gas Station	12	12	20	0	20002 Beach Blvd.	Huntington Beach	In the sidewalk alongside 20002 Beach Blvd	Clean Out	Debris	A gas station sewer line had become plugged by paper towels.	
8/22/02	3	PWA-City of Santa Ana	90	450	450	90	2502 W. Seventeenth St.	Santa Ana	Private property	Clean out	Grease combined with surgical gloves (dental office)	Grease combined with surgical gloves (dental office)	
9/16/02	3	CITY OF ANAHEIM	200	200	300	0	1511 N. Euclid Ave.	Anaheim	Clean out at back alley of 'Super Torta'	private clean out	grease; possible lint	grease and possible lint	

9/17/02	3	El Pollo Loco Restaurant, 1941 Harbor Bivd, Costa Mesa, CA 92626	0	0	0	0	1941 Harbor Bivd	Costa Mesa, CA	Grease blocked El Pollo Loco grease trap and cleanout.	El Pollo Loco grease trap and cleanout in sidewalk between facility and drive-thru.	Grease blocked EI Pollo Loco grease trap and cleanout	Grease blocked El Pollo Loco grease traja and deanout, causing overflow across sidewalk, across drive thru, intr alley down Bernard St gutter and into Harbor Bivd storm drain.	Grease blocked EI Polio Loco grease trap and cleanout, causing overflow across sidewalk, across drive thru, into alley down Bernard St gutter and into Harbor Blvd sto drain. EI Polio Loco contractor cleared grease trap and facility inside lines, but overflow thushed as described. Most important is the follow-up – Revisit to EI Polio Loco on 9-25- 02 - full cooperation from managers with documents/records review. Emphasized clean grease trap maintenance and proper flushing – Provided coyo of vater Quality Guidelines for Exterior Restauran Cleaning Operations' (OC Stormwater Porgam) and "Restaurant Owner's Guide for Grease Control" (CMSD). Further Follow-up Action: District is redistributing both guides with a "Warning Notice" attached to all District restaurants. Post-activity photograph taken of site reflecting cleaned area, with only vehicular road grime in drive-timu, alley and streats. El Polio Loco contractor & District vactored flush & storm drain.
9/18/02	3	Private: Lusardi Development	0	50	50	0	Harbor Blvd. N/O Ball Rd.	Anaheim	Sewer line break at Giannell Electric, Harbor Blvd. N/O Ball Rd.	sewer line	Break in sewer line	Sewer line break at Giannelli Electric	
9/18/02	3	Private Property	0	0	0	0	6234 Industrial Way Westminster	Westminster			grease & roots	grease & roots on private property	
10/9/02	3	Hannam Market, private property	0	0	0	0	4875 La Palma Ave.	La Palma	Private lateral	Manhole	Grease blockage on private property	Grease blockage on private property	Private contractor sanitized and cleaned up
10/17/02	3	Koo Koo Roo Restaurant, 212 E 17th St, Costa Mesa, CA 92627	120	120	170	0	17th St between Orange Avenue and Westminster	Costa Mesa, CA	Koo Koo Roo Restaurant lateral , biocked with grease and paper towels	Koo Koo Roo Restaurant lateral cleanout	Grease and paper towels blocked Koo Koo Roo Restauran lateral.	Grease and paper towels biocked Koo Koo Roo Restaurant lateral, causing SSO into E 17th St curb and gutter.	Main line running clear; Koo Koo Roo contracted plumber cleaned out private lateral; grease blockage cleared from lateral line into District Main Line; Crew contained SSO upon arrival, vactored SSO, flushed area with 50 gals fresh water and vactored up rine water. Koo Koo Roo manager showed documentation of lateral cleaning 3 months earlier; Field Crew advised Koo Koo Roo manager to clean out lateral more frequently- everp 5 weeks - to prevent another occurrence. Field Crew ran Main Line to ensure unclogged grease did not block main line. Crew further advised Koo Koo Roo manager to instal a grease trap. Staff is re-sending 2 brochures: CMSD "Restaurant Owner's Guide for Grease Control" and "Wanning" and OC "Water Quality Quidelines for Exterior Restaurant Cleaning Operations." Also informed Koo Koo Roo employees of need to properly dispose of paper towels in the trash and not in the sewer system.
10/22/02	3	Private	20	0	0	0	7 Holland	Irvine	n/a	n/a	n/a	Unknown	
10/25/02	3	Private	5	0	0	0	21212 Bake Pkwy.	Lake Forest	n/a	n/a	n/a	Unknown	
11/5/02	3	Yousef Ibrahim	551	100	600	451	7232 Edinger	Huntington Beach	7232 Edinger	Manhole	Grease	Chunks of Asphalt	None
11/6/02	3	Private Property	0	100	50	0	9191 Bolsa Ave Westminster	Westminster	grease interceptor	grease interceptor	grease	grease interceptor not properly serviced	
11/11/02	3	Private Lateral Tony Romas Rest.	800	700	1500	0	3642 Katella	Los Alamitos	private lateral	private lateral clean ou	Igrease	grease blockage	n/a
11/13/02	3	Private Lateral Tony Romas Rest.	500	500	1500	0	3642 Katella	Los Alamitos	private lateral	private lateral clean ou	Igrease	incomplete hydroflush	n/a
11/14/02	3	Private Party, Maguroya Japanese Restaurant located ir the Yorba Station shopping center.	100	100	200	0	Yorba Station Shopping Cente 18242 Imperial Hwy	Yorba Linda	Grease interceptor outside and behind restaurant	plugged interceptor device	grease	cooking grease in unmaintaine grease interceptor.	This was a private property overflow. The local health services agency addressed the restaurant management.
11/15/02	3	Carl's Jr,private property	0	20	0	0	5012 La Palma Ave.	La Palma	Private lateral	Private lateral cleanou	Grease blockage on private property	Grease blockage on private property	Private contractor sanitized and cleaned up
11/15/02	3	Pacific West Corp.	150	5 Gal.	24	146	101 Main Street	Huntington Beach	101 Main Street	Grease Interceptor	Grease	Possible Lack of Maintenance- Grease	None
11/21/02	3	Private Property	120	120	60	0	361-371 Oak Place	Brea	Sewer	Manhole	Don't Know	NA	This was a private property spill.
11/30/02	3	Denny's Resturant	165	35	0	0	n/a	n/a	Line blockage	Line Blockage	Line blockage	n/a	(Not in originally submitted OCHCA report or Region 8 reports. Listed in OCHCA Beach Closure report)
12/2/02	3	Private Property	100	10	110	90	2300 Main Street, east of Von Karman	Irvine	Private Lateral Sewer	Clean out	Blockage from Misc debris	N/A	NA
12/3/02	3	Private	150	100	0	0	Big Canyon Golf Course	Newport Beach	n/a	n/a	Roots and grease	See Remarks	Overflow on Big Canyon Golf Course

							1	1					
12/3/02	3	Richard Darling	180	90	190	90	16490 Bolsa Chica	Huntington Beach	16490 Bolsa Chica	Cleanout in Parking Lot	Unknown at the time, turned out to be a separation in the pipe.	Unknown at the time, turned ou to be a separation in the pipe.	None
12/4/02	3	HB Elks Lodge	218	100	250	118	7711 Talbert Ave.	Huntington Beach	7711 Talbert Ave.	Manhole cover in Parking Lot	Grease	Possible Lack of Maintenance- Grease	None
12/4/02	3	Richard Darling	480	400	490	90	16490 Bolsa Chica	Huntington Beach	16490 Bolsa Chica	Cleanout in Parking Lot	Unknown at the time, turned out to be a separation in the pipe.	Unknown at the time, turned ou to be a separation in the pipe.	None
12/10/02	3	Private Property	0	0	0	0	1770 W. La Habra	La Habra	n/a	n/a	n/a	n/a	
12/11/02	3	Private Lateral Yucatan Grill Rest.	900	900	1500	0	12147 Seal Beach Blvd	Seal Beach	private lateral	private lateral clean ou	ugrease	grease blockage	n/a
12/20/02	3	Private	640	1625	0	0	San Canyon & Burt Rd.	Irvine	n/a	n/a	Unknown	Unknown	
12/31/02	3	El Toro Bravo Restaurant, 739 W 19th St. Costa Mesa, CA 92627	0	480	300	0	El Toro Bravo restaurant @ 739 West 19th St	Costa Mesa, CA	Grease/commeal plugged E Toro Bravo lateral line forcing SSO out of cleanout cover and into the parking it where it was contained, returned to sever system. Field Crew informed E Toro Bravo manager of SSO status - asked manager to dean cleanout.	2 inches in height. Field crew remained in	pickhole 2 inches in	cleanout, located in the parking lot, percolated raw sewage out	Grease/commeal plugged EI Toro Bravo lateral line forcing SSO out of cleanout cover aria into the parking lot. Field Crew informed EI Toro Bravo manager of SSO status - asked manager to dean cleanout. Approximately 480 gallons of SSO spilled out of cleanout into EI Toro Bravo parking IO. Field Crew served manager fully contained SSO in parking lot. After Rescue Rooter unblocked lateral line, manager flushed parki to with fresh water. SSO and flush water wer disposed of into the sever system. Field Crew remained on site to ensure raw sewage was contained, parking lot was flushed and both severa and flushwater wer disposed of in the sever system. Staff called property owner, OCHCA, RWQCB, Office of Emergency Services, Costa Mesa Building Inspectors. EI Toro Bravo andré o' namager inglical hortos were taken. Staff alled proverty owner, OCHCA, RWQCB, Office of Emergency Services, Costa Mesa Building Inspectors, EI Toro Bravo'de o' namager inglical hortos were taken. Staff a working with City of Costa Mesa (CCM) Building representatives to clarify interpretation of CCM Ordinance 97-20 and Building/NPDES reporting requirements.
1/7/03	3	Rubios Restaurant	50	50	750	0	16672 Beach Blvd. Suite# 101	Huntington Beach	16672 Beach Blvd. Suite# 101	Grease Trap	Lack of Maintenance	Lack of Maintenance/Grease trap had not been cleaned out for over a year.	None
1/16/03	3	Private Spill: Rodi Properties	0	175	275	1	12th Street	Seal Beach	Private property; parking lot behind restaurant	Cleanout	Grease	Restaurant grease interceptor had stoppage	n/a
1/16/03	3	Freeway Industrial Park	2080	450	1070	1630	7402 Edinger	Huntington Beach	7402 Edinger	Cleanout	Lack of Maintenance	Lack of Maintenance/Grease/Crew Reported that grease logs were coming out into main sewer line	None
1/20/03	3	Private	0	0	0	0	3955 Alton Pkwy.	Irvine	n/a	n/a	Grease	Grease	
1/23/03	3	Private	300	0	0	0	19752 Macarther Blvd.	Irvine	n/a	n/a	Unknown	Unknown	
1/30/03	3	Private Spill	1000	0	0	0	3435 Newport Blvd.	Newport Beach	n/a	n/a	Grease, Paper products	See Remarks	(Pavillons Supermarket) Blockage of paper products, feminine hygiene products, grease. (Originally marked as unknown for surface water. Reported on OCHCA Beach Closure Report)
2/4/03	3	Private (KFC)	0	5	105	0	150 W Orangethorpe Ave	Fullerton	Private Lateral	Lateral Cleanouts and Grease Interceptor	Grease	Lateral was plugged upon arrival. Likely cause-grease, possibly toilet debris. KFC personnel rodded and cleared unknown blockage in lateral.	Upon arrival, City crew observed solidified grease in curb and gutter area and on private property at Kentucky Fried Chicken (KFC), KFC personnel on site informed City crew lateral was blocked. Crew continued inspection and observed grease trap full and lateral deanouts tulb unt or overflowing at the time. Area was wet form recent washdown by KFC personnel preventing City crew from pippointing overflow source. KFC plumbers arrived and cleared blockage in lateral. Service arrived to clean grease trap. City crew washed down, steam cleaned and vacuumed area. 5 gallons of grease were removed and transported to OCSD plant. Code enforcement to follow up.
2/27/03	3	Private Property	25	180	180	25	2097 E Orangethorpe Placenti	Placentia	private lateral line	clean out	Grease	Grease build up	Yorba Linda Water district Responded and cleaned up the spill also picked up the wash water. This spill was located on priviate property.
		PRIVATE PROPERTY		İ					1	i	1		

3/10/03	3	Private Business	0	10	60	0	150 S. Harbor Blvd.	Fullerton	Private grease trap manhole	Private grease trap manhole	Grease	Full grease trap	City crews Gonzalez, Hernandez and Rangel were called out to contain a private greate trap spill at Knowtwood restaurant. Grease and sewage spilled out of interceptor manhole onto surrounding sidewalk and parking tot to the rear of building. Crews contained spill with dir. Building owner. Code Enforcement. Police Dept. and Health Dept were notified. JC grease buyers was called to clean interceptor. City crews washed down, vacuumed and returned all sewage to sewer system.
3/18/03	з	Daniel Moran, Investors Property Services	0	240	300	0	1212 S. Bristol Street, Santa Ana, CA	Santa Ana	Private Spill	Clean out	Grease/Private Spill There are several restaurants located in the shopping center that maybe dumping grease in the lateral.	There are several restaurants located in the shopping center that maybe dumping grease in the lateral.	This was a private spill handled by Orange County Health.
3/27/03	3	Private	0	0	0	0	20 Goodyear	Irvine	n/a	n/a	Rocks	Rocks	
4/7/03	3	Private Lateral Sharam Afshani	500	500	1500	0	Grease Interceptor 4348 Katella	Los Alamitos	private lateral	private grease interceptor	grease	grease blockage	Grease interceptor was at a low point in the system and was not the cause.
4/20/03	3	Private Property	3	0	0	3	1091 OLD IRVINE BLVD.	Tustin	Private lateral	Private Clean out	Blockage Grease clog	N/A	N/A
4/21/03	3	Private Property	0	0	0	0	1400 Magnolia St. Westminste (14000 Magnolia - no 1400)	Westminster	cleanout	cleanout	grease	grease	This spill occurred on private property. The private security guard who called the spill into the Westminister PD reported the spill had been occurring for at least 24 to 48 hours, but the property owners had instructed him not to report it to anyone. He eventually reported to spill, but because it had been occurring for an undetermined amount of time, it was impossible for our rever to accurately assess how much sewage was spilled and how much escaped into the storm drain. Our field crew immediately called the OCHCA, and Jeff Warren responded.
5/1/03	3	Private	60	0	0	0	3 Burroughs	Irvine	n/a	n/a	Unknown	Unknown	
5/1/03	3	Private	0	25	0	0	2751 Coast Hwy.	Newport Beach	Grease Trap	Grease Trap	Unknown	See Remarks	Grease trap was overflowing. 5 gallons per minute.
5/1/03	3	Elis Nourafchan	900	900	1100	0	6905 Warner Ave.	Huntington Beach	6905 Warner Ave.	Cleanout	Grease and debris blockage	Grease buildup from a number of restaurants in the complex.	
5/7/03	3	700 N. Valley Street	200	20	30	200	700 N. Brookhurst Street	Anaheim	On Gramercy Avenue, east of Brookhurst Street	Private sewer clean or at Mobile Gas Station	Paper towels obstructing the flow.	Paper towels were obstructing the sewer line which caused th overflow.	
5/7/03	3	Private Property	0	0	0	0	BLACK ANGUS RESTAURANT, BROOKHURST ST. & TALBERT IN FOUNTAIN VALLEY.	Fountain Valley	Lateral	Cleanout	Blockage Grease clog	N/A	NA
5/15/03	3	Private Property	20	30	30	0	7100 KNOTT AVE.	Buena Park	Lateral	Cleanout	Blockage Root obstruction in lateral line	N/A	N/A
6/7/03	3	West Bay Café	40	40	40	0	6600 Admiralty Drive	Huntington Beach	6600 Admiralty Drive	Cleanout	Grease	Grease from Café caused blockage.	None
6/11/03	3	Kikuya Japanese Rest.	90	50	150	40	8052 Adams	Huntington Beach	Front of Restaurant on sidewalk	Manhole	Grease	Grease causes blockage in line Lack of Maintenance	None
7/14/03	3	Private Property Owners (4) of shared lateral.	20	40	340	20	1320 S. State College Boulevard	Anaheim	Near 1320 S. State College Boulevard	Private Cleanout	Grease	Grease buildup obstructing sewer flow.	Unusual situation as there are four (4) properties served by a single lateral. Based on observations it was clear the cause of the blockage was excessive grease. The only grease bearing operation is the Restaurant at 1259 S. State College Boulevard. However, because all four properties discharge to this line, the responsibility for the split as well as the routine maintenance must be shared.

7/30/03	3	Private - Albertsons Inc	0	200	600	0	455 N State College Blvd	Fullerton	Private lateral	Private lateral cleanou in parking lot	Rags	Rags in lateral connection	Raynoso, Hernandez, Miller, Rangel, and supervisor Roseberry responded to report o sewer overflow in the parking lot of Sav-on. Original notification was made to City Fire Dept, who contained the spill in the gutter and notified the Police Dept (Rocco), who then notified Doug Reneau, Supervisor in the Street Dept. Doug relayed message to Roseberry and crews were called out. Business was instructed not to use water. Property owner had private plumber respond to clear blockage. City crews washed down spill area and vacuumed all sewage and wash water and returned to sanitary sewer system. Property owner later video inspected the lateral line and is in process of repairing defect.
8/1/03	3	Private	2500	0	0	0	MAIN & MAC ARTHUR	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN TO LANE CHANNEL.	
8/24/03	3	Hannam Market, private property	0	50	55	0	4875 La Palma Ave.	La Palma	Private lateral	Manhole	Grease	Grease blockage on private property	Private contractor sanitized and cleaned up
8/28/03	3	Private Property	0	0	0	0	18802 BARDEEN AV	Irvine	SBCO 420 Charlie Ambriz to evaluate the problem. Spill was in the residential property.	N/A	N/A	N/A	None
9/4/03	3	Private Property	0	0	0	0	17792 McFadden	Tustin	Blockage was determined to be in private property	Toilets backed up in Shopping Center Area	U	N/A	NA
9/18/03	3	Private Property	0	0	0	0	630 N. Beach Blvd.	La Habra	n/a	Washrack	n/a	n/a	
10/1/03	3	George Gonzalez (714) 957- 2529 - Private	0	540	1800	0	1128 S. Bristol St.	Santa Ana	Private lateral	6" clean out	to a 4" lateral at the p/l. This lateral	Cause of spill was a combination of large amounts greese and the lateral is a 6° line that connects to a 4° latera at the p/t. This lateral serves a market and laundromat, this lateral should be a 6° all the wa to the sewer main.	
10/1/03	3	Private Property	0	0	0	0	Jamboree at Big Canyon Golf Course	Newport Beach	Private manhole	Private manhole	Roots and debris	See Remarks	Opened manhole and cleared roots and debris over 10 ft deep manhole. Private manhole. Private property: Sea Island Community Association.
10/3/03	3	George Gonzalez (714) 957- 2529 - Private	0	180	680	0	1128 S. Bristol St.	Santa Ana	Private lateral	Clean out	Grease - Cause of overflow was the same as the spill on 10/01/03, large amounts of grease.	Cause of overflow was the same as the spill on 10/01/03, large amounts of grease.	
10/7/03	3	George Gonzalez (714) 957- 2529 - Private	0	120	420	0	1128 S. Bristol St.	Santa Ana	Private lateral	Clean out	Grease - Large amounts of grease from market.	Large amounts of grease in market.	
10/25/03	3	Seadiff Health Care Center	400	375	795	25	18811 Florida Street	Huntington Beach	Parking lot of Seacliff Health Care Center, 18811 Florida St	Four inch clean out.	Debris clogged private lateral	Buildup of debris in line probably caused by insufficient maintenance.	
11/12/03	3	Private Party	40	305	0	0	10201 Valley View	Cypress	n/a	n/a	n/a	n/a	
11/17/03	3	5665 E La Palma	2700	100	200	500	5665 E. La Palma Avenue	Anaheim	5665 E. La Palma Avenue	Private cleanout	Paper Towels	Paper towels obstructed the flow of the sanitary sewer line causing it to overflow.	The majority of the sewage remaining on the surface of the parking lot was collected during a washdown with the City's vactor truck. However, due to a misdiagnosis of where the spill cutlet to the nearby channel, the washdown of the parking lot (intended clean 'tracked sewage' and fluxb out remaining sewage in storm drain) this portion of the washdown was not collected.
11/18/03	3	540 North Euclid	20	19	50	0	540 North Euclid Avenue	Anaheim	540 North Euclid	Private sewer manhole	Grease	Grease obstructed the flow of the sanitary sewer line causing it to overflow	

11/29/03	3	777 Convention Way	50	0	50	0	Hotel Way East of 777 Convention Way	Anaheim	777 Convention Way	Private sewer manhole	Grease	Grease released by Anaheim Hilton obstructed the flow of the sanitary sewer line causing the overflow	
12/12/03	3	Private property owner	0	125	200	0	1616 West Katella Avenue	Anaheim	1616 West Katella Avenue	Private Cleanout	Metal from broken grate		This incident started with a complaint of odor which was the result of flow coming from an outdoor trash compactor. The owner/operator of the compactor, Food 4 less, was required to stop this flow, and moved the compactor to do so. However, in moving it, they broke the grate which covered the sever cleanout under the compactor, dropping metal into the lateral resulting in an obstruction and subsequently a sever split.
12/27/03	3	Private Property	50	100	250	50	17231 E. 17th Street	Tustin	8" Sewer Lateral	Manhole	Blockage, Grease clog	N/A	N/A
1/12/04	3	La Palma Hospital, private property	0	300	500	0	7901 Walker Street	La Palma	Private lateral	Private lateral cleanouts	Grease blockage on private property as well as debris	Grease blockage on private property as well as debris	Private contractor sanitized and cleaned up
1/13/04	3	The Lodge, a Food Service Establishment (FSE) at The Camp, 2937 Bristol St, Costa Mesa, CA	100	100	200	100	The Lodge is one of 3 Food Service Establishments FSEs) at The Camp address: Interceptor for The Lodge was blocked, forcing the SSO out o a vent hole at 2937 Bristol St.	Costa Mesa, CA	The Lodge is one of 3 Food Service Establishments FSEs) at The Camp address, Intercoptor for The Lodge was blocked, forcing the SSO out of a venthole <i>z</i> 2337 Bristol St.	Establishments FSEs) at The Camp address; Interceptor for The Lodge was blocked,	District Field Crew verified FSE grease blocked The Lodge interceptor.	grease blocked. The Lodge	OCSD informed CMSD of the SSO at the Food Service Establishment (FSE) known as The Lodge at 2937 Bristol St. District Crew arrived, contained the SSO, discussed corrective action with The Lodge employees, called the City of Costa Mesa National Pollutant Discharge Elimination System (NPDES) manager to the site and ensured The Lodge arranged for a plumber to clean out the Grease Interceptor. The Grease Interceptor cover appaared to be rusted closed and had not been opened for a long tri The site management company (Remm Group) directed the tenant (The Lodge) to implement a quarterly interceptor cleaning program. CMSD added the site to the District FSE contractor follow-up visits and compliance. The site angreases to have experienced overflows in the past as evidenced by the drive markings and The Lodge manager had not addressed the apparent overflows. The District Policy is to backchar the responsible party for private SSOs to which the District must provide resources to control. Photos were taken and are attached.
1/17/04	3	Private Property Owner	560	1600	500	0	1630 W. Katella Ave.	Anaheim	1630 W. Katella Ave.	Private Cleanout	Grease	Grease obstructed the flow of the Sanitary Sewer Line causing it to overflow	Second spill in 15 months
1/17/04	3	Brea	300	50	50	0	105 W. lambert Rd.	Brea	unknown	intercepter	unknown	NA	The property management and Alexander Soles from OC Health dept were on site at time of the sewer stoppage.
2/12/04	3	Norms Restaurant	400	400	900	0	16572 Beach Blvd.	Huntington Beach	Norms Restaurant 16572 Beach Blvd.	Cleanout drain.	Grease and food debris.	Grease and food debris from Norms clogged the sewer lateral causing sewage to come out of their cleanout pipe.	Due to a construction project adjacent to the catch basin, sandbags existed at the catch basin prior to this SSO.
2/24/04	3	Private Property Owner	50	100	500	0	2610 E Katella Ave.	Anaheim	2610 E. Katella Ave.	Private cleanout and private clarifier	Grease	Grease formation caused the sanitary sewer line to overflow	The staff at Orange County offices (located next door to J.T. Schmidt's) noticed the flo of water at 10:30 and notified the restaurant manager. Private plumber arrived by 11:30 AM to clear blockage and City of Anaheim was notified at 11:15 AM. Anaheim In
2/25/04	3	Rossmoor/Los Alamitos Area Sewer Dist.	500	490	1500	0	3642 Katella	Los Alamitos	private lateral	private lateral clean ou	grease	grease blockage	n/a
3/22/04	3	Private Spill	300	200	0	0	4525 W. Coast Hwy	Newport Beach	n/a	n/a	Grease spill at ChronicTaco	See Remarks	Containment setup at storm drain. Vacuum truck clean up spill, grease and stop overflow.
4/7/04	3	Private Property	100	40	0	100	164 Yorba Linda	Placentia	Priavate property lateral	lateral line	grease	grease	Spill was caused by grease from business located on Kraemer / Yorba Linda in a priavate parking lot and ran through the parking lot ending up on Bradford Ave.
4/12/04	3	Foodland Market	100	50	0	0	910 S. Euclid St.	Anaheim	910 S. Euclid St.	Private Cleanout	Grease	Grease caused obstruction.	Meetings have been held with representatives from Foodland.
4/12/04	3	Private Business	0	8	200	0	814 Williamson Ave	Fullerton	Private Lateral	Private Lateral Cleanout	Unknown		City crews responded to report of sewage seeping out of cleanout. City crews assisted private business to contained intermittent overflow at a sump box approximately 100° from cleanout. City crews rodded private lateral to clear blockage. All sewage was confined to driveway, swale area and sump tox at industrial area of Williamson. City crews washed down and vacuumed area and sump.
5/29/04	3	Private Property	0	0	0	0	17502 17TH STREET	Tustin	Sewer Line	Manhole	Blockage	Grease clog	NA

													1
6/10/04	3	2349 W. La Palma Ave., Anaheim	10	40	500	0	2349 W. La Palma Ave.	Anaheim	2349 W. La Palma Ave.	Private Manhole	Sewer lateral offset	have offset the Sewer lateral,	Apparent delay in notification to RWQCB was due to the fact that the spill had apparently not left the site when City Staff arrived. However, after interviewing onsite personnel, it was discovered that the spill had left the site but the water was voluntarily shut off which stopped the spill and made it appear as if it had not left the site. The plumber that the private property owner hirden do not yshut off the water, but cleaned and televised the sever lateral. An offset was discovered and was thought to have been caused by a private stormdrain installation, completed over a year ago. This could not shown conclusively so the City performed repair.
6/16/04	3	Sushi Ya	100	75	100	175	50 Centerpointe Dr.	La Palma	Private lateral	Private lateral cleanou	uGrease	Grease interceptor failure.	Private contractor sanitized and cleaned up
6/24/04	3	Private Spill	400	100	0	0	500 Superior	Newport Beach	n/a	n/a	Unknown	See Remarks	Vactor setup dirt berm@catch basin. Vacuum setup @ manhole to stop SSO.
6/28/04	3	Private property owner	0	35	2000	0	305 N Harbor on Wilshire side	Fullerton	Private lateral from 305 N Harbor Blvd	Private lateral cleanou on Wilshire Ave	^{II} Roots and debris	Possible roots from parkway tree. To be determined	City crews responded to report of overflow on sidewalk. Flow was contained at 239 W Wilshine Ave. City crews cleared root and debris blockage in private lateral from businesses at 305 & 315 N Harbor. Crews washed down and vacuumed approximately 35 gallons of swage combined with heavy irrigation run off approximately 1000 feet down Wilshine Ave. guter area. Lateral line will be video inspected to determine if roots from the parkway tree are intruding into the lateral. Area sewer mains were maintenance jetted, no problems found.
6/29/04	3	Private Property	90	60	0	30	1300 Kraemer	Placentia	Private property lateral	lateral line	grease	grease	Spill was caused by grease from business located 1300 Kraemer in a priavate parking lot and ran through the parking lot ending ending up on Kraemer blvd.
7/12/04	3	Private Spill	600	0	0	0	1000 Dove St.	Newport Beach	Private cleanout	Private cleanout	Grease & Paper Products	See Remarks	Setup vactor on Dove to catch & contain overflow from private cleanout at driveway.
8/5/04	3	Private Party	20	180	0	0	4901 Lincoln Ave.	Cypress	n/a	n/a	n/a	n/a	
8/12/04	3	Private property owner	O	20	200	0	741 W Commonwealth Ave	Fullerton	Private lateral	Lateral cleanout near sidewalk	Unknown		City Vactor crew observed lateral cleanout from small business complex overflowing onto City street. Crews stopped and set up Vactor vacuum at 770 W Commonwealth Ave to contain spill. The City's lateral crew responded and cleared blockage in lateral to poverflow. City crews washed down and vacuum de swage on street, sidewalk, a curb. On 8-16-04, property owner was notified of problem and lateral responsibilities. Owner had recently had lateral cleaned and vide inspected. We advised owner to ha tenants keep a close eye on the problem and immediately call a plumber if another problem occurs, but call the City immediately cleanout overflows so our crews car contain spill until plumber arrives. Owner was cooperative.
9/9/04	3	Private	10	0	0	0	25361 Commerce Center Dr.	Lake Forest	n/a	n/a	Wood and concrete	Wood and concrete	
9/13/04	3	James Estrella - Facility Manager	5	10	10	0	1628 South Anaheim Way	Anaheim	1628 South Anaheim Way	Private cleanout	Foreign objects	Foreign objects clogged sewer line	The flow was intermittent resulting in an estimated rate of 10 gal/hr
10/8/04	3	Wendy's Restaurant	10	20	0	0	2011 East La Palma Avenue	Anaheim	2011 East La Palma Avenue	ePrivate manhole	Grease	Grease clogged sewer line	Any washdown was performed by Restaurant staff under supervision of OCHCA.
10/21/04	3	New Mark Merill Companies - Ralph Woebkey 2180 E. Lincoln Ave., Santa Ana 92806 (714) 956-3411	690	690	2660	690	2307 S. Bristol St.	Santa Ana	Private lateral	Clean out	Grease	There are several restaurants located in the shopping center that maybe discharging grease into the sewer system.	State ID #04-5508
11/1/04	3	Private party lateral blocked with grease;	0	50	100	0	200 East 17th St;	Costa Mesa, CA	SSO spilled from private lateral cleanout approximately 10 feet from the curb;	not have been	d Grease blocked the interceptor and the private lateral;	Grease blocked the private lateral cleanout at 200 E 17th St; Fully contained;	SSO spilled from private lateral cleanout approximately 10 feet from the curb; Grease interceptor appeared to not have been matitatined as evidenced from rusted bolts and cover, leading to grease blockage. District Crew blocked Storm Drain (SD) with rubbe mats to fully contain SSO. District Crew selimated SSO via visual pool estimated to be So gallons = a 3 agimin'n x60 minuse. Pivrate owner obtained services of plumber and cleaned out the lateral line - need to follow up to ensure interceptor is cleaned; placed site on maintenance program; Photographs were not taken;
11/4/04	3	South Coast Village	0	600	600	0	1001 W. MacArthur	Santa Ana	Unclear	Drain in laundry room	Roots	Build up of roots in sewer laters	1
11/5/04	3	Private	150	0	0	0	STANFORD AT NELSON	GARDEN GROVE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN.	NA

	1											1	,
11/15/04	3	Private	250	0	0	0	#1 Federation Way	Irvine	Private manhole	Private manhole	n/a	Private manhole, unknown blockage	
11/23/04	3	Private Property	0	0	0	0	171 FIRST ST.	Tustin	U	U	Blockage	Misc. debris	NA
11/24/04	3	FV	120	120	0	0	16175 Harbor Blvd	Fountain Valley			FOG accumulation	grease - no grease interceptor	NA
11/26/04	3	Private	1080	0	0	0	22 Pergola	Irvine	Private manhole	Private manhole	Roots	Private manhole, roots in line	
12/10/04	3	Private Property	0	0	0	0	4516 CHAPMAN AVE	Orange	NA	Manhole	U	U	NA
12/11/04	3	Woo Chung. 9944 Garden Grove Blvd., Garden Grove	20	80	100	0	2801 W. Ball Road	Anaheim	2801 W. Ball Road	Private Cleanouts	Grease	Roots blocked pipeline, causing sewage to overflow.	Apparently very little sewage actually reached the storm drain as it tended to pond on- site. Tenants informed us that a plumber had worked at this location before and removed a large amount of rocks. However, on this occasion hard evidence of discharging grease to the sewer line was the primary factor for the problem.
12/16/04	3	Royale Health Care Center	300	1600	1600	300	1027 W. Central Ave.	Santa Ana	Private sewer line	Pick hole of manhole	Grease	Large amounts of grease deposits from poor maintenance program	State ID #04-6597
12/19/04	3	Albertson's	0	200	0	0	3049 E. PCH, CDM	Newport Beach	Cleanout. Blockage on private lateral.	Cleanout	Blockage in private lateral	See Remarks	Kitty litter used to build control dykes to contained flow from cleanout. Overflow from supermarket. Parking tot was shutdown from one end to another to stop cars from driving thru puddes of sewage in to. OCHD (Control) and RWQCB (CSE) called. Corwin Brown and Monica Mazur cabled back from OCHD. OES Control # is WH6655 Plumber called by Henry the Mgr. from Albertsor's to clear blockage from private later Vacuum unit 5503 and hydro Unit 5517 used to clean up parking lot.
12/20/04	3	Private Property	0	0	0	0	2355 MAIN ST	Irvine	U	Manhole	Blockage	Other Debris	NA
12/21/04	3	Ron Marshall, Manager of Mr. Stox restaurant	188	100	400	0	1105 E. Katella Avenue	Anaheim	1105 E. Katella Avenue	Private cleanout	Paper Towels	Paper Towels blocked pipeline, causing sewage to overflow.	OCHCA visited the location to determine if there were any issues inside the restaurant
1/2/05	3	7232 Edinger shopping center	70	980	1,480	70	7232 Edinger	Huntington Beach	City's 8 inch sewer line	Manhole cover pick holes	Grease	Grease from a private shopping center lateral flowed into City's main line.	
1/14/05	3	Pavilions Von's	0	700	0	0	Von's Pavilon	Newport Beach	n/a	n/a	Grease logs & grease in pipe	See Remarks	Vactor used to vacuum up sewage flow. Flow did not enter drain.
1/17/05	3	Private	123	0	0	0	14400 Culver Dr.	Irvine	Grease Trap	Grease Trap	Grease	Grease Trap overflow	
1/19/05	3	Property Owner	60	100	200	60	3041 S. Bristol	Santa Ana	Private lateral	4" clean out	Paper/Grease/Priva e Property	Build up of paper and grease	None
1/19/05	3	Property Owner	0	0	0	0	201 E. 4th Street	Santa Ana	Private lateral	4" clean out	Grease	Plumber said there was grease in the lateral	None
1/31/05	3	Private	0	0	0	0	4362 LINCOLN	CYPRESS	N/A	N/A	BLOCKAGE - UNKNOWN		N/A
2/20/05	3	El Pollo Loco	20	20	20	0	969 S. Eudid St.	Anaheim	969 S. Euclid St.	Private cleanout and Private Manhole	Grease or possibly other.	Grease blocked pipeline, causing sewage to overflow.	Upon arrival, spoke with the Manager of Little Caesar's Pizza (Maria) that initially reported the spill at neighboring business, El Pollo Loco. City staff then went to check city's main line and found it to be flowing well. I contacted the assistant manager at El Pollo Loco and informed him of the sewage that was coming out of a clean-out on his property and running onto the sidewalk. He immediately contacted his plumber and the plumber was on is at 340 PM and had the blockage opened at 3:55 PM. City staff contained and cleaned up spill.
2/23/05	3	Carl's Jr	40	40	60	0	5012 La Palma Ave.	La Palma	Private Lateral	Manhole	Grease	Grease blockage from private property and sedement	Private contractor sanitized and cleaned up
2/26/05	3	FV	50	500	600	50	Euclid & Edinger	Fountain Valley	Between building & street cleanouts		grease build up	grease	Inspectd OCSD trunk line, they were flowing free and clear. Assisted City of Fountain Valley wivactor. Health Dept responded at 7:00pm and shut down the restaurant that was contributing to the spill.
2/26/05	3	Private	500	0	0	0	13011 NEWPORT	TUSTIN	N/A	N/A	BLOCKAGE - UNKNOWN	STORM DRAIN	NA
3/5/05	3	Private	40	0	0	0	540 FREEDOM	ORANGE	N/A	N/A	BLOCKAGE - UNKNOWN	STORM DRAIN/STREET	N/A

							I						
3/7/05	3	Private	842	842	0	0	10022 Garden Grove Blvd.	Garden Grove	n/a	n/a	n/a	n/a	
3/8/05	3	MBJ Property Management	290	400	2000	o	2500 E Chapman Ave @ St College	Fullerton	Private lateral to the rear of 2506 E Chapman Ave	Private lateral cleanou	Unknown		City crews responded to private lateral overflow from cleanout to the rear of 2506 E Chapman Ave. Sewage was flowing down alley swale to storm drain intel in approach alley off St College Bivd. City crews contained flow at storm drain and several areas in the alley. Vactor vacuum was set up to vacuum sewage while crews cleared blockage City crews cleared blockage with rodding equipment. City crews washed down alley swale and vacuumed all sewage and returned to sanihary sever system. MBJ propent management company was notified at 8.45 by Round Table Pizza to have private plumber respond. Private plumber had not responsibilities and has recently hired private plumber to video and assess lateral for possible replacement.
3/10/05	3	Private	64	64	0	0	12572 Harbor	Garden Grove	n/a	n/a	n/a	n/a	
3/14/05	3	Private	30	30	0	0	9691 Garden Grove Blvd.	Garden Grove	n/a	n/a	n/a	n/a	
3/16/05	3	Private Property	0	60	0	0	10488 Valley View	Buena Park	n/a	n/a	n/a	n/a	n/a
3/16/05	3	Denny's Restaurant	0	60	160	0	105 East 17th St	Costa Mesa, CA	Denny's Restaurant grease interceptor not maintained/cleaned; - District Crew Fully Contained SSO in parking lot and vactored;	Denny's Restaurant grease interceptor not bistrict Crew Fully Contained SSO in parking lot and vactored;	Denny's Restaurant grease interceptor not maintained/cleaned District Crew Fully Contained SSO in parking lot and vactored;	Denny's Restaurant grease interceptor not maintained/cleaned; - District Crew Fully Contained SSO in parking lot and vactored;	OC Environmental representative Mike (714-433-6120) called SSO in to CMSD; OC Environmental shut down Denny's Restaurant due to the SSO from the grease interceptor; Estimated 60 gallons SSO from single pickhole in a deanout; Crew contained SSO; SSO did not enter the storm drain (SD). District crew vactored approximately 60 gal of SSO and 100 gals of rinse water; Crew disposed of vactored SSO and rinsewater into District crainary server; District Crew estimated SSO to be 60 gals = 5 gal/min x 120 minutes; Denny's Restaurant grease interceptor not maintained/cleaned; - District Crew Verbind SSO in parking to Land Vactored; District crew arrived on site ensuring Denny's employees obtained a plumber to clean or the grease interceptor; District back-charged Denny's Restaurant for the services provided; District crew ensured Denny's Restaurant employees were aware of the requirement to maintain the grease interceptor; Denny's wesplaced on the District Hotspot list for Food Service Establishments (FSEs) inspections, permitting and grease interceptor maintenance; Photos were taken and are attached;
3/20/05	3	Private	350	150	0	0	745 DOVER	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	PRIVATE CLEAN OUT TO PARKING LOT TO STORM DRAIN TO NEWPORT BAY	N/A
4/1/05	3	Private	14	14	0	0	8042 Garden Grove Blvd.	Garden Grove	n/a	n/a	n/a	n/a	
4/7/05	3	FV	45	45	0	0	17099 Brookhurst Street	Fountain Valley	private property sewer laters	al	grease blockage	grease blockage private sewerlateral	NA
4/9/05	3	FV	150	100	0	0	18030 Brookhurst	Fountain Valley	unknown		grease blockage	sewage line back up at lowest point	Grease interceptor maintenance needed.
4/12/05	3	Private	200	100	50	0	1770 Harbor Blvd. Anaheim	Anaheim	1770 Harbor Blvd. Anaheim	Private clean out	Grease / Break in sewer line	Grease caused blockage. Pipeline broken during cleanou process	Video showed evidence of a break. Repairs are required by July 2
4/18/05	3	Private	75	75	0	0	11072 Magnolia	Garden Grove	n/a	n/a	n/a	n/a	
4/19/05	3	Business Properties Management Company	300	300	0	0	10132 Adams Ave.	Humtiogton Beach	Private business complex sewer line.	Private property manhole	Grease	Sewer line had grease and debris blocking the line.	This shopping center has at least five FSE's. They are on a sewer cleaning maintenance program, but will be making this program more frequent.
4/25/05	3	Private Property	0	0	0	0	515-523 HEATHER AVE	La Habra	n/a	n/a	Grease & Roots	n/a	
4/29/05	3	Private Property	0	0	0	0	119 1/2 LEORA ST	La Habra	n/a	Cleanout	n/a	n/a	
4/29/05	3	Private	100	0	0	0	6300 REGIO	BUENA PARK	N/A	LINE BREAK	LINE BREAK	STORM DRAIN.	N/A
5/4/05	3	Private	50	0	0	0	1773 W. Lincoln Ave.	Anaheim	1773 W. Lincoln Ave. Anaheim	Private clean out	Grease	Grease caused obstruction.	The splil had occurred internittently over the 24 hours prior to City Staff arrival. A clear link, which Bakery management acknowledged, was made between the excessive amounts grease in the manhole and the obstruction which caused the splil.
5/7/05	3	Private	0	0	0	0	4941 LA PALMA AVENUE	LA PALMA	N/A	N/A	GREASE	GUTTER TO STORM DRAIN	N/A
5/7/05	3	Hannam Matket	10	100	370	0	4800 La Palma Ave.	La Palma	Private Lateral	Manhole	Grease	Grease blockage from private property	Private contractor sanitized and cleaned up

5/15/05	3	FV	30	30	0	0	9037 Garfield	Fountain Valley	private property sewer latera	_	grease build up	grease blockage private sewer lateral	NA	
5/20/05	3	FV	25	25	0	0	16275 Harbor Blvd	Fountain Valley	private property sewer latera		blockage	clogged sewer lateral not grease interceptor	NA	
5/24/05	3	Private	20	0	0	0	Jeffrey/Walnut	Irvine	Grease interceptor	Grease interceptor	Grease	Grease interceptor overflow- Chinese Restaurant		
5/27/05	3	Private	0	20	200	200	1731 W. Katella Ave. Anaheim	Anaheim	1731 Katella Ave Anaheim	Private clean out	Paper towels and grease	Paper towels and grease caused obstruction.		
5/27/05	3	Watt Properties Management Company	25	25	25	0	8965 Atlanta Ave.	Huntington Beach	Private sewer pipe.	Sewer cleanout locate on private property.	Broken sewer pipe.	Broken sewer pipe at an isolation valve located in a shopping center.	All storm water in this area is being diverted into the sewer system.	
5/31/05	3	Private	100	0	0	0	17605 Harvard	Irvine	Grease interceptor	Grease interceptor	Grease	Grease interceptor overflow- Ralphs		
5/31/05	3	City of La Palma	0	15	40	0	7822 Walker Street	La Palma	Lateral line	Cleanout	Blockage	Roots	Private contractor sanitized and cleaned up	
5/31/05	3	Private Property	100	250	0	0	1040 Katella	Orange	n/a	Grse/Brkn Equip	Grse/Brkn Equip	n/a	n/a	
6/1/05	3	Pacific West Management Corp.	300	300	500	0	5971 Warner Ave.	Huntington Beach	Private sewer line	Private system clean out.	Grease blockage	Grease blockage from restaurants in business complex.	A citizen reported sewage spilling from this same clean out earlier in the day, but we could not see any evidence of this. If the spill did occur earlier in the day than an unknown amount of sewage could have made it into the E Garden Grove Wintersburg C	
6/3/05	3	Private	28	28	0	0	12158 Brookhurst	Garden Grove	n/a	n/a	n/a	n/a		
6/6/05	3	Private	0	40	200	200	175 S. Harbor Blvd.	Anaheim	175 S. Harbor Blvd.	Private clean out	Grease	Grease caused obstruction.	N/A	
6/6/05	3	FV	15	15	0	0	11707 Edinger Ave	Fountain Valley	just past interceptor at latera		grease build up	lack of interceptor maintenance	NA	
6/10/05	3	Private	100	800	200	200	537 N. Magnolia Ave.	Anaheim	537 N. Magnolia Ave.	Private clean out and private manhole	Pump shut down	Pump shut down caused obstruction	The property owner/manager contacted a pump company (Orange County Pumping) who corrected the problem with the pump station. The area in front of the building was washed by the City staff, however, other areas along the side of the building-not- acessable	
6/13/05	3	Private	75	75	0	0	10212 Westminster	Garden Grove	n/a	n/a	n/a	n/a		
6/20/05	3	Vons Market	50	25	0	0	1000 Bayside Dr.	Newport Beach	n/a	n/a	Grease	See Remarks	Water Crew built a berm to contain the overflow to and called for a vactor to clean up t spill. Vactor remained onsite until the blockage was clearned.	
6/20/05	3	Private Property	300	100	300	200	13102 NEWPORT BLVD	Tustin	8" Private Sewer	Private Manhole	Grease	Blockage	Sherrell Brown called divsion 420; Jeff Peterson is sending crew - Don Cleveland and Duane Smith to respond. Dindo Carrillo notified right away and called the Health Department. Mr. Fennessy of the Health Dept is responding.	
6/22/05	3	Private Property	676	636	886	40	13102 NEWPORT BLVD	Tustin	8" Private Sewer	Private Manhole	Grease	Blockage	City of Tustin on site called in spill. Sent OCSD crew with vactor truck to assist. Truck vactored up a total of 500 gallons, including 250 gallons of wash water. Spill was approx. 250 gallons. All was cleaned up at 1pm. Private plumber was called & Health Dept. on site as well. Approx. 40 gallons was not recovered from storm drain. Eliaine Yan from HCA visited spill site.	
6/28/05	3	Private	360	350	200	200	1151 N. Euclid St	Anaheim	1151 N. Euclid St	Private clean out	Grease	Grease caused obstruction.	NA	
6/30/05	3	FV	70	70	0	0	17075 Bushard	Fountain Valley	private property sewer latera		grease build up	private lateral	NA	
7/1/05	3	Private	0	0	0	0	2735 W. COAST HWY.	NEWPORT BEACH	N/A	N/A	GREASE	N/A	N/A	
7/7/05	3	Private	2	200	500	2	627 North Euclid Street	Anaheim	627 North Euclid Street	Private clean out	Grease	Grease caused obstruction	N/A	
7/17/05	3	Private Property	0	0	0	0	1800 W. WHITTIER BL.	La Habra	n/a	Grease Interceptor	Grease	n/a		
7/19/05	3	Pacific Comm.	450	2800	0	0	1000 Dove St.	Newport Beach	Private Cleanout	Private Cleanout	Grease & Paper Products	See Remarks	Burmed the gutter before the storm drain then set up the vactor before the burm. Notified the owne to call a plumber because it is a private clean out.	

1 2														
1 1	7/26/05	3	America	0	50	0	0	3601 Jamboree Rd	Newport Beach	Grease interceptor	Grease interceptor		See Remarks	responded with a vactor to vacuum contained material, code enforcement took pictures
12 12 <th12< th=""> 12 12 12<!--</td--><td>7/27/05</td><td>3</td><td>Private</td><td>0</td><td>900</td><td>600</td><td>0</td><td>2108 E. Lincoln Ave.</td><td>Anaheim</td><td>2108 E. Lincoln Ave.</td><td>Private clean out</td><td>Grease</td><td>Grease caused obstruction</td><td>to investigate and assist. Spill did not reach underground storm drain system because sandbags and filter fabric were already blocking catch basin in street, since constructi is underway on the Lincoin Avw3L College BNJ, widening project. Additionally the obstruction occurred in the middle of the private onsite sewer collection system, therefore, the focus of the remedia actions will be on those businesses upstream of the</td></th12<>	7/27/05	3	Private	0	900	600	0	2108 E. Lincoln Ave.	Anaheim	2108 E. Lincoln Ave.	Private clean out	Grease	Grease caused obstruction	to investigate and assist. Spill did not reach underground storm drain system because sandbags and filter fabric were already blocking catch basin in street, since constructi is underway on the Lincoin Avw3L College BNJ, widening project. Additionally the obstruction occurred in the middle of the private onsite sewer collection system, therefore, the focus of the remedia actions will be on those businesses upstream of the
Image Image <th< td=""><td>8/2/05</td><td>з</td><td>Private lateral Tony Romas</td><td>20</td><td>100</td><td>200</td><td>0</td><td>1300 S Harbor Blvd</td><td>Fullerton</td><td>Private lateral</td><td>lateral cleanout</td><td>Paper</td><td></td><td>contained sewage at storm drain, dispatched sewer on call crews. Restaurant called private plumber. There was no overflow inside facility. City crews washed down and vacuumed all sewage. Private plumber cleared blockage of paper in lateral line. The</td></th<>	8/2/05	з	Private lateral Tony Romas	20	100	200	0	1300 S Harbor Blvd	Fullerton	Private lateral	lateral cleanout	Paper		contained sewage at storm drain, dispatched sewer on call crews. Restaurant called private plumber. There was no overflow inside facility. City crews washed down and vacuumed all sewage. Private plumber cleared blockage of paper in lateral line. The
ind i	8/4/05	3	Private Property	0	0	0	0	821 CORTO WAY	La Habra	n/a	Cleanout	n/a	n/a	
initial initia initial initial	8/13/05	3	Sabatino's	0	10	0	0	251 Shipyard Way	Newport Beach	Holding tank	Holding tank	Grease	See Remarks	
initial initia initial initial	8/16/05	3	Private	20	0	0	0	6503 Quail Hill	Irvine	Effluent line	Effluent line	Plug		
a raise	8/16/05	3	Private	0	0	0	0	6885 WARNER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE	STORM DRAIN WITH DIVERSION.	NA
A A	8/23/05	3	Private	0	15	0	0	28232 BEACH BLVD.	HUNTINGTON BEACH	N/A	N/A	ROOTS	CONTAINED IN CURB AND GUTTER	NA
ACMAA<	9/19/05	3	Private	61	61	0	0	10012 Westminster	Garden Grove	n/a	n/a	n/a	n/a	
Image: Constraint of the state of the s	9/23/05	3	FV	48	28	0	0	11045 Warner Ave	Fountain Valley	private property sewer latera		grease build up		NA
101800 3 Private 4.00 4.20 0.00 1000 (NOR LINKO N) NA NA <td>9/24/05</td> <td>3</td> <td>Private</td> <td>2160</td> <td>1200</td> <td>200</td> <td>0</td> <td>1199 N. Euclid Street</td> <td>Anaheim</td> <td>1199 N. Euclid Street</td> <td>N/A</td> <td>Grease</td> <td>Grease caused spill</td> <td>OCHCA assisted onscene and washdown was performed by a private party.</td>	9/24/05	3	Private	2160	1200	200	0	1199 N. Euclid Street	Anaheim	1199 N. Euclid Street	N/A	Grease	Grease caused spill	OCHCA assisted onscene and washdown was performed by a private party.
Image: Constraint of the state of the s	10/18/05	3	Private	400	425	0	0	18555 YORBA LINDA BLVD.	YORBA LINDA	N/A	N/A			NA
Image: Note of the second s	10/19/05	3	Private	64	64	0	0	10072 Westminster	Garden Grove	n/a	n/a	n/a	n/a	
i c c c c c c c c c c c c c c c c c c c	11/6/05	3	Private	0	80	0	0	1530 PLACENTIA	NEWPORT BEACH	N/A	N/A	GREASE	CONTAINED ON SITE	N/A
1 1	11/10/05	3	Private	20	20	0	0	9802 Katella	Garden Grove	n/a	n/a	n/a	n/a	
Image: Note of the second s	11/14/05	3	Private Property	0	100	0	0	426 W. Almond Ave.	Orange	n/a	Building basement and Railroad right of way	Grease/Roots	Building basement and Railroad right of way	n/a
11/2000 3 Private 1220 0	11/18/05	3	Private	121	121	0	0	8042 Garden Grove Blvd.	Garden Grove	n/a	n/a	n/a	n/a	
1/22/05 3 Private Tony Roma's 160 30 50 0 1300 S Harbor Bivd Fullenon Private Iateral Sease debris Fullenon General manager was informed of responsibilities and assured City staff the facility would increase their maintenance. 12/205 3.0 Private Property 0.0 0.0 1233 W. La Habra BI. La Habra Na Private Iateral Na Na </td <td>11/25/05</td> <td>3</td> <td>Private</td> <td>225</td> <td>0</td> <td>0</td> <td>0</td> <td>26652 Portola Pkwy</td> <td>Foothill Ranch</td> <td>Private lateral</td> <td>Private lateral</td> <td>n/a</td> <td>Blockage in lateral between interceptor and main line</td> <td></td>	11/25/05	3	Private	225	0	0	0	26652 Portola Pkwy	Foothill Ranch	Private lateral	Private lateral	n/a	Blockage in lateral between interceptor and main line	
	11/28/05	3	Private - Tony Roma's Restaurant	160	30	50	0	1300 S Harbor Blvd	Fullerton	Private lateral	Private lateral cleanou	tGrease, debris		placed sand bags around storm drain. Sewer on call row responded, cleared grease blockage in lateral to stop overflow, cleaned area. Follow up activities will be performed by FOG inspection personnel. Private plumber responded for follow up. Private plumber installed new cap on cleanout to prevent discharge near storm drain inlet. General manager was informed or responsibilities and assured City staff the facility
12/4/05 3 Private 1000 0 0 0 Lake Forest & Rockfield Lake Forest n/a Grease Grease blockage	12/2/05	3	Private Property	0	0	0	0	1233 W. La Habra Bl.	La Habra	n/a	Cleanout	n/a	n/a	
	12/4/05	3	Private	1000	0	0	0	Lake Forest & Rockfield	Lake Forest	n/a	n/a	Grease	Grease blockage	

12/14/05	3	Private	143	2	0	0	8052 ADAMS	HUNTINGTON BEACH	N/A	N/A	GREASE	STORM DRAIN -> TALBERT CHANNEL (DIVERTED TO SEWER SYSTEM)	NA
12/27/05	3	Private	0	5	0	0	18302 GOTHARD	HUNTINGTON BEACH	N/A	N/A	ROOTS	VACUMMED UP FROM GUTTER	N/A
12/29/05	3	Private	2	2	0	0	10240 Westminster	Garden Grove	n/a	n/a	n/a	n/a	
1/3/06	3	Private Spill Kobe Restauran	120	50	200	0	3001 Old Ranch Parkway	Seal Beach	private sewer main line at 3001 Old Ranch Parkway	Restaurant clean-out	Grease	Restaurant had grease interceptor cleaned 3 days prior to overflow. Cleaning may have forced grease into their main line.	n/a
1/9/06	3	Private	30	90	40	0	1721 Claudina Avenue	Anaheim	1721 Claudina Avenue	Private Cleanout	Roots	Roots caused obstruction	N/A
1/9/06	3	Private	0	120	50	0	407 State College Blvd	Anaheim	407 State College Blvd.	Private Cleanout	Grease		Owner and or manager of location was unavailable to City staff. Workers of the restaurant did not have or would not release his information. Code enforcement as wel as Streets & Sanitation staff left contact information for the owner.
1/10/06	3	Private	0	40	50	0	407 State College Blvd	Anaheim	407 State College Blvd.	Private Cleanout	Grease	Grease caused the obstruction	NA
1/10/06	3	Private	0	0	0	0	104 EDINGER	HUNTINGTON BEACH	N/A	N/A	GREASE	N/A	NA
1/10/06	3	Private	0	0	0	0	2321 S. BRISTOL	SANTA ANA	N/A	N/A	BLOCKAGE - UNKNOWN	CONTAINED IN PARKING LOT	NA
1/10/06	3	Private	0	500	0	0	5812 EDINGER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE & DEBRIS	PARKING LOT	NA
1/11/06	3	Private	229	229	0	0	12342 Brookhurst	Garden Grove	n/a	n/a	n/a	n/a	
1/20/06	3	Maru Sushi Food Service Establishment manager;	O	260	360	0	1500 Adams Ave;	Costa Mesa, CA	Estimated 260 gallon SSO spilled from private property grease interceptor (GI);	Estimated 260 gallon SSO spilled from grease-blocked privatt property grease interceptor (GI);	aGrease blocked GI;	Estimated 260 gallon SSO spilled from grease-blocked private property grease interceptor (GI);	City of Costa Mesa Code Enforcement called event in to Comm Citr, District Maintenance Supervisor, in turn; National Plant Services, Inc contractor response crew dammed cleanout and Storm Drain (SD) upon artival; SSO did not enter SD. Estimated 20 galon SSO spilled from grease-blocked private property grease interceptor (GI); City of Costa Mesa crew vactored SSO and rinee water and disposed of the wastewater in the District Santhary sever system; District Staff and City of Costa Mesa PROES Manager counseled Mara Sushi Manager, Scott)949-468-5661, to increase frequency of GI cleaning; to use Best Managernem Practices (BMPs) and educate employees or proper disposal of Pats, Olis and Grease (FOG); Photos were taker;
1/20/06	3	Private	250	100	0	0	9882 ADAMS BLVD	HUNTINGTON BEACH	N/A	N/A	GREASE	CLEAN OUT TO PARKING LOT TO CURB AND GUTTER TO STORM DRAIN.	N/A
1/25/06	3	Private	0	0	0	0	770 S. PLACENTIA AVENUE	PLACENTIA	N/A	N/A	BLOCKAGE - UNKNOWN	CURB/GUTTER -> COLLECTION	N/A
1/26/06	3	Private Property	0	5	0	0	154 S.WALLACE ST.	La Habra	n/a	Cleanout	n/a	n/a	
1/30/06	3	Private	740	2500	1000	0	627 N. Euclid Street	Anaheim	627 N. Euclid Street	Private Cleanout	Grease and Break	Grease and break caused obstruction	HCA requested that the property manager perform disinfection of the affected area on private property. Although it is not common practice, the City allowed this work to proceed under HCA supervision and with the vactor truck fully containing the spill downstream.
2/3/06	3	Private	2360	2500	1000	0	627 N. Euclid St.	Anaheim	627 N. Euclid St.	Private cleanout	Grease and Break	Grease and break caused obstruction	NA
2/4/06	3	Private Property	50	0	0	0	1621 EDINGER AVE.	Tustin	υ	Cleanout	Blockage	Other	Div. 420 was sent to the location to determine the nature of problem and was requested to standby until Orange County Health department arrived on scene. Spill was on private property.
2/5/06	3	Private Spill - Michael Brinkmar (949) 650-9100	0	20	30	0	825 E. Chestnut - Private Property	Santa Ana	Private Property	Clean out	Cause unknown - private property	Ran out of parking structure, down driveway to street - cause unknown	Fire Dept. reported spill to both OC Health/Regional Board
2/7/06	3	Private	10	0	0	0	23344 El Toro Rd.	Lake Forest	n/a	n/a	Grease	Grease blockage	
2/16/06	3	FV	75	2	0	0	17815 Newhope Street	Fountain Valley	private property sewer latera		unknown	possible paper towel in toilet	NA

	1						1	r			Г	1	
2/26/06	3	Private	40	40	500	0	1040 N. Magnolia Ave.	Anaheim	1040 N. Magnolia Ave.	Private cleanout	Break	Break caused obstruction	The cause of the spill is still under investigation. The restaurant owner, who was also the reporting party, did all that was possible at the time to address the spill and investigate the problem, including hiring 2 separate plumbers. Despite having one
3/1/06	3	Private Party	0	200	0	0	5940 Cerritos Ave.	Cypress	n/a	n/a	n/a	n/a	
3/4/06	3	Private	113	150	100	0	501 N State College Bivd (Chipotle Grill)	Fullerton	Private lateral	Private lateral cleanou	n Debris, grease		City crews responded to private lateral overflow at Chipotle Grill/Pick up Stix restaurants. Health Care agency was on scene. Crews cleared blockage to stop overflow, some grease retrieved on rodding equipment. City crews washed down and vacuumed area.
3/20/06	3	Private Property Denny's Rest.	30	30	100	0	4232 Katella	Los Alamitos	private lateral	private grease interceptor	grease	grease blockage	n/a
3/23/06	3	Private	255	1500	500	0	3170 W. Lincoln Ave.	Anaheim	3170 W. Lincoln Ave.	Private cleanout	Grease	Grease caused obstruction	Property owner was very cooperative and reported this spill to the City themselves. There was a delay, however, in clearing the server line, since the "snake" that the first plumber used was not effective in clearing the obstruction. The second plumber managed to clear the obstruction with a jetting tool.
3/23/06	3	Private Property	0	450	0	0	1538 E. Chapman	Orange	n/a	n/a	unknown	n/a	n/a
3/29/06	3	Private, Albertsons Corp, 1955 W North, Malrose Park, Illinois 60160 contact:Barbara Mott 708-492-3100	20	180	800	0	455 N State College Blvd (Sav On)	Fullerton	Private lateral	3 lateral cleanouts in parking lot	Debris	Plumber cleared approx 10' of thick substance from line	City crews responded to report of sewage in parking tot of Sav On at State College & Chapma Ave. Lateral cleanots in parking tot were seeping with small amount of flow into gutter area down to acth basin. Flow was contained in parking to with sandbags City vactor crew was called for assistance with containment, private plumber was called by manager Of Sav On. City crews remained on scene until plumber arrived and clear vary thick blockage in line with rodding equipment. City crews assisted plumber with parking to robust mare in line. City crews assisted down and vacuumed sewage in parking lot and gutter areas. City contacted Sav On Corp office and recommended follow up activities to prevent future problems (see attachment).
3/30/06	3	Property Manager for 1875-B Newport Bivd (Triangle Square), Costa Mesa, CA property;	20	85	205	20	1875-B Newport Bivd;	Costa Mesa, CA	Grease blocked commercial lateral causing overflow from two of three cleanouts;	Two of three parking lot cleanouts;	Grease blocked commercial lateral causing overflow from two of three cleanouts;	Grease blocked commercial lateral causing overflow from two of three cleanouts;	Estimated 105 gallon SSO flowed from two of three private property cleanouts; Estima 20 gallons SSO trickled into storm drain (SD) used as a containment vessel; Recovered/vactored 85 gallons; City of Costa Mesa crew vactored SSO and rinse wa and disposed of the wastewater in the District starting sever system; Grease blocked commercial lateral causing overflow from two of three cleanouts; CMSD District Maintenance Supervisor on site; City of Costa Mesa crew blocked SD and vactored wastewater in the street and cutb while plumber was en route; Private plumber Proser cleaned lateral line; CMSD contractor, National Plant Services, Inc., cleaned the remaining grease pushed into the District Main Line on 3-31-06 @ 0930 hours; Photos were taken and are attached;
4/6/06	3	Private	140	0	40	0	969 S. Euclid St.	Anaheim	969 S. Euclid St.	Private cleanout	Grease and food	Grease and food caused obstruction	Sewage flowed south from parking lot behind Little Caesar's Pizza to Ball Road. On E Road it traveled west approximately 250 yards where it entered the catch basin located at 1791 W. Ball Road, on the north side of Ball Road.
4/7/06	3	Private	98	98	0	0	12188 Brookhurst	Garden Grove	n/a	n/a	n/a	n/a	
4/10/06	3	The Lodge Food Service Establishment (FSE);	0	10	60	0	2937 Bristol Street;	Costa Mesa, CA	Grease primarily and some debris blocked private lateral; SSO flowed from private MH on private property;	Private MH;	Grease primarily and some debris blocked private lateral;	Grease primarily and some debris blocked private lateral;	AB&R Plumbing called CMSD Maintenance Supervisor; Estimated 10 gallon SSO flowed from private Manhole (MH) on private property into Curb - City of Costa Mesa and CMSD Maintenance Supervisor dammed Storm Drain (SD) - fully contained; City Costa Mesa crev vactored SSO and rises water and disposed of the wastewater in the CMSD sanitary sever system; Visual Estimate of 10 gallons pooled wastewater - very shallow - 10 gallons over 30 minutes =33 gallons/minute; Grease primarily and some debris blocked private lateral; Photographs were taken and are attached;
4/11/06	3	Private	15	160	0	0	7402 EDINGER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE	STORM DRAIN -> FLOOD CONTROL CHANNEL (EAST GARDEN GROVE WINTERSBERG CHANNEL)	NA
4/24/06	3	Private	0	400	0	0	23691 ROCKFIELD	LAKE FOREST	N/A	LINE BREAK	LINE BREAK	SEWAGE CONTAINED ON SITE.	May be R-9
4/24/06 0943	3	Private Health Care Center	630	0	0	0	RXR easement behind 2800 N Harbor	Fullerton	Private lateral	Lateral cleanout	Grease, debris		Crews responded, contained, and cleared blockage in private lateral to stop flov Private plumber responded to follow up with clean up activities. All sewage soaked into the dirt channel near railroad easement. Skilled Healthcare Center will be added to the Citr/s FOG program.
5/7/06	3	Private	30	0	0	0	17575 Harvard Ave. (Corner Bakery)	Irvine	n/a	n/a	Grease	Grease blockage	

5/8/06	3	Private	0	300	0	0	23691 ROCKFIELD	LAKE FOREST	N/A	LINE BREAK	LINE BREAK	SEWAGE CONTAINED ON SITE.	May be R-9
5/9/06	3	Private - Sav On/Albertsons Store # 9598	0	20	400	0	455 N State College	Fullerton	Private lateral	Lateral cleanout in parking lot	6" lateral connectior to 4" lateral cleanou wye	new 6° lateral from building wa connected to existing 4° lateral line. problem appears to be at offset in connection	Correspondence with Sav On has been ongoing due to a previous overnow. Property owner had the line video inspected. Video revealed severe offset joint where 6" line.
5/10/06	3	Private	0	80	0	0	1365 Knollwood Circle	Anaheim	1365 Knollwood Circle	sample box	Lack of capacity and build up of fibers on sewer lateral		Sewer spills have been experienced at this location in the past, under similar circumstances. However, there has not been a spill in over three years.
5/15/06	3	Private	95	5	0	0	1755 W. La Palma Ave.	Anaheim	1755 W. La Palma Ave.	Private cleanout	Grease	Grease caused obstruction	Na
5/22/06	3	PetSmart Store - Private party	25	25	25	25	620 W 17th St - PetSmart Store lateral cleanout;	Costa Mesa, CA;	Private on-site PetSmart lift station failed - well container large volume of wastewater,		Private on-site PetSmart lift station failed - well contained large volume of wastewater;	Private on-site PetSmart lift station failed - weil contained large volume of wastewater;	Visual estimate of wastewater in SD and from path from the PetSmart cleanout to the SD and the curb: 15 gallons lost to SD; 10 gallons evaporated; 25 gallons vactored; Private on-site PetSmart tilt station failed - well contained large volume of wastewater; PetSmart Manager (Phil Morgenthaler (949-764-927) arranged for pulmers to repair station and clean out private tilt station well.Manager cloaded the business for the next day to ensure repairs were completed without additional SSO occurrence; Manager informed to maintain private tilt station on a regular maintenance program; SSO vactored and disposed of into the CMSD sanitary sever system; Photographs were taken and are attached;
5/23/06	3	Private	300	100	200	0	1731 W. Katella Ave.	Anaheim	1731 W. Katella Ave.	Private cleanout	Grease and paper	Grease and paper caused obstruction	NA
5/24/06	3	Private	60	160	500	0	905 E. Vermont Ave.	Anaheim	905 E. Vermont Ave.	Private cleanout	Toilet left running into tank	Toilet left running into tank caused obstruction	Because the spill flowed a significant distance before reaching the catch basin, it is believed that a significant portion of the spill was contained and collected before it was discharged into the catch basin.
5/30/06	3	FV	75	70	0	0	16155A-16175 Harbor Blvd	Fountain Valley	private property sewer latera		grease build up	private	NA
6/5/06	3	Sterling Shopping Center, manager, Ross Cannon.	360	200	700	160	17436 Beach Blvd., Sterling shopping center	Huntington Beach	Blockage was in the private lateral line of the shopping center.	Pick hole of the clean out cover.	Grease blockage.	Grease and debris blocked the private lateral line.	
6/12/06	3	Private	200	1800	0	0	3101 W. PACIFIC COAST HIGHWAY	NEWPORT BEACH	N/A	N/A	PUMP STATION FAILURE	STORM DRAIN -> NEWPORT BAY AT "MARINER MILE" MARINA DOCKS (3101 W. COAST HIGHWAY)	NA
6/14/06	3	Private	0	0	0	0	10631 LOS ALAMITOS	LOS ALAMITOS	N/A	LINE BREAK	LINE BREAK	SEWAGE DISCHARGED SUBSURFACE AND INTO DECORATIVE KOI POND.	NA
6/24/06	3	City of Huntington Beach	250	200	400	50 Gallons	17732 Goldenwest Street	Huntington Beach	Park Bench Café, 17732 Goldenwest Street	Private sewer lateral cleanout cap.	Grease and debris blockage.	Grease and debris buildup in the private sewer lateral.	The Park Bench Café is in a City park, the problem cleanout pipe is next to a large low grass area. All sewage was confined to this aera.
6/26/06	3	Restaurant at the end of the Newport Pier	0	0	0	0	Restaurant at the end of the Newport Pier	Newport Beach	Pipe joint	Pipe hangers holding ABS piping under the pier failed due to rust a corrosion, the piping dropped & a joint pulled apart.	Pipe joint separation	See Remarks	City of Newport Beach lift station crew tunned water off to Restaurant immediately and advised restaurant manager of the problem. Utilities office called Environmental Health Services and RWQCB.
6/27/06	3	Rainbow Disposal, trash hauler.	150	150	250	0	17121 Nichols Street	Huntington Beach	Blockage was in the private lateral line on Rainbow property.	Clean out pick hole.	Grease and debris blockage.	Grease and debris buildup in the private sewer lateral.	
7/6/06	3	Private	30	370	0	0	745 DOVER	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	PPO CLEAN OUT TO PARKING LOT TO STORM DRAIN.	N/A

7/7/06	3	Private Property Owner	0	20	400	0	Ziings / Revolucion Restaurants, 209 N Harbor Blvd (Rear driveway)	Fullerton	Private Grease Interceptor	Interceptor lid	Grease blockage in private lateral		City crews responded to report of grease interceptor overflowing behind restaurant complex. Crews contained and vacuumed overflow until blockage was cleared. Zlings and Revolucion restaurant's shared interceptor had been pumped within the past 3 months as required by the City's FOC program. Blockage in lateral line assumed to be grease. The City's FOC program inspector will follow up and monitor maintenance activities to re-evaluate pumping schedule.
7/11/06	3	Silk Thai Cuisine Restaurant	10	10	210	0	19690 Beach Blvd., Newland Shopping Center	Huntington Beach	Slik Thai Restaaurant in the Newland Shopping Center.	Cover of grease interseptor	Grease blockage	Phill's Plumbing while repairing the grease interceptor at The Silk Thai Restaurant 10 gallons of sewage spilled.	
7/12/06	3	PRIVATE SSO from PRIVATE 4" force main from PRIVATE lift station at 960 West 16th St;	2	15	65	2	960 West 16th St;	Costa Mesa, CA;	PRIVATE lift station 4* force main on PRIVATE property found to have a 3/16* hole in the plastic underground pipe;	PRIVATE lift station 4" force main on PRIVATE property found to have a 3/16" hole in the plastic underground pipe;	PRIVATE lift station 4* force mair on PRIVATE property found to have a 3/16* hole in the plastic underground pipe;	PRIVATE lift station 4* force main on PRIVATE property found to have a 3/16* hole in the underground pipe; Undetermined cause for the 3/16* hole;	PRIVATE SSO occurred from PRIVATE 4" force main from PRIVATE lift station at 960 West 16th St. Mesa Consolidate Water District dammed Storm Drain (SD) while excavating potential water line leak and plugged 4" force main hole with a bolt; City of Newpon Beach (CNB) crew vacuumed SSO and rinse water and disposed of the wasawater from PRIVATE lift station 4" force main, PRIVATE lift station 4" force main on PRIVATE property found in have 3/16" hole in the plastic underground pipe, Estimated flow of 15 galions over 1440 minutes = .01 gpm; City of Newpon Beach (CNB) crew accumed SSO and these water and absorded of the stationard flow of 15 galions over 1440 minutes = .01 gpm; City of Newpon Beach (CNB) crew accumed SSO and rines water and disposed of the wastewater in the CNB sanitary sever system; Rescue Rooter (1-800-669-6956) repaired PRIVATE lift station 4" force main on PRIVATE property. Photographs were taken and are attache
7/27/06	3	Pacific West Management Corporation, property manager Sharon Ference 714-433-7300	100	100	200	0	6941 Warner Avenue	Huntington Beach	Don Ramon's Mexican Restaurant in this shopping center.	Sewer lateral clean ou cover.	Grease blockage	Grease blockage in the private sewer lateral down stream of the Don Ramon's Restaurant.	
8/5/06	3	Private	300	0	0	0	24401 MUIRLANDS	LAKE FOREST	N/A	N/A	GREASE	GREASE INTERCEPTOR TO PARKING LOT TO STORM DRAIN TO SAN DIEGO CREEK (DRY).	May be R-9
8/11/06	3	A.K.A. Japanese Restaurant 714-374-9600 and Cavallino Italian Restaurant 714-536- 6665	55	55	155	0	8082 Adams Ave.	Huntington Beach	Between private manhole and City manhole at 8082 Adams Ave.	Pick holes of manhole cover.	Grease blockage	Grease buildup from two food service establishments.	
8/20/06	3	FV	10	10	0	0	9102 Edinger Avenue	Fountain Valley	private property sewer latera		grease	private sewer lateral	NA
8/31/06	3	El Taco Mexican Restaurant owner (213-249-0756);	0	30	80	0	2101 Harbor Blvd;	Costa Mesa, CA;	Grease blocked PRIVATE lateral line from EI Toro Mexican Restaurant;	Grease blocked PRIVATE lateral line from El Toro Mexican Restaurant;	Grease blocked PRIVATE lateral lind from El Toro Mexican Restaurant	Grease blocked PRIVATE lateral line from El Toro Mexican Restaurant;	EI Taco Mexican Restaurant owner (213-249-0756) called District Maintenance Supervisor: District Maintenance Supervisor called @ 1100 hrs, blocked SD @ 1112 hrs, called City of Costa Mesa Public Services to send a Vactor and clean the Public ROW, flush site with fresh water and vactor site; City of Costa crew vactored SSO from curb and gutter and returned/disposed of SSO in District sanitary sever system; Grease blocked RPIVATE lateral line from EI Tord Mexican Restaurant; EI Toro Mexican Restaurant owner reminded to increase frequency of cleaning grease from PRIVATE lateral line and follow PCG guidance of BMPs, training, and record keeping; Photographs were taken and are submitted with this monthly report;
9/28/06	3	Nora Balikciagli, owner of the Moble Gas Station	25	25	45	0	2002 Beach Blvd.	Huntington Beach	Lateral sewer line of 2002 Beach Blvd.	Private sewer clean ou cover.	Debris blockage	2002 Beach Blvd. Is a gas station. It is suspected that vandals put to much debris into the toilets.	
10/12/06	3	Private	300	0	0	0	3955 Alton Pkwy Olive Garden	Irvine	Private lateral	Private lateral	n/a	Blockage in customer's lateral	
10/16/06	3	Private	200	0	0	0	610 NEWPORT CENTER DRIVE	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	SEWAGE DISCHARGED TO STORM DRAIN AND INTO NEWPORT BAY	NA
11/3/06	3	Joe's Crab	0	20	0	0	2607 W. Coast Hwy	Newport Beach	Blocked Grease interceptor	Grease interceptor	Blocked Grease Interceptor	See Remarks	Met vactor, called for sand to build a berm around the grease that overflowed from the Restaurant interceptor. Contacted workers inside restaurant to call for a plumber/pump truck and informed them they would not be allowed to open until the problem was taken care of. Called the Orange County Health Dept. and Regional Water Qualty Control Board.
11/6/06	3	Private	1000	1520	1000	0	967 S. Euclid St.	Anaheim	927 S. Euclid St. interceptor	Private cleanout	Grease and settlable food solids	Grease and solids build up in interceptor and caused obstruction	A previous spill occurred at this address but not from this same line. Implementing a program to prevent the discharge of solids to the interceptor as well as a more frequent inspection and/or cleaning program should resolve this situation.

11/6/06	3	Market Broiler Restaurant	500	500	800	0	20111 Brookhurst Street	Huntington Beach	Broken sewer pipe three fee under the concrete slab of the Market Broiler building.	Concrete slab and sewer clean out cover.	Broken sewer pipe under the concrete slab.	Old sewer line had a break in it	
11/8/06	3	Private	162	162	0	0	11072 Magnolia	Garden Grove	n/a	n/a	n/a	n/a	
11/11/06	3	Private	100	0	0	0	602 CHAPMAN	PLACENTIA	N/A	N/A	BLOCKAGE - UNKNOWN	PARKING LOT -> CURB AND GUTTER (NO BACK UP INTO RESTAURANTS ACCORDING TO CITY CREW)	Resturant
11/13/06	3	Private	162	162	0	0	11072 Magnolia	Garden Grove	n/a	n/a	n/a	n/a	
11/15/06	3	Dominic J. Manna owner of this office building	25	25	75	0	17122 Beach Blvd.	Huntington Beach	Sewer lateral pipe at 17122 Beach Blvd.	Sewer clean out cover	Plugged sewer lateral.	Roots and debris in the private sewer lateral.	Owner of this office building was very cooperative and helpful.
11/16/06	3	Service First Management Corporation, property manager Encia Wemer 714-963-5555 ext. 378.	3,500	3,500	4,100	0	17742 Beach Blvd.	Huntington Beach	Beach Medical Associates Center, 17742 Beach Bivd. lateral sewer pipe.	Sewer clean out cover	Plugged sewer lateral.	Roots and debris in the private sever lateral. The landscaping parallel to this private sever lateral has about ten Flocus tree planted in it. The plumbing company pulled out many roots from this sever lateral. These roots restricted the sewage flow and	Property Manager Erica Werner cell phone 949-683-7184.
11/20/06	3	Service First Management Corporation, property manager Erica Werner 714-963-5555 ext. 378.	1,200	1,200	1,500	0	17742 Beach Blvd.	Huntington Beach	Beach Medical Associates Center, 17742 Beach Blvd. lateral sewer pipe.	Sewer clean out cover	Plugged sewer lateral.	Roots and debris in the private sewer lateral. Plumber on 11/16/06 did not get all roots cut and removed from the sewer system.	Property Manager Erica Werner cell phone 949-683-7184.
11/30/06	3	Private	400	500	500	0	1830 W. Romneya Drive	Anaheim	Pump Station at N/W corner of Euclid and Romneya	Private manhole	pump station failure	A sensor which monitors the level of sewage in the wet well failed	This was an unusual spill as it was caused by a failure of a private pump station. This failure is unlikely to occur again, however we will require assurances from the owner/operator to ensure this.
12/1/06	3	Private	10	40	0	0	415 Old Newport Blvd.	Newport Beach	Lateral	Lateral	Roots from the lateral before the CMSD mainline.	See Remarks	Call for: hydroflusher and vactor built erm at private storm drain box and set up vactor Beamed storm rain box and used hydro to flush curb and gutter to storm drain at Hospital Road to Newport Bivd. returend to parking tot and vacuumed at private storm drain box until jumber arrived and cleared the blockage. Used high pressure water to clean parking lot and washed to vacuume.
12/7/06	3	Charles Dunn Management Company, Laura Tarbutton Property manager	450	450	650	0	6918 Warner Avenue	Huntington Beach	6918 Warner Avenue	Clean out cover behind the Subway Sandwich shop.	Grease blockage	Grease blockage in the private lateral sewer line.	
12/19/06	3	Private Property owner, CVS Pharmacy	100	200	All	0	455 N State College Blvd	Fullerton	Private lateral	Lateral cleanout	Lateral defect, debris	6" lateral from building connects to old 4' lateral at sidewalk area creating offset	City crews responded to private overflow in CVS (formerty Saw-On) parking lot. Water crew responded to shut off water service to stop overflow. Store manager was not aware of problem prior to our arrival. Private plumber was dispatched and responded to clear blockage. City crews washed down and vacuumed all sewage from guiter and street, and contained overflow in parking lot. Private cleanup service was called by CP to clean parking lot. Sewer staff requested response by OCHA to record incident due to several prior incidents at this facility. City staff will notify CVS and require immediate repair of lateral line
12/20/06	3	Private	100	200	0	0	CHAPMAN/STATE COLLEGE	FULLERTON	N/A	N/A	CONSTRUCTION DEBRIS	PARKING LOT CLEAN OUT TO STREET, CURB AND GUTTER TO STORM DRAIN TO FULLERTON CHANNEL.	NA
12/22/06	3	Private	10	0	0	0	1151 N. Euclid St.	Anaheim	1151 N. Euclid lateral in alley behind building	Private cleanout	Grease	Grease caused obstruction	A previous spill occurred at this location. If routine cleaning and Kitchen BMPs can not prevent spills, an iterceptor will be required,.
12/23/06.	3	Private	100	200	0	0	3435 Newport Blvd.	Newport Beach	Grease trap	Grease trap	Grease from their grease trap.	See Remarks	Grease trap from Pavillions Market overflowing. Fire crew and Monica from Health De already on scene. Set up vacuum truck in parking lot. Spoke with the Manager at the market and told him he needs to get a plumber out. Health Dept. shut down the Market

12/30/06	3	Private	0	0	0	0	4232 KATELLA	LOS ALAMITOS	N/A	N/A	GREASE INTERCEPTOR	STREET -> CURB & GUTTER	Denny's resturant
Totals	268		50,121	54,412	59,203	6,395							
Inst/Public													
1/21/04		Private Lateral St. Hedwig School	50	50	300	0	11482 Los Alamitos Blvd.	Los Alamitos	private lateral	private lateral clean ou	roots	tree root blockage	n/a
4/15/04		City of Anaheim / Anaheim Fire Station #9	150	50	200	0	6300 Nohl Ranch Rd.	Anaheim	6300 Nohl Ranch Rd.	Sewer Lateral Cleanou	Construction damaged the lateral and allowed roots to invade sewer line	Roots	N/A
4/29/04	4	Orange County Head Start, INC.	5	5	0	0	14422Hammon Ln.	Huntington Beach	Drain pipe connecting to Grease Interceptor.	Grease Interceptor			Drain pipe for grease interceptor in the parking lot broke and caused the asphalt to cate in. West Duke Plumbing took care of the pipe repair and clean up.
11/6/02	4	Private-City owned facility	0	100	0	0	1 Newport Pier	Newport Beach	Cleanout	Cleanout under Lifeguard Headquarters was overflowing	Sand and grease	See Remarks	Cleanout under Llfeguard Headquarters was overflowing
1/18/03	4	Private	4680	0	0	0	WINDROW COMMUNITY PARK	IRVINE	N/A	LINE BREAK	LINE BREAK	STREET, CURB, GUTTER AND INTO STORM DRAIN	May be R-9
1/27/06	4	Private	0	2000	0	0	4600 BISON AVENUE (UCI)	IRVINE	N/A	N/A		PONDED IN A PIT ON CAMPUS SITE.	NA
Totals	6		4,885	2,205	500	0							
Totals	689		208,254	149,389	129,007	49,435							

APPENDIX E

Modified Master Private Property Spills 2002–2006 Sorted by Impact

Private Property Spills 2002-2006 Sorted by DATE and IMPACT

Date SSO is First Reported to Responding Agency	Responsible Party	Did SSO reach surface waters other than a storm drain?	SSO Volume Lost (Gallons)	Recovered SSO Volume (Gallons)	Recovered wash Water & Sewage Contaminated Water Volume	Lost Wash Wate & Sewage Contaminated Water Volume	, Location of overflow: Stree	t Location of overflow: City	Location of potential blockage or problem point	Description of component from which spill occurred	Likely cause of SSO	Overflow Cause - Detailed Description	Name or Description of Initial Receiving Water	Name or Description of Secondary Receiving Water	If the SSO did not reach surface waters, describe the final destination of sewage	Was the Local Health Services Agency Notified?	Remarks
2002																	
5/27/02	Private Property	yes	0	0	0	0	na	na	na	na	na	na	Newport Bay			yes	California Pizza Kitchen. Not listed in supplied OCHCA report or on Region 8 reports
6/6/02	Private Property	Yes	340	240	580	0	4117 W. McFadden Avenue	Santa Ana	Private Property	Clean out	Grease - Private Property. City of Santa Ana installer a siphon to make way for a storm drain system on the lateral. Spill occurred due to grease build up.	The City of Santa Ana installed a siphon to make way for a storm drain system on the lateral, the siphon backed up due to grease.	East Garden Grove Wintersberg C-05 Channel	Wetlands	n/a	Yes - Monica Mazar	
6/24/02	Private Property	Yes	100	250	450	0	510 E. Chestnut Avenue	Santa Ana	Private Property	Clean out		Blockage on sewer lateral was caused by grease and tree roots.	3 Santa Ana Delhi Channel	Upper Newport Bay	Upper Newport Bay	Yes - Corwin Brown	
6/30/02	Private Property	Y	300	0	0	0	3rd St & French St.	Santa Ana	Private property lateral	Cleanout	Blockage Grease clog	Not applicable - Not OCSD SSO	Not applicable - Not OCSD SSO	Not applicable - Not OCSD SSO	Not applicable - Not OCSD SSO	Not applicable - Not OCSD SSO	Called Don Cleveland to respond and evaluate, due to no response from Santa Ana Public Works. Don Cleveland arrived at this location at 1015 hour. City of Santa Ana Fire Department rrived onsite before 9am. A private plumber also responded to the site
7/2/02	Hamilton Pacific	yes	50	750	0	0	15622 Brookhurst Westminster	Westminster			grease	grease on private property	n/a	n/a			
7/30/02	Private	Y	450	120	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
8/18/02	Private	Yes	2250	10	25	0	4752 Pearce Street	Huntington Beach	In front of 4752 Pearce Street.	Clean Out	Debris, Blockage	Blockage caused by paper in line. Problem started after a recent slip lining project, according to residents.	Heil Channel, Christiana Bay, Huntington Harbor	Pacific Ocean		Yes	Orange County Health, Michael Fennessy stated he recovered samples of affected waters.
8/29/02	Jimni Service	Yes	528	100	50	0	20896 Seacoast	Huntington Beach	At the intersection of Beachcomber and Coastwatch	Manhole	Vandalism	Someone turned off power to pump station, causing the overflow.	None	None	Water went into Atlanta Storm Station which is currently being diverted to the sewer system.	Yes	Jimi Service cleaned up the spill and checked the pump station.
9/18/02	Private Property	yes	0	0	0	0	6234 Industrial Way Westminster	Westminster			grease & roots	grease & roots on private property	n/a	n/a	storm drain in Huntington Beach		
9/19/02	PWA-City of Santa Ana	Yes	600	300	900	600	2101 S. Pacific Ave.	Santa Ana	Private lateral	4" clean out	Private property spill, cause of overflow unknown.	Private property spill, cause of overflow unknown.	Santa Ana, Ana - Delhi open channel	Upper Newport Bay	N/A	Yes - Dispatcher	
9/26/02	Private: Seris Regio Group	YES	200	20	70	200	2050 Winston Rd.	Anaheim	cleanout near center of drive area at 2050 Winston Rd.	clean out onsite	break in the private sewer lateral	broken lateral in private sewer	Santa Ana River		N/A	YES	Property owner was notified of spill at 2:00 on 9/26/02 and was told the line would have to be cleaned immediately. Private plumber did not show up until the 27th. Due to difficulties cleaning the line it was determined there was a break in the private
10/12/02	Harbor Breeze Apartments	Yes	5,400	100	600	0	4841 Heil	Huntington Beach	4841 Heil	Cleanout-Manhole	Grease	Grease had built up in the line, probably due to lack of maintenance	Orange County Flood Control	Huntington Harbour	N/A	Yes	
10/18/02	Private Property - Mr. Wilson	Yes	800	200	200	800	210 S. Newhope Street	Santa Ana	Private Lateral	Private lateral clean out	Grease: Build up of grease in private lateral.	Build up grease in private lateral.	Entered C-5-F city channel, flowed to C- 5 O.C.F.C. channel to wetlands.	East Garden Grove Winterbergs wetlands	East Garden Grove - Winterbergs wetlands	Yes - J. Antonio Islas, Jr.	
11/3/02	Archstone Huntington Beach	Yes, Bolsa Chica	830	50	100	780	8925 Rockcreek	Huntington Beach	8925 Rockcreek	Manhole	Grease	Possible Lack of Maintenance Grease	East Wintersburg Channel	Bolsa Chica-Pacific Ocean	N/A	Yes	None
11/5/02	Yousef Ibrahim	Wintersburg Channel	551	100	600	451	7232 Edinger	Huntington Beach	7232 Edinger	Manhole	Grease	Chunks of Asphalt	City Edinger Channel	Wintersburg Channel	N/A	Yes	None
11/6/02	Private Property - Sullivan Mgmt Group Inc.	Yes	150	650	800	150	751 S. Harbor Blvd		20' S. of manhole where lateral connects to sewer system.	6" sewer clean out.	Grease build up caused by lack of routine maintenance program.	Grease build up caused by lack of routine maintenance program.	Entered storm drain at 901 S. Harbor Blvd.	Santa Clara River	Ocean	Yes - Karman Cheng	
11/13/02	Seebreeze Management Company	Pacific Ocean	N?A	N/A	N/A	N/A	410 Lake Street	Huntington Beach	410 Lake Street	Cleanout	Maintenance Crew	Maintenance Crew was cleaning sewer lines and allowing the sewage to flow down the drain.	Pacific Ocean	None	N/A	Yes	None

Private Property Spills 2002-2006 Sorted by DATE and IMPACT

11/15/02	Pacific West Corp.	Outfall on Sand	150	5 Gal.	24	146	101 Main Street	Huntington Beach	101 Main Street	Grease Interceptor	Grease	Possible Lack of Maintenance Grease	Pond at Outfall to Ocean	None	N/A	Yes	None
11/25/02	Private	No	0	1500	0	0	1068 Rutland	Newport Beach	Cleanout	Cleanout	Unknown (possible roots)	See Remarks	n/a	n/a	n/a	yes	Cleanout overflow - OCH care Agncy closed Upper Newpor Bay Water (Not in originally submmitted OCHCA report but in Beach Closure report)
11/30/02	Denny's Resturant	yes	165	35	0	0	n/a	n/a	Line blockage	Line Blockage	Line blockage	n/a	Santa Ana River	Pacific Ocean	n/a	yes	(Not in originally submitted OCHCA report or Region 8 reports. Listed in OCHCA Beach Closure report)
12/3/02	Richard Darling	Yes, OCFC-Sunset Channel	180	90	190	90	16490 Bolsa Chica	Huntington Beach	16490 Bolsa Chica	Cleanout in Parking Lot	Unknown at the time, turned out to be a separation in the pipe.	Unknown at the time, turned out to be a separation in the pipe.	OCFC Sunset Channel	Christiana Bay, Huntington Harbor	N/A	Yes	None
12/4/02	Richard Darling	Yes, OCFC-Sunset Channel	480	400	490	90	16490 Bolsa Chica	Huntington Beach	16490 Bolsa Chica	Cleanout in Parking Lot	Unknown at the time, turned out to be a separation in the pipe.	Unknown at the time, turned out to be a separation in the pipe.	OCFC Sunset Channel	Christiana Bay, Huntington Harbor	N/A	Yes	None
12/5/02	Private	No	500	100	0	0	1433 Superior Ave.	Newport Beach	Private system	Private system	Unknown	See Remarks	Newport Bay	n/a	n/a	yes	Plumber onsile removed blockage in private system as CNB news arrive on site (Beach House Appartments. Reported in OCHCA Beach Closure Report, not in originally submitted OCHCA report)
Totals		23	14,024	5,015	5,079	3,307											
2003																	
1/16/03	Freeway Industrial Park	Yes	2080	450	1070	1630	7402 Edinger	Huntington Beach	7402 Edinger	Cleanout	Lack of Maintenance	Lack of Maintenance/Grease/Crew Reported that grease logs were coming out into main sewer line	Murdy Channel	East Wintersburg Channel and Bolsa Chica	N/A	Yes	None
1/30/03	Private Spill	Unknown	1000	0	0	0	3435 Newport Blvd.	Newport Beach	n/a	n/a	Grease, Paper products	See Remarks	Newport Bay	n/a	n/a	yes	(Pavillons Supermarket) Blockage of paper products, feminine hygiene products, grease. (Originally marked as unknown for surface water. Reported on OCHCA Beach Closure Report)
2/25/03	Private Property	yes	3000	2000	0	0	1440 W. Lambert Rd.	La Habra	Line Blockage	Line Blockage	Grease	Grease line blockage	San Gabriel River	Pacific Ocean	n/a	yes	(Not listed in originally submitted OCHCA report. Listed in the OCHCA Beach Closure Report. Not indicated as private spill in Region 8 report)
2/9/03	Coral Cay HOA	Yes	55	5	25	55	16832 Coral Cay	Huntington Beach	16832 Coral Cay	Manhole	Grease	Grease/Lack of Maintenance	Harbor Channel	Pacific Ocean	N/A	Yes	None
4/4/03	Valley View Center, private property	e Yes	540	210	275	0	7811 Valley View St.	La Palma	Private lateral	Private lateral cleanout	Grease	Grease blockage on private property as well as debris	Moody Creek	San Gabriel River		Y	Private contractor sanitized and cleaned up
5/1/03	Private	Yes	0	25	0	0	2751 Coast Hwy.	Newport Beach	Grease Trap	Grease Trap	Unknown	See Remarks	Pacific Ocean	n/a	n/a	yes	Grease trap was overflowing. 5 gallons per minute.
5/7/03	700 N. Valley Street	Yes	200	20	30	200	700 N. Brookhurst Street	Anaheim	On Gramercy Avenue, east of Brookhurst Street	Private sewer clean out at Mobile Gas Station	Paper towels obstructing the flow.	Paper towels were obstructing the sewer line which caused the overflow.	Carbon Creek	N/A	N/A	YES	The owner of the Mobile Gas station, Morteza Yassini stated there was a small flow spilling from the clean out on 55/03 at 11 p.m. At the time, he assumed it was just water since the clean out had a lid that stated "Water" on it. Operations Crew Superv
5/26/03	Huntington by the Sea MH	IP Yes	960	40	40	920	21851 Newland Ave.	Huntington Beach	21851 Newland # 2-8	At hookup for the Coaches	Grease and debris blockage	Grease and debris from a lack of maintenance.	Talbert Marsh	Pacific Ocean		Yes	
6/11/03	Kikuya Japanese Rest.	Yes	90	50	150	40	8052 Adams	Huntington Beach	Front of Restaurant on sidewalk	Manhole	Grease	Grease causes blockage in line, Lack of Maintenance	OC Flood Control D01	None	None	Yes	None
7/1/03	Private Property Owner: 278 N. Wilshire Street	Yes	590	10	20	590	278 N. Wilshire Street	Anaheim	Near 278 N. Wilshire Street	Private Manhole	Swale in sewer lateral	Swale in pipe allowed debris to settle and accumulate resulting in blockage	Carbon Creek	N/A	N/A	Yes	Property Management was very difficult to get a hold of, however, the delay in their response will result in a large bill being issued to them for cost recovery, in conjunction with the notice of violation. Copy of this report was provided to OC Health C
7/17/03	Private Property: Paradise Pier Hotel 1717 Harbor Boulevard	Yes	100	200	1000	100	1717 Disneyland Drive	Anaheim	Near 1717 Disneyland Drive	Private Cleanout	Paper Towels	Overflow caused by buildup of paper towels in sewer line.	East GG Channel	Bolsa Chica	N/A	Yes	Disney was very forthcoming in providing the appropriate information, as well as notifying proper City and other agency staff for this incident. For many reasons, Disney has focused a great deal of effort on preventing any similar splits in the future an
8/3/03	Private	Yes	180	0	0	0	#7 ASPEN TREE LANE	IRVINE	N/A	LINE BREAK	LINE BREAK	STORM DRAIN TO SAN JOAQUIN CHANNEL.	SAN JOAQUIN CHANNEL	N/A	N/A	Yes	May be R-9
10/28/03	Private Property	Yes, possibly spill went into nearby creek.	0	0	0	0	JAMBOREE RD.	Newport Beach	8-inch clean out on private property	Clean out	Grease, other and debris	N/A	Nearby Creek	N/A	N/A	Y	N/A
10/30/03	Private	Yes	17	21	300	0	1708 Peppertree Ln in alley behind apartments	Fullerton	Private lateral	Private lateral cleanout	Roots and debris	Root intrusion into 6 inch sewer lateral through defective joint	Brea Creek Channel	Pacific Ocean		Yes	Crews responded to private lateral overflow. Overflow was intermittent between 0 and 3 gmr. Oth crews contained spill, cleared blockage, washed down and vacuumed area. Due to normal irrigation run-off and storm drain flow, crews were unable to contain
10/30/03	Private	Yes	24	20	0	0	n/a	Garden Grove	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	

11/17/03	5665 E La Palma	Yes	2700	100	200	500	5665 E. La Palma Avenue	Anaheim	5665 E. La Palma Avenue	Private cleanout	Paper Towels	Paper towels obstructed the flow of the sanitary sewer line causing it to overflow.	Santa Ana River	N/A		Yes	The majority of the sewage remaining on the surface of the parking lot was collected during a washdown with the Chy's vactor truck. However, due to a misdiagnosis of where the spill cutlet to the nearby channel, the washdown of the parking lot (intended
12/9/03	Bill Jarjour, owner of Hilltop Liquor	YES	1500	25	45	1475	815 Indianapolis Ave.	Huntington Beach	Private homeowners lateral at 815 Indianapolis Ave.	Private clean out	Grease	Grease clogged homeowners lateral line	Orange County Flood Control Channel DO-1	Talbert Marsh	Sewage was vacuumed up and put into the sewer system.	Yes	Difference of opinion by homeowner and person notifying city of spill as to length spill flowed. Location was next to bus stop see picture.
12/10/03	Private property owner	Yes	300	500	200	0	6103 Morningview Drive	Anaheim	6103 Morningview Drive	Private Cleanout PC192423	Roots	Roots clogged the sewer line and caused a overflow	Santa Ana River	N/A	N/A	YES	
12/15/03	Tritz Professional Management Services Inc.	YES	943	470	570	473	4171 Andros	Huntington Beach	Private eight-inch sewer line at 4171 Andros Ave.	Private sewer manhole	Grease and roots	Grease and roots caused the private homeowners sewer system to clog.	Huntington Harbor	Huntington Harbor		YES	
12/29/03	Richard LI, owner of the apartments	Yes	2312	200	300	2112	7872 Stark Street.	Huntington Beach	Private homeowners latera at 7872 Stark Street	Private clean out	Grease	Grease clogged apartment complex lateral line	East Garden Grove Winter Burge Channel (C-05)	Bolsa Chica Ecological Reserve.		Yes	Agnes Do from the Orange County Health Care Agency was on scene and wrote a report.
Totals		20	16,591	4,346	4,225	8,095											
2004																	
1/4/04	Private Property Owner	Yes	600	o	0	0	1415 W. Ball Rd.	Anaheim	1415 W. Ball Rd.	Private Manhole	Grease	Grease obstructed the flow of the Sanitary Sewer Line causing it to overflow	Westminster	N/A	N/A	Yes	The Anaheim Fire Department responded initially. Then Streets and Sanitation was called out and responded. Spill duration was estimated at 1 hour as the property manger found the sewer manhole flowing out heavily. Fire said that the spill was 3 inches abo
3/7/04	Sycamore Canyon Townhomes	Yes	800	200	200	0	8282 E. Oak Ridge Circle	Anaheim	8282 E. Oak Ridge Circle	Private clean out	Roots	Roots obstructed private clear out	Santa Ana River		N/A	Yes	Private plumber did not arrive until 9:35 pm and had difficulty with their equipment. Obstruction was finally cleared at 3am. Private plumber and City Staff worked to washdown and clean affected area.
3/19/04	Parkview One Homeowners	Yes	960	60	1000	0	6518 E. Camino Vista	Anaheim	6518 E. Camino Vista	Private Sewer Manhole	Roots	Roots obstructed private sewer line.	City Golf Course	Santa Ana River	N/A	Yes	The spill was not reported for an estimated 2 days, due to the fact that the residents of this complex did not identify this spill as being sewage.
4/4/04	CMSD	Y	2475	525	300	0	1599 Superior Ave / 700 Block of West 16th St;	Costa Mesa, CA	Root balls blocked private sewer lateral forcing SSO out of private cleanout; possible root entry point at Ductile Iron Pipe fitting to lateral on private property;	Root balls blocked private sewer lateral forcing SSO out of private cleanout; possible root entry point at Ductile Iron Pipe fitting to lateral on private property;	Root balls blocked private sewer lateral forcing SSO out of private cleanout;	Root balls blocked private sewer lateral forcing SSO out of private cleanout;	Newport Beach Harbor	None	Vactored SSO and rinse water were disposed of in the sanitary sewer system at the Corporate Yard;	Y; 4/05/2004 @ 1545 hrs	Root balls blocked private server lateral forcing SSQ out of private deanout; possible root entry point at Ductile tron Pipe Itting to lateral on private property; Olen Properties Propenty Manage 44 EX Solvenizer called for two plumbing companies to clear the SSO lateral blockage. First company unable to clear lateral with rotary cutiling black – but removed not clusters from tateral; Second company used a min lydrojet to clear remaining blockage; District Field Crew recommends the Property Manager vide doe tateitare; Joint of class NPDE S Manager also on-site and took photos; CMSD Crew dammed storm drain, vactored and disposed of the contained SSO and rines water into the District samilary sever system at the Corporate Yard; Photographs were taken and are attached.
4/15/04	City of Anaheim / Anaheim Fire Station #9	Yes	150	50	200	0	6300 Nohl Ranch Rd.	Anaheim	6300 Nohl Ranch Rd.	Sewer Lateral Cleanout	Construction damaged the lateral and allowed roots to invade sewer line	Roots	Flood Control Channel	Santa Ana River	N/A	Yes	NA
6/24/04	Private Spill	Unknown	400	100	0	0	500 Superior	Newport Beach	n/a	n/a	Unknown	See Remarks	Newport Bay	n/a	n/a	yes	Vactor setup dirt berm@catch basin. Vacuum setup @ manhole to stop SSO. (Not in the OCHCA originally submitted report. Listed in the OCHCA Beach Closure Report and Region 8 report)
7/11/04	Golden West Property Management Inc. (714) 491- 9005	Yes	3024	0	50	3024	Behind 6101 Morningside Drive	Huntington Beach	Grease blockage inside of eight inch private sewer line.	Manhole	Grease blockage	Grease buildup from a lack of maintenance.	Bolsa Chica Wetlands	None, all sewage stayed in wetland area.		Yes	Sewage flowes from 200 residents through this line. All upstreem sewer lines were cleaned 7/19/04. These lines will be put on a scheduled cleaning.
7/29/04	1743 S. Clementine (Extended Stay America)	Yes	260	1100	300	200	1742 S. Clementine Street	Anaheim	1742 S. Clementine Street	Private Manhole	Cloth and other debris	Cloth and debris clogged pipeline, causing sewage to overflow.	Bolsa Chica	N/A	Bolsa Chica	Yes	
8/5/04	Private Party	yes	20	180	0	0	4901 Lincoln Ave.	Cypress	n/a	n/a	n/a	n/a	Coyote Creek	n/a	n/a	n/a	
9/5/04	Broadmoor Huntington Harbour HOA	Yes	50	0	100	100	6905 Warner Ave.	Huntington Beach	Private sewer lateral at 3251 Moritz Drive.	Cleanout	Grease and debris blockage	Grease and debris buildup from two condo units sharing plumbing pipes.	Huntington Harbour	Pacific Ocean		Yes	Spill was reported to Huntington Beach Police Dept. they referred spill to wrong Dept Wastewater arrived at spill two hours after reported time and sewage flow was stopped.
9/11/04	Prudential Real Estate	Yes	276	200	450	76	21851 Newland Ave.	Huntington Beach	Private sewer lateral at 7931 Stark Ave.	Cleanout	Tree roots	Tree roots clogged sewer lateral for an eight unit residential complex	Wintersburg Channel, CO5	Bolsa Chica Wetlands		Yes	
9/21/04	Lincoln Inn, Kelly Erickson - Maint. Manager	Yes	100	0	100	0	2748 W. Lincoln Avenue	Anaheim	2748 W. Lincoln Avenue	Private cleanout	Feminine hygiene products	Feminine hygiene products got lodged in line.	Carbon Creek	N/A	N/A	Yes	Hotel cleared blockage with their own equipment and proceeded to wash the spill into the onsite drop inlet before City Staff arrived onsite. Hotel Management was informed that the spill had to be contained onsite and City had to be contacted in the event
9/21/04	Private Property	Y	0	400	0	0	15701 TUSTIN VILLAGE WAY	Unincorporated County of Orange	^y 4° clean out	Clean out	Blockage	Misc. debris	Peters Canyon Wash	Peters Canyon Wash	Peters Canyon Wash	Y; 9/21/2004 9:05:00 AM	CITY OF TUSTIN TOOK PHOTOS & WILL FORWARD THEM TO OCSD. TOTAL SPILL LESS THAN 1,000 GALLONS PER FIELD OBSERVATION.
10/21/04	New Mark Merill Companies - Ralph Woebkey 2180 E. Lincoln Ave., Santa Ana 92806 (714) 956-3411	Yes	690	690	2660	690	2307 S. Bristol St.	Santa Ana	Private lateral	Clean out	Grease	There are several restaurants located in the shopping center that maybe discharging grease into the sewer system.	Upper Newport Bay	Upper Newport Bay	N/A	Yes	State ID #04-5508

11/12/04	Anaheim Hilton	Yes	880	20	400	0	777 Convention Way	Anaheim	777 Convention Way	Private Manhole and Cleanout	Grease	Grease blocked sewer line, causing sewage to overflow.	Anaheim Barber Channel	N/A	Anaheim Barber Channel	Yes	This spill was observed on Wednesday flowing only for a couple hours in the morning which is what the flow estimate is based on. There is clear evidence that despite the large flow carried by the 15° line which was obstructed, the actual amount of sewage
12/16/04	Royale Health Care Center	Yes	300	1600	1600	300	1027 W. Central Ave.	Santa Ana	Private sewer line	Pick hole of manhole	Grease	Large amounts of grease deposits from poor maintenance program	Upper Newport Bay	None	Returned to sewer system	Yes	State ID #04-6597
12/21/04	Ron Marshall, Manager of Mr. Stox restaurant	Yes	188	100	400	0	1105 E. Katella Avenue	Anaheim	1105 E. Katella Avenue	Private cleanout	Paper Towels	Paper Towels blocked pipeline, causing sewage to overflow.	Bolsa Chica	N/A	N/A	Yes	OCHCA visited the location to determine if there were any issues inside the restaurant.
12/29/04	Private Property	Yes	50	25	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Totals		18	11,223	5,250	7,760	4,390											
2005																	
1/2/05	7232 Edinger shopping center	Yes	70	980	1,480	70	7232 Edinger	Huntington Beach	City's 8 inch sewer line	Manhole cover pick holes	Grease	Grease from a private shopping center lateral flowed into City's main line.	Murdy Channel	East Garden Grove Winterburg Channel		Yes	
1/2/05	George Galanoues owner of apartment complex	Yes	2,100	900	1,400	2,100	2208 Delaware St.	Huntington Beach	Private sewer lateral	Private 4 inch sewer clean out pipe.	Grease	Grease buildup in private sewer lateral.	Huntington Beach Channel	Talbert Channel at Brookhurst St.		Yes	There were several different estimates from residents in the complex stating when the sewage started flowing above ground.
1/4/05	Lake Summit Association	Yes	60	40	500	0	920 S. Ridgecrest Circle	Anaheim	Near 920 S. Ridgecrest Circle	Private Manhole	Grease	Grease blocked pipeline, causing sewage to overflow.	Santa Ana River	Pacific Ocean	N/A	Yes	Spill appeared to be flowing at a far greater rate than 50 gph. However, the sewer line that was obstructed only serves 20 homes and a typical flow at 10 am would likely be approximately 50 gph. Therefore, the additional flow is suspected to be from Inflo
1/13/05	Wonson Kim, owner, Fullerton Inn Hotel	Yes	700	200	3000	0	2601 W Orangethorpe - Fullerton Inn Hotel	Fullerton	Private lateral @ 2601 W Orangethorpe	Private lateral cleanout	Debris, paper	City lateral rod crew cleared unknown blockage from upstream	Ash Channel to Fullerton Creek Channel	Pacific Ocean		Yes	City sewer crews noticed sewage flow from driveway at small hotel. City crews set up vactor vacuum at downstream catch basin while waiting for additional crews. City noding crews and additional combo truck responded, cleared private lateral, washed down
1/19/05	Property Owner	Yes	60	100	200	60	3041 S. Bristol	Santa Ana	Private lateral	4* clean out	Paper/Grease/Private Property	Build up of paper and grease	Santa Ana/Alton Channel	None	N/A	Yes	None
1/25/05	Victoria Townhouse Apartments	Yes	1050	7500	500	0	2256 W. Lincoln Ave.	Anaheim	2256 W. Lincoln Ave.	Private Manhole	Grease & Roots	Roots and grease blocked pipeline, causing sewage to overflow.	Coyote Creek	San Gabriel River	N/A	Yes	Property owner called private plumber at 2:00 PM but did not show up until 6:00 PM. City crews cleared the obstruction at 5:45 PM. Plumber would not have been able to clear blockage anyway, since he did not have the equipment to do so. Attached are two vo
2/28/05	Richard Li property owner	YES	200	175	375	25	7872 Stark St.	Huntington Beach	Private sewer lateral	Private sewer lateral clean out at 7873 Stark St.	Grease	Buildup of grease in private sewer lateral.	East Garden Grove Winterburg Channel	Bolsa Chica wetlands		YES	Only one tenant home doing laundry at the time of the spill.
3/1/05	Private	Yes	0	0	0	0	453 SUMMERFIELD CIRCLE	ANAHEIM	N/A	N/A	GREASE	STORM DRAIN -> EAST GARDEN GROVE WINTERSBERG CHANNEL - > LOWER BOLSA	WINTERSBERG CHANNEL	N/A	N/A	Yes	NA
3/8/05	MBJ Property Management	Yes	290	400	2000	0	2500 E Chapman Ave @ St College	Fullerton	Private lateral to the rear of 2506 E Chapman Ave	Private lateral cleanout	Unknown		Fullerton Creek Channel	Pacific Ocean		Yes	City crews responded to private lateral overflow from cleanout to the rear of 2506 E Chapman Ave. Sewage was flowing down alley swale to storm drain inlet in approach to alley off St College Bivd. City crews contained flow at storm drain and several are
3/12/05	Private Property	Yes	700	200	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
3/20/05	Private	Yes	350	150	0	0	745 DOVER	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	PRIVATE CLEAN OUT TO PARKING LOT TO STORM DRAIN TO NEWPORT BAY	Newport Bay	N/A	N/A	Yes	NA
5/4/05	Private	Yes	50	0	0	0	1773 W. Lincoln Ave.	Anaheim	1773 W. Lincoln Ave. Anaheim	Private clean out	Grease	Grease caused obstruction.	Carbon Creek	N/A	Carbon Creek	Yes	The spill had occurred intermittently over the 24 hours prior to City Staff arrival. A clear link, which Bakery management acknowledged, was made between the excessive amounts grease in the manhole and the obstruction which caused the spill.
5/29/05	Private	Yes	3000	1200	200	200	801 N. Loara Street Anaheim	Anaheim	801 N. Loara Street Anaheim	Private clean out	Rags	Blockage caused by rags clogging lateral line.	Carbon Creek	Crecent Retarding Basin	Crecent Retarding Basin	Yes	
6/10/05	Private	Yes	100	800	200	200	537 N. Magnolia Ave.	Anaheim	537 N. Magnolia Ave.	Private clean out and private manhole	Pump shut down	Pump shut down caused obstruction	Coyote Creek	N/A		Yes	The property owner/manager contacted a pump company (Orange County Pumping) who corrected the problem with the pump station. The area in front of the building was washed by the City staff, however, other areas along the side of the building-not-acessable
6/18/05	Private Property	Yes	100	0	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
6/20/05	Vons Market	Yes	50	25	0	0	1000 Bayside Dr.	Newport Beach	n/a	n/a	Grease	See Remarks	Pacific Ocean	n/a	n/a	yes	Water Crew built a berm to contain the overflow to and called for a vactor to clean up the spill. Vactor remained onsite until the blockage was clearned.
8/2/05	Private lateral Tony Romas	Yes	20	100	200	0	1300 S Harbor Blvd	Fullerton	Private lateral	lateral cleanout	Paper		Discharge basin at Riverside Frwy	Unknown		Yes	The City's emergency crew responded to report of sso from private cleanout. City crew contained sewage at storm drain, dispatched sever on call crews. Restaurant called private plumber. There was no overflow inside facility. City crews washed down and

Private Property Spills 2002-2006 Sorted by DATE and IMPACT

9/24/05	Private	Yes	2160	1200	200	0	1199 N. Euclid Street	Anaheim	1199 N. Euclid Street	N/A	Grease	Grease caused spill	Fullerton Creek	San Gabriel River		Yes	OCHCA assisted onscene and washdown was performed by a private party.
10/20/05	Private	Yes	29	50	0	0	17199 BLUEWATER LANE	HUNTINGTON BEAC	HN/A	N/A	ROOTS & GREASE	MANHOLE TO SIDEWALK TO BULKHEAD TO BAY WATER	N/A	N/A	N/A	Yes	NA
10/25/05	Private	Yes	20	10	o	0	behind 2235 Pacific Dr	Newport Beach	Broken pipe	Broken pipe	Broken pipe on the hillside that was discharging sewage.	e See Remarks	n/a	n/a	n/a	yes	Setup beam and vactor on Bayside Dr, used two flagmen for traffic control. Contacted Michael Bayer at 2235 Pacific Dr. to advise him he had a problem.
11/28/05	Private - Tony Roma's Restaurant	Yes	160	30	50	0	1300 S Harbor Blvd	Fullerton	Private lateral	Private lateral cleanout	Grease, debris		Discharge basin at 91 Frwy/ S Harbor Blvd	Unknown		Yes	Emergency right crew responded to private lateral overflow at Tory Romas. Crew placed sand bags around storm drain. Sewer on call crew responded, cleared grease blockage in lateral to stop overflow, cleaned area. Follow up activities will b performed
12/14/05	Private	Yes	143	2	0	0	8052 ADAMS	HUNTINGTON BEAC	H N/A	N/A	GREASE	STORM DRAIN -> TALBERT CHANNEL (DIVERTED TO SEWER SYSTEM)	TALBERT CHANNEL	N/A	N/A	Yes	N/A
Totals		22	11,412	14,062	10,305	2,655											
2006																	
1/3/06	Private Spill Kobe Restaurant	Yes, OC Flood Control Basin	120	50	200	0	3001 Old Ranch Parkway	Seal Beach	private sewer main line at 3001 Old Ranch Parkway	Restaurant clean-out	Grease	Restaurant had grease interceptor cleaned 3 days prior to overflow. Cleaning may have forced grease into their main line.	Bixby Storm Channel	n/a	Los Alamitos Basin	Yes	nía
1/6/06	Merit Management Group (Armstrong Ranch) 800- 428-5588	Yes	540	200	500	340	3301 S. Sheffield	Santa Ana	Private property sewer system	Starter pot	Grease/ Construction/ Private Property	Combination of construction debri and grease was the cause of the spill.	Santa Ana/ Delhi Channel	Upper Newport Bay	Upper Newport Bay	Yes	
1/9/06	Private	Yes	30	90	40	0	1721 Claudina Avenue	Anaheim	1721 Claudina Avenue	Private Cleanout	Roots	Roots caused obstruction	Los Alamitos	Bolsa Chica		Yes	N/A
1/16/06	Private	Yes	2050	250	1000	0	453 W. Summerfield Circle	Anaheim	453 W. Summerfield Circle	Private Cleanout	Grease	Grease caused the obstruction	East GG Wintersburg	N/A		Yes	This is the first clear instance of a repeat spill in many years. This will require highe level enforcement to ensure this does not happen again.
1/28/06	Private	Yes	10800	0	o	0	5238 MICHELSON	IRVINE	N/A	N/A	ROOTS	MASON CREEK AND SAN DIEGO CREEK TO UPPER NEWPORT BAY	MASON CREEK AND SAN DIEGO CREEK	UPPER NEWPORT BAY	N/A	Yes	May be R-9
2/15/06	Private - Calvin Sekhon, property owner (714) 878- 1540	Yes	700	100	1000	0	2309 W Valencia	Fullerton	Private lateral	3 lateral cleanouts on property	Debris, grease		Fullerton Creek Channel	Pacific Ocean		Yes	Crews responded to private overflow from three cleanout locations within apartmen complex. City crews contained SSO at private drain in parking area. City crews se up vactor vacuum in gutter, cleared blockage to stop overflow, washed down and vacuumed
2/16/06	Private - Calvin Sekhon, property owner (714) 878- 1540	Yes	587	200	1000	0	2309 W Valencia	Fullerton	Private lateral	3 lateral cleanouts on property	Debris, grease	Private lateral line was not completely cleared from previous blockage	Fullerton Creek Channel	Pacific Ocean		Yes	Crews responded to private overflow from three cleanout locations within apartmen complex. City crews contained SSO at private drain in parking area. City crews se up vactor vacuum in gutter, private plumber responded and cleared blockage to stop over
3/4/06	Private	Yes	113	150	100	0	501 N State College Blvd (Chipotle Grill)	Fullerton	Private lateral	Private lateral cleanout	Debris, grease		Fullerton Creek Channel	Pacific Ocean		Yes	City crews responded to private lateral overflow at Chipotle Grill/Pick up Stix restaurants. Health Care agency was on scene. Crews cleared blockage to stop overflow, some grease retrieved on rodding equipment. City crews washed down and vacuumed area.
3/7/06	Private	Yes	500	40	20	0	105 E. Leatrice Ln.	Anaheim	105 E. Leatrice Ln.	Private cleanout	Vandalism	Vandalism caused spill	Los Alamitos	Garden Grove		Yes	This spill was reported to have been flowing for several days by the tenants. The odor in the area and the volume of solids near the spill bears this out. However, th property owner was very responsive in taking care of the obstruction as well as aid
3/23/06	Private	Yes	255	1500	500	0	3170 W. Lincoln Ave.	Anaheim	3170 W. Lincoln Ave.	Private cleanout	Grease	Grease caused obstruction	Carbon Creek	N/A		Yes	Property owner was very cooperative and reported this spill to the City themselves. There was a delay, however, in clearing the sever line, since the "snake" that the first plumber used was not effective in clearing the obstruction. The second plumber m
3/29/06	Private, Albertsons Corp, 1955 W North, Malrose Park, Illinois 60160 contact:Barbara Mott 708- 492-3100	Yes	20	180	800	0	455 N State College Blvd (Sav-On)	Fullerton	Private lateral	3 lateral cleanouts in parking lot	Debris	Plumber cleared approx 10' of thick substance from line	Fullerton Creek Channel	Pacific Ocean		Yes	City crews responded to report of sewage in parking lot of Sav On at State College & Chapma Ave. Lateral deanouts in parking lot were seeping with small amount of flow into guiter area down to catch basin. Flow was contained in parking lot with sandba
4/6/06	Private	Yes	140	0	40	0	969 S. Euclid St.	Anaheim	969 S. Euclid St.	Private cleanout	Grease and food	Grease and food caused obstruction	Los Alamitos	Bolsa Chica		Yes	Sewage flowed south from parking lot behind Little Caesar's Pizza to Ball Road. On Ball Road it traveled west approximately 250 yards where it entered the catch basin located at 1791 W. Ball Road, on the north side of Ball Road.
4/6/06	Private	Yes	400	200	0	0	7850 SLATER AVENUE	HUNTINGTON BEAC	H N/A	N/A	GREASE	HUNTINGTON CENTRAL PARK LAKE - WILL POST SOME CLOSURE SIGNS AT DRAIN ENTRY TO LAKE FOR A FEW DAYS - INCIDENTAL CONTACT LAKE.	HUNTINGTON CENTRAL PARK LAKE	N/A	NA	Yes	NA

Private Property Spills 2002-2006 Sorted by DATE and IMPACT

4/11/06	Private	Yes	15	160	0	0	7402 EDINGER AVENUE	HUNTINGTON BEACH	N/A	N/A	GREASE	STORM DRAIN -> FLOOD CONTROL CHANNEL (EAST GARDEN GRÖVE WINTERSBERG CHANNEL)	WINTERSBERG	N/A	N/A	Yes	NA
4/24/06	Private Health Care Center	Yes	630	0	0	0	RXR easement behind 2800 N Harbor	Fullerton	Private lateral	Lateral cleanout	Grease, debris		Brea Creek dirt channel		Sewage soaked into dirt channel	Yes	Crews responded, contained, and cleared blockage in private lateral to stop flow. Private plumber responded to follow up with clean up activities. All sewage soaked into the dirt channel near railroad easement. Skilled Healthcare Center will be added t
6/5/06	Sterling Shopping Center, manager, Ross Cannon.	Yes	360	200	700	160	17436 Beach Blvd., Sterling shopping center	Huntington Beach	Blockage was in the private lateral line of the shopping center.	Pick hole of the clean out cover.	Grease blockage.	Grease and debris blocked the private lateral line.	Jefferson City Channel	County Ocean View Channel to the Wintersburg Channel then the Bolsa Chica Wetlands.		Yes	
6/11/06	Private	Yes	600	1800	20	600	8000 Naples Ln.	Anaheim	8000 Naples Ln.	Private cleanout	roots	Roots caused obstruction	Santa Ana River	N/A	N/A	Yes	N/A
6/12/06	Private		200	1800	0	0	3101 W. PACIFIC COAST HIGHWAY	NEWPORT BEACH	N/A	N/A	PUMP STATION FAILURE	STORM DRAIN -> NEWPORT BAY AT "MARINER MILE" MARINA DOCKS (3101 W. COAST HIGHWAY)	NEWPORT BAY	n/a	n/a	yes	(Surface water unmarked in original Region 8 report. Listed on OCHCA Beach Closure report.)
6/26/06	Restaurant at the end of the Newport Pier	No	0	0	0	0	Restaurant at the end of the Newport Pier	Newport Beach	Pipe joint	Pipe hangers holding ABS piping under the pier failed due to rust & corrosion, the piping dropped & a joint pulled apart.	Pipe joint separation	See Remarks	n/a	n/a	n/a	Yes	City of Newport Beach lift station orew tunred water off to Restaurant immediately and advised restaurant manager of the problem. Utilities office called Environmental Health Services and RWQCB. (Surface water marked no in Region 8 report. Listed in OCHCA Beach Closure report.)
7/17/06	Private Property	Yes	50	100	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
8/5/06	Private	Yes	300	0	0	0	24401 MUIRLANDS	LAKE FOREST	N/A	N/A	GREASE	GREASE INTERCEPTOR TO PARKING LOT TO STORM DRAIN TO SAN DIEGO CREEK (DRY).	SAN DIEGO CREEK (DRY)	N/A	N/A	Yes	May be R-9
8/20/06	Private Property	Yes	100	100	0	0	n/a	Buena Park	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
9/28/06	Private	Yes	25	0	0	0	Grant Street	Newport Beach	n/a	n/a	n/a	n/a	Nwport Slough	Santa Ana River	n/a	yes	(Listed only on the OCHCA Beach Closure Report)
10/16/06	Private	Yes	200	0	0	0	610 NEWPORT CENTER DRIVE	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	SEWAGE DISCHARGED TO STORM DRAIN AND INTO NEWPORT BAY	NEWPORT BAY	N/A	N/A	Yes	NA
11/6/06	Private	Yes	1000	1520	1000	0	967 S. Euclid St.	Anaheim	927 S. Euclid St. Interceptor	Private cleanout	Grease and settlable food solid	Grease and solids build up in interceptor and caused obstruction	Catch basin	Anahiem Barber Channel/ Huntington Harbor	N/A	Yes	A previous spill occurred at this address but not from this same line. Impliementing a program to prevent the discharge of solids to the interceptor as well as a more frequent inspection and/or cleaning program should resolve this situation.
11/30/06	Private	Yes	400	500	500	0	1830 W. Romneya Drive	Anaheim	Pump Station at N/W corner of Euclid and Romneya	Private manhole	pump station failure	A sensor which monitors the level of sewage in the wet we failed	I Catch basin	Fullerton Creek/Coyote Creek	, N/A	Yes	This was an unusual spill as it was caused by a failure of a private pump station. This failure is unlikely to occur again, however we will require assurances from the owner/operator to ensure this.
12/19/06	Private Property owner, CVS Pharmacy	Yes	100	200	All	0	455 N State College Blvd	Fullerton	Private lateral	Lateral cleanout	Lateral defect, debris	6" lateral from building connects to old 4" lateral at sidewalk area creating offset	Fullerton Creek Channel	Pacific Ocean		Yes	City crews responded to private overflow in CVS (formerly Sav-On) parking lot. Water crew responded to shut off water service to stop overflow. Store manager was not aware of problem prior to our arrival. Private plumber was dispatched and responded to
12/20/06	Private	Yes	100	200	0	0	CHAPMAN/STATE COLLEGE	FULLERTON	N/A	N/A	CONSTRUCTION DEBRIS	PARKING LOT CLEAN OUT TO STREET, CURB AND GUTTER TO STORM DRAIN TO FULLERTON CHANNEL.	FULLERTON CHANNEL	N/A	N/A	Yes	NA
12/22/06	Private	Yes	10	0	0	0	1151 N. Euclid St.	Anaheim	1151 N. Euclid lateral in alley behind building	Private cleanout	Grease	Grease caused obstruction	Catch basin	Fullerton Creek/Coyote Creek	, N/A	Yes	A previous spill occurred at this location. If routine cleaning and Kitchen BMPs can not prevent spills, an iterceptor will be required,.
12/23/06.	Private	Yes	100	200	0	0	3435 Newport Blvd.	Newport Beach	Grease trap	Grease trap	Grease from their grease trap.	See Remarks	n/a	n/a	n/a	yes	Grease trap from Pavillions Market overflowing. Fire crew and Monica from Health Dept. already on scene. Set up vacuum truck in parking lot. Spoke with the Marager at the market and told him he needs to get a plumber out. Health Dept. shut down the Market
12/28/06	Private	Yes	200	400	200	0	537 N. Magnolia Ave.	Anaheim	Pump Station Failure	Private manhole	pump station failure	pumps are believed to have burned out	Catch basin	Carbon Creek	N/A	Yes	This was an unusual spill since it is the third at this location, however, since it was caused by something different each time it has occurred, the order will focus on items that may not have been satisfied in previous orders and items that would hel pr
12/30/06	Private	yes	100	2000	2000	2000	2704 W. Ball Road	Anaheim	lateral from last manhole in complex to street	Private cleanout	grease and perhaps roots or a break	Grease alone or in conjunction with a break or roots caused the obstruction	Catch basin	anaheim barber channel	N/A	Yes	
Totals		32	20,745	12,140	9,620	3,100											
Totals		115	73,995	40,813	36,989	21,547											

APPENDIX F

Modified Master Private Property Spills 2002–2006 Sorted by Beach Closure

Private Property Spills 2002-2006 Sorted by DATE and Beach Closures

Date SSO is First Reported to Responding Agency	Responsible Party	Did SSO reach surface waters other than a storm drain?	Days Closed	Beach Mile Days	SSO Volume Lost (Gallons)	Recovered SSO Volume (Gallons)	Recovered wash Water & Sewage Contaminated Water Volume	Lost Wash Water & Sewage Contaminated Water Volume	Location of overflow: Street	Location of overflow: City	Location of potential blockage or problem point	Description of component from which spill occurred	Likely cause of SSO	Overflow Cause - Detailed Description	Name or Description of Initial Receiving Water	Name or Description of Secondary Receiving Water	If the SSO did not reach surface waters, describe the final destination of sewage	Was the Local Health Services Agency Notified?	Remarks
2002																			
5/27/02	Private Property	yes	3	0.09	0	0	0	0	na	na	na	na	na	na	Newport Bay	na	na	Yes	California Pizza Kitchen. Not listed in supplied OCHCA report or on Region 8 reports
8/18/02	Private	Yes	3	0.75	2250	10	25	0	4752 Pearce Street	Huntington Beach	In front of 4752 Pearce Street.	Clean Out	Debris, Blockage	Blockage caused by paper in line. Problem started after a recent slip lining project, according to residents.	Heil Channel, Christiana Bay, Huntington Harbor	Pacific Ocean		Yes	Orange County Health, Michael Fennessy stated he recovered samples of affected waters.
10/12/02	Harbor Breeze Apartments	Yes	3	0.51	5,400	100	600	0	4841 Heil	Huntington Beach	4841 Heil	Cleanout-Manhole	Grease	Grease had built up in the line, probably due to lack of maintenance	Orange County Flood Control	Huntington Harbour	N/A	Yes	
11/25/02	Private	No	3	0.57	0	1500	0	0	1068 Rutland	Newport Beach	Cleanout	Cleanout	Unknown (possible roots)	See Remarks	n/a	n/a	n/a	yes	Cleanout overflow - OCH care Agncy closed Upper Newpor Bay Water (Not in originally subminited OCHCA report but in Beach Closure report)
11/30/02	Denny's Resturant	yes	6	0.68	165	35	0	0	n/a	n/a	Line blockage	Line Blockage	Line blockage	n/a	Santa Ana River	Pacific Ocean	n/a	yes	(Not in originally submitted OCHCA report or Region 8 reports. Listed in OCHCA Beach Closure report)
12/3/02	Richard Darling	Yes, OCFC- Sunset Channel	3	0.17	180	90	190	90	16490 Bolsa Chica	Huntington Beach	16490 Bolsa Chica	Cleanout in Parking Lot	Unknown at the time, turned out to be a separation in the pipe.	Unknown at the time, turned out to be a separation in the pipe.	OCFC Sunset Channel	Christiana Bay, Huntington Harbor	N/A	Yes	None
12/5/02	Private	No	4	0.23	500	100	0	0	1433 Superior Ave.	Newport Beach	Private system	Private system	Unknown	See Remarks	Newport Bay	n/a	n/a	yes	Plumber onsite removed blockage in private system as CNB news arrive on site (Beach House Appartments. Reported in OCHCA Beach Closure Report, not in originally submitted OCHCA report)
Totals		7	25	3.00	8,495	1,835	815	90											
2003																			
2/9/03	Coral Cay HOA	Yes	4	1.00	55	5	25	55	16832 Coral Cay	Huntington Beach	16832 Coral Cay	Manhole	Grease	Grease/Lack of Maintenance	Harbor Channel	Pacific Ocean	N/A	Yes	None
2/25/03	Private Property	yes	4	1.00	3000	2000	0	0	1440 W. Lambert Rd.	La Habra	Line Blockage	Line Blockage	Grease	Grease line blockage	San Gabriel River	Pacific Ocean	n/a	yes	(Not listed in originally submitted OCHCA report. Listed in the OCHCA Beach Closure Report. Not indicated as private spill in Region 8 report)
5/1/03	Private	Yes	2	0.11	0	25	0	0	2751 Coast Hwy.	Newport Beach	Grease Trap	Grease Trap	Unknown	See Remarks	Pacific Ocean	n/a	n/a	yes	Grease trap was overflowing. 5 gallons per minute.
5/26/03	Huntington by the Sea MHP	Yes	2	0.76	960	40	40	920	21851 Newland Ave.	Huntington Beach	21851 Newland # 2-8	At hookup for the Coaches	Grease and debris blockage	Grease and debris from a lack of maintenance.	Talbert Marsh	Pacific Ocean		Yes	
12/15/03	Tritz Professional Management Services Inc.	YES	2	0.03	943	470	570	473	4171 Andros	Huntington Beach	Private eight-inch sewer line at 4171 Andros Ave.	Private sewer manhole	Grease and roots	Grease and roots caused the private homeowners sewer system to clog.	Huntington Harbor	Huntington Harbor		YES	
Totals		5	14	2.90	4,958	2,540	635	1,448											
2004																			
4/4/04	CMSD	Y	4	0.17	2475	525	300	0	1599 Superior Ave / 700 Block of West 16th St;	Costa Mesa, CA	Root balls blocked private sever lateral forcing SSO out of private cleanout; possible root entry point at Ductile from Pipe fitting to lateral on private property;	forcing SSO out of private cleanout;	Root balls blocked private sewer lateral forcing SSO out of private cleanout;	Root balls blocked private sewer lateral forcing SSO out of private cleanout;	Newport Beach Harbor	None	Vactored SSO and rinse water were disposed of in the sanitary sever system at the Corporate Yard;	Y; 4/05/2004 @ 1545 hrs	company used a min mycropet to cear referming blockages, Uainet Hed Clew recommende the Propenty Manager video he siteral: Q1 of Costa Meas NPDES Manager also on-site and took photos; CMSD Crew demmed atom Manager and the site of the siteral site of the siteral site of the site of the District sinality as were system at the Corporate Yard; Photographs were taken and are attached.
6/24/04	Private Spill	Unknown	2	0.11	400	100	0	0	500 Superior	Newport Beach	n/a	n/a	Unknown	See Remarks	Newport Bay	n/a	n/a	yes	Vactor setup dirt berm@catch basin. Vacuum setup @ manhole to stop SSO. (Not in the OCHCA originally submitted report. Listed in the OCHCA Beach Closure Report and Region 8 report)
9/5/04	Broadmoor Huntington Harbour HOA	Yes	3	0.34	50	0	100	100	6905 Warner Ave.	Huntington Beach	Private sewer lateral at 3251 Moritz Drive.	Cleanout	Grease and debris blockage	Grease and debris buildup from two condo units sharing plumbing pipes.	Huntington Harbour	Pacific Ocean		Yes	Spill was reported to Huntington Beach Police Dept. they referred spill to wrong Dept. Wastewater arrived at spill two hours after reported time and sewage flow was stopped.
Totals		3	9	1	2925	625	400	100											

Private Property Spills 2002-2006 Sorted by DATE and Beach Closures

2005																			
3/20/05	Private	Yes	3	0.09	350	150	0	0	745 DOVER	NEWPORT BEACH	N/A	N/A	BLOCKAGE - UNKNOWN	PRIVATE CLEAN OUT TO PARKING LOT TO STORM DRAIN TO NEWPORT BAY	Newport Bay	N/A	N/A	Yes	NA
6/20/05	Vons Market	Yes	2	0.06	50	25	0	0	1000 Bayside Dr.	Newport Beach	n/a	n/a	Grease	See Remarks	Pacific Ocean	n/a	n/a	yes	Water Crew built a berm to contain the overflow to and called for a vactor to clean up the spill. Vactor remained onsite until the blockage was clearned.
10/20/05	Private	Yes	3	0.17	29	50	0	0	17199 BLUEWATER LANE	HUNTINGTON BEACH	N/A	N/A	ROOTS & GREASE	MANHOLE TO SIDEWALK TO BULKHEAD TO BAY WATER	N/A	N/A	N/A	Yes	N/A
10/25/05	Private	Yes	2	0.06	20	10	0	0	behind 2235 Pacific Dr	Newport Beach	Broken pipe		Broken pipe on th hillside that was discharging sewage.	e See Remarks	n/a	n/a	n/a	yes	Setup beam and vactor on Bayside Dr, used two flagmen for traffic control. Contacted Michael Bayer at 2235 Pacific Dr. to advise him he had a problem.
Totals		4	10	0.38	449	235	0	0											
2006																			
6/12/06	Private		2	0.76	200	1800	O	0	3101 W. PACIFIC COAST HIGHWAY	NEWPORT BEACH	N/A	N/A	PUMP STATION FAILURE	STORM DRAIN -> NEWPORT BAY AT "MARINER MILE" MARINA DOCKS (3101 W. COAST HIGHWAY)	NEWPORT BAY	n/a	n/a	yes	(Surface water unmarked in original Region 8 report. Listed on OCHCA Beach Closure report.)
6/26/06	Restaurant at the end of the Newport Pier	No	2	0.76	0	0	0	0	Restaurant at the end of the Newport Pier	Newport Beach	Pipe joint	Pipe hangers holding ABS piping under the pier failed due to rust & corrosion, the piping dropped & a joint pulled apart.		See Remarks	n/a	n/a	n/a	Yes	City of Newport Beach IIIt station crew turned water off to Restaurant immediately and advised restaurant manager of the problem. Utilities office called Environmental Health Services and RWQCB. (Surface water marked no in Region 8 report. Listed in OCHCA Beach Closure report.)
9/28/06	Private	Yes	2	0.16	25	0	0	0	Grant Street	Newport Beach	n/a	n/a	n/a	n/a	Nwport Slough	Santa Ana River	n/a	yes	(Listed only on the OCHCA Beach Closure Report)
10/16/06	Private	Yes	2	0.11	200	0	0	0	610 NEWPORT CENTER DRIVE	NEWPORT BEACH	N/A		BLOCKAGE - UNKNOWN	SEWAGE DISCHARGED TO STORM DRAIN AND INTO NEWPORT BAY		N/A	N/A	Yes	N/A
11/6/06	Private	Yes	2	0.11	1000	1520	1000	0	967 S. Euclid St.	Anaheim	927 S. Euclid St. Interceptor	Private cleanout	Grease and settlable food solids	Grease and solids build up in interceptor and caused obstruction	Catch basin	Anahiem Barber Channel/ Huntington Harbor	N/A	Yes	A previous spill occurred at this address but not from this same line. Implementing a program to prevent the discharge of solids to the interceptor as well as a more frequent inspection and/or cleaning program should resolve this situation.
12/23/06.	Private	Yes	3	0.17	100	200	0	0	3435 Newport Blvd.	Newport Beach	Grease trap	Grease trap	Grease from their grease trap.	See Remarks	n/a	n/a	n/a	yes	Grease trap from Pavillons Market overflowing. Fire crew and Monica from Health Dept. already on scene. Set up vacuum truck in parking lot. Spoke with the Manager at the market and told him he needs to get a plumber out. Health Dept. shut down the Market
Totals		6	13	2.07	1,525	3,520	1,000	0											
Totals		25	71	8.97	18,352	8,755	2,850	1,638											

APPENDIX G


Initial Summary Analysis

Spill Data 2002-2006 (Updated)

Agency Name	P P Spills	Total Spills	Percent
Anaheim	88	130	68%
Brea	5	10	50%
Buena Park	16	33	48%
Costa Mesa SD	30	92	33%
Cypress	6	14	43%
El Toro WD	1	15	7%
Fountain Valley	13	18	72%
Fullerton	27	121	22%
Garden Grove	92	173	53%
Huntington Beach	67	119	56%
IRWD	33	53	62%
La Habra	29	77	38%
La Palma	14	19	74%
Midway City SD	9	19	47%
Newport Beach	23	57	40%
OCSD	66	107	62%
Orange	40	113	35%
Placentia	40	22	18%
RLAASD	7	12	58%
Santa Ana	26	59	58 <i>%</i> 44%
Seal Beach	4	10	40%
	4 7		
Stanton		25	28%
Sunset Beach	0	0	00/
Villa Park	0	1	0%
Yorba Linda WD	1	19	5%
Yorba Linda	0	6	0%
Total	608	1324	46%
Orange County HC			
2002	1		
2003	9		
2004	7		
2004	143		
2006	149		
2000	149		
Total	309	=	
Trends (Anaheim)			
2002 (Partial year)	6	14	43%
2003	17	26	65%
2004	20	29	69%
2005	21	27	78%
2006	30	34	88%
		-	

APPENDIX H

Region 8 and 9 Orange County Boundary Line



Region 8 and 9 Orange County Boundary Line

APPENDIX I City of La Palma Sewer Ordinance

ORDINANCE NO. 2007-02

AN ORDINANCE OF THE CITY COUNCIL OF THE CITY OF LA PALMA ADDING SECTION 21-11.1 RELATED TO SEWER MAINTENANCE, REPAIR, DESIGN AND RESTRICTION OF DEPOSIT INTO SEWERS

WHEREAS, the City of La Palma prepared and submitted a Sewer System Management Plan (SSMP) to the California Regional Water Quality Control Board – Santa Ana Region on September 5, 2002 in accordance with the requirement of Order No. R8-2002-0014;

WHEREAS, the Sewer System Management Plan, among other things, required that the City enact an ordinance or other legally binding procedures that:

- (A) Controls infiltration and inflow sources including connections and satellite systems;
- (B) Documents proper design and construction practices for sewers and connections;
- (C) Describes proper installation, testing and inspection of new and rehabilitated ; sewers
- (D) Limits discharge of Fats, Oils, Greases and other Debris; and
- (E) Ensures compliance with the National Pre-treatment Program 40 CFR 403.5.

NOW, THEREFORE, the City Council of the City of La Palma does hereby ordain as follows:

Section 1.

SEC. 11.1 shall be added to Chapter 21 of the La Palma Municipal Code to read in its entirety as follows:

SEC. 21-11.1. <u>Sewer Maintenance, Repair, Design and Restrictions of Deposit into</u> Sewers

- (a) <u>Responsibility: Main House and Connecting Sewer, Repair and Upkeep:</u>
 - The property owner or agent is responsible for the maintenance, repair and upkeep of the connecting sewer and house sewer from the property owner's structure up to and including the point of connection (e.g. wyes, tees, saddles, manhole structures, etc.) to the main sewer line. The property owner or agent is responsible for all routine and emergency cleaning of the connecting sewer and house sewer lines.
 - 2. The city is responsible for the maintenance, repair and upkeep of the main sewer. It shall be the responsibility of the city to keep the main sewer free and clear for the even flow of sewage.

- 3. Should repairs to or replacement of the house sewer or connecting sewer be needed, which will require excavation in the public right-of-way, the property owner or agent must first obtain an encroachment permit from the City of La Palma before the work can begin, in accordance with Section 21-3 through Section 21-12 of this Code.
- (b) <u>Restrictions of Deposit in Sewer:</u> No person shall throw or deposit any material or liquid into any vessel or receptacle directly or indirectly connected to a public sewer that is not in conformance with current Orange County Sanitation District regulations. This shall include, but not be limited to, storm drain discharge, ground water discharge, and toxic or malodorous gases or materials. In addition, the City shall enforce the general and specific prohibitions of the national pretreatment program under Title 40 of the Code of Federal Regulations, Section 403.5, as they pertain to the City's status as a collector system for the Orange County Sanitation District. No person shall therefore introduce any of the following into the city's sewer system:
 - Pollutants which create a fire or explosion hazard in the sewer collection system or the Publicly Owned Treatment Works (POTW), including, but not limited to, waste streams with a closed cup flashpoint of less than 140°F (140 degrees Fahrenheit) or 60°C (60 degrees Centigrade) using the test methods specified in 40 CFR 261.21
 - 2. Pollutants which cause corrosive structural damage to the sewer collection pipes and structures, but in no case discharges with a pH lower than five, unless the works are specifically designed to accommodate such discharges.
 - 3. Solid or viscous pollutants in amounts which will cause obstruction to the flow in the sewer collection system or the POTW, resulting in interference.
 - 4. Any pollutant, including oxygen-demanding pollutants (BOD, etc.) released in a discharge at a flow rate and/or pollutant concentration which will cause interference with the POTW.
 - 5. Heat in amounts which will inhibit biological activity in the POTW resulting in interference, but in no case heat in such quantities that the temperature at the POTW Treatment Plant exceeds 140° (40°C), unless the approval authority, upon request of the POTW, approves alternate temperature limits.
 - 6. Petroleum oil, non-biodegradable cutting oil or products of mineral oil in amounts that will cause interference or pass through.
 - 7. Pollutants which result in the presence of toxic gasses, vapors or fumes within the sewer collection system or the POTW in a quantity that may cause acute worker health and safety problems.
 - 8. Any trucked or hauled pollutants, except at discharge points designated by the POTW.

APPROVED AND ADOPTED by the City Council of the City of La Palma at a regular meeting held on the 16th day of January 2007.

dman. Mavor

ATTEST:

aurie A. Murray, City

STATE OF CALIFORNIA) COUNTY OF ORANGE) SS. CITY OF LA PALMA)

I, LAURIE A. MURRAY, City Clerk of the City of La Palma, California, DO HEREBY CERTIFY that the foregoing Ordinance was adopted by the City Council of said City at a regular meeting of said City Council held on the 16th day of January 2007, and that it was so adopted by called vote as follows:

AYES: Barnes, Charoen, Herman, Rodriguez, Waldman

NOES: None

Laurie A. Murray, City Clerk

APPENDIX J *Private Property BMP Ranking*

Private Property BMP Ranking

BMP Multi Family Dwelling	Effectiveness 1 to 5	Problem Addressed 1 to 5	Cost 1 to 5	Cost Paid by: A = Agency O = Owner T = Tenant	Feasibility	Comments
Educational program to inform property owners of the proper use of the sewer system.	2	3.5	1	O,A	4	
FOG program to collect private property FOG accumulations.	5	5	5	A,O,T	1	AB 939 and other solid waste issues.
Inspection of private lateral following a blockage or overflow.	5	5	1.5	0	5	
Public agency notification to property owners when a deficiency is noted during the agency's maintenance of the sewer main.	5	4.5	0.5	A	4.5	
*Inspection of private lateral on a reoccuring basis based upon the age of the lateral.	5	5	1.5	0	5	
*Inspection of the private lateral conjunctive with the remodel or addition of plumbing fixtures.	4	3	1.5	0	4.5	
*Inspection of the private lateral upon sale or transfer of the property.	4	3	1.5	0	2	
*Certification program for licensed plumbers to perform inspections/repairs.	1	0.5	2	А	3	
*Financial assistance programs for private property owners funded from sewer fees.	5	5	5	A	1	

*Alternate BMP for future.

APPENDIX K

CR&R Waste & Recycling Services Letter

FOG in the Solid Waste Stream

Our Understanding:

OCSD is interested in removing FOG from the sanitary sewer systems and into solid waste containers. Currently there exits commercial efforts for FOG separation; the proposal is to expand this into the residential water generators and place FOG into the solid waste stream.

Question:

Are FOG considered "Solid Waste" as defined in California State regulations? If FOG is a liquid waste (under 50% solids as with sludge and grit), it is restricted from solid waste collection by State law.

Facts:

Haulers have no desire to add any liquid wastes in the Solid Waste Stream due to the following:

- If cities have their solid waste processed at a Material Recovery Facility, the processing trommels and shakers will be clogged-up and will malfunction causing significant repairs and maintenance.
- Material Recovery Facilities in the past several years have spent millions of dollars to revamp processing equipment to produce recovered materials with any value. Adding FOG may cause irreparable damage to recoverable materials, and thusly, needed diversion for the municipalities we serve.
- FOG added to the waste at our Material Processing Centers may cause Health concerns, including rodent and odor issues.
- Containers to be provided for resident collection and storage of FOG may break in the compaction truck and contaminate other products currently being recycled.
- Liquid wastes create unwanted leachate at the landfills.
- Liquids can create leakage from compacter trucks onto public roadways.

If there is an interest in providing containers to residential users for FOG, this will increase "total waste generation" in the communities (both with the containers and the FOG). This is contrary to California Integrated Waste Management Board interests and will negatively impact cities overall diversion; especially if this waste product is intended to be delivered directly to the landfill.

Providing a drop-off alternative for residential users should be considered, or in the alternative, a separate collection procedure.

Is there a value to this product? And if so, recycling the product is a necessity.

By: CR&R Incorporated, Dean Ruffridge

APPENDIX L

City of Santa Barbara Private Lateral Policy

Chapter 14.46 BUILDING SEWER INSPECTIONS

Sections:

14.46.010 Definitions.
14.46.020 Maintenance of Private Building Sewer Laterals.
14.46.030 Building Sewer Inspections – Access to Premises.
14.46.040 Mandatory Building Sewer Inspections.
14.46.050 Requirements for a Proper Building Sewer Lateral Inspection Report.
14.46.060 Required Building Sewer Lateral Repairs.
14.46.070 Common Interest Developments.
14.46.080 Administrative Guidelines for Inspections.

14.46.010 Definitions.

Unless the context indicates otherwise, the following definitions apply to the use of the following terms for the purposes of this Chapter 14.46:

A. BUILDING SEWER LATERAL. That part of the horizontal piping of a drainage system which extends from the end of the building drain and which receives the discharge of the building drain and conveys it to a public sewer, private sewer, individual sewage disposal system, or other point of disposal. For the purposes of this Chapter, a Building Sewer Lateral shall also include a Septic Tank if one exists upon the Property and it is in use.

B. BUILDING SEWER INSPECTION. An inspection of a Building Sewer Lateral that consists of the retention of a licensed plumber (as certified under Section 14.46.050) by the Owner in order to visually examine and inspect a Building Sewer Lateral in the manner deemed appropriate by the City Public Works Director. Such an inspection shall, at a minimum, include the use of a closed-circuit television inspection device for the purposes of determining whether the Building Sewer Lateral complies with the requirements of this Chapter, the Regulation adopted under Section 14.46.080, and any applicable state laws.

C. COMMERCIAL PROPERTY. Any real property not used for residential purposes and not a Common Interest Development.

D. COMMON INTEREST DEVELOPMENT. A development characterized by individual ownership of a condominium housing unit or a residential parcel coupled with the shared ownership of (or right to use) common areas and facilities, including, but not limited to, condominium projects, community apartment projects, stock cooperatives and planned unit developments, which contains three (3) or more dwelling units and which has a Building Sewer Lateral shared by three (3) more dwelling units.

E. NOTICE TO REPAIR. The notice issued by the City Public Works Director to the Owner advising that the Owner appears to be in violation of the Santa Barbara Municipal Code with respect to the Owner's Building Sewer Lateral, or in violation of the Code in the manner of the Building Sewer Lateral's connection to the City sewer system, which order directs the abatement of the identified apparent violation in a timely manner.

F. OWNER. Any person, partnership, association, corporation or fiduciary having legal title (or any partial interest) in any real property situated within the City.

G. SEPTIC TANK. As the term is defined in Santa Barbara Municipal Code Section 14.34.100. (Ord. 5396, 2006.)

14.46.020 Maintenance of Private Building Sewer Laterals.

A. MAINTENANCE OF BUILDING SEWER LATERALS. Each Owner shall maintain his or her Building Sewer Lateral(s) free of displaced joints, open joints, root intrusion, substantial deterioration of the line, cracks, leaks, inflow, or infiltration of extraneous water, root intrusion, grease and

sediment deposits, or any other similar conditions, defects, or obstructions likely to cause or increase the chance for blockage of the Building Sewer Lateral.

B. MAINTENANCE OF SEPTIC TANK. Each Owner shall maintain his or her Septic Tank free of deterioration, corrosion, damage, disposal failure or any other similar deficiencies or defects likely to increase failure of the Septic Tank.

C. GENERAL MAINTENANCE REQUIREMENTS. The maintenance obligation imposed by this Section shall be in addition to and supplemental of the general private sewer system maintenance obligations imposed by Section 14.44.160 of this Code. (Ord. 5396, 2006.)

14.46.030 Building Sewer Inspections – Access to Premises.

The Public Works Director or the City Health Officer (or any designated representative thereof) is hereby authorized to inspect any Building Sewer Lateral in use within the City and connected to the City sewer system for the following purposes:

- 1. To determine the size, depth, and location of any sewer connection.
- 2. To determine the end outlet of any sewer connection by depositing harmless testing materials in any plumbing fixture attached thereto and flushing the same, if necessary.
- 3. To determine, by measurements and samples, the quantity and nature of the sewage or waste water being discharged into any sewer.
- 4. To determine the location of the roof, swimming pool, floor and surface drains, and whether or not they physically connect to a sewer.

Nothing herein shall be deemed to provide the Public Works Director (or the Director's designee) with any right or authority to enter a building or other apparently private or interior area of a real property, except to the extent such entry is expressly authorized by state law. (Ord. 5396, 2006.)

14.46.040 Mandatory Building Sewer Inspections.

A. HEALTH AND SAFETY BASIS FOR REQUIRING A BUILDING SEWER LATERAL INSPECTION. An Owner shall have the Building Sewer Lateral of his or her real property inspected in accordance with the requirements of this Chapter (as directed and within the time period indicated by the Public Works Director) upon the occurrence of any of the following events:

1. Overflow or Malfunction. Whenever the Public Works Director has sufficient evidence (as determined by the Director) that the Building Sewer Lateral has recently overflowed or has recently malfunctioned;

2. Lateral Failure or Lack of Maintenance. Whenever, based on sewer system testing conducted by the City (of either the Building Sewer Lateral or the City's public sewer system), the Public Works Director finds that there is sufficient evidence to conclude that the Building Sewer Lateral has failed, is likely to fail, or has not been properly maintained.

3. Public Health Threat. Upon any other reasonable cause to believe that there is a threat to the public health, safety, or welfare due to the condition of a Building Sewer Lateral.

B. EVENTS REQUIRING A BUILDING SEWER LATERAL INSPECTION – RESIDENTIAL PROPERTIES. An Owner shall have the Building Sewer Lateral of his or her residential Property inspected in accordance with the requirements of this Chapter upon the occurrence of any of the following events:

1. Home Additions. Prior to the issuance of a City building permit for a residential building addition or new improvements on the real property in excess of four (400) hundred square feet of habitable space as that phrase is defined in the Uniform Building Code;

2. New Plumbing Fixtures. Prior to the issuance of a City building permit for two or more new plumbing fixtures attached to the Building Sewer Lateral upon the residential Property.[For the purposes of this section, the phrase "new plumbing fixtures" shall refer only to an increase in the number of plumbing fixtures in use on the real property prior to the application for a building permit for the "new" plumbing fixtures.]

C. SCHEDULE FOR LATERAL INSPECTIONS - NON-RESIDENTIAL AND COMMON INTEREST DEVELOPMENT REAL PROPERTIES.

1. Non-Residential Properties. An Owner or Owners of a non-residential property within the City shall have that Property's Building Sewer Lateral(s) inspected in accordance with the requirements of this Chapter once every ten (10) years beginning January 1st of the year following the adoption of the Ordinance first enacting this Chapter. Within each ten (10) year period of time, such lateral inspections shall occur in accordance with and not later than the Citywide area map and schedule attached to this Chapter as Exhibit 1 and dated as of September 26, 2006, in the order and by district as established on Exhibit 1. [For the purposes of this section, a property which has a mixture of allowed residential and non-residential uses shall be considered a non-residential property with respect to its compliance with the sewer lateral inspection requirements of this section.]

2. Common Interest Developments. The Owner or Owners of a Common Interest Development shall have that Property's Building Sewer Lateral(s) inspected in accordance with the requirement of this Chapter once every ten (10) years beginning January 1st of the second year following the enactment of the Ordinance first enacting this Chapter. Within each ten (10) year period of time, such lateral inspections shall occur in accordance with and not later than the Citywide area map and schedule attached to this Chapter as Exhibit 1 and dated as of September 26, 2006, in the order and by district as established on Exhibit 1, an official full size color copy of which shall remain on file in the City Clerk's office.

D. EXCEPTION TO INSPECTION FOR RECENT PRIOR INSPECTIONS AND REPAIRS.

The following are exceptions to the Inspection requirements of subparagraphs (B) and (C) above:

1. Prior Replacement of Sewer Lateral. An Owner otherwise required to perform a Building Sewer Lateral inspection under Section 14.46.040(B) or (C) hereof shall not be required to perform such an inspection if the Owner (or the Owner's predecessor-in-interest) has originally installed or has replaced his or her Property's Building Sewer Lateral within the twenty (20) years prior to the date of the application for a building permit.

2. Prior Inspection or Repair of a Building Sewer Lateral. An Owner otherwise required to perform an inspection under Section 14.46.040(B) or (C) shall not be required to perform such an inspection if the Owner has either completed a remedial inspection (conducted in accordance with the Inspection requirements of this Chapter) or completed a permitted repair of the Building Sewer Lateral within the three (3) years prior to the date the inspection would otherwise be required. (Ord. 5396, 2006.)

14.46.050 Requirements for a Proper Building Sewer Lateral Inspection Report.

A. INSPECTION REPORT STANDARDS. The Building Sewer Inspection Reports required by this Chapter shall be prepared in accordance with the following requirements and specifications:

- 1. The Inspection Report shall be prepared by a licensed plumber;
- 2. The Inspection Report shall identify all of the following:

a. Any of the following conditions: displaced joints, open joints, root intrusion, substantial deterioration of the line, cracks, leaks, inflow or infiltration of extraneous water, root intrusion, grease and sediment deposits or other conditions likely to increase the chance for blockage of the Building Sewer.

b. Whether any connection, by pipes or otherwise, allows rainwater or groundwater to enter the Building Sewer or public sewer.

c. Whether the Building Sewer has an installed backwater device where any outlet or trap of the Building Sewer is below the level of the nearest manhole. If a backwater device is already installed, the report shall indicate whether the backwater device is functioning properly.

d. Where the Building Sewer includes a Septic Tank, the report shall identify the extent to which the Septic Tank is deteriorated, corroded, damaged, whether the disposal field has failed or any other relevant deficiency.

3. The Inspection Report shall contain an express certification from the certified inspector that the property has been inspected for any outdoor drain connection to the City sewer system and that no

such unpermitted connection is present. It shall also contain either a videotape or DVD of the video inspection of the Building Sewer Lateral in a format acceptable to the City, as established by the City regulations.

B. COMPLIANCE WITH REGULATIONS. The Inspection Report shall, in all other aspects, comply with the requirements and specifications described in the Public Works Director's specifications for a Building Sewer Lateral Inspection Report as established by the regulations authorized under Section 14.46.080 hereof. (Ord. 5396, 2006.)

14.46.060 Required Building Sewer Lateral Repairs.

A. NOTICE TO REPAIR. Upon receipt of the Building Sewer Inspection Report pursuant to this Chapter, the Public Works Director (or his or her designee) will determine whether it indicates any deficiencies in the operation of the Building Sewer Lateral and, thereafter, shall provide the Owner(s) with a Notice to Repair or Replace as may be deemed appropriate by the Director. The Notice to Repair/Replace shall specifically identify the deficiencies to be corrected and shall establish a deadline within which the Owner(s) shall complete the required corrective actions. The corrective action may include a requirement that the lateral be replaced altogether and also may include the installation of cleanouts and backwater valves if those devices are otherwise required by this Code or any uniform code adopted by the City.

B. OBLIGATIONS OF THE OWNER. The Owner shall repair his or her Building Sewer Lateral to the satisfaction of the Public Works Director, and, if a building permit is required for the repairs, the Owner shall obtain a final permit inspection and approval of the City Building Official.

C. REPAIRS UPON OTHER PROPERTIES NOT REQUIRED. If a Building Sewer Lateral traverses private property other than the Owner's Property, the Owner shall only be responsible for the repairs to that portion of the Building Sewer Lateral that are upon the Owner's Property and also to that portion of the Building Sewer within a public right-of-way. (Ord. 5396, 2006.)

14.46.070 Common Interest Developments.

The homeowners association of a Common Interest Development shall, along with the Owner, be jointly and severally liable for the duties and obligations imposed by this Chapter 14.46 in relation to any Building Sewer Lateral located within a common area of the Development. If no homeowners association exists, then the individual unit owners, both jointly and individually, shall be liable for the duties and obligations with respect to Building Sewer Laterals established by this Chapter. (Ord. 5396, 2006.)

14.46.080 Administrative Guidelines for Inspections.

Within ninety (90) days of the adoption of the ordinance enacting this Chapter, the Public Works Director shall prepare and promulgate the public administrative guidelines which shall, among other things, establish the following:

1. A certification program for licensed plumbers who will be accepted by the City to perform Inspections and the basis for obtaining and maintaining such a certification or for a decertification;

2. Develop a standard Inspection report form and specifications for Building Sewer Inspection reports; and

3. Establish a Notice format and standard enforcement timelines for the Notice to Repair and for repair and inspection service of that Notice in a manner consistent with the requirements of due process. Such administrative guidelines shall be approved by a resolution of the City Council. (Ord. 5396, 2006.)

rev. 12/31/06 City of Santa Barbara

APPENDIX M

City of Berkeley Private Lateral Policy

ORDINANCE NO. 6,914–N.S.

ADDING CHAPTER 17.24 TO THE BERKELEY MUNICIPAL CODE REGULATING SEWER LATERALS ON PRIVATE PROPERTY

BE IT ORDAINED by the Council of the City of Berkeley as follows:

Section 1. That Berkeley Municipal Code Chapter 17.24 is added to read as follows:

Chapter 17.24

ABATEMENT OF NONCONFORMING/SUBSTANDARD SEWER LATERALS ON PRIVATE PROPERTY

Sections:

- 17.24.010 Purpose and findings.
- 17.24.020 Definitions.
- 17.24.030 Standards for Maintenance of Private Sewer Laterals.
- 17.24.040 Cleanouts Required.
- 17.24.050 Public Nuisance Conditions.
- 17.24.060 Determination of Public Nuisance by City Engineer Appeal.
- 17.24.070 Correction or Abatement.
- 17.24.080 Inspection at Time of Sale.
- 17.24.090 Inspection at Time of Major Remodel.
- 17.24.100 Reserved.
- 17.24.110 Reserved.
- 17.24.120 Inspection and Repair Requirements.
- 17.24.130 Sewer Lateral Certificates.
- 17.24.140 Exceptions.
- 17.24.150 Reserved.
- 17.24.160 Fees.
- 17.24.170 Violation Penalty.
- 17.24.180 Remedies.
- 17.24.190 Severability.

17.24.010 Purpose and Findings.

A. The purpose of this chapter is to codify requirements for the testing, repair, replacement, and ongoing maintenance of the privately owned sewer laterals within the City of Berkeley.

B. The requirements of this chapter are intended to comply with requirements of the U.S. Environmental Protection Agency (The Clean Water Act (CWA) Section 301(a)), the State of California Water Resources Control Board (California Water Code Section 13243), and the Regional Water Quality Control Board, San Francisco Bay Region (Order No. R2-2004-0010, NPDES Permit No. CA 0038466), for reducing infiltration and inflow in the City of Berkeley sanitary sewer collection system. To this end, this chapter requires that all private sewer laterals be maintained by their owners in accordance with the standards set forth in this chapter.

C. In 1986, the State Regional Water Quality Control Board (SRWQCB), San Francisco Bay Region, in its enforcement of the 1972 Federal Clean Water Quality Act, and the requirement to control sewage overflows, issued a cease and desist order to the East Bay Municipal Utility District (EBMUD),

the City of Berkeley and other East Bay Communities (Order No. 86-17, reissued with Order No. 93-134).

D. In an effort to solve the problem of sewage overflows in compliance with the cease and desist order, the affected jurisdictions jointly developed a compliance plan. The plan used a broad based Sewer System Evaluation Study completed in 1985 by CDM Jordan/Montgomery. The CDM Jordan/Montgomery study found that a significant component of infiltration and inflow (I/I) is infiltration, consisting of groundwater or runoff from rainfall that passes through the soil into defects in the sewer pipes and associated structures.

E. In addition, City staff has observed that there exists in the City numerous non-conforming storm water inflow connections into sewer laterals, such as downspouts and storm drains on private property.

F. The City's evaluation estimates that as much as 40-50% of the I/I peak flows during heavy wet weather events are from private laterals and non-conforming storm drain connections on private property.

G. Infiltration and non-sanitary sewer connections (inflows) are major sources of the I/I that occurs during the rainy season. Evidence supporting this conclusion includes leakage test data, internal inspection by television, smoke test results, conditions documented by "archaeological" type excavations, and direct flow measurements.

H. The CDM Jordan/Montgomery study recommended that the affected jurisdictions update and enforce their sewer ordinances as required to implement the program's recommendations, including an ordinance requiring testing and repair of the privately owned portion of sewer laterals as a condition on the sale of property; and to require all property owners to disconnect nonconforming storm water connections and correct defective sewers identified through smoke testing.

I. In order to meet the Regional Water Quality Control Board and Cease and Desist Order requirements for comprehensive rehabilitation and I/I reduction, it is necessary to address the issues of private lateral repair or replacement, and disconnection of non-sanitary sewer connections to the sanitary sewer system, as set forth in this chapter.

17.24.020 Definitions.

The following terms apply to this chapter and are the same as, or supplement the definitions found in the Berkeley Plumbing Code, Berkeley Municipal Code Chapter 19.36:

A. "Sewer Lateral Certificate" is a certificate issued by the City Engineer indicating that the lateral is in "Satisfactory Condition" as defined herein.

B. "Main line", "Sewer Main", or "Main Sewer" is a common sewer directly controlled by the City of Berkeley.

C. "Lateral", "Building Sewer", or "Lateral Sewer Line" is that part of the horizontal piping of a drainage system which extends from the end of the building drain to the main sewer and conveys the discharge of the building drain to the main sewer.

D. "Private Sewer Lateral" or "Upper Lateral" is the portion of a building sewer from the building drain to a City cleanout, usually located near the curb line. When a building sewer connects to a rear yard sewer main, the entire building sewer or lateral, including the connection to the main sewer, shall be considered a private sewer lateral.

E. "Lower Lateral" or "Lower Lateral Sewer line" is the portion of a building sewer that is located in the public right-of-way or easement and extends from a City cleanout to the main sewer.

F. "Cleanout" is a pipe fitting and associated piping connected to a building sewer or lateral sewer line that provides access to the line for purposes of routine flushing, rodding, cleaning and other maintenance and diagnostic purposes.

G. "Two-Way City Cleanout" or "City Cleanout" is a cleanout at or near the property line or street curb line that is maintained by the City which allows flushing, rodding, cleaning and other maintenance and diagnostic procedures in the sewer lateral.

H. "Private Cleanout" is a cleanout located on the private sewer line.

I. "Satisfactory Condition" is a condition indicated by fulfilling either:

1. Final inspection and approval of a City Building or Plumbing Permit that specifically calls for replacement of the private lateral and disconnection of any area or roof water collection system, including approved redirection of any storm water connections, completed within the previous 20 years; or

2. Approval by the City Engineer of a tape video record of Closed Circuit Television (CCTV) inspection of the private lateral or by a contractor approved by the City Engineer to accomplish such inspection.

J. "Non-sanitary Sewer Connections" is any facility that directly or indirectly conveys storm water, surface water, roof runoff, intercepted groundwater or subsurface drainage into sanitary sewers, including, but not limited to, down spouts, yard drains or other sources of storm water or other run-off.

K. "Structure" is any structure or building as defined in the Berkeley Plumbing Code that is provided with public sewer service by the City of Berkeley.

L. "City Engineer" is the City Engineer or his or her designee.

17.24.030 Standards for Maintenance of Private Sewer Laterals.

A. The standards for maintenance of private laterals are as follows:

1. The private lateral shall be kept free from roots, grease deposits, and other solids, which may impede the flow or obstruct the transmission of waste;

2. All joints shall be tight and all pipes shall be sound;

3. The private lateral shall be free of any structural defects such as cracks, breaks, openings, rodent holes or missing portions, and the grade shall be uniform without sags or offsets;

4. The private lateral shall have cleanouts in accordance with Section 17.24.040. All cleanouts shall be securely sealed with a proper cap at all times; and

5. All non-sanitary sewer connections shall be disconnected and such connections shall be rerouted in accordance with the Berkeley Building and Plumbing Codes and other applicable standards.

B. These standards shall apply to existing private sewer laterals only pursuant to Sections 17.24.050 or 17.24.080 through 17.24.120, or when a person performs any work on a private sewer lateral, in which case such work shall comply with the requirements for repairs and maintenance of private laterals established by the City Engineer and the California Plumbing Code as adopted by the City of Berkeley.

17.24.040 Cleanouts Required.

A. Each sewer lateral shall have a standard two-way cleanout located in the City right-of-way or easement. Such cleanouts shall be installed by the property owner after obtaining all applicable permits from the City.

B. Each private lateral shall also have a privately maintained cleanout within 30 inches of the building or as specified by the California Plumbing Code as adopted by the City of Berkeley, whichever is more restrictive. Such cleanouts shall be installed by the property owner consistent with the California Plumbing Code as adopted by the City of Berkeley, after obtaining all applicable permits from the City.

C. Installation of cleanouts under this section may be undertaken at any time with applicable permits, but shall not be required until testing and/or inspection is required pursuant to Sections 17.24.050, or 17.24.080 through 17.24.120.

17.24.050 Public Nuisance Conditions.

A. A private lateral constitutes a public nuisance when either of the following conditions exists:

1. The piping and fittings have leaks or breaks, or it is otherwise subject to exfiltration or leakage of sewage; or

2. The piping and fittings provide connections other than those permitted by this chapter and the California Plumbing Code as adopted by the City of Berkeley, or is otherwise subject to inflow and infiltration, whether accidentally, negligently, or intentionally.

B. A cleanout constitutes a public nuisance if it:

- 1. Is uncapped or improperly capped;
- 2. Has leaks or breaks or is otherwise subject to exfiltration or leakage of sewage; or

3. Has non-sanitary sewer connections or is otherwise subject to inflow and infiltration, whether accidentally, negligently or intentionally.

17.24.060 Determination of Public Nuisance by City Engineer – Appeal.

A. The City Engineer may require the inspection and/or testing of any private lateral, and may determine and declare that a private lateral or cleanout is a public nuisance as defined in this chapter. Testing and inspection and repairs shall be conducted as set forth in regulations adopted by the City Engineer.

B. If the City Engineer determines and declares that a private lateral or cleanout is a public nuisance, the City Engineer may issue a written notice ordering the property owner to make whatever repairs the City Engineer reasonably deems necessary, within a reasonable period of time that shall be specified in the notice.

C. Determinations under this section may be appealed as set forth in Chapter 1.24.

17.24.070 Correction or Abatement.

A. Owners shall obtain all required plumbing and sewer permits prior to making such repairs, and shall retain the inspection card(s), signed and approved by City inspector(s), as proof of completion of work.

B. Upon approval of such repairs and payment of the required fee, the City Engineer shall issue a Sewer Lateral Certificate.

C. In the event a property does not comply with a final notice and order under Section 17.24.060, the City may abate the public nuisances as set forth in Chapter 1.24.

D. The City may recover any costs incurred in abating a public nuisance under this chapter, as set forth in Chapter 1.24.

17.24.080 Inspection at Time of Sale.

A. Prior to the sale of property that contains any structure with a building sewer line that was installed more than 20 years prior to the sale of the property, the owner shall have the building sewer line tested for infiltration and inflow.

B. All required repair or replacement work shall be completed prior to transfer of title. Alternatively, funds may be retained in escrow, or a bond may be posted, sufficient to complete the work within six months thereafter, if permitted by, and subject to any conditions required by, the City Engineer. Except as otherwise provided in this chapter or by the City Engineer, the owner of the property is responsible for compliance with this section.

C. The seller of any real property shall be responsible for disclosing to prospective purchasers that the requirements of this chapter and the compliance status of the real property in question.

17.24.090 Inspection at Time of Major Remodel.

A. Whenever a person applies for a building and/or plumbing permit for a construction valuation that exceeds either \$100,000, or \$50,000 when involving two or more plumbing fixtures, in 2005 dollars, adjusted every year for inflation as shown in the Master Fee Schedule, the property owner shall have the building sewer line tested for infiltration and inflow, unless he or she presents satisfactory proof to the City Engineer that the private lateral sewer line is less than 20 years old or has been repaired but not completely replaced within the last 10 years.

B. In order to ensure compliance with this section, the property owner shall obtain a Sewer Lateral Certificate prior to approval of a building permit application for that work.

C. The City of Berkeley Building Official is hereby authorized to implement this section.

17.24.100 Reserved.

17.24.110 Reserved.

17.24.120 Inspection and Repair - Requirements.

A. All testing and inspection procedures shall be in accordance with standard procedures, or reviewed and approved by the City Engineer.

B. CCTV inspections shall be performed by a qualified licensed plumbing contractor or utility evaluation service, unless the owner presents satisfactory proof to the City Engineer that the private lateral is less than 20 years old or has been repaired but not completely replaced within the last 10 years.

C. All repair or replacement work identified by the testing procedure as necessary to prevent infiltration and inflow must be completed and approved by the City Engineer.

D. If non-sewer connections to the private lateral sewer line are found, the property owner will be required to disconnect them and contain, disperse on site, or redirect, storm water run-off within six months, as required by the City Engineer, unless granted an exception under Section 17.24.140.

E. The property owner shall submit a copy of the inspection card, signed and approved by a City inspector, as proof of compliance.

F. Failure to comply with an order issued under this section shall be deemed a violation of this chapter, and the condition of the private lateral sewer line in such cases shall be deemed, and is hereby declared, a public nuisance.

17.24.130 Sewer Lateral Certificates.

A. All properties governed by this chapter are required to obtain Sewer Lateral Certificates. Sewer Lateral Certificates shall be issued by the City Engineer upon sufficient proof that a property owner has complied with this chapter, and upon payment of any required fee.

B. Sewer Lateral Certificates shall be effective for the following periods of time:

- 1. A period of 10 years after:
- a. Acceptance of a test performed under this chapter if no repairs were required;

b. Inspection and approval by the City of completed alterations (partial repairs) to a lateral of or connections to a lateral;

c. Inspection and approval by the City of completed repairs to a lateral or cleanout ordered by the City Engineer.

2. A period of 20 years after inspection and approval by the City of replacement of the private lateral.

17.24.140 Exceptions.

The City Engineer may waive inspections under Sections 17.24.080 through 17.24.90, and/or repairs under Section 17.24.120, if he or she determines that compliance is infeasible.

17.24.150 Reserved.

17.24.160 Fees.

The City Council may establish fees by resolution for administration of this chapter.

17.24.170 Violation – Penalty.

Any violation of any provisions of this chapter shall be deemed a misdemeanor but may be cited and prosecuted, in the discretion of the enforcing officer, as an infraction, and shall be punishable as set forth in Chapter 1.20 of this Code.

17.24.180 Remedies.

The remedies specified in this chapter are cumulative.

17.24.190 Severability.

If any article, section, subsection, paragraph, sentence, clause or phrase of this chapter for any reason shall be held to be invalid or unconstitutional, the decision shall not affect the remaining portions of this chapter. The Council of the City of Berkeley hereby declares that it would have passed this chapter and each article, section, subsection, paragraph, sentence, clause or phrase which is a part thereof, irrespective of the fact that anyone or more articles, sections, subsections, paragraphs, sentences, clauses or phrases are declared to be invalid or unconstitutional.

Section 2. This ordinance shall be effective July 1, 2006.

Section 3. Copies of this Ordinance shall be posted for two days prior to adoption in the display case located near the walkway in front of Old City Hall, 2134 Martin Luther King Jr. Way. Within 15 days of adoption, copies of this Ordinance shall be filed at each branch of the Berkeley Public Library and the title shall be published in a newspaper of general circulation.

At a regular meeting of the Council of the City of Berkeley held on April 18, 2006, this Ordinance was passed to print and ordered published by posting by the following vote:

Councilmembers Anderson, Capitelli, Maio, Moore, Olds, Spring, Worthington, Ayes: Wozniak and Mayor Bates.

Noes: None.

Absent: None.

At a regular meeting of the Council of the City of Berkeley held on April 25, 2006, this Ordinance was adopted by the following vote:

Councilmembers Capitelli, Maio, Moore, Olds, Wozniak and Mayor Bates. Ayes:

Noes: None.

Absent: Councilmember Anderson.

Tom Bates, Mayor

ATTEST:

Sara T. Cox, City Clerk

In effect: May 25, 2006.

APPENDIX N

City of Burlingame Private Lateral Policy


CITY OF BURLINGAME BUILDING SEWERS ORDINANCE TESTING PROCEDURE CODE REQUIREMENT

PRIVATE SEWER LATERAL AND TESTING PROCEDURE AND REQUIREMENTS

Ordinance No. 1329, which was adopted July 7, 1986 and became effective August 7, 1986 and was modified by Ordinance 1623 on March 23, 2000, requires the abatement of sewer laterals and cleanouts which are found to contain leaks or separations; laterals covered are from the building served to the cleanout in the City right-of-way. The ordinance also requires the testing and repair of laterals prior to the sale of property if the building was constructed 25 years or more before the date of sale. Date of construction shall be the date the Building Permit was finaled. In addition, testing is required if two (2) or more plumbing fixture units are added to a property. The following procedures and requirements are adopted to implement Ordinance No. 1329.

It shall be the owner's responsibility to determine if testing is needed. Contact the Building Department to determine the age of the structure and if the lateral had been tested and/or repaired within the past ten (10) years. It can be assumed that testing and repairs have not been done unless the property has been sold after August 1986. If the lateral needs testing, the property owner shall obtain a contractor or plumber to perform the test. The test shall be performed as follows:

- 1. The test must be witnessed by a City representative. Call (650) 558-7230 to make an appointment. All arrangements and set up should be completed by the time the City representative arrives to witness the test.
- 2. Each lateral is to have a cleanout located in the City right-of-way. If one does not exist, a cleanout shall be installed. The private owner's contractor will install the cleanout with an Encroachment Permit from the Department of Public Works. City personnel will spend a limited amount of time to assist in locating the cleanout or lateral. A cleanout located adjacent to the building will be a help in testing and repairing and is also required by the Uniform Plumbing Code. A Plumbing Permit is required for the cleanout adjacent to the building.
- 3. Testing will be accomplished by either a water exfiltration test or an air test. The air test shall be used in hillside areas where the hydraulic head pressures are too high.
- 4. If the lateral fails the test, the lateral shall be either repaired or replaced and retested until the lateral passes. There will be a \$10 fee for the second retest and each retest thereafter, payable at the Department of Public Works. A Plumbing Permit will be required for any repairs or replacement. A complete replacement from building to City cleanout is effective for 25 years. A repaired and tested lateral is effective for ten (10) years.
- 5. The City neither has not will make any determination as to who will pay for the testing and repairing. That is to be decided between the parties involved in the sale.



Length of Rod in Angle riser 0.45 Degrees (in feet)	Vertical Depth to lateral at clean Out (in feet)	Test Pressures min. of 4 psi (in psi) See Note #1
1	0.7	4.0
2	1.4	4.0
3	2.1	4.0
4	2.8	4.0
5	3.5	4.2
6	4.2	4.5
7	4.9	4.8
8	5.7	5.2
9	6.4	5.5
10	7.1	5.8
11	7.8	6.1
12	8.5	6.4
13	9.2	5.7
14	9.9	7.0
15	10.5	7.3
16	11.3	7.6

Note:

1. Ground water is assumed at 3'-0" below grade.

APPENDIX O

City of Pacific Grove Certified Plumbers List



PLUMBER RESOURCE LIST

FOR PROPERTY OWNER LATERAL LINE INSPECTION SERVICES

- City of Pacific Grove and Monterey Regional Water Pollution Control Agency -



Business Name	Years Experience in Pacific Grove	VHS or DVD CCTV	P.G. Business License #	Contractors License #	Phone Number
Partners in Sewage Spill Prevention: The following businesses for participating in	• • •	•	0		ncy recognize the
A & R Plumbing	30	VHS	88	300628	394-7221
Ben Franklin Plumbing	27	VHS	8367	531809	394-3475
Crazy Drains	5+	VHS	8345	833944	649-2500
Mr. Rooter Plumbing	11	VHS	5834	783377	373-6100
Peninsula Plumbing	2+	DVD	8447	814252	899-0600
PSTS, Inc.	42	VHS	29	494738	659-2465
R.K. Wilson Plumbing	15	VHS	6240	544519	899-4864
Wilson's Plumbing and Heating	63	VHS	162	312880	375-4591
Other Businesses: Other businesses that m	ay be qualified to conduct	lateral line inspec	tion services.		
Acme Plumbing	5+	VHS	7458	755124	649-2312
Alvarez Plumbing	~25	VHS	7958	404419	757-5465
American Plumbing	30	VHS	1056	714206	394-3100
ARS/Rescue Rooter	5	VHS	7930	645050	(408) 287-2165
Chris Wilson Plumbing & Heating	5+	VHS	7580	772474	393-9321
Marina Plumbing and Hardware	30	VHS	1049	574447	384-8206
Quality Plumbing	6	VHS	7862	757742	775-0201
Ramirez Plumbing	15	DVD	7834	774622	393-9804
Roto-Rooter Plumbing & Drain Service	50	VHS	133	277615 C36	372-8303
Val's Plumbing & Heating	50	VHS	142	236164	424-1633

Note: This list is intended as a resource for Pacific Grove property owners seeking certified plumbers to inspect their sewer lateral lines. The City of Pacific Grove and Monterey Regional Water Pollution Control Agency do not recommend or endorse any business listed and is not responsible for the accuracy of the information provided herein. For additional information please call the Community Development Department at (831) 648-3199 or visit http://www.ci.pg.ca.us/sewers